

Proposed Rules

Federal Register

Vol. 88, No. 17

Thursday, January 26, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-0017; Project Identifier AD-2022-01418-T]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company Model 757 airplanes. This proposed AD was prompted by the potential for cracks to start in hidden areas underneath the scuff plates in the fuselage skin and bear strap of certain doors. This proposed AD would require an inspection or a maintenance records check for repairs in the areas around the fuselage skin door cutout lower corners of certain doors, and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by March 13, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket

No. FAA-2023-0017; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website *myboeingfleet.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at *regulations.gov* by searching for and locating Docket No. FAA-2023-0017.

FOR FURTHER INFORMATION CONTACT:

Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712 4137; phone: 562-627-5234; email: *Peter.Jarzomb@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-0017; Project Identifier AD-2022-01418-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712 4137; phone: 562-627-5234; email: *Peter.Jarzomb@faa.gov*. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA has received a report indicating operators of Model 767 airplanes have reported cracks in the fuselage skin and bear strap under the No. 1 and No. 2 passenger entry door scuff plates at the aft lower corners of the fuselage skin door cutout. Although no cracks have been reported at these locations on Model 757 airplanes in service, both Model 757 and 767 airplanes have the potential for cracks to start in hidden areas underneath the scuff plates caused by higher fatigue stresses at the fuselage skin door cutout lower corners. In addition, similar lower door corner skin and bear strap cracks were found on the Model 757 fatigue test article at the No. 2 and No. 4 passenger entry doors, and the forward cargo door. Certain maintenance inspections do not include a step to remove the scuff plates, which also contributes to the inability to find cracks before they become critical. Cracks underneath the scuff plates in the fuselage skin and bear strap, if not addressed, could adversely affect the structural integrity of the airplane.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 757–53A0119 RB, dated October 12, 2022. This service information specifies procedures for either a general visual inspection or a maintenance records check for repairs in the areas around the fuselage skin door cutout lower corners of the No. 1, No. 2, and No. 4 passenger entry doors;

crew entry door; No. 1, No. 2, and No. 3 cargo doors; and main deck cargo door; and applicable on-condition actions, including repetitive low frequency and high frequency eddy current inspections for cracks in the skin or bear strap in the unrepaired areas, and crack repair. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in

the service information already described except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this service information at *regulations.gov* by searching for and locating Docket No. FAA–2023–0017.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 482 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
General visual inspection for repairs	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$40,970

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of the proposed inspection. The agency has no way of determining

the number of aircraft that might need these on-condition actions:

ON-CONDITION COSTS

Labor cost	Parts cost	Cost per product
Up to 27 work-hours × \$85 per hour = \$2,295	(*)	Up to \$2,295.

* The FAA has received no definitive data on which to base the cost estimates for parts required for any on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order

13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

The Boeing Company: Docket No. FAA–2023–0017; Project Identifier AD–2022–01418–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by March 13, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 757–200, –200PF, –200CB, and –300 series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by the potential for cracks to start in hidden areas underneath the scuff plates in the fuselage skin and bear strap of certain doors. The FAA is issuing this AD to address cracks caused by higher fatigue stresses at the fuselage skin door cutout lower corners. This unsafe condition, if not addressed, could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-53A0119 RB, dated October 12, 2022, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0119 RB, dated October 12, 2022.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757-53A0119, dated October 12, 2022, which is referred to in Boeing Alert Requirements Bulletin 757-53A0119 RB, dated October 12, 2022.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time column and notes of the tables in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-53A0119 RB, dated October 12, 2022, use the phrase "the original issue date of Requirements Bulletin 757-53A0119 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 757-53A0119RB, dated October 12, 2022, specifies "General Visual Inspection (GVI) or a maintenance records check for any existing repair", if only a Maintenance Records Check is accomplished with no GVI, then any directly follow-on condition actions that specify a compliance time "Before further flight" are required prior to the accumulation of 30,000 total flight cycles, or within 3,000 flight cycles after the effective date of this AD, whichever occurs later.

(3) Where Boeing Alert Requirements Bulletin 757-53A0119 RB, dated October 12, 2022, specifies contacting Boeing for repair instructions or for alternative inspections: This AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions, before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures

found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: *9-ANM-LAACO-AMOC-Requests@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Peter Jarzomb, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712 4137; phone: 562-627-5234; email: *Peter.Jarzomb@faa.gov*.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757-53A0119 RB, dated October 12, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website *myboeingfleet.com*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, *fr.inspection@nara.gov*, or go to: *www.archives.gov/federal-register/cfr/ibr-locations.html*.

Issued on January 11, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-01463 Filed 1-25-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Office of the Secretary****14 CFR Part 399**

[Docket No. DOT-OST-2022-0109]

RIN 2105-AF10

Enhancing Transparency of Airline Ancillary Service Fees

AGENCY: Office of the Secretary (OST), Department of Transportation (DOT or the Department).

ACTION: Denial of Request for Extension of Comment Period.

SUMMARY: The U.S. Department of Transportation (Department or DOT) declines to extend the comment period beyond January 23, 2023 for its proposed rule on Enhancing Transparency of Airline Ancillary Service Fees.

DATES: Comments on the rulemaking should be filed by January 23, 2023. Late-filed comments will be considered to the extent practicable. Petitions for a hearing pursuant to 14 CFR 399.75(b)(1) must also be filed by January 23, 2023.

ADDRESSES: You may file comments identified by the docket number DOT-OST-2022-0109 by any of the following methods:

- *Federal eRulemaking Portal:* go to *https://www.regulations.gov* and follow the online instructions for submitting comments.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Ave. SE, West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* West Building Ground Floor, Room W12-140, 1200 New Jersey Ave. SE, Washington, DC, between 9 a.m. and 5 p.m. ET, Monday through Friday, except Federal holidays. Commenters using this method of delivery should contact Docket Services at 202-366-9826 or 202-366-9317 before delivery to ensure staff is available to receive the delivery.

- *Fax:* (202) 493-2251.

Instructions: You must include the agency name and docket number DOT-OST-2022-0109 or the Regulatory Identification Number (RIN 2105-AF10) for the rulemaking at the beginning of your comment. All comments received will be posted without change to *https://www.regulations.gov*, including any personal information provided.

Privacy Act: Anyone is able to search the electronic form of all comments received in any of our dockets by the name of the individual submitting the comment (or signing the comment, if