

to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD or email to: ANE-AD-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

(1) For more information about this AD, contact Sungmo Cho, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7241; email: sungmo.d.cho@faa.gov.

(2) For service information identified in this AD that is not incorporated by reference, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, DE24 8BJ, United Kingdom; phone: +44 (0)1332 242424; fax: +44 (0)1332 249936; website: rolls-royce.com/contact-us.aspx. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency AD 2022-0129, dated June 30, 2022.

(ii) [Reserved]

(3) For EASA AD 2022-0129, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on February 17, 2023.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-04860 Filed 3-9-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0521; Project Identifier MCAI-2022-00273-T; Amendment 39-22187; AD 2022-20-03]

RIN 2120-AA64

Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain MHI RJ Aviation ULC Model CL-600-2C10 (Regional Jet Series 700, 701 & 702); CL-600-2C11 (Regional Jet Series 550); CL-600-2D15 (Regional Jet Series 705); CL-600-2D24 (Regional Jet Series 900); and CL-600-2E25 (Regional Jet Series 1000) airplanes. This AD was prompted by laboratory tests that showed that the oxygen tubes of the crew oxygen system may be contaminated with lubricants, as a result of the manufacturing and cleaning procedures used. This AD requires cleaning and flushing the crew oxygen system. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 14, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 14, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2022-0521; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For service information identified in this final rule, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America

toll-free telephone 833-990-7272 or direct-dial telephone 450-990-7272; fax 514-855-8501; email thd.crj@mhirj.com; website mhirj.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2022-0521.

FOR FURTHER INFORMATION CONTACT:

Chirayu Gupta, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain MHI RJ Aviation ULC Model CL-600-2C10 (Regional Jet Series 700, 701 & 702); CL-600-2C11 (Regional Jet Series 550); CL-600-2D15 (Regional Jet Series 705); CL-600-2D24 (Regional Jet Series 900); and CL-600-2E25 (Regional Jet Series 1000) airplanes. The NPRM published in the **Federal Register** on May 17, 2022 (87 FR 29841). The NPRM was prompted by AD CF-2022-06, dated February 28, 2022, issued by Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada (referred to after this as the MCAI). The MCAI states that laboratory tests showed that the oxygen tubes of the crew oxygen system may be contaminated with lubricants, as a result of the inadvertent use of a non-conforming aqueous degreasing process for oxygen line flushing and cleaning during the manufacturing process. If not corrected, lubricant remaining in oxygen lines could lead to a fire within the oxygen tubes or a health hazard related to the inhalation of lubricant fumes through the masks when masks are in use.

In the NPRM, the FAA proposed to require cleaning and flushing the crew oxygen system. The FAA is issuing this AD to address the contaminated oxygen tubes of the crew oxygen system, which could lead to a fire within the oxygen tubes, or a health hazard related to the inhalation of lubricant fumes when the masks are in use.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2022-0521.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from MHI RJ Aviation ULC. The following presents the comment received on the NPRM and the FAA’s response to the comment.

Request To Change MHI RJ Contact Information

MHI RJ Aviation ULC requested that the NPRM be revised to correct its contact information.

The FAA has included the correct contact information under **ADDRESSES** in this final rule and in paragraph (k)(3) of this AD.

Conclusion

This product has been approved by the aviation authority of another

country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

The FAA reviewed MHI RJ Service Bulletin 670BA–35–016, Revision B,

dated December 17, 2021. This service information specifies procedures for low-pressure and high-pressure cleaning of the crew oxygen tubes. The tasks include cleaning the end fittings and threads, cleaning the inner wall of the tubes with solvent, and flushing the inner wall of the tubes with nitrogen.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD would affect 34 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
51 work-hours × \$85 per hour = \$4,335	Up to \$1,240	Up to \$5,575	Up to \$189,550.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–20–03 MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.): Amendment 39–22187; Docket No. FAA–2022–0521; Project Identifier MCAI–2022–00273–T.

(a) Effective Date

This airworthiness directive (AD) is effective April 14, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier, Inc.) airplanes identified in paragraphs (c)(1) through (4) of this AD, certificated in any category.

(1) Model CL–600–2C10 (Regional Jet Series 700, 701 & 702) and CL–600–2C11 (Regional Jet Series 550) airplanes, serial numbers 10346 and 10347.

(2) Model CL–600–2D15 (Regional Jet Series 705) and CL–600–2D24 (Regional Jet Series 900) airplanes, serial numbers 15413 through 15484 inclusive.

(3) Model CL–600–2E25 (Regional Jet Series 1000) airplanes, serial numbers 19049 through 19064 inclusive.

(4) Model CL–600–2C10, CL–600–2C11, CL–600–2D15, CL–600–2D24 and CL–600–2E25 airplanes equipped with tube part numbers installed after the dates indicated in Section 1.A.(2) of MHI RJ Service Bulletin (SB) 670BA–35–016, Revision B, dated December 17, 2021.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Unsafe Condition

This AD was prompted by laboratory tests that showed that the oxygen tubes of the crew oxygen system may be contaminated with lubricants, as a result of the manufacturing and cleaning procedures. The

FAA is proposing this AD to address the contaminated oxygen tubes of the crew oxygen system, which could lead to a fire within the oxygen tubes, or a health hazard related to the inhalation of lubricant fumes when the masks are in use.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Within 8,800 flight hours after the effective date of this AD, clean and flush the crew oxygen system, in accordance with the Accomplishment Instructions of MHI RJ Service Bulletin 670BA-35-016, Revision B, dated December 17, 2021.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by this AD, if those actions were performed before the effective date of this AD, using the service information identified in paragraph (h)(1) or (2) of this AD.

(1) MHI RJ Service Bulletin 670BA-35-016, dated February 26, 2021.

(2) MHI RJ Service Bulletin 670BA-35-016, Revision A, dated November 5, 2021.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or MHI RJ Aviation ULC's TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

(1) Refer to TCCA AD CF-2022-06, dated February 28, 2022, for related information. This TCCA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-0521.

(2) For more information about this AD, contact Chirayu Gupta, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) MHI RJ Service Bulletin 670BA-35-016, Revision B, dated December 17, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America toll-free telephone 833-990-7272 or direct-dial telephone 450-990-7272; fax 514-855-8501; email thd.crj@mhjr.com; website mhjr.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on September 13, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

Editorial Note: This document was received for publication by the Office of the Federal Register on March 7, 2023.

[FR Doc. 2023-04946 Filed 3-9-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0873; Project Identifier MCAI-2022-00060-T; Amendment 39-22183; AD 2022-19-14]

RIN 2120-AA64

Airworthiness Directives; Embraer S.A. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Embraer S.A. Model EMB-545 and EMB-550 airplanes. This AD was prompted by a report that there is a possibility of the shoulder belt getting stuck during flight due to a step between the divan shroud chamfer and the sideledge panel. This AD requires

installing, on the right- and left-hand side divan, a protective fairing covering on the divan shroud and the sideledge panel, as specified in an Agência Nacional de Aviação Civil (ANAC) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 14, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 14, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-0873; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference (IBR) in this AD, contact ANAC, Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246-190—São José dos Campos—SP, Brazil; telephone 55 (12) 3203-6600; email pac@anac.gov.br; website anac.gov.br/en/. You may find this IBR material on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-0873.

FOR FURTHER INFORMATION CONTACT: Ho-Joon Lim, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3405; email ho-joon.lim@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Embraer S.A. Model