

pipes on the lower fuselage truss for corrosion, and a general visual inspection of the pipes on the lower fuselage truss for rivets with missing stems, in accordance with steps 13 and 14 of Part A, in Part 2, Work Procedure, of Vulcanair Aircraft V1 series Service Bulletin VA-22, rev. 0, dated June 15, 2022 (Vulcanair SB VA-22).

(1) If, during the inspections required by the introductory text of paragraph (g) of this AD, no missing sealant and no corrosion of the LH and RH lower rear attachments are detected, and no corrosion and no missing rivet stems of the lower fuselage truss pipes are detected, before further flight, install part number (P/N) 5034-011 plugs on both the RH and LH rear attachments, in accordance with step 16 of Part A, in Part 2, Work Procedure, of Vulcanair SB VA-22. After installation of the plugs, no further action is required by this AD.

(2) If, during the inspections required by the introductory text of paragraph (g) of this AD, corrosion, missing sealant, or missing rivet stems are detected, before further flight, do the following as applicable:

(i) If corrosion or missing sealant is detected during the detailed visual inspection or tactile inspection of the RH and LH lower rear attachments, remove any sealant and do a detailed visual inspection for corrosion in accordance with step 26 of Part B, in Part 2, Work Procedure, of Vulcanair SB VA-22.

(ii) If corrosion or missing rivet stems are detected during the general visual inspection of the lower fuselage truss pipes, do a detailed visual inspection and tap test for corrosion in accordance with steps 27 and 28 of Part B, in Part 2, Work Procedure, of Vulcanair SB VA-22.

(3) If, during any inspection required by paragraph (g)(2) of this AD, any corrosion is detected on the lower fuselage truss, before further flight, contact the Manager, International Validation Branch, FAA; or European Union Aviation Safety Agency (EASA); or Vulcanair's EASA Design Organization Approval (DOA) for corrective action instructions and do the corrective actions. If approved by the DOA, the approval must include the DOA-authorized signature.

(4) If, during the inspections required by paragraph (g)(2) of this AD, no corrosion is detected, before further flight, apply sealant on rivets with absent stems, restore as necessary the sealant inside the RH and LH lower rear attachments, and install plugs P/N 5034-011 on both the RH and LH rear attachments, in accordance with the instructions in steps 31 and 32 of Part B, in Part 2, Work Procedure, of Vulcanair SB VA-22.

#### (h) Special Flight Permits

Special flight permits are prohibited.

#### (i) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local

Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j)(2) of this AD or email to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov). If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Additional Information

(1) Refer to EASA AD 2022-0155, dated August 1, 2022, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1218.

(2) For more information about this AD, contact John DeLuca, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (516) 228-7369; email: [john.p.deluca@faa.gov](mailto:john.p.deluca@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Vulcanair Aircraft V1 series Service Bulletin VA-22, rev. 0, dated June 15, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Vulcanair S.p.A., via G. Pascoli, 7, 80026 Casoria (NA), Italy; phone: +39 081 5918111; email: [info@vulcanair.com](mailto:info@vulcanair.com); website: [support.vulcanair.com](https://support.vulcanair.com).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](https://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on June 20, 2023.

**Gaetano A. Sciortino,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023-13497 Filed 6-26-23; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1398; Project Identifier AD-2023-00472-P]

RIN 2120-AA64

#### Airworthiness Directives; Hamilton Sundstrand Corporation Propellers

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Hamilton Sundstrand Corporation (Hamilton Sundstrand) Model 14SF-17 and 14SF-19 propellers. This proposed AD was prompted by a report of an auxiliary motor and pump failing to feather a propeller in flight. This proposed AD would require replacement of a certain auxiliary motor and pump. This proposed AD would also prohibit installation of a certain auxiliary motor and pump on any propeller. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by July 27, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA-2023-1398; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For service information identified in this NPRM, contact Hamilton Sundstrand, One Hamilton Road, Windsor Locks, CT 06096-1010, phone: (877) 808-7575; email: [CRC@collins.com](mailto:CRC@collins.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

**FOR FURTHER INFORMATION CONTACT:** Isabel Saltzman, Aviation Safety Engineer, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (781) 238-7649; email: [9-AVS-AIR-BACOCOS@faa.gov](mailto:9-AVS-AIR-BACOCOS@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1398; Project Identifier AD-2023-00472-P” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

The FAA has been informed that Hamilton Sundstrand has done some outreach with affected operators regarding the proposed corrective actions for this unsafe condition. As a result, affected operators are already aware of the proposed corrective actions and, in some cases, have already begun planning for replacement of certain auxiliary motors and pumps. Therefore, the FAA has determined that a 30-day comment period is appropriate given the particular circumstances related to the proposed correction of this unsafe condition.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each

substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Isabel Saltzman, Aviation Safety Engineer, FAA, 1701 Columbia Avenue, College Park, GA 30337. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA received a report of an auxiliary motor and pump installed on a non-Hamilton Sundstrand propeller failing to feather the propeller in flight through either the primary or the backup means. The failure was caused by motor magnets in the auxiliary motor and pump that were de-bonded due to corrosion at the magnet and housing interface. The de-bonded motor magnets prevented motor rotation. Hamilton Sundstrand Model 14SF-17 and 14SF-19 propellers use the same auxiliary motor and pump. These propellers are installed on, but not limited to, Viking Air Limited (Type Certificate previously held by Bombardier Inc.; Canadair Limited) Model CL-215-6B11 (CL-215T & CL-415 Variants) airplanes. This condition, if not addressed, could result in reduced controllability of the aircraft and consequent loss of control of the aircraft.

**FAA’s Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed Hamilton Sundstrand Service Bulletin (SB) 14SF-61-168, Revision 1, dated December 21, 2016. This service information specifies instructions for replacing the auxiliary motor and pump. Hamilton Sundstrand Corporation is a UTC Aerospace Systems Company. This service information is identified as both Hamilton Sundstrand Corporation and UTC Aerospace Systems. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

**Proposed AD Requirements in This NPRM**

This proposed AD would require the removal from service of an auxiliary motor and pump having part number (P/N) 782655-3 (Aerocontrollex P/N 4122-006009) and replacement with an auxiliary motor and pump having P/N 782655-4 (Aerocontrollex P/N 4122-056000). This proposed AD would also prohibit installation of an auxiliary motor and pump having P/N 782655-3 (Aerocontrollex P/N 4122-006009) on any propeller.

**Differences Between This Proposed AD and the Service Information**

Where the service information specifies returning certain parts to Hamilton Sundstrand, this proposed AD does not contain that requirement.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 20 propellers installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace auxiliary motor and pump.	2 work-hours × \$85 per hour = \$170 .....	\$11,000	\$11,170	\$223,400
Perform post-installation system test.	1 work-hour × \$85 per hour = \$85 .....	0	85	1,700

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Hamilton Sundstrand Corporation:** Docket No. FAA-2023-1398; Project Identifier AD-2023-00472-P.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by July 27, 2023.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Hamilton Sundstrand Corporation (Hamilton Sundstrand) Model 14SF-17 and 14SF-19 propellers.

**Note 1 to paragraph (c):** These propellers are known to be installed on, but not limited to, Viking Air Limited (Type Certificate previously held by Bombardier Inc.; Canadair Limited) Model CL-215-6B11 (CL-215T and CL-415 Variants) airplanes.

#### (d) Subject

Joint Aircraft System Component (JASC) Code 6123, Propeller Feathering/Reversing.

#### (e) Unsafe Condition

This AD was prompted by a report of an auxiliary motor and pump failing to feather a propeller in flight. The FAA is issuing this AD to prevent the failure of a certain auxiliary motor and pump to feather propellers. The unsafe condition, if not addressed, could result in reduced controllability of the aircraft and consequent loss of control of the aircraft.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

(1) Within 90 days after the effective date of this AD, remove from service an auxiliary motor and pump having part number (P/N) 782655-3 (Aerocontrolex P/N 4122-006009) and replace with an auxiliary motor and pump having P/N 782655-4 (Aerocontrolex P/N 4122-056000) in accordance with the Accomplishment Instructions, paragraphs 3.B., 3.C., and 3.E. of Hamilton Sundstrand Service Bulletin (SB) 14SF-61-168, Revision 1, dated December 21, 2016 (Hamilton Sundstrand SB 14SF-61-168, Revision 1).

(2) After replacement of the auxiliary motor and pump, perform a post-installation system test in accordance with the Accomplishment Instructions, paragraph 3.F. of Hamilton Sundstrand SB 14SF-61-168, Revision 1.

#### (h) Installation Prohibition

After the effective date of this AD, do not install an auxiliary motor and pump having P/N 782655-3 (Aerocontrolex P/N 4122-006009) on any propeller.

#### (i) No Return of Parts

Where the service information referenced in the Accomplishment Instructions, paragraph 3.B. of Hamilton Sundstrand SB

14SF-61-168, Revision 1, specifies returning certain parts to the manufacturer for modification, this AD does not include that requirement.

#### (j) Credit for Previous Actions

You may take credit for the actions required by paragraph (g) of this AD if you performed those actions before the effective date of this AD using Hamilton Sundstrand SB 14SF-61-168, Original Issue, dated December 14, 2016.

#### (k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, East Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the branch office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: 9-AVS-AIR-BACO-COS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (l) Related Information

(1) For more information about this AD, contact Isabel Saltzman, Aviation Safety Engineer, FAA, 1701 Columbia Avenue, College Park, GA 30337; phone: (781) 238-7649; email: 9-AVS-AIR-BACO-COS@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (4) of this AD.

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Hamilton Sundstrand Corporation Service Bulletin 14SF-61-168, Revision 1, dated December 21, 2016.

**Note 2 to paragraph (m)(2)(i):** Hamilton Sundstrand Corporation is a UTC Aerospace Systems Company. This service information is identified as both Hamilton Sundstrand Corporation and UTC Aerospace Systems.

(ii) [Reserved]

(3) For service information identified in this AD, contact Hamilton Sundstrand, One Hamilton Road, Windsor Locks, CT 06096-1010, phone: (877) 808-7575; email: CRC@collins.com.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on

the availability of this material at NARA, email: [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on June 21, 2023.

**Michael Linegang,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2023-13582 Filed 6-26-23; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-1220; Project Identifier MCAI-2023-00478-T]

RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A330-200 series airplanes; Model A330-200 Freighter series airplanes; Model A330-300 series airplanes; Model A330-800 series airplanes; Model A330-900 series airplanes; Model A340-200 series airplanes; and Model A340-300 series airplanes. This proposed AD was prompted by a report of cracks found in the fuel control unit housing assembly of a Honeywell GTCP331-350 auxiliary power unit (APU), which caused fuel leakage in the APU compartment. This proposed AD would require replacing any affected APU fuel control unit or affected APU, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). This proposed AD would also prohibit the installation of affected parts under certain conditions. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 11, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](http://regulations.gov). Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1220; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

• For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find this material on the EASA website at [ad.easa.europa.eu](http://ad.easa.europa.eu). It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA-2023-1220.

• For Honeywell service information identified in this NPRM, contact Honeywell International, Inc., 111 South 34th Street, Phoenix, AZ 85034; phone: (800) 601-3099; fax: (602) 365-5577; website: [myaerospace.honeywell.com/wps/portal](http://myaerospace.honeywell.com/wps/portal).

• You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

**FOR FURTHER INFORMATION CONTACT:** Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 206-231-3667; email [Timothy.P.Dowling@faa.gov](mailto:Timothy.P.Dowling@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-1220; Project Identifier MCAI-2023-00478-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](http://regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 206-231-3667; email [Timothy.P.Dowling@faa.gov](mailto:Timothy.P.Dowling@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2023-0057, dated March 16, 2023 (EASA AD 2023-0057), to correct an unsafe condition for all Airbus SAS Model 330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-841, A330-941, A330-743L, A340-211, A340-212, A340-213, A340-311, A340-312, and A340-313 airplanes. Airbus SAS Model A330-743L airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability. The MCAI states cracks were found in the fuel control unit housing assembly of a Honeywell GTCP331-350 APU, which caused fuel leakage in the APU compartment. This condition, if not addressed, could lead to an