

EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as required by paragraph (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3667; email timothy.p.dowling@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023-0029, dated February 1, 2023.

(ii) [Reserved]

(3) For EASA AD 2023-0029, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 8, 2023.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-14878 Filed 7-13-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1412; Project Identifier MCAI-2022-01588-E]

RIN 2120-AA64

Airworthiness Directives; Austro Engine GmbH Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Austro Engine GmbH Model E4 and E4P engines. This proposed AD was prompted by reports of piston failures and the determination that certain batches of pistons were manufactured with a dimensional deviation in the piston pin bore and piston diameter. This proposed AD would require repetitive engine oil analysis for aluminum content outside the acceptable limits and, if necessary, replacement of the pistons, piston rings, con-rods assembly, and crankcase or, as an alternative, replacement of the engine core. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by August 28, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2023-1412; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Austro Engine

GmbH, Rudolf-Diesel-Strasse 11, A-2700 Weiner Neustadt, Austria; phone: +43 2622 23000; website: austroengine.at.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT:

Barbara Caufield, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (781) 238-7146; email:

barbara.caufield@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-1412; Project Identifier MCAI-2022-01588-E" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI

should be sent to Barbara Caufield, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0240R1, dated December 15, 2022 (referred to after this as the MCAI), to address an unsafe condition on Austro Engine GmbH Model E4 and E4P engines. The MCAI states that a manufacturer investigation into reports of piston failures determined that certain batches of pistons were manufactured with a dimensional deviation in the piston pin bore and in the piston diameter, which could cause piston failure, with consequent loss of oil, loss of engine power, and reduced control of the airplane. To address the unsafe condition, EASA issued EASA AD 2022-0240, dated December 6, 2022, to specify repetitive oil analyses and replacement of the pistons, piston rings, con-rods assembly, and crankcase, or as an alternative, replacement of the engine core. EASA AD 2022-0240 also

prohibited release to service of an airplane until receipt of the results for each oil analysis.

Since EASA AD 2022-0240 was issued, the manufacturer determined that aluminum levels outside of the acceptable limits would be found during the first oil analysis, and are unlikely to be found during subsequent oil analyses. As a result, EASA revised EASA AD 2022-0240 and issued the MCAI to allow release to service of airplanes for a limited number of flight hours immediately after the second and subsequent oil samples are taken for analyses.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2023-1412.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Austro Engine GmbH Mandatory Service Bulletin MSB-E4-039/1, Revision 1, dated April 24, 2023, which specifies procedures for oil analysis and replacement of the pistons, piston rings, con-rods assembly, crankcase, and engine core.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

FAA's Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require initial and repetitive engine oil analysis for aluminum content outside the acceptable limits and, if necessary, replacement of the pistons, piston rings, con-rods assembly, and crankcase, or as an alternative, replacement of the engine core.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 357 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Oil Analysis25 work-hours × \$85 per hour = \$21.25	\$0	\$21.25	\$7,586.25

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed inspection. The agency has no way of determining the

number of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace engine core	50 work-hours × \$85 per hour = \$4,250	\$15,524	\$19,774
Replace pistons, piston rings, and con-rods assembly	60 work-hours × \$85 per hour = \$5,100	2,216	7,316
Replace pistons, piston rings, con-rods assembly, and crankcase.	70 work-hours × \$85 per hour = \$5,950	4,141	10,091

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA

with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Austro Engine GmbH: Docket No. FAA–2023–1412; Project Identifier MCAI–2022–01588–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 28, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Austro Engine GmbH Model E4 and E4P engines with a serial number listed in Tables 1, 2, 3, and 4 of Austro Engine GMBH Mandatory Service Bulletin MSB–E4–039/1, Revision 1, dated April 24, 2023 (MSB–E4–039/1).

(d) Subject

Joint Aircraft System Component (JASC) Codes 8530, Reciprocating Engine Cylinder Section; 8550, Reciprocating Engine Oil System.

(e) Unsafe Condition

This AD was prompted by reports of piston failures and the determination that certain batches of pistons were manufactured with a dimensional deviation in the piston pin bore and piston diameter. The FAA is issuing this AD to prevent piston failure. The unsafe condition, if not addressed, could result in loss of oil, loss of engine power, and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) For all affected engines, within the applicable compliance times specified in Table 1 to paragraph (g)(1) of this AD, perform an oil analysis in accordance with paragraph 2., Technical Details, Engine Oil Analysis of MSB–E4–039/1, and do not return the engine to service until the results of the oil analysis have been determined.

TABLE 1 TO PARAGRAPH (g)(1)—OIL ANALYSIS FOR ALL AFFECTED ENGINES

Engine group	Compliance time	Interval
Group 1 and Group 3	Within 15 flight hours (FHs) from the effective date of this AD.	Before exceeding 50 FHs since last oil analysis.
Group 2 and Group 4	Within 25 FHs from the effective date of this AD.	Before exceeding 100 FHs since last oil analysis.

(2) Thereafter, repeat the oil analysis required by paragraph (g)(1) of this AD before exceeding the applicable interval specified in Table 1 to paragraph (g)(1) of this AD.

(3) Following each repetitive oil analysis, the engine may be returned to service for no more than the applicable interval specified in Table 1 to paragraph (g)(1) of this AD, until receipt of the oil analysis result.

(4) If the result of any oil analysis required by paragraph (g)(1) of this AD indicates the

aluminum content of the oil is greater than the limit specified in paragraph 2., Technical Details, Engine Oil Analysis, Table 5—Oil check analysis—Aluminum PPM allowable of MSB–E4–039/1, before further flight, replace the pistons, piston rings, con-rods assembly, and crankcase, or replace the engine core in accordance with paragraph 2., Technical Details, Engine core replacement; or Pistons, piston rings, crankcase and con-

rod assy replacement; as applicable, of MSB–E4–039/1.

(5) For Group 3 and Group 4 engines, within the applicable compliance times specified in Table 2 to paragraph (g)(5) of this AD, replace the pistons, piston rings, and con-rods assembly, or replace the engine core in accordance with paragraph 2., Technical Details, Engine core replacement; or Pistons, piston rings and con-rod assy replacement, as applicable, of MSB–E4–039/1.

TABLE 2 TO PARAGRAPH (g)(5)—REPLACEMENT FOR GROUPS 3 AND 4 ENGINES

Engine group	Compliance time
Group 3	Before exceeding 900 FHs since new, or within 15 FHs after the effective date of this AD, whichever occurs later.
Group 4	Before exceeding 1,000 FHs since new, or within 25 FHs after the effective date of this AD, whichever occurs later.

Note 1 to paragraph (g)(5): FHs since new indicated in Table 2 to paragraph (g)(5) of this AD are FHs accumulated by the engine since first installation on an airplane or since last overhaul as of the effective date of this AD.

(h) Terminating Action

(1) Replacement of the pistons, piston rings, con-rods assembly, and crankcase, or replacement of the engine core, as specified in paragraph (g)(4) of this AD, constitutes terminating action for the repetitive oil

analysis required by paragraph (g)(2) of this AD.

(2) Replacement of the pistons, piston rings, and con-rods assembly, or replacement of the engine core, as specified in paragraph (g)(5) of this AD, constitutes terminating

action for the repetitive oil analysis required by paragraph (g)(2) of this AD.

(i) Definitions

(1) For the purpose of this AD, Group 1 engines are engines having a serial number (S/N) listed in Table 1 of MSB-E4-039/1.

(2) For the purpose of this AD, Group 2 engines are engines having an S/N listed in Table 2 of MSB-E4-039/1.

(3) For the purpose of this AD, Group 3 engines are engines having an S/N listed in Table 3 of MSB-E4-039/1.

(4) For the purpose of this AD, Group 4 engines are engines having an S/N listed in Table 4 of MSB-E4-039/1.

(j) Credit for Previous Actions

You may take credit for the actions required by paragraph (g)(1), (4), or (5) of this AD, if you performed those actions before the effective date of this AD using Austro Engine Mandatory Service Bulletin MSB-E4-039/0, dated October 24, 2022.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(2) of this AD and email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Additional Information

(1) Refer to European Union Aviation Safety Agency (EASA) AD 2022-0240R1, dated December 15, 2022, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1412.

(2) For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (781) 238-7146; email: barbara.caufield@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Austro Engine GMBH Mandatory Service Bulletin MSB-E4-039/1, Revision 1, dated April 24, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact Austro Engine GmbH, Rudolf-Diesel-Strasse 11, A-2700 Weiner Neustadt, Austria; phone: +43 2622 23000; website: austroengine.at.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 7, 2023.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-14751 Filed 7-13-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1493; Project Identifier MCAI-2022-01105-T]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-700-2A12 airplanes. This proposed AD was prompted by a report that some of the multi-function spoiler (MFS) anti-rotation plates failed in-service due to a thin wall design. This proposed AD would require replacing the MFS anti-rotation plates, inspecting the MFS anti-rotation plates for cracking and hinge bolts for evidence of rotation, accomplishing applicable corrective actions, and performing a functional test of the multi-function spoiler control surfaces. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by August 28, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1493; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

• For service information identified in this NPRM, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email ac.yul@aero.bombardier.com; website bombardier.com.

• You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT:

Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1493; Project Identifier MCAI-2022-01105-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.