

either \$0.74 or an adjuster equal to the 24-month (August–July) rolling simple average difference between the Advanced Class III and Class IV skim milk prices.

Proposal 15: Submitted by the Milk Innovation Group

This proposal seeks to retain the current “average of” formula for the base Class I skim milk price and proposes to update the adjuster monthly using a 24-month look back period with a 12-month lag, *i.e.*, the preceding the 13-to-36-month period. The “rolling” adjuster calculation would be the *difference between* the “higher of” the advanced Class III or IV skim milk price for each month and the “average of” the advanced Class III or IV skim milk price, averaged over the preceding 13-to-36-month period, *plus* the “average of” the Class III and IV advanced skim milk prices for that month.

Proposal 16: Submitted by Edge Dairy Farmer Cooperative

This proposal seeks to change the base Class I skim milk price to the announced Class III skim milk price, plus an adjuster. The proposal seeks to amend calculation of Class I prices to use announced rather than advanced prices. The proposed adjuster would be a 36-month average (August–July) of the monthly differences between the “higher of” the advanced Class III skim milk price or advanced Class IV skim milk price, and the Class III skim milk price.

Proposal 17: Submitted by Edge Dairy Farmer Cooperative

This proposal seeks to use the “higher of” the Class III skim milk price or the Class IV skim milk price to calculate the base Class I skim milk price. The proposal also seeks to amend calculation of Class I prices to use announced rather than advanced prices.

Proposal 18: Submitted by the American Farm Bureau Federation

This proposal seeks to eliminate the advanced pricing of Class I milk and components, and Class II skim milk and components. As proposed, the Class II skim milk price would be equal to the Announced Class IV skim milk price plus the Class II differential; the Class II nonfat solids price would be equal to the Announced Class IV nonfat solids price plus one-hundredth of the Class II differential. The proponent proposes the Class I skim milk price would be the “higher of” the Announced Class III or Class IV skim milk prices plus the Class I differential; and the Class I butterfat price would be equal to the butterfat

price plus one-hundredth of the Class I differential.

Class I and Class II Differentials

Proposal 19: Submitted by the National Milk Producers Federation

This proposal seeks to update the Adjusted Class I differentials as referenced in all Federal orders for the 3,108 named counties, parishes, and independent cities in the contiguous 48 United States. The proposed update would increase Class I differentials at all locations, in varying amounts.

Proposal 20: Submitted by the Milk Innovation Group

This proposal seeks to lower the current base Class I differential from \$1.60 to \$0.00.

Proposal 21: Submitted by the American Farm Bureau Federation

This proposal seeks to update the Class II differential to \$1.56. Specifically, the proposal seeks to calculate the Class II differential using the current nonfat dry milk make allowance multiplied by the current nonfat solids yield factor and updated butterfat and nonfat solids tests for milk in the FMMOs.

Proposal 22: Submitted by Dairy Program, Agricultural Marketing Service:

Make such changes as may be necessary to make the respective marketing orders conform with any amendments thereto that may result from this hearing.

From the time that a hearing notice is issued and until the issuance of a final decision in a proceeding, USDA employees involved in the decision-making process are prohibited from discussing the merits of the hearing issues on an *ex parte* basis with any person having an interest in the proceeding. For this proceeding, the prohibition applies to employees in the following organizational units:

Office of the Secretary of Agriculture
Office of the Administrator, Agricultural Marketing Service
Office of the General Counsel
Dairy Program, Agricultural Marketing Service (Washington, DC Office, and the Offices of all Market Administrators)

Procedural matters are not subject to the above prohibition and may be discussed at any time.

List of Subjects in 7 CFR Part 1000

Milk marketing orders.

Erin Morris,

Associate Administrator, Agricultural Marketing Service.

[FR Doc. 2023–15496 Filed 7–21–23; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1413; Project Identifier AD–2023–00087–T]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737–600, –700, –700C, –800, –900 and –900ER airplanes. This proposed AD was prompted by reports of cracks in the forward galley door cutout forward upper corner bear strap. It has been determined that the cracks were caused by high operating stresses in the fuselage skin door cutout corner area due to stress concentration at the door cutout. This proposed AD would require an inspection of the fuselage skin and the bear strap at the forward galley door cutout forward upper corner for existing repairs, and applicable related investigative and corrective inspections. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by September 7, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1413; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website myboeingfleet.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at [regulations.gov](https://www.regulations.gov) by searching for and locating Docket No. FAA–2023–1413.

FOR FURTHER INFORMATION CONTACT: Bill Ashforth, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3520; email: bill.ashforth@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2023–1413; Project Identifier AD–2023–00087–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other

information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Bill Ashforth, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3520; email: bill.ashforth@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA has received reports indicating cracks in the forward galley door cutout forward upper corner bear strap. The airplanes had accumulated between 33,070 and 44,224 total flight cycles at the time of the crack findings. The cracks were caused by high operating stresses in the fuselage skin door cutout corner area due to stress concentration at the door cutout. This condition, if not addressed, could result in an undetected crack in the fuselage skin and bear strap, and could increase in length until the fuselage skin and bear strap severs. If not detected and

corrected, a severed fuselage skin and bear strap may lead to the inability to sustain limit loads and may result in rapid decompression of the fuselage and loss of structural integrity of the aircraft.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022. This service information specifies procedures for an external general visual inspection of the fuselage skin at the forward galley door cutout forward upper corner for any repair, and applicable related investigative and corrective actions. Related investigative actions include detailed inspections for cracking of the fuselage skin and bear strap. Corrective actions include obtaining and following instructions for crack repair.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the service information already described and except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this service information at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1413.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 1,938 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
External general visual inspection for repairs.	0.5 work-hour × \$85 per hour = \$42.50 per inspection cycle.	\$0	\$42.50 per inspection cycle.	\$82,365 per inspection cycle.
External detailed and eddy current inspection for cracks.	3.5 work-hours × \$85 per hour = \$197.50.	0	\$197.50	\$576,555.
External eddy current inspection without a quadrupler repair.	4 work-hours × \$85 per hour = \$340 per inspection cycle.	0	\$340 per inspection cycle	Up to \$658,920 per inspection cycle.
External eddy current inspection with a quadrupler repair.	4 work-hours × \$85 per hour = \$340 per inspection cycle.	0	\$340 per inspection cycle	Up to \$658,920 per inspection cycle.

ESTIMATED COSTS—Continued

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Internal eddy current inspection for cracks.	26 work-hours × \$85 per hour = \$2,210.	0	\$2,210	\$4,282,980.

The FAA has received no definitive data on which to base the cost estimates for the on-condition repairs or for the alternative inspections specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

The Boeing Company: Docket No. FAA–2023–1413; Project Identifier AD–2023–00087–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by September 7, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737–600, –700, –700C, –800, –900 and –900ER airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks in the forward galley door cutout forward upper corner bear strap. The FAA is issuing this AD to address cracks in the fuselage skin and bear strap, which could increase in length until the fuselage skin and bear strap severs. If not detected and corrected, a severed fuselage skin and bear strap may lead to the inability of the principal structural element (PSE) to sustain limit loads and may result in rapid decompression of the fuselage and loss of structural integrity.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022, do all applicable

actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–53A1407, dated December 20, 2022, which is referred to in Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time columns of the tables in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022, use the phrase "the original issue date of Requirements Bulletin 737–53A1407 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 737–53A1407 RB, dated December 20, 2022, specifies contacting Boeing for repair instructions or for alternative inspections, this AD requires doing the repair, or doing the alternative inspections and applicable on-condition actions, using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Bill Ashforth, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3520; email: bill.ashforth@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-53A1407 RB, dated December 20, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 7, 2023.

Michael Linegang,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-15304 Filed 7-21-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2023-1053; Project Identifier AD-2023-00164-T]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 757-200, -200CB, and -200PF series airplanes. This proposed AD was prompted by a crack growth analysis, which indicated that current

inspections are not adequate to detect cracks in certain sections of the upper frame at the frame splice between certain stringers before a single frame fails. This proposed AD would require an inspection or records review for existing repairs; repetitive inspections for cracks of the upper frame at the frame splices between certain stringers in certain sections, and applicable on-condition actions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by September 7, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2023-1053; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov by searching for and locating Docket No. FAA-2023-1053.

FOR FURTHER INFORMATION CONTACT: Wayne Ha, Aviation Safety Engineer, Continued Operational Safety Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: 562-627-5238; email: wayne.ha@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2023-1053; Project Identifier AD-2023-00164-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Wayne Ha, Aviation Safety Engineer, Continued Operational Safety Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: 562-627-5238; email: wayne.ha@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA has received a report indicating that cracking has occurred in the frame splice doubler and may occur in the upper frame at the upper frame splice between stringer S-13 and S-14 on Boeing Model 737-300, -400, and -500 airplanes at multiple frame locations. The FAA issued AD 2021-26-