

and duplication, as applicable to different categories of requesters, to respond to requests under § 1703.105. Direct costs include, for example, the hourly salary and projected benefits costs of agency employees who search for, review, or duplicate records in response to a request. Overhead expenses such as cost of space, and heating or lighting the facility in which DNFSB records are stored are not included in direct costs.

* * * * *

(2) *Fees.* (i) If documents are requested for commercial use, DNFSB shall charge the hourly salary and projected benefits costs of agency employees who search for and review records in response to a request, and for the costs of duplication as set out in subsection (b)(6) of this section.

(ii) If documents are not sought for commercial use and the request is made by an educational or noncommercial scientific institution, whose purpose is scholarly or scientific research, or a representative of the news media, DNFSB's charges shall be limited to the direct costs of duplication as set out in subsection (b)(6) of this section.

(iii) For a request not described in paragraphs (b)(2) (i) or (ii) of this section, DNFSB shall charge the hourly salary and projected benefits costs of the agency's employee(s) who search for records in response to a request and the direct costs of duplication as set out in subsection (b)(6) of this section. There shall be no charge for document review time, and the first 100 pages of reproduction and the first two hours of search time will be provided without charge.

* * * * *

(6) *Schedule of Fees.* (1) To the extent authorized by these regulations, DNFSB is authorized to seek the following fees to recover costs incurred in responding to FOIA requests:

(i) Document Search Charges

(A) *Manual:* Salary rate(s) (basic hourly pay plus 16 percent) of employee(s) performing records search or review.

(B) *Electronic:* Salary rate(s) (basic hourly pay plus 16 percent) of employee(s) performing search or review.

(ii) *Document Review Charges:* Salary rate(s) (basic hourly pay plus 16 percent) of employee(s) performing search or review.

(2) DNFSB will charge requesters who seek records for commercial purposes for the cost of reviewing them to determine whether they are exempt from mandatory disclosure. The agency will assess these charges only when the

records are first analyzed to determine the applicability of a specific exemption to a record or portion thereof. DNFSB will not charge for the review of an exemption previously applied at the administrative review level. If a record or portion thereof was withheld in full under an exemption that is subsequently found inapplicable, it may be reviewed again to determine the applicability of other exemptions not previously considered. DNFSB may charge for the cost of such review.

(3) Copying Charges

(i) *Paper:* \$.05 per page, if done in-house, or generally available commercial rate, approximately \$0.10 per page.

(ii) *Electronic Media:* Direct cost, including operator time (employee's basic hourly pay plus 16 percent).

(iii) *Audio and Video Cassette:* Actual commercial rates.

(iv) *Duplication of CD or DVD:* Direct cost, including operator time (employee's basic hourly pay plus 16 percent).

(v) *Large Documents, e.g., maps or diagrams:* Actual commercial rates.

Dated: November 8, 2023.

Joyce Connery,
Chair.

[FR Doc. 2023-25074 Filed 11-14-23; 8:45 am]

BILLING CODE 3670-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-2000; Project Identifier MCAI-2023-00415-T]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. This proposed AD was prompted by reports that some overheat detection sensing elements of the bleed air leak detection system were manufactured with insufficient salt fill, which can result in an inability to detect hot bleed air leaks. This proposed AD would require maintenance records verification, and if an affected part is installed, would prohibit the use of certain Master Minimum Equipment

List (MMEL) items under certain conditions by requiring revising the operator's existing MEL. This proposed AD would also require testing the overheat detection sensing elements, marking each serviceable sensing element with a witness mark, and replacing each non-serviceable part with a serviceable part. This proposed AD would also prohibit the installation of affected parts under certain conditions. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 2, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-2000; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Bombardier service information identified in this NPRM, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email: ac.yul@aero.bombardier.com; website: [bombardier.com](https://www.bombardier.com).

- For Liebherr-Aerospace Toulouse SAS service information identified in this NPRM, contact Liebherr-Aerospace Toulouse SAS, 408, Avenue des Etats-Unis—B.P.52010, 31016 Toulouse Cedex, France; telephone +33 (0)5.61.35.28.28; fax +33 (0)5.61.35.29.29; email: techpub.toulouse@liebherr.com; website: www.liebherr.aero.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the

availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT: Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-2000; Project Identifier MCAI-2023-00415-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600

Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

Transport Canada, which is the aviation authority for Canada, has issued Transport Canada AD CF-2023-17, dated March 8, 2023 (Transport Canada AD CF-2023-17) (also referred to after this as the MCAI), to correct an unsafe condition on certain Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes. The MCAI states that Bombardier received reports from the supplier of the overheat detection sensing elements of a manufacturing quality escape. Some of the sensing elements of the bleed air leak detection system were manufactured with insufficient salt fill. This condition can result in an inability to detect hot bleed air leaks, which can cause damage to surrounding structures and systems and prevent continued safe flight and landing.

The FAA is proposing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2023-2000.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Liebherr Service Bulletin CFD-F1958-26-01, dated May 6, 2022, which specifies part numbers for affected sensing elements.

The FAA reviewed the following Bombardier service bulletins, which specify procedures for testing each leak detection loop (LDL) sensing element installed on the airplane, marking each serviceable sensing element with a witness mark, and replacing each non-serviceable part with a serviceable part. These documents are distinct since they apply to different airplane models and configurations:

- Bombardier Service Bulletin 700-1A11-36-005 Basic Issue, dated December 23, 2022;
- Bombardier Service Bulletin 700-36-026 Basic Issue, dated December 23, 2022;
- Bombardier Service Bulletin 700-36-5002 Basic Issue, dated December 23, 2022;

- Bombardier Service Bulletin 700-36-5501 Basic Issue, dated December 23, 2022;

- Bombardier Service Bulletin 700-36-6002 Basic Issue, dated December 23, 2022; and

- Bombardier Service Bulletin 700-36-6501 Basic Issue, dated December 23, 2022.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require maintenance records verification. If an affected part is installed, this proposed AD would prohibit the use of certain MMEL items unless specific dispatch instructions are followed by revising the operator’s existing MEL and accomplishing the actions specified in the service information already described. For certain airplanes, this proposed AD would also require testing each LDL sensing element installed on the airplane, marking each serviceable sensing element with a witness mark, and replacing each non-serviceable part with a serviceable part. This proposed AD would also prohibit the installation of affected parts under certain conditions.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 160 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 140 work-hours × \$85 per hour = Up to \$11,900.	\$0	Up to \$11,900	Up to \$1,904,000.

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this proposed AD. The FAA estimates it would take up to 1.5 hours to replace a sensing element.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and

- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Bombardier, Inc.: Docket No. FAA-2023-2000; Project Identifier MCAI-2023-00415-T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 2, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD-700-1A10 and BD-700-1A11 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code: 36, Pneumatic.

(e) Unsafe Condition

This AD was prompted by reports that some overheat detection sensing elements of the bleed air leak detection system were manufactured with insufficient salt fill. The FAA is issuing this AD to address non-conforming sensing elements of the bleed air leak detection system. The unsafe condition, if not addressed, could result in an inability to detect hot bleed air leaks and consequent

damage to surrounding structures and systems, which could prevent continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For the purpose of this AD, the definitions specified in paragraphs (g)(1) through (3) of this AD apply.

(1) The following Model BD-700-1A10 and BD-700-1A11 airplane groups are identified in (g)(1)(i) through (iv) of this AD:

(i) Group A airplanes: serial numbers (S/N) 9002 through 9151 inclusive, and 9153.

(ii) Group B airplanes: S/N 9152, 9154 through 9879 inclusive, 9998, 60001 through 60041 inclusive, 60043, 60044, 60045, and 60051.

(iii) Group C airplanes: S/N 60042, 60046, 60047, 60049, 60053, and subsequent.

(iv) Group D airplanes: S/N 60048, 60050, and 60052.

(2) An affected part is a sensing element marked with a date code A0448 through A2104 inclusive and having an LTS/Kidde part number specified in Liebherr Service Bulletin CFD-F1958-26-01, dated May 6, 2022, unless that sensing element meets the criteria specified in paragraph (g)(2)(i) or (ii) of this AD.

(i) The sensing element has been tested as specified in Section 3 of the Accomplishment Instructions of Kidde Aerospace and Defense Service Bulletin CFD-26-1, Revision 6, dated February 28, 2022, or earlier revisions, and has been found to be serviceable; and the sensing element has been marked on one face of its connector hex nut and packaged as specified in Section 3.C. of the Accomplishment Instructions of Kidde Aerospace and Defense Service Bulletin CFD-26-1, Revision 6, dated February 28, 2022, or earlier revisions.

(ii) The sensing element has been tested and found to be serviceable as specified in paragraph (j) of this AD; and the sensing element has been marked on one face of one connector hex nut with one green mark, as specified in Figure 4 (the figure is representative for all sensing elements) in the Accomplishment Instructions of the applicable Bombardier service bulletin (BA SB) in figure 1 to paragraph (g)(2)(ii) of this AD.

Figure 1 to paragraph (g)(2)(ii)—Applicable service information

BILLING CODE 4910-12-P

Aeroplane Model (Marketing Designation)	Applicable BA SB
BD-700-1A10 (Global Express & Global Express XRS)	SB 700-36-026 Basic Issue, dated 23 December 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A11 (Global 5000)	SB 700-1A11-36-005 Basic Issue, dated 23 December 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A11 (Global 5000 featuring Global Vision Flight Deck)	SB 700-36-5002 Basic Issue, dated 23 December 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A10 (Global 6000)	SB 700-36-6002 Basic Issue, dated 23 December 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A11 (Global 5500)	SB 700-36-5501 Basic Issue, dated 23 December 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada
BD-700-1A10 (Global 6500)	SB 700-36-6501 Basic Issue, dated 23 December 2022, or later revisions approved by the Chief, Continuing Airworthiness, Transport Canada

(3) A serviceable part is a sensing element that is not an affected part.

(h) Maintenance Records Verification

For Groups A and C whose airplane date of manufacture, as identified on the identification plate of the airplane, is on or before July 27, 2022 (the effective date of Transport Canada AD CF-2022-38): Within 60 days after the effective date of this AD, examine the airplane maintenance records to verify whether any affected part has been installed since the airplane date of

manufacture, as identified on the identification plate of the airplane.

(1) If the maintenance records confirm that an affected part has been installed, or if it cannot be confirmed that an affected part has not been installed, paragraphs (i) and (j) of this AD must be complied with within the applicable compliance times specified in paragraphs (i) and (j) of this AD.

(2) For Groups A and C airplanes: if the maintenance records confirm that no affected parts have been installed since airplane date

of manufacture, then paragraphs (i) and (j) of this AD are not applicable.

(i) Minimum Equipment List (MEL) Revision

For Groups B and D airplanes, and Groups A and C airplanes required by paragraph (h) of this AD: Within 90 days after the effective date of this AD, revise the operator's existing MEL by incorporating the information specified in figures 2 through 8 to paragraph (i) of this AD, as applicable. This may be done by inserting a copy of this information into the operator's existing MEL.

Figure 2 to paragraph (i) – MMEL Item 36-12-01

MMEL Item 36-12-01			
1. System & Sequence N° Item	2. Number Installed	3. Number Required For Dispatch	4. Remarks or Exceptions
N° de système/série article	Nombre d'article installés	Nombre d'articles à expédier	
36 - <u>PNEUMATICS</u> 12-01 Bleed Leak Detection Loops C	18	9	(O) Either loop A or loop B may be inoperative provided redundant loop in the same zone is operative.

1. PLACARD

(1) Put a BLEED LEAK DETECTION LOOPS INOPERATIVE placard on the instrument panel.

2. OPERATIONS (O)

Before each flight:

(1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.

a. Connect electrical power to the aeroplane as follows:

Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

i. Connect external AC power, OR

ii. Start the APU as follows:

1. On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
2. On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
3. On the APU control panel, turn the APU switch to START.

b. When external AC power is on or APU is running, wait a minimum of 6 minutes.

c. After 6 minutes, make sure that the EICAS primary display shows as follows:

i. If the Advisory L BLEED FAULT or R BLEED FAULT shows, DISPATCH IS PERMITTED.

Note: If the Advisory L BLEED FAULT or R BLEED FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.

ii. If the Advisory L BLEED FAULT or R BLEED FAULT does not show, DISPATCH IS NOT PERMITTED.

Note: If the Advisory L BLEED FAULT or R BLEED FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.

d. If required, remove external AC power from the aeroplane.

e. If required, set APU BLEED to AUTO.

Figure 3 to paragraph (i) – MMEL Item 36-12-01-1

MMEL Item 36-12-01-1			
1. System & Sequence No Item	2. Number Installed	3. Number Required For Dispatch	4. Remarks or Exceptions
Nº de système/série article	Nombre d'article installés	Nombre d'articles à expédier	
36 - <u>PNEUMATICS</u> 12-01 Bleed Leak Detection Loops C	18	9	(O) Either loop A or loop B may be inoperative provided redundant loop in the same zone is operative.
1) Wing Anti-Ice Leak C	12	6	(M) (O) One loop in each section may be inoperative provided: a) Power-up BIT test is performed on system prior to each dispatch into icing, and b) Cause of WING ANTI-ICE FAULT Advisory message is confirmed by maintenance.

1. PLACARD
(1) Put a WING ANTI-ICE LEAK INOPERATIVE placard on the instrument panel.

2. OPERATIONS (O)
Before each flight:

(1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.

a. Connect electrical power to the aeroplane as follows:

Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

i. Connect external AC power, OR

ii. Start the APU as follows:

1. On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
2. On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
3. On the APU control panel, turn the APU switch to START.

b. When external AC power is on or APU is running, wait a minimum of 6 minutes.

c. After 6 minutes, make sure that the EICAS primary display shows as follows:

i. If the Advisory WING A/ICE FAULT shows, DISPATCH IS PERMITTED unless step (2) of the Maintenance (M) procedure under (3) below does not pass, in which case DISPATCH IS NOT PERMITTED.

Note: If the Advisory WING A/ICE FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.

- ii. If the Advisory WING A/ICE FAULT does not show, DISPATCH IS NOT PERMITTED.

Note: If the Advisory WING A/ICE FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.

- d. If required, remove external AC power from the aeroplane.
- e. If required, set APU BLEED to AUTO.

3. MAINTENANCE (M)

The requirement to perform this section is conditional on (1)(c)(i) under the Operations (O) procedure above.

- (1) Power-up BIT test is performed on system prior to each dispatch into icing.
- (2) The cause of the WING ANTI-ICE FAULT Advisory message is to be confirmed by maintenance personnel to make sure that no section has encountered a dual loop failure.

Figure 4 to paragraph (i) – MMEL Item 36-12-01-2

MMEL Item 36-12-01-2

1. System & Sequence No Item No de système/série article	2. Number Installed Nombre d'article installés	3. Number Required For Dispatch Nombre d'articles à expédier	4. Remarks or Exceptions
36 - <u>PNEUMATICS</u> 12-01 Bleed Leak Detection Loops C ...	18	9	(O) Either loop A or loop B may be inoperative provided redundant loop in the same zone is operative. ...
2) Trim Air Leak C	2	1	(O) Except for ER operations, one loop may be inoperative.

1. PLACARD

- (1) Put a TRIM AIR LEAK INOPERATIVE placard on the instrument panel.

2. OPERATIONS (O)

Before each flight:

- (1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.
 - a. Connect electrical power to the aeroplane as follows:

Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

 - i. Connect external AC power, OR
 - ii. Start the APU as follows:
 1. On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
 2. On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
 3. On the APU control panel, turn the APU switch to START.
 - b. When external AC power is on or APU is running, wait a minimum of 6 minutes.
 - c. After 6 minutes, make sure that the EICAS primary display shows as follows:
 - i. If the Advisory TRIM AIR FAULT shows, DISPATCH IS PERMITTED.

Note: If the Advisory TRIM AIR FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.
 - ii. If the Advisory TRIM AIR FAULT does not show, DISPATCH IS NOT PERMITTED.

Note: If the Advisory TRIM AIR FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.
 - d. If required, remove external AC power from the aeroplane.
 - e. If required, set APU BLEED to AUTO.

Figure 5 to paragraph (i) – L BLEED FAULT

L BLEED FAULT		
CAS Indication	1.	2. Dispatch Consideration
L BLEED FAULT (Advisory)	C	(O) Aircraft may be dispatched provided, prior to each flight: a) None of the following messages are also posted: – R BLEED SYS FAIL Caution; – R WING ANTI-ICE FAIL Caution; – XBLEED FAIL Caution; – R BLEED FAULT Advisory; – WING ANTI-ICE FAULT Advisory; b) Left PRV and left HPSOV open and close correctly in response to L BLEED OFF switch selection, as indicated on Synoptic Page; c) Left HPSOV is open at engine idle and closed at high thrust settings, as indicated on Synoptic Page; d) WING XBLEED FROM R is selected and remains open; and e) Operations are not conducted in known or forecast icing conditions.

1. OPERATIONS (O)

Before each flight:

(1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.

a. Connect electrical power to the aeroplane as follows:

Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

i. Connect external AC power, OR

ii. Start the APU as follows:

1. On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
2. On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
3. On the APU control panel, turn the APU switch to START.

b. When external AC power is on or APU is running, wait a minimum of 6 minutes.

- c. After 6 minutes, make sure that the EICAS primary display shows as follows:
 - i. If the Advisory L BLEED FAULT shows, DISPATCH IS PERMITTED.
Note: If the Advisory L BLEED FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.
 - ii. If the Advisory L BLEED FAULT does not show, DISPATCH IS NOT PERMITTED.
Note: If the Advisory L BLEED FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.
- d. If required, remove external AC power from the aeroplane.
- e. If required, set APU BLEED to AUTO.

2. OPERATIONS (O)

Before each flight and after engine start:

- (1) On the EICAS primary display, make sure that the messages that follow do not show:
 - R BLEED SYS FAIL (Caution)
 - R WING ANTI-ICE FAIL (Caution)
 - XBLEED FAIL (Caution)
 - R BLEED FAULT (Advisory)
 - WING ANTI-ICE FAULT (Advisory)
- (2) Make sure that the left Pressure Regulator Valve (PRV) and left High Pressure Shut Off Valve (HPSOV) open and close as follows:
 - a. On the BLEED/AIR COND control panel, set the L ENG BLEED switch to OFF.
 - b. On the BLEED/ANTI-ICE synoptic page, make sure that the left PRV and left HPSOV show closed.
 - c. On the BLEED/AIR COND control panel, set the L ENG BLEED switch to AUTO.
 - d. On the BLEED/ANTI-ICE synoptic page, make sure that the left PRV and left HPSOV show open.
- (3) Make sure that the left High Pressure Shut Off Valve (HPSOV) switching operates as follows:
 - a. Slowly advance the left throttle to high thrust setting.
 - b. On the BLEED/ANTI-ICE synoptic page, make sure that the left HPSOV shows closed.
 - c. Slowly retard the left throttle to engine idle.
 - d. On the BLEED/ANTI-ICE synoptic page, make sure that the left HPSOV shows open.
- (4) On the ANTI-ICE control panel, set the WING XBLEED to FROM R for the rest of the flight.
- (5) Operations are not conducted in known or forecast icing conditions.

Figure 6 to paragraph (i) – R BLEED FAULT

R BLEED FAULT		
CAS Indication	1.	2. Dispatch Consideration
R BLEED FAULT (Advisory)	C	(O) Aircraft may be dispatched provided, prior to each flight: a) None of the following messages are also posted: – L BLEED SYS FAIL Caution; – L WING ANTI-ICE FAIL Caution; – XBLEED FAIL Caution; – L BLEED FAULT Advisory; – WING ANTI-ICE FAULT Advisory; b) Right PRV and right HPSOV open and close correctly in response to R BLEED OFF switch selection, as indicated on Synoptic Page; c) Right HPSOV is open at engine idle and closed at high thrust settings, as indicated on Synoptic Page; d) WING XBLEED FROM L is selected and remains open; and e) Operations are not conducted in known or forecast icing conditions.

1. OPERATIONS (O)

Before each flight:

(1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.

a. Connect electrical power to the aeroplane as follows:

Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

i. Connect external AC power, OR

ii. Start the APU as follows:

- On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
- On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
- On the APU control panel, turn the APU switch to START.

b. When external AC power is on or APU is running, wait a minimum of 6 minutes.

c. After 6 minutes, make sure that the EICAS primary display shows as follows:

- If the Advisory R BLEED FAULT shows, DISPATCH IS PERMITTED.
Note: If the Advisory R BLEED FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.
- If the Advisory R BLEED FAULT does not show, DISPATCH IS NOT PERMITTED.
Note: If the Advisory R BLEED FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.

d. If required, remove external AC power from the aeroplane.

e. If required, set APU BLEED to AUTO.

2. OPERATIONS (O)

Before each flight and after engine start:

(1) On the EICAS primary display, make sure that the messages that follow do not show:

- L BLEED SYS FAIL (Caution)
 - L WING ANTI-ICE FAIL (Caution)
 - XBLEED FAIL (Caution)
 - L BLEED FAULT (Advisory)
 - WING ANTI-ICE FAULT (Advisory)
- (2) Make sure that the right Pressure Regulator Valve (PRV) and right High Pressure Shut Off Valve (HPSOV) open and close as follows:
- a. On the BLEED/AIR COND control panel, set the R ENG BLEED switch to OFF.
 - b. On the BLEED/ANTI-ICE synoptic page, make sure that the right PRV and right HPSOV show closed.
 - c. On the BLEED/AIR COND control panel, set the R ENG BLEED switch to AUTO.
 - d. On the BLEED/ANTI-ICE synoptic page, make sure that the right PRV and right HPSOV show open.
- (3) Make sure that the right High Pressure Shut Off Valve (HPSOV) switching operates as follows:
- a. Slowly advance the right throttle to high thrust setting.
 - b. On the BLEED/ANTI-ICE synoptic page, make sure that the right HPSOV shows closed.
 - c. Slowly retard the right throttle to engine idle.
 - d. On the BLEED/ANTI-ICE synoptic page, make sure that the right HPSOV shows open.
- (4) On the ANTI-ICE control panel, set the WING XBLEED to FROM L for the rest of the flight.
- (5) Operations are not conducted in known or forecast icing conditions.

Figure 7 to paragraph (i) – WING A/ICE FAULT

WING A/ICE FAULT	
CAS Indication	1. 2. Dispatch Consideration
WING A/ICE FAULT (Advisory)	C (O) Aircraft may be dispatched provided, prior to each departure: a) Flight is not conducted in known or forecast icing conditions; b) A power-up test is performed by cycling WING A/ICE switch from OFF to ON; and c) None of the following CAS messages are also posted: – ICE DETECT FAIL Caution; – L BLEED SYS FAIL Caution; – R BLEED SYS FAIL Caution; – ICE DETECT FAULT Advisory; – L BLEED FAULT Advisory; – R BLEED FAULT Advisory.

1. OPERATIONS (O)
Before each flight:

(1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.

a. Connect electrical power to the aeroplane as follows:

Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

i. Connect external AC power, OR

ii. Start the APU as follows:

- On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
- On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
- On the APU control panel, turn the APU switch to START.

b. When external AC power is on or APU is running, wait a minimum of 6 minutes.

c. After 6 minutes, make sure that the EICAS primary display shows as follows:

- If the Advisory WING A/ICE FAULT shows, DISPATCH IS PERMITTED.
Note: If the Advisory WING A/ICE FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.
- If the Advisory WING A/ICE FAULT does not show, DISPATCH IS NOT PERMITTED.
Note: If the Advisory WING A/ICE FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.

d. If required, remove external AC power from the aeroplane.

e. If required, set APU BLEED to AUTO.

2. OPERATIONS (O)
Before each flight and after engine start:

(1) Perform a power-up test as follows:

- On the ANTI-ICE control panel, cycle the WING switch from OFF to ON.
- On the EICAS primary display, make sure that the following CAS status message is shown:
– WING A/ICE ON
- On the EICAS primary display, make sure that the following CAS messages are not shown:
– L WING A/ICE FAIL (Caution)
– R WING A/ICE FAIL (Caution)

(2) On the EICAS primary display, make sure that the following CAS messages are not shown:

- ICE DETECT FAIL (Caution)
- L BLEED SYS FAIL (Caution)
- R BLEED SYS FAIL (Caution)
- ICE DETECT FAULT (Advisory)
- L BLEED FAULT (Advisory)
- R BLEED FAULT (Advisory)

(3) Operations are not conducted in known or forecast icing conditions.

Figure 8 to paragraph (i) – TRIM AIR FAULT

TRIM AIR FAULT		
CAS Indication	1.	2. Dispatch Consideration
TRIM AIR FAULT (Advisory)	C	(O) Aircraft may be dispatched provided: a) Duct temperature indications are operative for all three ducts; b) Either HASOV showing incorrect indication on Synoptic page is verified CLOSED; and c) L PACK FAIL or R PACK FAIL Caution messages are not displayed.

1. OPERATIONS (O)

Before each flight:

(1) Make sure that the aeroplane is not powered on and that engines and APU are OFF.

a. Connect electrical power to the aeroplane as follows:
Note: Do not use a Jet Airstart Cart or High Pressure Ground Cart.

i. Connect external AC power, OR

ii. Start the APU as follows:

- On the ELECTRICAL control panel, set the BATT MASTER switch to ON.
- On the BLEED/AIR COND control panel, make sure that the APU BLEED switch is set to OFF.
- On the APU control panel, turn the APU switch to START.

b. When external AC power is on or APU is running, wait a minimum of 6 minutes.

c. After 6 minutes, make sure that the EICAS primary display shows as follows:

i. If the Advisory TRIM AIR FAULT shows, DISPATCH IS PERMITTED.
Note: If the Advisory TRIM AIR FAULT shows, it confirms it is not heat related and therefore cannot be a potential leak in the presence of an affected part.

ii. If the Advisory TRIM AIR FAULT does not show, DISPATCH IS NOT PERMITTED.
Note: If the Advisory TRIM AIR FAULT does not show, it confirms that it is heat related and therefore could be a potential leak in the presence of an affected part.

d. If required, remove external AC power from the aeroplane.

e. If required, set APU BLEED to AUTO.

2. OPERATIONS (O)

Before each flight and after engine start:

(1) On the AIR CONDITIONING synoptic page, make sure that the duct temperature indications are operative for all three ducts.

(2) Make sure that either HASOV that shows incorrect indication on the AIR CONDITIONING synoptic page is verified CLOSED as follows:

- On the BLEED/AIR COND control panel, alternate the TRIM AIR switch from ON to OFF to ON.
- At the same time, on the AIR CONDITIONING synoptic page, identify the HASOV that shows incorrect indication.
- In the flight compartment, on the EMS CDU, open the applicable circuit breaker as follows:

SYSTEM NAME	CIRCUIT BREAKER NAME	BUS NAME
AIR COND/PRESS	L ECS HASOV	DC ESS
AIR COND/PRESS	R ECS HASOV	DC ESS

d. In the aft equipment compartment, make sure that any identified HASOV is in the CLOSED position.

(3) On the EICAS primary display, make sure that the following CAS messages are not shown:

- L PACK FAIL (Caution)
- R PACK FAIL (Caution)

(j) Testing and Replacement of Affected Overheat Detection Sensing Elements

(1) For Group B and D airplanes, and Group A and C airplanes required by paragraph (h) of this AD: Within 2,000 flight hours or 120 months, whichever occurs first, from the effective date of this AD, test the overheat detection sensing elements to determine if they are serviceable, in accordance with the Accomplishment Instructions of the applicable Bombardier service bulletin in paragraphs (j)(1)(i) through (vi) of this AD.

(i) For Model BD-700-1A11 (Global 5000) airplanes: Bombardier Service Bulletin 700-1A11-36-005 Basic Issue, dated December 23, 2022.

(ii) For Model BD-700-1A10 (Global Express and Global Express XRS) airplanes: Bombardier Service Bulletin 700-36-026 Basic Issue, dated December 23, 2022.

(iii) For Model BD-700-1A11 (Global 5000 featuring Global Vision Flight Deck) airplanes: Bombardier Service Bulletin 700-36-5002 Basic Issue, dated December 23, 2022.

(iv) For Model BD-700-1A11 (Global 5500) airplanes: Bombardier Service Bulletin 700-36-5501 Basic Issue, dated December 23, 2022.

(v) For Model BD-700-1A10 (Global 6000) airplanes: Bombardier Service Bulletin 700-36-6002 Basic Issue, dated December 23, 2022.

(vi) For Model BD-700-1A10 (Global 6500) airplanes: Bombardier Service Bulletin 700-36-6501 Basic Issue, dated December 23, 2022.

(2) For each sensing element that is serviceable, as determined by paragraph (j)(1) of this AD, before further flight, mark the sensing element with a witness mark in accordance with the Accomplishment Instructions in the applicable Bombardier service bulletin in paragraphs (j)(1)(i) through (vi) of this AD.

(3) For each sensing element that is not serviceable, as determined by paragraph (j)(1) of this AD, before further flight, replace the sensing element with a serviceable part in accordance with the Accomplishment Instructions in the applicable Bombardier Service Bulletin in paragraphs (j)(1)(i) through (vi) of this AD.

(k) Parts Installation Prohibition

As of the effective date of this AD, no person may install, on any airplane, any affected part unless it is a serviceable part.

(l) No Reporting Requirement

Although Bombardier service bulletins in figure 1 to paragraph (g)(2)(ii) of this AD specify to submit certain information to the manufacturer, this AD does not include that requirement.

(m) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your

request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to ATTN: Program Manager, Continuing Operational Safety, at the address identified in paragraph (n)(2) of this AD or email to: 9-avs-nyaco-cos@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(n) Additional Information

(1) Refer to Transport Canada AD CF-2023-17, dated March 8, 2023, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-2000.

(2) For more information about this AD, contact Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email: 9-avs-nyaco-cos@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 700-1A11-36-005 Basic Issue, dated December 23, 2022.

(ii) Bombardier Service Bulletin 700-36-026 Basic Issue, dated December 23, 2022.

(iii) Bombardier Service Bulletin 700-36-5002 Basic Issue, dated December 23, 2022.

(iv) Bombardier Service Bulletin 700-36-5501 Basic Issue, dated December 23, 2022.

(v) Bombardier Service Bulletin 700-36-6002 Basic Issue, dated December 23, 2022.

(vi) Bombardier Service Bulletin 700-36-6501 Basic Issue, dated December 23, 2022.

(vii) Liebherr Service Bulletin CFD-F1958-26-01, dated May 6, 2022.

(3) For Bombardier service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-2999; email: ac.yul@aero.bombardier.com; website: [bombardier.com](https://www.bombardier.com).

(4) For Liebherr-Aerospace Toulouse SAS service information identified in this AD, contact Liebherr-Aerospace Toulouse SAS, 408, Avenue des Etats-Unis—B.P.52010, 31016 Toulouse Cedex, France; telephone +33 (0)5.61.35.28.28; fax +33 (0)5.61.35.29.29; email: techpub.toulouse@liebherr.com; website: www.liebherr.aero.

(5) You may view this service information at the FAA, Airworthiness Products Section,

Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on October 26, 2023.

Caitlin Locke,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-24007 Filed 11-14-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[[Docket No. FAA-2023-2247; Airspace Docket No. 23-ACE-4]

RIN 2120-AA66

Amendment of VOR Federal Airway V-132 and Revocation of VOR Federal Airways V-131, V-307, and V-350 in the Vicinity of Chanute, KS

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Very High Frequency Omnidirectional Range (VOR) Federal airway V-132 and revoke VOR Federal airways V-131, V-307, and V-350. The FAA is proposing this action due to the planned decommissioning of the VOR portion of the Chanute, KS (CNU), VOR/Distance Measuring Equipment (VOR/DME) navigational aid (NAVAID). The Chanute VOR is being decommissioned in support of the FAA's VOR Minimum Operational Network (MON) program.

DATES: Comments must be received on or before January 2, 2024.

ADDRESSES: Send comments identified by FAA Docket No. FAA-2023-2247 and Airspace Docket No. 23-ACE-4 using any of the following methods:

* *Federal eRulemaking Portal:* Go to www.regulations.gov and follow the online instructions for sending your comments electronically.

* *Mail:* Send comments to Docket Operations, M-30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

* *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building