

Branch, mail it to the address identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-NYACO-COS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Additional Information

For more information about this AD, contact Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyaco-cos@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF-2022-54R1, dated October 4, 2022.

(ii) [Reserved]

(3) For Transport Canada AD CF-2022-54R1, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca. You may find this Transport Canada AD on the Transport Canada website at tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on April 2, 2024.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-09340 Filed 4-30-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1214; Project Identifier AD-2023-00181-T; Amendment 39-22726; AD 2024-07-05]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 757-200, 757-200CB, and 757-300 airplanes. This AD was prompted by cracks on both sides of the airplane in the station (STA) 1640 frame web between S-14 and S-15. This AD requires an inspection or maintenance records check for existing liner holes in the STA 1640 frame web between S-14 and S-15, and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 5, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 5, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2023-1214; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Boeing material, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2023-1214.

FOR FURTHER INFORMATION CONTACT:

Wayne Ha, Aviation Safety Engineer,

FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: 562-627-5238; email: Wayne.Ha@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 757-200, 757-200CB, and 757-300 airplanes. The NPRM published in the **Federal Register** on July 21, 2023 (88 FR 47090). The NPRM was prompted by cracks on both sides of the airplane at certain stringers. In the NPRM, the FAA proposed to require an inspection or a maintenance records check for existing liner holes at certain stringers, and applicable on-condition actions. The FAA is issuing this AD to address liner holes that could create a stress concentration around the hole and lead to cracks, which could result in the inability of a structural element to sustain limit load and could adversely affect the structural integrity of the airplane.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from the Air Line Pilots Association, International, who supported the NPRM without change, and additional comments from Aviation Partners Boeing (APB), Boeing, Delta Air Lines, FedEx, and United Airlines. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request to Clarify Location of Crack Findings

Boeing requested that the **SUMMARY** section of the NPRM be revised to clarify the location of the cracks by replacing the phrase "at certain stringers" with "in the STA 1640 frame web between S-14 and S-15" in two places. Boeing stated that cracks were not detected at the stringer locations, but rather in the frame web between S-14 and S-15.

The FAA concurs with the change and has revised this final rule accordingly.

Request To Clarify Applicable On-Condition Actions

Boeing requested a revision to the NPRM section "Related Service Information Under 1 CFR part 51" to clarify that all on-condition actions depend on the airplane configuration and may include a combination of the actions.

The FAA concurs with the request and has revised this final rule accordingly.

Request To Clarify Required Actions

Paragraph (e) of the proposed AD stated that the AD would address “unplugged liner holes” that could create a stress concentration around “the unplugged hole” and lead to cracks. Boeing requested that the word “unplugged” be removed in both locations. Boeing stated that although the primary concern is unplugged liner holes, the proposed AD would also require actions for certain plugged holes.

The FAA agrees with the request and has changed paragraph (e) of this AD accordingly.

Request To Change Grouping for Certain Airplanes

FedEx stated that all its airplanes affected by the NPRM are Model 757–200 airplanes, and all of these airplanes are currently considered to be Group 1 airplanes, as defined by Boeing Alert Requirements Bulletin 757–53A0120 RB, dated January 17, 2022. FedEx added that its Model 757–200 airplanes were converted to a configuration similar to Boeing Model 757–200SF airplanes (special freighter airplanes with supplemental type certificate (STC) ST00916WI–D) per VT Mobile Aerospace Engineering STC ST03562AT, and therefore its airplanes are no longer configured as passenger airplanes. Because the inspection areas for its airplanes have been modified by STC ST03562AT, FedEx stated that the inspection areas specified for Group 1 airplanes are no longer applicable. FedEx therefore requested that Group 1 airplanes modified by STC ST03562AT be considered Group 3 airplanes, and required to follow all inspections, methods, and compliance times for Group 3 airplanes. FedEx requested this change to avoid the need for an alternative method of compliance (AMOC) for its airplanes when the AD becomes effective.

The FAA agrees that airplanes modified in accordance with STC ST03562AT are no longer Group 1 airplanes, as identified in Boeing Alert Requirements Bulletin 757–53A0120 RB, dated January 17, 2022, and are now Group 3. Paragraph (h)(4) of this AD has been added to specify that Group 1 airplanes that have been converted from a passenger to freighter configuration with STC ST03562AT must do the applicable actions specified for Group 3 airplanes.

Request To Extend Compliance Time

FedEx requested an extension of the initial compliance time to 3,000 flight cycles for actions in Tables 13 through 16 of Boeing Alert Requirements Bulletin 757–53A0120 RB, dated January 17, 2022. FedEx reported that not all of its airplanes will be scheduled for a heavy maintenance visit within the proposed compliance time, and that a 3,000-flight-cycle compliance time would match the Model 757–200SF heavy maintenance schedule. FedEx added that any compliance time requirement sooner than 3,000 flight cycles would force FedEx to schedule airplanes in inopportune times and locations, and would become an even bigger burden to repair any cracking found during the inspections.

The FAA does not agree to change the compliance time. In developing an appropriate compliance time for this action, the FAA considered the recommendations of the manufacturer, the urgency associated with the subject unsafe condition, and the practical aspect of compliance with the AD within a period of time that corresponds to the normal scheduled maintenance for most affected operators. In consideration of these items, the FAA determined that the compliance time, as proposed, will ensure an acceptable level of safety. The FAA has not changed this AD as a result of this comment. However, under the provisions of paragraph (i) of this AD, the FAA will consider requests for approval of alternative compliance times if sufficient data are submitted to substantiate that the change would provide an acceptable level of safety.

Request To Clarify Compliance Times for Airplanes With STC

Delta reported that it operates a number of Boeing Model 757 airplanes with STC ST01518SE installed but without winglets—a configuration approved under STC ST01518SE. Delta noted that paragraph (h)(3) of the proposed AD did not address this configuration. Delta requested that the proposed AD be revised to clarify whether the reduced compliance time specified in paragraph (h)(3) of this AD applies only to airplanes with winglets installed.

The FAA provides the following clarification. A compliance time for airplanes with STC ST01518SE but without winglets has not been evaluated; therefore, that compliance-time requirement applies to all configurations with the STC ST01518SE modification. For clarification, paragraph (h)(3) of this AD has been

revised to specify that the reduced compliance time applies to airplanes modified in accordance STC ST01518SE, with or without blended or scimitar blended winglets installed. However, as specified in paragraph (i) of this AD, the FAA will consider requests for approval of alternative compliance times if sufficient data are submitted to substantiate that the change would provide an acceptable level of safety.

Request To Require Different Service Information

APB requested that the proposed AD be revised to require using Aviation Partners Boeing Service Bulletin AP757–53–004, Revision 1, dated February 15, 2023, for airplanes on which APB blended or scimitar blended winglets are installed by STC ST01518SE. APB provided no justification for this request.

Delta requested that paragraph (h)(3) of the proposed AD be revised, for airplanes with STC ST01518SE, to provide the less restrictive compliance times and methods than those specified in the proposed AD by using Aviation Partners Boeing Service Bulletin AP757–53–004, Revision 1, dated February 15, 2023. Delta stated that the conservative compliance times and repeat intervals specified in paragraph (h)(3) of the proposed AD would impose a great operational burden on Delta. Delta reported that it would be unable to accomplish the inspection in a regularly scheduled check environment within the proposed 1,000-flight-cycle compliance time. Delta added that the subject inspections require significant access procedures, which would result in extended unscheduled ground time, and could similarly affect all operators. Delta stated that APB, in its comments on the NPRM, reported that APB Service Bulletin AP757–53–004, Revision 1, dated February 15, 2023, had been independently reviewed by a designated engineering representative (DER) and recommended for FAA approval.

The FAA disagrees with the requests. The FAA has not reviewed nor approved the APB service bulletin. And given the urgency of the identified unsafe condition, the FAA has determined that delaying this AD while this service bulletin is reviewed and approved would be inappropriate. However, under the provisions of paragraph (i) of this AD, the FAA will consider requests for approval of alternative actions and compliance times if sufficient data are submitted to substantiate that the change would provide an acceptable level of safety. The FAA has not changed this AD as a result of this comment.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022. This service information specifies procedures for a general visual inspection or maintenance records check of the STA 1640 fuselage frame web between S-14 and S-15, left and right sides, for an existing liner hole, and applicable on-condition actions. Depending on the airplane configuration, on-condition actions include repetitive surface high frequency eddy current (HFEC) inspections for cracks of the web around

the fastener (plug), zero-timing the liner hole, plugging the liner hole, repetitive open-hole HFEC inspections of the web for cracks, and crack repair, or some combination of these actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Costs of Compliance

The FAA estimates that this AD affects 419 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	69 work-hours × \$85 per hour = \$5,865	\$0	\$5,865	\$2,457,435

The FAA estimates the following costs to do any necessary on-condition actions that would be required based on

the results of the inspection. The agency has no way of determining the number

of aircraft that might need these on-condition actions:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
HFEC inspections, plugging the liner hole, zero-timing of plugged liner hole.	2 work-hours × \$85 per hour = \$340	\$5	\$345

The FAA has received no definitive data on which to base the cost estimates for the crack repair specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-07-05 The Boeing Company:

Amendment 39-22726; Docket No. FAA-2023-1214; Project Identifier AD-2023-00181-T.

(a) Effective Date

This airworthiness directive (AD) is effective June 5, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 757-200, 757-200CB, and 757-300 airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by cracks on both sides of the airplane in the station (STA) 1640 frame web between stringer S-14 and S-15. The FAA is issuing this AD to address liner holes that could create a stress concentration around the holes and lead to cracks. The unsafe condition, if not addressed, could result in the inability of a structural element to sustain limit load and could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022. Actions identified as terminating action in Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022, terminate the applicable required actions of this AD, provided the terminating action is done in accordance with the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757-53A0120, dated January 17, 2022, which is referred to in Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022.

(h) Exceptions to Service Information Specifications

(1) Where the Compliance Time columns of the tables in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022, refer to the original issue date of Requirements Bulletin 757-53A0120 RB, this AD requires using the effective date of this AD.

(2) Where Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022, specifies contacting Boeing for repair instructions: This AD requires doing the repair before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(3) For airplanes that have been modified in accordance with supplemental type certificate (STC) ST01518SE, with or without blended or scimitar blended winglets installed: This AD requires all compliance times and repetitive intervals required by this AD, as specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022, to be divided by a factor of 2.

(4) For airplanes identified as Group 1 in Boeing Alert Requirements Bulletin 757-

53A0120 RB, dated January 17, 2022, that have been converted from a passenger to freighter configuration with VT Mobile Aerospace Engineering (MAE) STC ST03562AT: This AD requires compliance with all applicable actions and compliance times specified for Group 3 airplanes.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to AMOC@FAA.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Wayne Ha, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: 562-627-5238; email: Wayne.Ha@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757-53A0120 RB, dated January 17, 2022.

(ii) [Reserved]

(3) For Boeing material, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on March 29, 2024.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-09338 Filed 4-30-24; 8:45 am]

BILLING CODE 4910-13-P

COMMODITY FUTURES TRADING COMMISSION**17 CFR Parts 23 and 37****RIN 3038-AF34****Swap Confirmation Requirements for Swap Execution Facilities**

AGENCY: Commodity Futures Trading Commission.

ACTION: Final rule.

SUMMARY: The Commodity Futures Trading Commission (Commission or CFTC) is amending its swap execution facility (SEF) regulations related to uncleared swap confirmations, and making associated technical and conforming changes.

DATES: This rule is effective May 31, 2024.

FOR FURTHER INFORMATION CONTACT: Roger Smith, Associate Chief Counsel, (202) 418-5344, rsmith@cftc.gov, Division of Market Oversight, Commodity Futures Trading Commission, 77 West Jackson Blvd., Suite 800, Chicago, Illinois 60604.

SUPPLEMENTARY INFORMATION:**Table of Contents**

- I. Background
 - A. Regulatory History: The Part 37 Rules
 - B. Summary of Amendments to § 37.6
 - C. Consultation With Other U.S. Financial Regulators
- II. Final Regulations
 - A. § 37.6—Enforceability
 - 1. Regulation § 37.6(b)(1)—Uncleared Swap Confirmations: Incorporation by Reference of Underlying Previously Negotiated Agreements
 - 2. Amendment to § 37.6(b)—Timing of Swap Transaction Confirmation
 - 3. Amendment to § 37.6(b)—Conflicting Terms
 - 4. Clarification of § 37.6(b)
 - 5. Clarification of § 37.6(a)
 - B. Amendments to § 23.501(a)(4)(i)
- III. Effective Date
- IV. Related Matters
 - A. Regulatory Flexibility Act
 - B. Paperwork Reduction Act
 - C. Cost-Benefit Considerations
 - D. Antitrust Considerations