

TABLE 1 TO PARAGRAPH (c)(3)—Continued

Data element	Explanation
Start leg amount	The amount of cash transferred to the cash borrower on the open leg of the transaction at the inception of the transaction.
Close leg amount	The amount of cash to be transferred by the cash borrower on the end date of the transaction.
Current cash amount	The amount of cash to be transferred by the cash borrower, inclusive of principal, accrued interest and other adjustments, as of the end of the business day.
Start leg currency	The currency which is used in the Start leg amount field.
Rate	The rate of interest paid by the cash borrower on the transaction, expressed as an annual percentage rate on an actual/360-day basis.
Floating rate benchmark	The name of the benchmark interest rate upon which the transaction is based.
Floating rate reset frequency	The time period, in calendar days, describing the frequency of the floating rate resets.
Spread	The contractual spread over (or below) the benchmark rate referenced in the repurchase agreement.
Securities identifier type	The identifier type for the securities transferred between cash borrower and cash lender.
Security identifier	The identifier of securities transferred between the cash borrower and the cash lender in the repo.
Securities quantity	The number of units (e.g., shares, bonds, bills, notes) transferred to the cash lender as of the end of the business day.
Securities value	The market value of the transferred securities as of the end of the business day, inclusive of accrued interest.
Securities value at inception	The market value of the transferred securities at the inception of the transaction, inclusive of accrued interest.
Securities value currency	The currency used in the Securities value and Securities value at inception fields.
Haircut	The difference between the market value of the transferred securities and the purchase price paid at the inception of the transaction.
Special instructions, notes, or comments ..	The covered reporter may characterize any detail of the transaction with special instructions, notes, or comments.

(d) *Reporting process.* Covered reporters shall submit the required data for each business day by 11 a.m. Eastern Time on the following business day. The Office may either collect the data itself or designate a collection agent for that purpose.

(e) *Compliance date.* (1) Any financial company that meets the criteria set forth in paragraph (b)(2)(i) of this section as of the effective date of this section shall comply with the reporting requirements pursuant to this section 150 days after the effective date of this section. Any such covered reporter's first submission shall be submitted on the first business day after such compliance date.

(2) Any financial company that meets the criteria set forth in paragraph (b)(2)(ii) of this section as of the effective date of this section shall comply with the reporting requirements pursuant to this section 270 days after the effective date of this section. Any such covered reporter's first submission shall be submitted on the first business day after such compliance date.

(3) Any financial company not described in subparagraph (e)(1) or (2) of this section that meets the criteria set forth in paragraph (b)(2)(i) of this section shall comply with the reporting requirements pursuant to this section 150 days after the last day of the calendar quarter in which such financial company becomes a covered reporter.

(4) Any financial company not described in subparagraph (e)(1) or (2) of this section that meets the criteria set

forth in paragraph (b)(2)(ii) of this section after the effective date of this section shall comply with the reporting requirements pursuant to this section 270 days after the last day of the calendar quarter in which such financial company becomes a covered reporter.

James D. Martin,
Acting Director.

[FR Doc. 2024-08999 Filed 5-3-24; 8:45 am]

BILLING CODE 4810-AK-P-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-0036; Project Identifier MCAI-2023-00731-E; Amendment 39-22739; AD 2024-08-06]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Rolls-Royce Deutschland Ltd & Co KG (RRD) Model Trent 1000-A, Trent 1000-A2, Trent 1000-AE, Trent 1000-AE2, Trent 1000-C, Trent 1000-C2, Trent 1000-CE, Trent 1000-CE2, Trent 1000-D, Trent 1000-D2, Trent 1000-E, Trent 1000-E2, Trent 1000-G, Trent 1000-G2,

Trent 1000-H, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 engines. This AD was prompted by reports of wear in the combining spill valve (CSV) assembly of certain hydro-mechanical units (HMUs). This AD requires removing certain HMUs from service and replacing with a serviceable part. This AD also prohibits the installation of certain HMUs unless the HMU is a serviceable part or the CSV assembly has been replaced, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 10, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 10, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2024-0036; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For EASA service information, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2024-0036.

FOR FURTHER INFORMATION CONTACT: Sungmo Cho, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7241; email: sungmo.d.cho@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all RRD Model Trent 1000-A, Trent 1000-A2, Trent 1000-AE, Trent 1000-AE2, Trent 1000-C, Trent 1000-C2, Trent 1000-CE, Trent 1000-CE2, Trent 1000-D, Trent 1000-D2, Trent 1000-E, Trent 1000-E2, Trent 1000-G, Trent 1000-G2, Trent 1000-H, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 engines. The NPRM published in the **Federal Register** on January 24, 2024 (89 FR 4582). The NPRM was prompted by EASA AD 2023-0113, dated June 1, 2023 (EASA AD 2023-0113) (also referred to as the MCAI), issued by

EASA, which is the Technical Agent for the Member States of the European Union. The MCAI states that occurrences have been reported of finding wear in the CSV assembly of certain HMUs. This wear can reduce the fuel flow output when the engine is operated at high power conditions and lead to thrust reduction. To address this unsafe condition, the manufacturer published service information that specifies procedures to remove certain HMUs from service and replace with a serviceable part. The MCAI also specifies an implementation schedule, based on engine flight-hour (EFH) limits, for replacement of each affected part with a serviceable part and prohibits installation or reinstallation of affected HMUs that have exceeded the allowable EFH limit unless the HMU is a serviceable part or the CSV assembly has been replaced.

In the NPRM, the FAA proposed to require removing certain HMUs from service and replacing with a serviceable part. The NPRM also proposed to prohibit installation of certain HMUs unless the HMU is a serviceable part or the CSV assembly has been replaced. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2024-0036.

Discussion of Final Airworthiness Directive

Comments

The FAA received one comment from Boeing which supported the NPRM without change.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting the AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

The FAA reviewed EASA AD 2023-0113, which specifies procedures for removing certain part-numbered HMUs from service and replacing with a serviceable part. The MCAI also specifies prohibiting installation or reinstallation of an affected HMU on any engine unless the HMU is a serviceable part.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Costs of Compliance

The FAA estimates that this AD affects 28 engines installed on airplanes, of U.S. registry.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace the HMU	7 work-hours × \$85 per hour = \$595	\$552,000	\$552,595	\$15,472,660

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and

procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-08-06 Rolls-Royce Deutschland Ltd & Co KG: Amendment 39-22739; Docket No. FAA-2024-0036; Project Identifier MCAI-2023-00731-E.

(a) Effective Date

This airworthiness directive (AD) is effective June 10, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Rolls-Royce Deutschland Ltd & Co KG Model Trent 1000-A, Trent 1000-A2, Trent 1000-AE, Trent 1000-AE2, Trent 1000-C, Trent 1000-C2, Trent 1000-CE, Trent 1000-CE2, Trent 1000-D, Trent 1000-D2, Trent 1000-E, Trent 1000-E2, Trent 1000-G, Trent 1000-G2, Trent 1000-H, Trent 1000-H2, Trent 1000-J2, Trent 1000-K2, and Trent 1000-L2 engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7300, Engine Fuel and Control.

(e) Unsafe Condition

This AD was prompted by reports of wear in the combining spill valve (CSV) assembly of certain hydro-mechanical units (HMUs). The FAA is issuing this AD to prevent thrust reduction. The unsafe condition, if not addressed, could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: Perform all required actions within the compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023-0113, dated June 1, 2023 (EASA AD 2023-0113).

(h) Exceptions to EASA AD 2023-0113

(1) Where EASA AD 2023-0113 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Table 1 of EASA AD 2023-0113 specifies “15 June 2023”, replace that text with “As of the effective date of this AD.”

(3) Where Table 1 of EASA AD 2023-0113 specifies “01 January 2025”, replace that text with “Within 4 months after the effective date of this AD or January 1, 2025, whichever occurs later.”

(4) Where the service information referenced in EASA AD 2023-0013 specifies to discard certain parts, this AD requires those parts to be removed from service.

(5) This AD does not adopt the Remarks paragraph of EASA AD 2023-0113.

(i) Definitions

For the purposes of this AD, the “implementation date” is defined as the date that the applicable engine flight hour limit takes effect.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR-520 Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the AIR-520 Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Sungmo Cho, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone: (781) 238-7241; email: *sungmo.d.cho@faa.gov*.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023-0113, dated June 1, 2023.

(ii) [Reserved]

(3) For EASA AD 2023-0113, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: *ADs@easa.europa.eu*; website: *easa.europa.eu*. You may find this material on the EASA website at *ad.easa.europa.eu*.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA,

visit www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov.

Issued on April 17, 2024.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-09555 Filed 5-3-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2024-0030; Project Identifier AD-2023-01066-E; Amendment 39-22722; AD 2024-07-02]

RIN 2120-AA64

Airworthiness Directives; CFM International, S.A. Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for CFM International, S.A. (CFM) Model LEAP-1A23, LEAP-1A24, LEAP-1A24E1, LEAP-1A26, LEAP-1A26CJ, LEAP-1A26E1, LEAP-1A29, LEAP-1A29CJ, LEAP-1A30, LEAP-1A32, LEAP-1A33, LEAP-1A33B2, and LEAP-1A35A engines. This AD was prompted by detection of melt-related freckles in the billet, which may reduce the life of certain high-pressure turbine (HPT) rotor interstage seals. This AD requires removing the affected HPT rotor interstage seals from service and replacing with a part eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective June 10, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 10, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2024-0030; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference: