

§ 51.1445 Fairly well developed.

Fairly well developed means that the kernel is full-meated in over 50 percent of its width and length.

§ 51.1446 Poorly developed.

Poorly developed means that the kernel is full-meated in less than 25 percent of its width and length.

§ 51.1447 Uniform in color.

Uniform in color means that 95 percent or more of the kernels in the lot have skin color within the range of one or two color classifications.

§ 51.1448 Fairly uniform in color.

Fairly uniform in color means that 85 percent or more of the kernels in the lot have skin color within the range of one or two color classifications.

§ 51.1449 Uniform in size.

Uniform in size means that, in a representative sample of 100 halves, the 10 smallest halves weigh not less than 25 percent as much as the 10 largest halves.

§ 51.1450 Fairly uniform in size.

Fairly uniform in size means that, in a representative sample of 100 halves, the 10 smallest halves weigh not less than 50 percent as much as the 10 largest halves.

§ 51.1451 Foreign material.

Foreign material includes rocks, wood, glass, plastic, or any similar material. It does not include hard shell, center wall, or pecan weevil larvae.

§ 51.1452 Damage.

Damage means any specific defect described in this section; or an equally objectionable variation of any one of these defects, or any other defect, or any combination of defects, which materially detracts from the appearance or the edible or marketing quality of the individual portion of the kernel or of the lot as a whole. The following defects shall be considered as damage:

(a) Adhering material from inside the shell when attached to more than one-fourth of the surface on one side of the half-kernel or piece;

(b) Dust or dirt adhering to the kernel when conspicuous;

(c) Internal flesh discoloration of a medium shade of gray or brown extending more than one-fourth the length of the half-kernel or piece, or lesser areas of dark discoloration affecting the appearance to an equal or greater extent;

(d) Kernel which is not well dried;

(e) Kernel which is "dark amber" or darker color;

(f) Kernel having more than one dark kernel spot, or one dark kernel spot

more than one-eighth inch in greatest dimension;

(g) Poorly developed kernel; and

(h) Shriveling when the surface of the kernel is very conspicuously wrinkled.

§ 51.1453 Serious damage.

Serious damage means any specific defect described in this section; or an equally objectionable variation of any one of these defects, or any other defect, or any combination of defects, which seriously detracts from the appearance or the edible or marketing quality of the individual portion of kernel or of the lot as a whole. The following defects shall be considered as serious damage:

(a) Adhering material from inside the shell when attached to more than one-half of the surface on one side of the half-kernel or piece;

(b) Any plainly visible mold;

(c) Dark kernel spots when more than three are on the kernel, or when any dark kernel spot or the aggregate of two or more spots affect an area of more than 10 percent of the surface of the half-kernel or piece;

(d) Dark skin discoloration, darker than "dark brown," when covering more than one-fourth of the surface of the half-kernel or piece;

(e) Decay affecting any portion of the kernel;

(f) Insects, web, or frass or any distinct evidence of insect feeding on the kernel;

(g) Internal discoloration, which is dark gray, dark brown, or black and extends more than one-third the length of the half-kernel or piece; and

(h) Rancidity when the kernel is distinctly rancid to taste. Staleness of flavor shall not be classed as rancidity.

Note 1 to § 1453(h): Rancidity refers to the tendency of the oil in a pecan kernel to become tainted as a result of oxidation or hydrolysis. Industry measures to determine the tendency of a kernel to become rancid include testing the kernel's peroxide and free fatty acid values. Peroxide values should be less than 5 mEq/kg and free fatty acids acid value should be less than 1 percent. These analyses are not performed in determination of grade.

Erin Morris,

Associate Administrator, Agricultural Marketing Service.

[FR Doc. 2024-13584 Filed 6-25-24; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2024-1688; Project Identifier MCAI-2024-00299-T; Amendment 39-22772; AD 2024-12-08]

RIN 2120-AA64

Airworthiness Directives; Embraer S.A. (Type Certificate Previously Held by Yaborã Indústria Aeronáutica S.A.; Embraer S.A.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Embraer S.A. Model ERJ 170 airplanes. This AD was prompted by a report of a landing gear not locked indication during the final approach, which led the flight crew to declare an emergency. This AD requires reviewing maintenance records of the main landing gear (MLG) assemblies to determine whether the MLG was modified according to a certain service bulletin or restored during overhaul maintenance; inspecting the left and right MLG locking-stay bracket assemblies to verify that the correct attaching hardware is correctly installed on the brackets; replacing nuts having certain part numbers (P/Ns); replacing the locking-stay bracket assembly, if necessary; and prohibits the installation of affected parts on the MLG locking-stay bracket assembly; as specified in an Agência Nacional de Aviação Civil (ANAC) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 11, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 11, 2024.

The FAA must receive comments on this AD by August 12, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1688; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For ANAC material, contact National Civil Aviation Agency (ANAC), Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246-190—São José dos Campos—SP, Brazil; telephone 55 (12) 3203-6600; email pac@anac.gov.br; website anac.gov.br/en/. You may find this material on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1688.

FOR FURTHER INFORMATION CONTACT:

Krista Greer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3221; email krista.greer@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include the “Docket No. FAA-2024-1688; Project Identifier MCAI-2024-00299-T” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal

information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Krista Greer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206-231-3221; email krista.greer@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

ANAC, which is the aviation authority for Brazil, has issued ANAC Emergency AD E2024-05-09R01, effective May 29, 2024 (ANAC AD E2024-05-09R01) (also referred to as the MCAI), to correct an unsafe condition for certain Embraer S.A. Model ERJ 170 airplanes. The MCAI states that a landing gear not locked indication during the final approach led the flight crew to declare an emergency. Although the event did not result in serious consequences, it was found that a failure could occur in the MLG locking-stay bracket assembly, due to the installation of a particular self-locking nut (P/N MS17826-5) installed during modification according to Embraer Service Bulletin 170-32-0089 or during restoration in overhaul maintenance.

The FAA is issuing this AD to address failure of the MLG locking-stay bracket assembly due to failure of this self-locking nut, which can result in uncommanded retraction of the landing gear and consequent loss of directional control of the airplane on the ground if the landing gear collapses.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1688.

Related Material Under 1 CFR Part 51

ANAC AD E2024-05-09R01 specifies checking the airplane maintenance records to identify whether the MLG was modified according to a certain service bulletin or restored during overhaul maintenance. ANAC AD E2024-05-09R01 also specifies procedures for a general visual inspection of the left and right MLG locking-stay bracket assemblies to verify that the correct screws, washers, nuts, and cotter pins are correctly installed on the bracket; replacement of nuts having certain part numbers; and replacement of the locking-stay bracket assembly if any anomaly (looseness, missing parts, bending, cracking, or other damage) is detected in any attachment parts installed on the bracket. ANAC AD E2024-05-09R01 further prohibits the installation of nuts having P/N MS17826-5 on the MLG locking-stay bracket. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in ANAC AD E2024-05-09R01 described previously, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, ANAC AD E2024-05-09R01 is incorporated by reference in this AD. This AD requires compliance with ANAC AD E2024-05-09R01 in its entirety through that incorporation, except for any differences

identified as exceptions in the regulatory text of this AD. Service information required by ANAC AD E2024-05-09R01 for compliance will be available at *regulations.gov* under Docket No. FAA-2024-1688 after this AD is published.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance.

Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because failure of the locking-stay bracket assembly due to failure of a certain self-locking nut can result in uncommanded retraction of the landing gear and consequent loss of directional control of the airplane on the ground if the landing gear collapses. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 728 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$61,880

The FAA estimates the following costs to do any on-condition actions that would be required based on the results

of any required actions. The FAA has no way of determining the number of

aircraft that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
Up to 3 work-hours × \$85 per hour = \$255	Up to \$3,740	Up to \$3,995.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-12-08 Embraer S.A. (Type Certificate Previously Held by Yaborã Indústria Aeronáutica S.A.; Embraer S.A.): Amendment 39-22772; Docket No. FAA-2024-1688; Project Identifier MCAI-2024-00299-T.

(a) Effective Date

This airworthiness directive (AD) is effective July 11, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Embraer S.A. (Type Certificate previously held by Yaborã Indústria Aeronáutica S.A.; Embraer S.A.) Model ERJ 170–100 LR, –100 STD, –100 SE, and –100 SU airplanes, and Model ERJ 170–200 LR, –200 SU, –200 STD, and –200 LL airplanes, certificated in any category, as identified in Agência Nacional de Aviação Civil (ANAC) Emergency AD E2024–05–09R01, effective May 29, 2024 (ANAC AD E2024–05–09R01).

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Unsafe Condition

This AD was prompted by a report of a landing gear not locked indication during the final approach, which led the flight crew to declare an emergency. The FAA is issuing this AD to address failure of the main landing gear (MLG) locking-stay bracket assembly due to failure of this self-locking nut, which can result in uncommanded retraction of the landing gear and consequent loss of directional control of the airplane on the ground if the landing gear collapses.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, ANAC AD E2024–05–09R01.

(h) Exceptions to ANAC AD E2024–05–09R01

(1) Where ANAC AD E2024–05–09R01 refers to May 21, 2024, the effective date of ANAC Emergency AD E2024–05–09, this AD requires using the effective date of this AD.

(2) Where ANAC AD E2024–05–09R01 refers to its effective date, this AD requires using the effective date of this AD.

(3) ANAC AD E2024–05–09R01 does not specify a compliance time for the actions specified in paragraphs (b)(2)(i), (b)(2)(i)(I), (c)(2)(i), and (c)(2)(i)(I) of ANAC AD E2024–05–09R01. For this AD, after accomplishing the inspection required by paragraph (b)(2) or (c)(2), as applicable, of ANAC AD E2024–05–09R01, the actions required by paragraphs (b)(2)(i), (b)(2)(i)(I), (c)(2)(i), and (c)(2)(i)(I) of ANAC AD E2024–05–09R01 must be done before further flight, if there is no anomaly in the hardware installation on the bracket P/N 1840A0700–03 or 1840A0700–04, or nut having P/N MS17826–5 installed, as applicable.

(4) Where paragraph (e) of ANAC AD E2024–05–09R01 refers to “After the effective date of this AD,” for this AD, replace that text with “As of the effective date of this AD.”

(5) This AD does not adopt paragraph (g) of ANAC AD E2024–05–09R01.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International

Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

(j) Additional Information

For more information about this AD, contact Krista Greer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3221; email krista.greer@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Agência Nacional de Aviação Civil (ANAC) Emergency AD E2024–05–09R01, effective May 29, 2024.

(ii) [Reserved]

(3) For ANAC AD E2024–05–09R01, contact National Civil Aviation Agency (ANAC), Aeronautical Products Certification Branch (GGCP), Rua Dr. Orlando Feirabend Filho, 230—Centro Empresarial Aquarius—Torre B—Andares 14 a 18, Parque Residencial Aquarius, CEP 12.246–190—São José dos Campos—SP, Brazil; telephone 55 (12) 3203–6600; email: pac@anac.gov.br; website anac.gov.br/en/. You may find this ANAC AD on the ANAC website at sistemas.anac.gov.br/certificacao/DA/DAE.asp.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on June 11, 2024.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–13938 Filed 6–21–24; 11:15 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2024–1687; Project Identifier AD–2024–00253–T; Amendment 39–22771; AD 2024–12–07]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for The Boeing Company Model 757–200 airplanes modified by particular supplemental type certificates. This AD was prompted by reports of cracking in the structure in and around the lavatory service panel. This AD requires repetitively inspecting the lavatory service panel, access pan, and attaching structure for cracks; reinforcing the attaching structure; and if necessary, replacing the access pan or repairing cracked parts. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 11, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 11, 2024.

The FAA must receive comments on this AD by August 12, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov by searching for and locating Docket No. FAA–2024–1687; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above.