

(k) Retained Exceptions to EASA AD 2023–0004, With No Changes

This paragraph restates the exceptions specified in paragraph (h) of AD 2023–12–03, with no changes.

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2023–0004.

(2) Paragraph (3) of EASA AD 2023–0004 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after August 7, 2023 (the effective date of AD 2023–12–03).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2023–0004 is on or before the applicable “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2023–0004, or within 90 days after August 7, 2023 (the effective date of AD 2023–12–03), whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraphs (4) of EASA AD 2023–0004.

(5) This AD does not adopt the “Remarks” section of EASA AD 2023–0004.

(l) Retained Provisions for Alternative Actions and Intervals From AD 2023–12–03, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2023–12–03, with no changes. Except as required by paragraph (n) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (e.g., inspections) and intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2023–0004.

(m) Retained Terminating Action From AD 2023–12–03, With No Changes

This paragraph restates the terminating action specified in paragraph (j) of AD 2023–12–03, with no changes. Accomplishing the actions required by paragraph (j) of this AD terminates the corresponding requirements of paragraph (g) of this AD, for the tasks identified in the material referenced in EASA AD 2023–0004 only.

(n) New Revision of the Existing Maintenance or Inspection Program

Except as specified in paragraph (o) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2024–0005, dated January 5, 2024 (EASA AD 2024–0005). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraphs (g) and (j) of this AD.

(o) Exceptions to EASA AD 2024–0005

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2024–0005.

(2) Paragraph (3) of EASA AD 2024–0005 specifies revising “the approved AMP,” within 12 months after its effective date, but this AD requires revising the existing

maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2024–0005 is at the applicable “limitations” and “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2024–0005, or within 90 days after the effective date of this AD, whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraphs (4) and (5) of EASA AD 2024–0005.

(5) This AD does not adopt the “Remarks” section of EASA AD 2024–0005.

(p) New Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (n) of this AD, no alternative actions (e.g., inspections) and intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2024–0005.

(q) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (r) of this AD. Information may be emailed to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(r) Additional Information

For more information about this AD, contact Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email dat.v.le@faa.gov.

(s) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following material was approved for IBR on November 15, 2024.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0005, dated January 5, 2024.

(ii) [Reserved]

(4) The following material was approved for IBR on August 7, 2023 (88 FR 42598, July 3, 2023; corrected August 7, 2023 (88 FR 52024)).

(i) EASA AD 2023–0004, dated January 6, 2023.

(ii) [Reserved]

(5) The following material was approved for IBR on April 10, 2023 (88 FR 13668, March 6, 2023).

(i) EASA AD 2022–0125, dated June 28, 2022.

(ii) [Reserved]

(6) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA material on the EASA website at ad.easa.europa.eu.

(7) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(8) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 11, 2024.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–23540 Filed 10–10–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2024–2329; Project Identifier AD–2024–00451–R; Amendment 39–22864; AD 2024–20–05]

RIN 2120–AA64

Airworthiness Directives; Columbia Helicopters, Inc., and Restricted Category Model CH–47D Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Columbia Helicopters, Inc., Model 234 helicopters and restricted category Model CH–47D helicopters. This AD was prompted by two reports of a flight control rigid connecting link (link) failure, due to a manufacturing defect.

This AD requires removing certain links from service and prohibits installing those links. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 28, 2024.

The FAA must receive comments on this AD by November 25, 2024.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2329; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above.

Related Material: For Boeing material identified in this AD, contact Billings Flying Service, Inc., 309 Jellison Road, Billings, MT 59101; phone: (406) 252-6937; email: jed@flybfs.com.

FOR FURTHER INFORMATION CONTACT: David Herron, Aviation Safety Engineer, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: (206) 231-3544; email: david.herron@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2024-2329; Project Identifier AD-2024-00451-R” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR

11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to David Herron, Aviation Safety Engineer, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: (206) 231-3544; email: david.herron@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA received two reports of a link part number (P/N) 145C3340-10 failure involving a Model CH-47D helicopter. In both reports, it was determined that the failed link was manufactured by Aero Components Inc., which was not an approved supplier for these links. Boeing advised that failure of one link was caused by an eccentricity of the threaded bore in the end of the tube associated with the rod-end installation, which was determined to be a manufacturing defect; this resulted in a thin wall condition on one side. Failure of the other link showed the same contributor, but on the opposite end of the tube.

Boeing advised some links having P/N 145C3340 have been found to have missing or illegible markings; however, both failed links involve clear Aero Components Inc. CAGE code markings. Columbia Helicopters, Inc., Model 234 helicopters are also affected by the unsafe condition since the affected links may also be installed on that model helicopter.

This condition, if not addressed, could result in link failure within the flight control system due to fatigue. The

FAA is issuing this AD to address the unsafe condition on these products and subsequent immediate loss of control of the helicopter.

FAA’s Determination

The FAA is issuing this AD because the agency determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Related Material

The FAA reviewed Boeing CH-47 Service Bulletin No. 145-67-1047, dated May 22, 2024. This material specifies procedures for inspecting link P/N 145C3340-10 to determine its manufacturing code and, depending on the results, contacting Boeing for additional assistance or replacing the link.

AD Requirements

This AD requires removing links P/N 145C3340-10 with manufacturing CAGE code 59213 from service and prohibits installing those links on any helicopter.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because the affected component is part of an assembly that is critical to the flight control of a helicopter, such that if failure occurs in the affected component subsequent immediate loss of control of a helicopter will occur. As the FAA has no information pertaining to the extent of fatigue of the affected component that may currently exist in helicopters or how quickly the condition may propagate to failure, the actions required by this AD must be accomplished within 5 days. The compliance time in this AD is shorter than the time necessary for the public to comment and for publication of the final

rule. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 36 helicopters of U.S. registry. Labor costs are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

Replacing a link will take 8 work-hours and parts will cost \$1,963 for an estimated cost of \$2,643 per helicopter.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-20-05 Columbia Helicopters, Inc., and Restricted Category Model CH-47D Helicopters: Amendment 39-22864; Docket No. FAA-2024-2329; Project Identifier AD-2024-00451-R.

(a) Effective Date

This airworthiness directive (AD) is effective October 28, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the helicopters identified in paragraphs (c)(1) and (2) of this AD with a flight control rigid connecting link (link) part number (P/N) 145C3340-10 having manufacturing CAGE code 59213, a link P/N 145C3340-10 having an unknown manufacturing CAGE code, a link with an unknown P/N having manufacturing CAGE code 59213, or a link with an unknown P/N and unknown manufacturing CAGE code, installed.

- (1) Columbia Helicopters, Inc., Model 234 helicopters, certificated in any category; and
- (2) Restricted category Model CH-47D helicopters; current type certificate holders include, but are not limited to, Billings Flying Service, Inc., Columbia Helicopters, Inc., Tandem Rotor, LLC, and Unical Air Inc.

Note 1 to paragraph (c): A flight control rigid connecting link is also referred to as a rigid connecting link in related material.

Note 2 to paragraph (c): The P/N and manufacturing CAGE code information may be located on the tube of the link assembly. Information about the location of the P/N and manufacturing CAGE code is available in Boeing Service Bulletin CH-47, No. 145-67-1047, dated May 22, 2024.

(d) Subject

Joint Aircraft System Component (JASC) Code: 2700, Flight control systems.

(e) Unsafe Condition

This AD was prompted by two reports of a link failure, due to a manufacturing defect. The FAA is issuing this AD to address non-conforming links. The unsafe condition, if not addressed, could result in a link failure within the flight control system due to fatigue and subsequent immediate loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 5 days after the effective date of this AD, remove the link from service and replace it with an airworthy link.

(h) Parts Installation Prohibition

As of the effective date of this AD, do not install a link identified in the introductory text of paragraph (c) of this AD on any helicopter.

(i) Special Flight Permit

Special flight permits are prohibited.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, West Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the West Certification Branch, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

(1) For more information about this AD, contact David Herron, Aviation Safety Engineer, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712; phone: (206) 231-3544; email: david.herron@faa.gov.

(2) For Boeing material identified in this AD that is not incorporated by reference, contact Billings Flying Service, Inc., 309 Jellison Road, Billings, MT 59101; phone: (406) 252-6937; email: jed@flybfscom.

(l) Material Incorporated by Reference

None.

Issued on October 3, 2024.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-23547 Filed 10-8-24; 11:15 am]

BILLING CODE 4910-13-P