

FAA is issuing this AD to address ELT antenna failure. The unsafe condition, if not addressed, could result in loss of the ELT antenna and the development of fuselage cracks that can result in an inability to maintain cabin pressure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF-2022-67.

(h) Exception to Transport Canada AD CF-2022-67

(1) Where Transport Canada AD CF-2022-67 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where Transport Canada AD CF-2022-67 refers to April 1, 2021 (the effective date of Transport Canada AD CF-2021-10, dated March 18, 2021), this AD requires using May 4, 2021 (the effective date of AD 2021-09-03).

(3) Where Transport Canada AD CF-2022-67 refers to hours air time, this AD requires using flight hours.

(4) Where paragraph C of Transport Canada AD CF-2022-67 specifies to “replace the ELT antenna with a new aluminum ELT antenna and inspect the exterior fuselage skin around the ELT antenna attachment holes for damage, repairing any damage found before further flight,” this AD requires replacing that text with “replace the ELT antenna with a new aluminum ELT antenna, including doing an inspection of the exterior fuselage skin around the ELT antenna attachment holes for damage, and, before further flight, repair any damage found.”

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-NYACO-COS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved previously for AD 2021-09-03 are not approved as AMOCs for the corresponding provisions of Transport Canada AD CF-2022-67 that are required by paragraph (g) of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation

Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership’s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

For more information about this AD, contact Yaser Osman, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 860-386-1786; email: yaser.m.osman@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF-2022-67, dated December 6, 2022.

(ii) [Reserved]

(3) For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888-663-3639; email TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca; website tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on October 24, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024-25977 Filed 11-8-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-1894; Project Identifier MCAI-2024-00036-T; Amendment 39-22873; AD 2024-22-02]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2023-21-02, which applied to certain Airbus SAS

Model A330-200 series, A330-200 Freighter series, A330-300 series, A330-800 series, and A330-900 series airplanes. AD 2023-21-02 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD continues to require certain actions in AD 2023-21-02 and requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 17, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 17, 2024.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of December 11, 2023 (88 FR 76107, November 6, 2023).

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2024-1894; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2024-1894.

FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aviation Safety Engineer, FAA, 1600 Stewart Avenue,

Suite 410, Westbury, NY 11590; telephone 206-231-3229; email vladimir.ulyanov@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2023-21-02, Amendment 39-22574 (88 FR 76107, November 6, 2023) (AD2023-21-02). AD 2023-21-02 applied to certain Airbus SAS Model 330-201, -202, -203, -223, -223F, -243, -243F, -301, -302, -303, -321, -322, -323, -341, -342, -343, -841 and -941 airplanes. AD 2023-21-02 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2023-21-02 to address fatigue cracking, accidental damage, and corrosion in principal structural elements; such fatigue cracking, accidental damage, and corrosion could result in reduced structural integrity of the airplane.

The NPRM published in the **Federal Register** on July 24, 2024 (89 FR 59853). The NPRM was prompted by AD 2024-0011, dated January 10, 2024 (EASA AD 2024-0011) (also referred to as the MCAI), issued by EASA, which is the Technical Agent for the Member States of the European Union. The MCAI states that new or more restrictive airworthiness limitations have been developed.

In the NPRM, the FAA proposed to continue to require certain actions in AD 2023-21-02 and to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2024-0011. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1894.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from Air Line Pilots Association, International (ALPA), who supported the NPRM without change.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described

in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2024-0011, dated January 10, 2024, specifies new or more restrictive airworthiness limitations for airplane structures.

This AD also requires EASA AD 2022-0187, dated September 13, 2022, and EASA AD 2023-0015, dated January 19, 2023, which the Director of the Federal Register approved for incorporation by reference as of December 11, 2023 (88 FR 76107, November 6, 2023).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 126 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA estimates the total cost per operator for the retained actions from AD 2023-21-02 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new actions to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive (AD) 2023-21-02, Amendment 39-22574 (88 FR 76107, November 6, 2023); and
 - b. Adding the following new AD:

2024-22-02 Airbus SAS: Amendment 39-22873; Docket No. FAA-2024-1894; Project Identifier MCAI-2024-00036-T.

(a) Effective Date

This airworthiness directive (AD) is effective December 17, 2024.

(b) Affected ADs

This AD replaces AD 2023–21–02, Amendment 39–22574 (88 FR 76107, November 6, 2023) (AD 2023–21–02).

(c) Applicability

This AD applies to Airbus SAS airplanes, identified in paragraphs (c)(1) through (5) of this AD, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before October 20, 2023.

- (1) Model A330–201, –202, –203, –223, and –243 airplanes.
- (2) Model A330–223F and –243F airplanes.
- (3) Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes.
- (4) Model A330–841 airplanes.
- (5) Model A330–941 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address fatigue cracking, accidental damage, and corrosion in principle structural elements. The unsafe condition, if not addressed, could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision of the Existing Maintenance or Inspection Program, With New Terminating Action

This paragraph restates the requirements of paragraph (j) of AD 2023–21–02, with new terminating action. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before November 18, 2022: Except as specified in paragraph (h) of this AD, comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0187, dated September 13, 2022 (EASA AD 2022–0187), and AD 2023–0015, dated January 19, 2023 (EASA AD 2023–0015); as applicable. Where EASA AD 2023–0015 affects the same airworthiness limitations as those in EASA AD 2022–0187, the airworthiness limitations referenced in EASA AD 2023–0015 prevail. Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

(h) Retained Exceptions to EASA AD 2022–0187 and EASA AD 2023–0015, With No Changes

This paragraph restates the exceptions specified in paragraph (k) of AD 2023–21–02, with no changes.

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2022–0187 and of EASA AD 2023–0015.

(2) Paragraph (3) of EASA AD 2022–0187 and of EASA AD 2023–0015 specifies revising “the AMP” within 12 months after the respective EASA AD’s effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after December 11, 2023 (the effective date of AD 2023–21–02).

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0187 and of EASA AD 2023–0015 is at the applicable “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2022–0187 and of EASA AD 2023–0015, or within 90 days after December 11, 2023 (the effective date of AD 2023–21–02), whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraphs (4) and (5) of EASA AD 2022–0187.

(5) Where EASA AD 2022–0187 defines “The ALS,” replace the text “Airbus A330 Airworthiness Limitations Section (ALS) Part 2 Revision 05,” with “Airbus A330 Airworthiness Limitations Section (ALS) Part 2 Revision 05 Issue 02.”

(6) This AD does not adopt the provisions specified in paragraph (4) of EASA AD 2023–0015.

(7) This AD does not require incorporating Section 4, “Damage Tolerant—Airworthiness Limitations Items—Tasks Beyond MPPT,” of “the ALS” specified in EASA AD 2022–0187 and in EASA AD 2023–0015.

(8) This AD does not adopt the “Remarks” section of EASA AD 2022–0187 and of EASA AD 2023–0015.

(i) Retained Provisions for Alternative Actions and Intervals, With a New Exception

This paragraph restates the provisions of paragraph (l) of AD 2023–21–02, with a new exception. Except as required by paragraph (j) of this AD, no alternative actions (*e.g.*, inspections) and intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2022–0187 or of EASA AD 2023–0015.

(j) New Revision of the Existing Maintenance or Inspection Program

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2024–0011, dated January 10, 2024 (EASA AD 2024–0011). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

(k) Exceptions to EASA AD 2024–0011

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2024–0011.

(2) Paragraph (3) of EASA AD 2024–0011 specifies revising “the approved AMP,” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2024–0011 is at the applicable “associated thresholds” as incorporated by

the requirements of paragraph (3) of EASA AD 2024–0011, or within 90 days after the effective date of this AD, whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraphs (4) and (5) of EASA AD 2024–0011.

(5) This AD does not adopt the “Remarks” section of EASA AD 2024–0011.

(6) This AD does not require incorporating Section 4, “Damage Tolerant—Airworthiness Limitations Items—Tasks Beyond MPPT,” of “the ALS” specified in EASA 2024–0011.

(l) New Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (*e.g.*, inspections) and intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2024–0011.

(m) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (n) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(n) Additional Information

For more information about this AD, contact Vladimir Ulyanov, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3229; email vladimir.ulyanov@faa.gov.

(o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following material was approved for IBR on December 17, 2024.

(i) European Union Aviation Safety Agency (EASA) AD 2024–0011, dated January 10, 2024.

(ii) [Reserved]

(4) The following material was approved for IBR on December 11, 2023 (88 FR 76107, November 6, 2023).

(i) European Union Aviation Safety Agency (EASA) AD 2022–0187, dated September 13, 2022.

(ii) European Union Aviation Safety Agency (EASA) AD 2023–0015, dated January 19, 2023.

(5) For EASA AD 2022–0187, EASA AD 2023–0015, and EASA AD 2024–0011, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find these EASA ADs on the EASA website at ad.easa.europa.eu.

(6) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov.

Issued on October 23, 2024.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–25980 Filed 11–8–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2024–2007; Project Identifier MCAI–2023–01270–T; Amendment 39–22871; AD 2024–21–04]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Bombardier, Inc., Model BD–100–1A10 airplanes. This AD was prompted by a determination that new or more restrictive maintenance tasks are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance tasks. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 17, 2024.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of December 17, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2024–2007; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Bombardier, Inc. material identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email ac.yul@aero.bombardier.com; website bombardier.com.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at regulations.gov under Docket No. FAA–2024–2007.

FOR FURTHER INFORMATION CONTACT:

Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone: 516–228–7300; email: 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Bombardier, Inc., Model BD–100–1A10 airplanes. The NPRM published in the **Federal Register** on August 9, 2024 (89 FR 65267). The NPRM was prompted by AD CF–2023–78, dated December 19, 2023, issued by Transport Canada, which is the aviation authority for Canada (also referred to as the MCAI). The MCAI states that airplanes could experience misleading electrical system status indications (push button annunciators (PBA) and engine instrument and crew alerting system (EICAS)) as a result of contamination of electrical contacts in the left-hand (LH) direct current power center (DCPC) internal communication data bus. The MCAI states that new or more restrictive maintenance tasks have been developed to rectify lower time LH DCPC units not addressed by previously issued ADs.

In the NPRM, the FAA proposed to require revising the existing

maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance tasks. The FAA is issuing this AD to address erratic indications, which could cause the flightcrew to turn off fully operational electrical power sources, leading to partial or complete loss of electrical power. The unsafe condition, if not addressed, could result in loss of flight displays and reduced controllability of the airplane.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA–2024–2007.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed the following documents:

- Task 24–61–01–101*, “Restoration of the left DC Power Center (DCPC) (Pre SB100–24–30),” Section 5–10–20, “Time Limits—Supplementary Limitations,” of Part 2, “Airworthiness Limitations,” of the Bombardier Challenger 300 Time Limits/Maintenance Checks, Publication No. CH 300 TLMC, Revision 24, dated August 9, 2023.

- Task 24–61–01–101*, “Restoration of the Left DC Power Center (DCPC) (Pre SB350–24–005),” Section 5–10–20, “Time Limits—Supplementary Limitations,” of Part 2, “Airworthiness Limitations,” of the Bombardier Challenger 350 Time Limits/Maintenance Checks, Publication No. CH 350 TLMC, Revision 14, dated August 9, 2023.

This material specifies new or more restrictive airworthiness limitations for