

(2) Carry out the obligations of the Board under any contracts or agreements entered into pursuant to this subpart;

(3) From time to time account for all receipts and disbursements and deliver all property on hand, together with all books and records of the Board and trustees, to such person or persons as the Secretary directs; and

(4) Upon request of the Secretary, execute such assignments or other instruments necessary or appropriate to vest in such persons title and right to all funds, property, and claims vested in the Board or the trustees pursuant to this subpart.

(c) Any person to whom funds, property, or claims have been transferred or delivered pursuant to this subpart shall be subject to the same obligations imposed upon the Board and upon the trustees.

(d) Any residual funds not required to defray the necessary expenses of liquidation shall be turned over to the Secretary to be disposed of, to the extent practical, to one or more organizations in the United States whose mission is generic natural grass sod promotion, research, and information programs.

§ 1240.74 Effect of termination or amendment.

Unless otherwise expressly provided by the Secretary, the termination of this subpart or of any regulation issued pursuant thereto, or the issuance of any amendment to either thereof, shall not:

(a) Affect or waive any right, duty, obligation, or liability which shall have arisen, or which may thereafter arise in connection with any provision of this subpart, or any regulation issued thereunder;

(b) Release or extinguish any violation of this subpart or any regulation issued thereunder; or

(c) Affect or impair any rights or remedies of the United States, or of the Secretary or of any other persons, with respect to any such violation.

§ 1240.75 Personal liability.

No member or employee of the Board shall be held personally responsible, either individually or jointly with others, in any way whatsoever, to any person for errors in judgment, mistakes, or other acts, either of commission or omission, as such member or employee, except for acts of dishonesty or willful misconduct.

§ 1240.76 Severability.

If any provision of this subpart is declared invalid or the applicability of it to any person or circumstances is held invalid, the validity of the remainder of

this subpart, or the applicability thereof to other persons or circumstances shall not be affected thereby.

§ 1240.77 Amendments.

Amendments to this subpart may be proposed from time to time by the Board or any interested person affected by the provisions of the Act, including the Secretary.

§ 1240.78 OMB control number.

The control numbers assigned to the information collection requirements by the OMB pursuant to the PRA of 1995, 44 U.S.C. chapter 35, are OMB control numbers 0505-0001 (Background Information Form), 0581-0093 (Organic Exemption), and 0581-0349.

* * * * *

Melissa Bailey,

Associate Administrator, Agricultural Marketing Service.

[FR Doc. 2024-28389 Filed 12-9-24; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-2552; Project Identifier MCAI-2022-01243-R]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2021-09-14, which applies to certain Airbus Helicopters (Airbus) Model SA330J helicopters. AD 2021-09-14 requires repetitively inspecting for a gap between the main gearbox (MGB) oil cooling fan assembly (fan) rotor blade and the upper section of the guide vane bearing housing, installing improved MGB fan rotor shaft bearings, and repetitively inspecting the improved MGB fan rotor shaft bearings. Since the FAA issued AD 2021-09-14, Airbus has developed modifications to the components of the MGB fan bearing assembly and issued new material regarding these modifications. This proposed AD would retain the actions required by AD 2021-09-14 and would also require installing the improved MGB fan rotor bearing assembly, which would constitute terminating action for the repetitive inspections. These actions

are specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by January 24, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2552; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-2552.

FOR FURTHER INFORMATION CONTACT: Hal Jensen, Aviation Safety Engineer, FAA; 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (303) 342-1080; email: hal.jensen@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2024-2552; Project

Identifier MCAI–2022–01243–R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Hal Jensen, Aviation Safety Engineer, FAA; 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (303) 342–1080; email: hal.jensen@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2021–09–14, Amendment 39–21528 (86 FR 26829, May 18, 2021) (AD 2021–09–14), for Airbus Model SA330J helicopters with MGB fan rotor shaft bearings (both rear and front) part number (P/N) 704A33651114 (manufacturer P/N (MP/N) 205FFTX74K6–G33) or P/N 704A33651268 (MP/N 594918), installed. AD 2021–09–14 was prompted by an MCAI originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued EASA AD 2020–0171, dated July 28, 2020 (EASA AD

2020–0171), to correct an unsafe condition.

AD 2021–09–14 requires repetitively inspecting for a gap between the MGB fan rotor blade and the upper section of the guide vane bearing housing and, depending on the results or within a specified compliance time, installing improved MGB fan rotor shaft bearings and repetitively inspecting the improved MGB fan rotor shaft bearings. The FAA issued AD 2021–09–14 to prevent rotor burst of the MGB fan, damage to the hydraulic lines and flight controls, and subsequent loss of control of the helicopter.

Actions Since AD 2021–09–14 Was Issued

Since the FAA issued AD 2021–09–14, EASA superseded EASA AD 2020–0171 and issued EASA AD 2022–0191, dated September 15, 2022 (EASA AD 2022–0191), to correct an unsafe condition on Airbus Helicopters Model SA 330 J helicopters. EASA AD 2022–0191 states since EASA AD 2020–0171 was issued, Airbus has developed modifications (mod) 0776102 and mod 0776104, which introduce a new Kevlar protection on the fan bearing rectifier and a new flexible duct. Additionally, Airbus issued revised material to provide in-service modification instructions.

The FAA is proposing this AD to prevent rotor burst of the MGB fan, damage to the hydraulic lines and flight controls, and subsequent loss of control of the helicopter. See EASA AD 2022–0191 for additional background information. You may examine EASA AD 2022–0191 in the AD docket at *regulations.gov* under Docket No. FAA–2024–2552.

Lastly, this NPRM uses an updated format. As a result, the applicability paragraph has changed.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2022–0191, which requires repetitively inspecting for play (a gap) on the MGB fan rotor shaft bearings (both rear and front) between the MGB fan rotor blade and the upper section of the guide vane bearing housing. If there is play that does not meet the minimum requirement or at a specified compliance time, EASA AD 2022–0191 requires replacing the affected MGB fan rotor shaft bearings with serviceable MGB fan rotor shaft bearings (both rear and front) as defined in EASA AD 2022–0191. Additionally, EASA AD 2022–0191 allows credit for performing these inspections and corrective action, provided specific requirements are met.

EASA AD 2022–0191 also requires modifying the MGB fan bearing assembly, which would constitute terminating action for the repetitive inspections.

Lastly, EASA AD 2022–0191 only allows installing serviceable MGB fan rotor shaft bearings as defined in EASA AD 2022–0191 and installing an improved MGB fan bearing assembly as defined in EASA AD 2022–0191, provided certain requirements are met.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the EASA AD referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would retain all the requirements of AD 2021–09–14 and would require accomplishing the actions specified in EASA AD 2022–0191 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD and except as discussed under “Differences Between this Proposed AD and EASA AD 2022–0191.”

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2022–0191 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2022–0191 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section of

EASA AD 2022–0191 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2022–0191. Material referenced in EASA AD 2022–0191 for compliance will be available at *regulations.gov* under Docket No. FAA–2024–2552 after the FAA final rule is published.

Differences Between This Proposed AD and EASA AD 2022–0191

The inspection material referenced in EASA AD 2022–0191 specifies returning certain parts to the manufacturer, whereas this proposed AD would require removing those parts from service instead. The inspection material referenced in EASA AD 2022–0191 specifies completing a response form, whereas this proposed AD would not require that action.

The modification material referenced in EASA AD 2022–0191 specifies sending the fan-bearing assembly to an approved D-level maintenance center for modification, whereas this proposed AD would require installing modification 0776102, and as applicable, modification 0725373.

Costs of Compliance

The FAA estimates that this AD would affect 6 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates that operators may incur the following costs in order to comply with this proposed AD.

Inspecting for a gap between the MGB fan rotor blade and the upper section of the guide vane bearing housing would take 2 work-hours for an estimated cost of \$170 per helicopter and \$1,020 for the U.S. fleet, per inspection cycle.

Replacing the MGB fan rotor shaft bearings would take 6 work-hours and parts would cost \$1,938 for an estimated cost of \$2,448 per helicopter and \$14,688 for the U.S. fleet.

Removing the flexible duct, installing new flexible duct MOD 0776104, removing the fan-bearing assembly, and installing the modified fan-bearing assembly would take 8 work-hours and parts would cost \$10,000 for an estimated cost of \$10,680 per helicopter and \$64,080 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive 2021–09–14, Amendment 39–21528 (86 FR 26829, May 18, 2021); and
 - b. Adding the following new airworthiness directive:

Airbus Helicopters: Docket No. FAA–2024–2552; Project Identifier MCAI–2022–01243–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 24, 2025.

(b) Affected ADs

This AD replaces AD 2021–09–14, Amendment 39–21528 (86 FR 26829, May 18, 2021) (AD 2021–09–14).

(c) Applicability

This AD applies to Airbus Helicopters Model SA330J helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 6322, Main Gearbox Oil Cooler.

(e) Unsafe Condition

This AD was prompted by the development of a modification for an improved MGB fan rotor bearing assembly. The FAA is issuing this AD to prevent rotor burst of the MGB fan, damage to the hydraulic lines and flight controls, and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0191, dated September 15, 2022 (EASA AD 2022–0191).

(h) Exceptions to EASA AD 2022–0191

(1) Where EASA AD 2022–0191 refers to August 11, 2020 (the effective date of EASA AD 2020–0171, dated July 28, 2020) and to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2022–0191 refers to flight hours (FH), this AD requires using hours time-in-service.

(3) Where “the inspection ASB” material referenced in EASA AD 2022–0191 specifies to return certain parts to Airbus Helicopters, this AD requires removing those parts from service.

(4) Where “the inspection ASB” material referenced in EASA AD 2022–0191 specifies completing the response form in Appendix 4, this AD does not require that action.

(5) Where the “the modification ASB” material referenced in EASA AD 2022–0191 specifies sending the fan-bearing assembly to an approved D-level maintenance center to integrate modification 0776102 and where applicable, modification 0725373, this AD requires installing modification 0776102, and as applicable, modification 0725373.

(6) This AD does not adopt the “Remarks” section of EASA AD 2022–0191.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2022–0191 specifies to submit certain

information to the manufacturer, this AD does not require that action.

(j) Special Flight Permits

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the actions of this AD can be performed, provided there are no passengers onboard.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(l) Additional Information

For more information about this AD, contact Hal Jensen, Aviation Safety Engineer, FAA; 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (303) 342-1080; email: hal.jensen@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022-0191, dated September 15, 2022.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on December 3, 2024.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-28831 Filed 12-9-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2024-2391; Airspace Docket No. 24-ANM-108]

RIN 2120-AA66

Establishment of Class E Airspace; Stanford/Biggerstaff Field, Stanford, MT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class E airspace extending upward from 700 feet above the surface at Stanford/Biggerstaff Field, Stanford, MT. This action would support the airport's transition from visual flight rules (VFR) to instrument flight rules (IFR) operations.

DATES: Comments must be received on or before January 24, 2025.

ADDRESSES: Send comments identified by FAA Docket No. FAA-2024-2391 and Airspace Docket No. 24-ANM-108 using any of the following methods:

* *Federal eRulemaking Portal:* Go to www.regulations.gov and follow the online instructions for sending your comments electronically.

* *Mail:* Send comments to Docket Operations, M-30; U.S. Department of Transportation, 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

* *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

* *Fax:* Fax comments to Docket Operations at (202) 493-2251.

Docket: Background documents or comments received may be read at www.regulations.gov at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FAA Order JO 7400.11J, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/. You may also contact the Rules and Regulations Group, Office of Policy, Federal Aviation

Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT: Nathan A. Chaffman, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231-3460.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority, as it would establish Class E airspace extending upward from 700 feet above the surface to support IFR operations at Stanford/Biggerstaff Field, Stanford, MT.

Comments Invited

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one time if comments are filed electronically, or commenters should send only one copy of written comments if comments are filed in writing.

The FAA will file in the docket all comments it receives, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments it receives on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this proposal in light of the comments it receives.