§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–05–11 ATR—GIE Avions de Transport Régional: Amendment 39– 22983; Docket No. FAA–2024–2330; Project Identifier MCAI–2024–00393–T.

(a) Effective Date

This airworthiness directive (AD) is effective April 22, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all ATR—GIE Avions de Transport Régional Model ATR42–200, ATR42–300, ATR42–320, and ATR42–500 airplanes; and Model ATR72–101, ATR72–102, ATR72–201, ATR72–212, and ATR72–212 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire protection.

(e) Unsafe Condition

This AD was prompted by a report of a manufacturing defect identified in the lavatory fire extinguisher. This defect could potentially result in leakage at the eutectic tip, leading to a loss of pressure in the cylinder, making fire extinguishing capabilities ineffective. The FAA is issuing this AD to address this condition, which, if not detected and corrected, in combination with fire in the lavatory waste bin, could result in the propagation of an uncontrolled fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0132, dated July 9, 2024 (EASA AD 2024–0132).

(h) Exceptions to EASA AD 2024-0132

- (1) Where EASA AD 2024–0132 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where EASA AD 2024–0132 defines a serviceable part as "Any lavatory (waste bin) compartment fire extinguishers, eligible for installation in accordance with ATR instructions, which is not an affected part," this AD requires replacing that text with "Any lavatory (waste bin) compartment fire extinguishers, eligible for installation, which is not an affected part."
- (3) This AD does not adopt the "Remarks" section of EASA AD 2024–0132.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International

Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or ATR—GIE Avions de Transport Régional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Additional Information

For more information about this AD, contact Shahram Daneshmandi, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 206–231–3220; email shahram.daneshmandi@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) European Union Aviation Safety Agency (EASA) AD 2024–0132, dated July 9, 2024.
 - (ii) [Reserved]
- (3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.
- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations, or email fr.inspection@nara.gov.

Issued on March 6, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–04389 Filed 3–17–25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-2554; Project Identifier MCAI-2024-00492-T; Amendment 39-22989; AD 2025-06-01]

RIN 2120-AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Canada Limited Partnership Model BD-500-1A10 and BD-500-1A11 airplanes. This AD was prompted by a design review that discovered software protection logic for potential large leaks from the engine bleed duct inside the engine core compartments was partially impaired. This AD requires revising the existing airplane flight manual (AFM) to incorporate the procedures for the flightcrew to manually isolate the opposite functional engine in the event of an engine bleed duct large leak condition, as specified in a Transport Canada AD, which is incorporated by reference (IBR). The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 22,

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 22, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2024–2554; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

• For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5,

Canada; telephone 888–663–3639; email *TC.AirworthinessDirectives-Consignesdenavigabilite.TC*@tc.gc.ca. You may find this material on the Transport Canada website at *tc.canada.ca/en/aviation*.

• You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available at *regulations.gov* under Docket No. FAA–2024–2554.

FOR FURTHER INFORMATION CONTACT: Joseph Catanzaro, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 516–

Des Moines, WA 98198; phone: 516–228–7300; email: *9-avs-nyaco-cos@faa.gov.*

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Canada Limited Partnership Model BD–500–1A10 and BD–500–1A11 airplanes. The NPRM published in the **Federal Register** on December 13, 2024 (89 FR 100923). The NPRM was prompted by AD CF–2024–30, dated August 27, 2024, issued by Transport Canada, which is the aviation authority for Canada (Transport Canada AD CF–2024–30) (also referred to as the MCAI). The MCAI states a design review discovered software protection logic for

potential large leaks from the engine bleed duct inside the engine core compartments was partially impaired. Under certain large leak conditions (e.g., a duct burst at a specific portion of the engine's bleed ducting), Pratt & Whitney's PW1500G engine's electronic engine control (EEC) would not transmit the necessary information to the aircraft controller to automatically isolate the opposite engine from the leak path in the bleed system. This failure condition could lead to a dual engine failure.

In the NPRM, the FAA proposed to require revising the existing AFM to incorporate the procedures for the flightcrew to manually isolate the opposite functional engine in the event of an engine bleed duct large leak condition, as specified in Transport Canada AD CF-2024-30.

The FAA is issuing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2024–2554.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from Air Line Pilots Association, International (ALPA) who supported the NPRM without change.

Conclusion

This product has been approved by the aviation authority of another

country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

Transport Canada AD CF-2024-30 specifies procedures for revising the "Non-Normal Procedure" of the AFM to incorporate the procedures for the flightcrew to manually isolate the opposite functional engine in the event of an engine bleed duct large leak condition. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 132 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$11,220

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an

unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(f), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025-06-01 Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39-22989; Docket No. FAA-2024-2554; Project Identifier MCAI-2024-00492-T.

(a) Effective Date

This airworthiness directive (AD) is effective April 22, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD–500–1A10 and BD–500–1A11 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 72, Turbine/turboprop engine.

(e) Unsafe Condition

This AD was prompted by a design review that discovered software protection logic for potential large leaks from the engine bleed duct inside the engine core compartments was partially impaired. Under certain large leak conditions (e.g., a duct burst at a specific portion of the engine's bleed ducting), Pratt & Whitney's PW1500G engine's electronic engine control (EEC) would not transmit the necessary information to the aircraft controller to automatically isolate the opposite engine from the leak path in the bleed system. The FAA is issuing this AD to address the unsafe condition, which if not addressed, could result in dual engine failure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with Transport Canada AD CF–2024–30, dated August 27, 2024 (Transport Canada AD CF–2024–30).

(h) Exception to Transport Canada AD CF-2024_30

(1) Where Transport Canada AD CF–2024– 30 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph B. of Transport Canada AD CF-2024-30 specifies to "inform all flight crews of these changes in the AFM procedures and thereafter operate the aeroplane accordingly," this AD does not require those actions as those actions are already required by existing FAA operating regulations (see 14 CFR 91.9, 14 CFR 91.505, and 14 CFR 121.137).

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the Continued Operational Safety Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

For more information about this AD, contact Joseph Catanzaro, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 516–228–7300; email: 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) Transport Canada AD CF-2024-30, dated August 27, 2024.
 - (ii) [Reserved]
- (3) For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email *TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca*, You may view this material on the Transport Canada website at *tc.canada.ca/en/aviation*.
- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations, or email fr.inspection@nara.gov.

Issued on March 11, 2025.

Peter A. White.

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025–04320 Filed 3–17–25; 8:45 am] **BILLING CODE 4910–13–P**

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R09-OAR-2023-0625; FRL-11613-02-R9]

Air Plan Approval; California; Eastern Kern Air Pollution Control District; Tehama County Air Pollution Control District; San Diego County Air Pollution Control District; Emissions Statement Requirements

AGENCY: Environmental Protection

Agency (EPA). **ACTION:** Final rule.

SUMMARY: The Environmental Protection Agency (EPA) is taking final action to approve revisions, under the Clean Air Act (CAA or "Act"), to portions of the California State Implementation Plan (SIP) regarding emissions statements (ES) requirements for the 2015 ozone national ambient air quality standards (NAAQS). In addition, we are approving that the following California nonattainment areas meet the ES requirements for the 2015 ozone NAAQS: Tuscan Buttes, Kern County (Eastern Kern), and San Diego County.

DATES: This rule is effective April 17, 2025.

ADDRESSES: The EPA has established a docket for this action under Docket ID No. EPA-R09-OAR-2023-0625. All documents in the docket are listed on the https://www.regulations.gov website. Although listed in the index, some information is not publicly available, e.g., Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, is not placed on the internet and will be publicly available only in hard copy form. Publicly available docket materials are available through https:// www.regulations.gov, or please contact the person identified in the FOR FURTHER **INFORMATION CONTACT** section for additional availability information. If you need assistance in a language other than English or if you are a person with a disability who needs a reasonable accommodation at no cost to you, please