### DEPARTMENT OF THE INTERIOR

### Minerals Management Service

### **Outer Continental Shelf Civil Penalties**

**AGENCY:** Minerals Management Service (MMS), Interior.

**ACTION:** Notice summarizing Outer Continental Shelf Civil Penalties paid from January 1, 2006, through December 31, 2006.

**SUMMARY:** This notice provides a listing of civil penalties paid from January 1, 2006, through December 31, 2006, for violations of the Outer Continental Shelf Lands Act (OCSLA). The goal of the MMS Outer Continental Shelf (OCS) Civil Penalties Program is to assure safe and clean operations in the OCS. Through the pursuit, assessment, and collection of civil penalties and referrals for the consideration of criminal penalties, the program is designed to encourage compliance with OCS statutes and regulations. The purpose of publishing the penalties summary is to provide information to the public on violations of special concern in OCS operations and to provide an additional incentive for safe and environmentally sound operations.

**FOR FURTHER INFORMATION CONTACT:** Joanne McCammon, Program Coordinator, at 703–787–1292.

SUPPLEMENTARY INFORMATION: The Oil Pollution Act of 1990 (OPA 90) strengthened section 24 of the OCSLA Amendments of 1978. Subtitle B of OPA 90, titled "Penalties," increased the amount of the civil penalty from a maximum of \$10,000 to a maximum of \$20,000 per violation for each day of noncompliance. More importantly, in cases where a failure to comply with applicable regulations constitutes or constituted a threat of serious, irreparable, or immediate harm or damage to life (including fish and other aquatic life); property; any mineral deposit; or the marine, coastal, or human environment; OPA 90 provided the Secretary of the Interior (Secretary) with the authority to assess a civil penalty without regard to the requirement of expiration of a period of time allowed for corrective action.

The provisions of OPA 90 also require the Secretary to adjust the maximum civil penalty to reflect any increases in the Consumer Price Index. Every 3 years, MMS analyzes the civil penalty maximum amount in conjunction with the CPI prepared by the U.S. Department of Labor. If an adjustment is necessary, MMS informs the public through the **Federal Register** of the new maximum amount. The MMS has published regulations adjusting the civil penalty assessment to \$25,000 on August 8, 1997 (62 FR 42668), and to \$30,000 on November 28, 2003 (68 FR 61622).

Between August 18, 1990, and January 2007, MMS initiated 583 civil penalty reviews. Operators have paid 459 civil penalties for a total of \$15,370,792 in fines.

On September 1, 1997, the Associate **Director for Offshore Minerals** Management issued a notice informing lessees and operators of Federal oil, gas, and sulphur leases in the OCS that MMS will annually publish a summary of OCS civil penalties paid. The annual summary will highlight the identity of the party, the regulation violated, and the amount paid. The following table provides a listing of the 41 penalties paid between January 1, 2006, and December 31, 2006. The total amount collected was \$1,480,000. A quarterly update of the list is posted on MMS's home page, *http://www.mms.gov/* civilpenalties/CP\_2006.HTM.

### 2006 CIVIL/CRIMINAL PENALTIES SUMMARY; ALL PENALTIES PAID IN CALENDAR 2006

[01/01/2006-12/31/2006]

Operator name (contractor) and case No.	Violation and date(s)	Penalty paid and date paid	Regulation(s) violated (30 CFR)
The Houston Exploration Com- pany. (Grasso Production Management)	Failed to conduct one annual crane inspection	\$10,000 8/25/06	§250.108.
G–2003–004	7/1/02–9/30/02		
PetroQuest Energy, LLC	Missing grating & handrails, corroded unsafe steps, and severe corrosion around the fuel scrubber created an unsafe situation for personnel. Also, the flowline and departing pipeline did not have secondary over-pressure protection.	\$60,000 1/3/06	§ 250.802(b), § 250.107.
G–2004–026 El Paso Production Oil and Gas Company. G–2005–007	6/29/04–6/29/04 Explosion and fire occurred on platform from welding and cutting operations near hydrocarbons. 12/23/04–12/23/04	\$25,000 2/7/06	§250.107
Exxon Mobil Corporation	The Pressure Safety Low (PSL) for Well G–24 had the incorrect spring and piston installed; the spring tension was backed off to a point where it would not function. This violation occurred for 11 days.	\$25,000 6/8/06	§250.803(b)(2)(i).
G–2005–012	12/19/04–12/29/04		
Apache Corporation (Wood Group Production Serv- ices). G-2005-014	During an annual inspection, the inspector discovered that the Emergency Shut Down (ESD) stations for both the North and South boat landings were out-of-service. 10/15/04–10/18/04	\$28,000 3/10/06	§250.803.
Noble Energy, Inc (Hercules Offshore Drilling)	The gas detector panel that monitors the mud pit room and shale shaker area was found to be in bypass during a monthly rig in- spection. The operator forgot to put it back in service after cali- brating the sensors. When the panel was taken out of bypass and tested, the audible alarm failed to activate.	\$160,000 2/15/06	§ 250.459(b).
G-2005-015	2/23/05-3/2/05	¢0.000	\$ 050 800(a)
Energy Partners Ltd	The level safety high (LSH) shut-in sensor for the deck drain sump tank was bypassed at the main panel. Neither the LSH nor the operating condition of the sump tank were being monitored by platform personnel.	\$8,000 1/10/06	§250.803(c).
G–2005–016			

# 2006 CIVIL/CRIMINAL PENALTIES SUMMARY; ALL PENALTIES PAID IN CALENDAR 2006—Continued [01/01/2006–12/31/2006]

EI Paso Production Oil and Gas Company.       Shut down valve connected in such a way that it would not oper- ate as designed; pressure would not bleed off if an upset had occurred.         G-2005-020       3/10/05-3/10/05         Grating missing on the plus 10 deck level in two areas and area not barricaded to prevent personnel from entering.         (G-2005-021       4/10/05-4/10/05         Apache Corporation       4/10/05-4/10/05         During a production follow-up inspection on February 20, 2005, wells A002 and A003 Surface Safety Valves (SSVs) were pinned out of service in the open position, and the wells were not flagged or monitored.         G-2005-022       2/20/05-2/20/05         ATP Oil & Gas Corporation       The vertical run Surface Safety Valve (SSV) for Well C-2 was by- passed and locked out of service with a locking cap.         G-2005-023       5/17/05-5/19/05         Unsafe and un-workmanlike operations were conducted in that the policies and procedures for Confined Space Entry were not being adhered to as per Operator's Health, Safety and Environ- ment manual.         G-2005-024       3/30/05-3/30/05         Noble Energy       During an inspection on May 2, 2005, the top and bottom isolation valves on the Level Safety Low (LSL) for the Bad Oil Tank (ABJ-5020) were found blocked out of service and not flagged or being monitored.         G-2005-025       5/1/05-5/2/05         Apache Corporation       5/1/05-5/2/05         Apache failed to comply with the safe and workmanlike manner and well control requiremen		(30 CFR)
Apache CorporationGrating missing on the plus 10 deck level in two areas and area not barricaded to prevent personnel from entering.(Wood Group Production Services).4/10/05–4/10/05(Wood Group Production Services).During a production follow-up inspection on February 20, 2005, wells A002 and A003 Surface Safety Valves (SSVs) were pinned out of service in the open position, and the wells were not flagged or monitored.G-2005-0222/20/05–2/20/05ATP Oil & Gas Corporation2/20/05–2/20/05ATP Oil & Gas Corporation5/17/05–5/19/05Millennium Offshore Group, Inc. (TODCO)5/17/05–5/19/05G-2005-0245/17/05–5/19/05Noble EnergyUnsafe and un-workmanlike operator's Health, Safety and Environ- ment manual. 3/30/05–3/30/05G-2005-025Juring an inspection on May 2, 2005, the top and bottom isolation valves on the Level Safety Low (LSL) for the Bad Oil Tank (ABJ-5020) were found blocked out of service and not flagged or being monitored.G-2005-025S/1/105–5/2/05Apache CorporationS/1/05–5/2/05Apache CorporationS/1/05–5/2/05Apache CorporationApache failed to comply with the safe and workmanlike manner and well control requirements addressed in the regulations. A remote blowout preventer (BOP) station on the rig floor would not operate nor function the bottom pipe ram and the hydraulic (HCR) choke valve. An accumulation of hydraulic oil on derrick	\$10,000 8/7/06	§250.802(b).
Apache CorporationDuring a production follow-up inspection on February 20, 2005, wells A002 and A003 Surface Safety Valves (SSVs) were pinned out of service in the open position, and the wells were not flagged or monitored. 2/20/05-2/20/05G-2005-0222/20/05-2/20/05ATP Oil & Gas Corporation2/20/05-2/20/05The vertical run Surface Safety Valve (SSV) for Well C-2 was by- passed and locked out of service with a locking cap.(Wood Group Production Services). G-2005-0235/17/05-5/19/05G-2005-0245/17/05-5/19/05Millennium Offshore Group, IncUnsafe and un-workmanlike operations were conducted in that the 	\$66,000 2/9/06	§250.107.
<ul> <li>ATP Oil &amp; Gas Corporation</li></ul>	\$24,000 3/13/06	§250.803(c).
Millennium Offshore Group, IncUnsafe and un-workmanlike operations were conducted in that the policies and procedures for Confined Space Entry were not being adhered to as per Operator's Health, Safety and Environ- ment manual. 3/30/05–3/30/05G=2005–0243/30/05–3/30/05Noble EnergyDuring an inspection on May 2, 2005, the top and bottom isolation valves on the Level Safety Low (LSL) for the Bad Oil Tank (ABJ–5020) were found blocked out of service and not flagged 	\$21,000 6/22/06	§250.803(c).
Noble Energy       During an inspection on May 2, 2005, the top and bottom isolation valves on the Level Safety Low (LSL) for the Bad Oil Tank (ABJ–5020) were found blocked out of service and not flagged or being monitored.         G-2005-025       S/1/05-5/2/05         Apache Corporation       S/1/05-5/2/05         Apache Corporation       Apache failed to comply with the safe and workmanlike manner and well control requirements addressed in the regulations. A remote blowout preventer (BOP) station on the rig floor would not operate nor function the bottom pipe ram and the hydraulic (HCR) choke valve. An accumulation of hydraulic oil on derrick	\$10,000 7/27/06	§250.107.
Apache Corporation Apache failed to comply with the safe and workmanlike manner and well control requirements addressed in the regulations. A remote blowout preventer (BOP) station on the rig floor would not operate nor function the bottom pipe ram and the hydraulic (HCR) choke valve. An accumulation of hydraulic oil on derrick	\$8,000 3/24/06	§250.803(c).
beams and board rack, oily and slippery hand rail, and no grat- ing over mud pits demonstrated Apache's failure to maintain all equipment in a safe condition.	\$28,000 5/11/06	§250.107, §250.615(c).
G=2005-026       7/25/05-7/25/05         Pioneer Natural Resources USA, Inc.       7/25/05-7/25/05         Operations were not performed in a safe manner as Personnel attempted to replace a 2" ball valve on the water dump bypass line on the Chem-Electric Treater without draining the vessel. This created an uncontrolled oil release from the vessel over the structure's open grating, and into the containment skid which was damaged and unable to contain the oil. As a result, approximately 1 barrel of oil polluted the Gulf.	\$45,000 5/10/06	§ 250.300(b), § 250.300(a), § 250.107(a).
G-2005-027       6/10/05-6/10/05         SPN Resources, LLC       The sump system could not automatically maintain the oil at a level sufficient to prevent discharge of oil into offshore waters.	\$10,000 6/13/06	§250.300(b).
G-2005-028       5/6/05-5/6/05         ATP Oil & Gas Corporation       The Level Safety Low (LSL) on the water section of the Heater Treater was bypassed and blocked out of service. Startup, maintenance, or testing procedures were not being performed; personnel were not monitoring the bypassed and blocked out functions; and the LSL was not flagged.         G-2006-001       10/31/05-10/31/05	\$5,000 6/27/06	§250.803(c).
G-2006-001	\$20,000 6/8/06	§250.803(c).

# 2006 CIVIL/CRIMINAL PENALTIES SUMMARY; ALL PENALTIES PAID IN CALENDAR 2006—Continued [01/01/2006–12/31/2006]

Operator name (contractor) and case No.	Violation and date(s)	Penalty paid and date paid	Regulation(s) violated (30 CFR)
Apache Corporation	An employee was injured since work had been performed in an unsafe and un-workmanlike manner. On 10–3–05, in order to access a well slot, 33" openings were cut in the grating on the well deck and on the lower production deck. The two holes cut in the decking were never barricaded, covered, guarded, or made inaccessible until 10–5–05, after the employee fell 8' through the unguarded hole cut in the well deck and into the opening cut on the lower production deck. He was able to catch himself before falling completely through the second opening into the cross members and well slot guide 40' below 10/3/05–10/5/05	\$70,000 5/16/06	§250.107.
G-2006-003	While enroute to another destination, the Minerals Management Service (MMS) Inspectors noticed a multi-colored sheen on the water coming from the ST 196 Platform B. They landed on the platform and found oil flowing out of the vent hatch on the Sump Tank ABH–4760. The MMS Inspectors also found the Sump System did not automatically maintain the oil level sufficiently enough to prevent discharge of oil into offshore waters. 10/18/05–10/18/05	\$50,000 7/13/06	§ 250.300(a), § 250.300(b).
Kerr-McGee Oil & Gas Corpora- tion.	Three safety devices were found bypassed at the panel—the level safety low for the wet/dry oil tank, the shut down valve for the dry oil pump, and the shut down valve for the incoming pipeline. Proposed amount mitigated from information supplied in letter. 11/12/04–11/12/04	\$15,000 7/19/06	§250.1004, §250.803.
ATP Oil & Gas Corporation	An injury occurred as a result of unsafe and un-workmanlike oper- ations. A contract worker fell 30' through an unsecured access hatch. Additionally, large openings in the deck were found and sections of heliport skirting were missing.	\$110,000 12/29/06	§250.107.
G-2006-006 Union Oil Company of California	<ul> <li>10/29/04–11/6/04</li> <li>A pollution incident occurred as a result of improperly isolating the turbine compressor from the production train.</li> <li>9/10/04–9/10/04</li> </ul>	\$25,000 7/25/06	§250.300(a).
G–2006–007 Tana Exploration Company, LLC	The primary and secondary surface safety valves (SSV), in addi- tion to the fuel gas were bypassed on Caisson Well No. 28. The relays were placed in bypass by BP Exploration and Production employees (acting as contractors for Tana) on February 14, 2005. When an upset occurred on February 19, 2005, on the upstream processing platform, the Well No. 28 did not shut in due to these safety devices being bypassed. The pipeline expe- rienced overpressure and the flange gasket ruptured allowing gas/condensate to escape. The Well was shut in using the boat landing emergency shut down pull loop.	\$165,000 8/31/06	§250.803(c), §250.803(c).
G-2006-008 Energy Partners, Ltd G-2006-009	2/14/05–2/19/05 The pressure safety low (PSL) on the departing high-pressure transfer gas pipeline (KAH–103) was by-passed at the master panel, leaving the pipeline unprotected from a leak or rupture. The relay was not flagged and conditions were not being mon- itored. 7/6/05–7/7/05	\$10,000 6/22/06	§250.1004.
Arena Offshore, LLC (Island Operators Co., Inc.)	Pollution occurred in offshore waters from overflow of vessel to deck caused from a pipeline being tested which was using FSVs instead of block valves. This overflow went to the deck contain- ment system and the deck drain sump system tank was inoper- able. 8/26/05–8/26/05	\$27,000 8/25/06	§ 250.300(b), § 250.300(a).
Callon Petroleum Operating Com- pany.	The fuel gas supply for the sump pump was manually closed, placing the sump pump in an out of service mode. Neither the sump pump nor the sump tank where being monitored by plat- form personnel.	\$5,000 5/11/06	§250.300(b).
G-2006-011 Forest Oil Corporation (Production Management Indus- tries, LLC). G-2006-012	12/12/05–12/12/05 Operations were not performed in a safe and workmanlike man- ner, and equipment had not been maintained in a safe condition. Pollution occurred since a fuel tank was filled beyond capacity and the sump system had not been properly maintained. 6/17/05–6/17/05	\$45,000 9/6/06	§ 250.107, § 250.107, § 250.300(a).

# 2006 CIVIL/CRIMINAL PENALTIES SUMMARY; ALL PENALTIES PAID IN CALENDAR 2006—Continued [01/01/2006–12/31/2006]

Operator name (contractor) and case No.	Violation and date(s)	Penalty paid and date paid	Regulation(s) violated (30 CFR)
Palace Operating Company Island Operators Co.)	During an annual inspection, the MMS inspector detected that the Surface Safety Valve (SSV) on well #2 was locked open using a fusible SSV stem cap rendering the valve inoperable or by- passed. This valve would not close had an undesirable event occurred (under pressure or overpressure of the flowline).	\$5,000 10/27/06	§250.803(c).
G–2006–013 Fotal E&P USA, Inc	11/28/05–11/28/05 The Emergency Shut Down Valves were bypassed on both boat landings. The two PSVs on the Intermediate Production Sepa- rator were found closed thus taking them out of service (by- passed).	\$130,000 6/16/06	§ 250.803, § 250.803.
A-2006-014 Iorthstar Gulfsands, LLC Offshore Contract Services LLC) A-2006-015	8/15/05–8/21/05 The level safety low (LSL) on the atmospheric bad oil tank was manually closed placing it in bypass. 1/4/06–1/5/06	\$15,000 9/6/06	§250.803.
lippon Oil Exploration U.S.A	The Platform's two primary means of escape had not been ade- quately maintained. Personnel on the platform had no safe means of egress due to missing grating and handrails.	\$30,000 9/28/06	§250.107.
3-2006-017	1/3/06–1/3/06 Platform's emergency equipment had not been adequately main- tained. The winch and lower flange kit on the south capsule was severely corroded and unsafe for use.	\$30,000 10/30/06	§250.107(a)(2).
G-2006-018	8/9/05–8/9/05 The level controller which starts the sump pump was improperly set, therefore rendering the sump pump incapable of maintaining the oil in the sump tank at a safe level to prevent discharge into the gulf waters.	\$12,000 9/22/06	§250.300(b).
i-2006-019 TP Oil & Gas Corporation Nood Group Production Serv- ices).	9/19/04–9/19/04 The Emergency Shut Down (ESD) Stations on the condensate ac- cumulator deck, sump deck, well bay area, and boat landing were all rendered out of service since the ESD supply line was disconnected.	\$20,000 9/22/06	§250.803(c).
à–2006–020 Iarathon Oil Company à–2006–022	11/9/04–11/9/04 The Temperature Sensing Element for the +10 deck drain Sump Pump was bypassed. 9/23/04–9/30/04	\$40,000 11/9/06	§250.803.
P America Production Company	Operations were not performed in a safe and workmanlike man- ner. While making an assessment of the unsafe conditions on the platform that needed repairing, the construction crew did not barricade a 3'4" x 3'4" opening in the stairway landing. Later, one of the crew members was injured when he fell through the open hole, approximately 20' and into the Gulf of Mexico.	\$25,000 10/25/06	§250.107(a)(1).
OM Shelf LLC Crown Oilfield Services, Inc.)	While attempting to secure and barricade hurricane related dam- ages on the sub-cellar deck, a contract employee was seriously injured since the work was not performed in a safe and workmanlike manner. He was not wearing fall protection while he was in the direct vicinity of open holes in the deck grating, and he fell approximately 25–30 feet through a 3' x 3' opening onto the +10 deck.	\$30,000 10/6/06	§250.107(a).
a-2006-026 Vioneer Natural Resources USA, Inc.	2/10/06–2/10/06 The main safety panel was bypassed during testing. In order to test any safety device on this panel, they all had to be placed in bypass. When the panel was in total bypass, the supply to the indicators was removed not allowing them to trip when an ab- normal condition became present, thus there was no way for personnel to monitor the bypassed devices.	\$20,000 12/13/06	§250.803(c).
3-2006-034 /enoco, Inc	7/17/06–7/17/06 During well recompletion operations, an accident occurred, which resulted in a loss of well control (blowout), and a 3 gallon oil spill. An investigation revealed removal of a lockdown pin from the well head during the alignment of the split tube hanger had discussed the blower provestor events.	\$30,000 4/27/06	§250.300(a), §250.107(a).
P–2005–001	circumvented the blowout preventer system. 11/19/04–11/19/04		

### 12827

## 2006 CIVIL/CRIMINAL PENALTIES SUMMARY; ALL PENALTIES PAID IN CALENDAR 2006—Continued [01/01/2006–12/31/2006]

Operator name (contractor) and case No.	Violation and date(s)	Penalty paid and date paid	Regulation(s) violated (30 CFR)
Nuevo Energy Company P-2004-002	On February 16, 2004, a transformer on a variable speed drive (VSD) unit over-heated and caught fire. A Minerals Management Service (MMS) investigation of the incident determined the fire, which was confined to the motor control center room, was due to the following causes: The electrical overload protection on the VSD had been placed in a non-functional mode. High amperage from a downhole electric submersible pump caused transformer to overload on the VSD, which subsequently overheated. Melting metal from the transformer dripped into a pan of threading oil below the transformer. A cotton glove that was laying in the pan of threading oil ignited. The resultant fire was extinguished by platform personnel investigating the source of smoke from the motor control center. 2/16/04–2/16/04 3/31/04–3/31/04	\$8,000 2/8/06	<b>U</b> /
Total Penalties Paid: 1/1/2006–12/31/2006, 41 Cases: (\$1,480,000)			

The purpose of publishing the penalties summary is to provide information to the public on violations of special concern in OCS operations and to provide an additional incentive for safe and environmentally sound operations.

Authority: 43 U.S.C. 1331 *et seq.*, 31 U.S.C. 9701.

Dated: January 30, 2007.

### Gregory J. Gould,

Acting Associate Director for Offshore Minerals Management. [FR Doc. E7–4876 Filed 3–16–07; 8:45 am] BILLING CODE 4310–MR–P

### DEPARTMENT OF THE INTERIOR

### National Park Service

### General Management Plan/Draft Environmental Impact Statement, Valley Forge National Historical Park, Pennsylvania

**AGENCY:** National Park Service, Department of the Interior. **ACTION:** Notice of Availability of the Draft Environmental Impact Statement for the General Management Plan, Valley Forge National Historical Park.

**SUMMARY:** Pursuant to the National Environmental Policy Act of 1969, 42 U.S.C. 4332(2)(C), the National Park Service announces the availability of the Draft General Management Plan and Environmental Impact Statement for Valley Forge National Historical Park, Pennsylvania. An electronic version of the document is currently available for public review on the National Park Service Planning, Environment and Public Comment Web site at *http:// parkplanning.nps.gov*. However, printed copies of the document will not be available until on or about February, 2007.

**DATES:** The National Park Service will accept comments on the Draft General Management Plan and Environmental Impact Statement from the public for a period of 60 days following publication of the Environmental Protection Agency's Notice of Availability in the **Federal Register**. Public meetings will be scheduled during the comment period. Interested persons may check the park Web site at *http://www.nps.gov/vafo* for date, time, and place.

ADDRESSES: Information will be available for public review and comment online at *http:// parkplanning.nps.gov,* at the Valley Forge NHP Welcome Center, 1400 North Outer Line Drive, King of Prussia, Pennsylvania, 610–783–1099 and at the following locations:

- Lower Providence Community Library, 50 Parklane Drive, Eagleville, PA 19403–1171.
- Tredyffrin Public Library, 582 Upper Gulph Rd., Strafford-Wayne, PA 19087–2052.
- Phoenixville Public Library, 183 Second Avenue, Phoenixville, PA 19460.
- Montgomery County-Norristown Public Library, 1001 Powell Street, Norristown, PA 19401.
- Upper Merion Township Library, 175 West Valley Forge Road, King of Prussia, PA 19406.

### FOR FURTHER INFORMATION CONTACT:

Deirdre Gibson, Valley Forge NHP, 1400

North Outer Line Drive, King of Prussia, Pennsylvania 19406, Deirdre gibson@nps.gov.

SUPPLEMENTARY INFORMATION: If you wish to comment, you may submit your comments by any one of several methods. You may mail comments to Superintendent Mike Caldwell, Valley Forge NHP, 1400 North Outer Line Drive, King of Prussia, PA 19406. You may also comment via the Internet at http://parkplanning.nps.gov. If you do not receive a confirmation from the system that we have received your Internet message, contact us directly (Deirdre Gibson, 610-783-1047). Finally, you may hand-deliver comments to Valley Forge NHP, 1400 North Outer Line Drive, King of Prussia, PA 19406. Before including your address, phone number, e-mail address, or other personal identifying information in your comment, you should be aware that your entire comment-including your personal identifying information-may be made publicly available at any time. While you can ask us in your comment to withhold your personal identifying information from public review, we cannot guarantee that we will be able to do so.

Dated: January 22, 2007.

### Michael A. Caldwell,

Acting Regional Director, Northeast Region, National Park Service.

[FR Doc. E7-4907 Filed 3-16-07; 8:45 am] BILLING CODE 4310-DJ-P