

Issued in Renton, Washington, on July 25, 2007.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-14867 Filed 7-31-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28645; Directorate Identifier 2007-CE-059-AD]

RIN 2120-AA64

Airworthiness Directives; EADS SOCATA Model TBM 700 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

This Airworthiness Directive (AD) results from one report about imperfect locking on ground of the upper access door opening interior handle which has enabled its opening without actuating unlocking knob.

If not corrected an inadvertent action on the handle without actuating the unlocking knob could lead to a door opening.

Investigations identified the unsafe condition resulting from interference between the window trim panel and the handle locking mechanism.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by August 31, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room

W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-28645; Directorate Identifier 2007-CE-059-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Emergency Airworthiness (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

This Airworthiness Directive (AD) results from one report about imperfect locking on ground of the upper access door opening interior handle which has enabled its opening without actuating unlocking knob.

If not corrected an inadvertent action on the handle without actuating the unlocking knob could lead to a door opening.

Investigations identified the unsafe condition resulting from interference between the window trim panel and the handle locking mechanism.

Requirements of this AD are first, check for proper operation the locking handle and secondly modification of the window trim panel.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

EADS SOCATA has issued Mandatory Service Bulletin TBM Aircraft SB 70-150, dated May 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 23 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$5 per product. Where the service information lists

required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$3,795, or \$165 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

EADS SOCATA: Docket No. FAA-2007-28645; Directorate Identifier 2007-CE-059-AD.

Comments Due Date

(a) We must receive comments by August 31, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to TBM 700 airplanes, serial numbers 1 through 9, 11 through 17, 19 through 22, 25 through 27, 29 through 31, 33 and 34, 38, 46, and 49, that are:

- (1) Certificated in any category;
- (2) Not equipped with modification No. MOD70-019-25; and
- (3) Equipped with an interior handle unlocking device through push-button.

Subject

(d) Air Transport Association of America (ATA) Code 52: Doors.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: This Airworthiness Directive (AD) results from one report about imperfect locking on ground of the upper access door opening interior handle which has enabled its opening without actuating unlocking knob. If not corrected an inadvertent action on the handle without actuating the unlocking knob could lead to a door opening.

Investigations identified the unsafe condition resulting from interference between the window trim panel and the handle locking mechanism.

Requirements of this AD are first, check for proper operation the locking handle and secondly modification of the window trim panel.

Actions and Compliance

(f) Unless already done, do the following actions:

- (1) Before each flight after the effective date of this AD until the actions of paragraph (f)(2) of this AD have been done, check the handle locking using paragraph A of the accomplishment instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-150, dated May 2007. If any discrepancy is found, do the following before further flight until the modification in paragraph (f)(2) of this AD is done:

(i) Fabricate a placard using letter at least 1/8 inches in height with the words "FLIGHT ALLOWED WITH ONLY THE FLIGHT DECK SEATS OCCUPIED."

(ii) Install this placard on the instrument panel within clear view of the pilot.

(iii) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do both the pre-flight checks and the placard requirements of this AD. Make an entry in the aircraft records showing compliance with this portion of the AD following section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(2) Within the next 12 months after the effective date of this AD modify the window trim panel using paragraph B of the accomplishment instructions in EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-150, dated May 2007. This modification terminates the requirements of paragraph (f)(1) of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Emergency AD No: 2007-0172-E, dated June 15, 2007; and EADS SOCATA Mandatory TBM Aircraft Service Bulletin SB 70-150, dated May 2007, for related information.

Issued in Kansas City, Missouri, on July 26, 2007.

James E. Jackson,

*Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E7-14857 Filed 7-31-07; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R01-OAR-2007-0401; FRL-8448-3]

Approval and Promulgation of Air Quality Implementation Plans; Massachusetts; State Implementation Plan Revision To Implement the Clean Air Interstate Rule

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve a revision to the Massachusetts State Implementation Plan (SIP) submitted on March 30, 2007. This revision addresses the requirements of EPA's Clean Air Interstate Rule (CAIR), promulgated on May 12, 2005 and subsequently revised on April 28, 2006 and December 13, 2006. EPA is proposing to determine that the SIP revision fully implements the CAIR requirements for Massachusetts. Therefore, as a consequence of the SIP approval, EPA will also withdraw the CAIR Federal Implementation Plan (CAIR FIP) concerning NO_x ozone-season emissions for Massachusetts. The CAIR FIPs for all States in the CAIR region were promulgated on April 28, 2006 and subsequently revised on December 13, 2006.

In the SIP revision that EPA is proposing to approve, Massachusetts would meet CAIR requirements by participating in the EPA-administered cap-and-trade program addressing NO_x ozone-season emissions. Massachusetts's SIP revision is based on EPA's model CAIR NO_x ozone season rule and is in most respects substantively identical to that model rule. The Massachusetts CAIR program has two major substantive differences from that model rule (expanded applicability, and a different methodology for allocating NO_x allowances), both of which are consistent with the flexibility allowed under CAIR for state participation in the EPA-administered cap-and-trade program. The SIP revision complies with the statutory and regulatory requirements for approval of a CAIR NO_x ozone-season program.

DATES: Comments must be received on or before August 31, 2007.

ADDRESSES: Submit your comments, identified by FDMS Docket ID No. EPA-R01-OAR-2007-0401, by one of the following methods:

1. *www.regulations.gov*: Follow the on-line instructions for submitting comments.

2. *E-mail*: arnold.anne@epa.gov.

3. *Fax*: (617) 918-0047.

4. *Mail*: "FDMS Docket ID No. EPA-R01-OAR-2007-0401", Anne Arnold, U.S. Environmental Protection Agency, EPA New England Regional Office, One Congress Street, Suite 1100 (mail code CAQ), Boston, MA 02114-2023.

5. *Hand Delivery or Courier*: Deliver your comments to: Anne Arnold, Manager, Air Quality Planning Unit, Office of Ecosystem Protection, U.S. Environmental Protection Agency, EPA New England Regional Office, One Congress Street, 11th floor, (CAQ), Boston, MA 02114-2023. Such deliveries are only accepted during the Regional Office's normal hours of operation. The Regional Office's official hours of business are Monday through Friday, 8:30 to 4:30, excluding federal holidays.

Instructions: Direct your comments to Docket ID No. "FDMS Docket ID No. EPA-R01-OAR-2007-0401". EPA's policy is that all comments received will be included in the public docket without change and may be made available online at <http://www.regulations.gov>, including any personal information provided, unless the comment includes information claimed to be Confidential Business Information (CBI) or other information whose disclosure is restricted by statute. Do not submit through www.regulations.gov or e-mail, information that you consider to be CBI or otherwise protected. The www.regulations.gov Web site is an "anonymous access" system, which means EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send an e-mail comment directly to EPA without going through www.regulations.gov, your e-mail address will be automatically captured and included as part of the comment that is placed in the public docket and made available on the Internet. If you submit an electronic comment, EPA recommends that you include your name and other contact information in the body of your comment and with any disk or CD-ROM you submit. If EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, EPA may not be

able to consider your comment. Electronic files should avoid the use of special characters and any form of encryption and should be free of any defects or viruses. For additional information about EPA's public docket visit the EPA Docket Center homepage at <http://www.epa.gov/epahome/dockets.htm>.

Docket: All documents in the electronic docket are listed in the www.regulations.gov index. Although listed in the index, some information is not publicly available, i.e., CBI or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, is not placed on the Internet and will be publicly available only in hard copy form. In addition to publicly available docket materials available electronically in www.regulations.gov, the hard copy of these materials, including the state submittal and EPA's technical support document, is available at the Office of Ecosystem Protection, U.S. Environmental Protection Agency, EPA New England Regional Office, One Congress Street, Suite 1100, Boston, MA. EPA requests that if at all possible, you contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section to schedule your inspection. The Regional Office's official hours of business are Monday through Friday, 8:30 to 4:30, excluding federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions concerning today's proposal, please contact Alison C. Simcox, Air Quality Planning Unit, U.S. Environmental Protection Agency, EPA New England Regional Office, One Congress Street, Suite 1100 (CAQ), Boston, MA 02114-2023, telephone number (617) 918-1684, fax number (617) 918-0684, e-mail simcox.alison@epa.gov.

SUPPLEMENTARY INFORMATION:

Table of Contents

- I. What Action Is EPA Proposing to Take?
- II. What Is the Regulatory History of CAIR and the CAIR FIPs?
- III. What are the General Requirements of CAIR and the CAIR FIPs?
- IV. What are the Types of CAIR SIP Submittals?
- V. Analysis of Massachusetts's CAIR SIP Submittal
 - A. State Budgets for Allowance Allocations
 - B. CAIR Cap-and-Trade Programs
 - C. Applicability Provisions for non-EGU NO_x SIP Call Sources
 - D. NO_x Allowance Allocations
 - E. Individual Opt-in Units
- VI. Proposed Action
- VII. Statutory and Executive Order Reviews