DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[U.S. DOT Docket Number NHTSA-2007-28104]

Reports, Forms, and Recordkeeping Requirements

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation.

ACTION: Correction Notice.

SUMMARY: This document corrects the mailing addresses and the completeness of the notice published on June 21, 2007 (72 FR 34348) for the Paperwork Reduction Action of 1995 (44 U.S.C. 3501 *et seq.*, OMB Control Number 2127–0573).

DATES: Comments must be received on or before August 20, 2007.

FOR FURTHER INFORMATION CONTACT: Ms. Deborah Mazyck at the National Highway Traffic Safety Administration, Office of International Vehicle, Fuel Economy and Consumer Standards, 1200 New Jersey Avenue, SE., West Building, Room W43–443, Washington, DC 20590. Ms. Mazyck's telephone number is (202–366–4139). Please identify the relevant collection of information by referring to its OMB Control Number.

SUPPLEMENTARY INFORMATION: The National Highway Traffic Safety Administration is correcting the mailing addresses in the June 21, 2007 notice. The U.S. Department of Transportation's Docket Management Facility has moved to a new location. You may mail comments identified by DOT Docket No. NHTSA-2007-28104 to Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building, Ground Floor, Room W12-140, Washington, DC 20590.

You may hand deliver comments or obtain access to the docket to read background documents or comments received on this collection by going to 1200 New Jersey Avenue, SE., West Building, Ground Floor, Room W12–140, Washington, DC between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

Additionally, NHTSA is correcting the omission of information from the June 21, 2007, notice. Specifically, comments are invited on: Whether the proposed collection of information is necessary for the proper performance of the functions of the Department, including whether the information will have practical utility; the accuracy of

the Department's estimate of the burden of the proposed information collection; ways to enhance the quality, utility and clarity of the information to be collected; and ways to minimize the burden of the collection of information on respondents, including the use of automated collection techniques or other forms of information technology.

Issued on: August 10, 2007.

Stephen R. Kratzke,

Associate Administrator for Rulemaking. [FR Doc. E7–16108 Filed 8–15–07; 8:45 am]

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2007-28733; Notice 1]

Bentley Motors, Inc., Receipt of Petition for Decision of Inconsequential Noncompliance

Bentley Motors, Inc. (Bentley) has determined that certain motor vehicles that it produced between July 2006 and March 2, 2007 do not comply with paragraphs S4.5.1(b)(3) and S4.5.1(e)(3) of 49 CFR 571.208, Federal Motor Vehicle Safety Standard (FMVSS) No. 208, Occupant Crash Protection.

Bentley has filed an appropriate report pursuant to 49 CFR Part 573, Defect and Noncompliance Responsibility and Reports.

Pursuant to 49 U.S.C. 30118(d) and 30120(h), Bentley has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of Bentley's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

Affected are a total of approximately 244 model year 2007 Bentley Arnage and Azure model passenger cars produced between July 2006 and March 2, 2007. Paragraph S4.5.1(b)(3)of FMVSS No. 208 requires:

(3) Vehicles certified to meet the requirements specified in S19, S21, or S23 on or after September 1, 2003 shall have a label permanently affixed to either side of the sun visor, at the manufacturer's option, at each front outboard seating position that is equipped with an inflatable restraint. The label shall conform in content to the label shown in Figure 11 of this standard and shall comply with the requirements of S4.5.1(b)(3)(i) through S4.5.1(b)(3)(iv).

- (i) The heading area shall be yellow with the word "WARNING" and the alert symbol in black.
- (ii) The message area shall be white with black text. The message area shall be no less than $30 \text{ cm} 2 (4.7 \text{ in}^2)$.
- (iii) The pictogram shall be black on a white background. The pictogram shall be no less than 30 mm (1.2 in) in length.
- (iv) If the vehicle does not have a back seat, the label shown in the figure may be modified by omitting the statement: "The BACK SEAT is the SAFEST place for CHILDREN."
- (v) If the vehicle does not have a back seat or the back seat is too small to accommodate a rear-facing child restraint consistent with S4.5.4.1, the label shown in the figure may be modified by omitting the statement: "Never put a rear-facing child seat in the front."

Paragraph S4.5.1(e)(3) of FMVSS No. 208 requires:

- (3) Vehicles certified to meet the requirements specified in S19, S21, and S23 on or after December 1, 2003, that are equipped with an inflatable restraint for the passenger position shall have a label attached to a location on the dashboard or the steering wheel hub that is clearly visible from all front seating positions. The label need not be permanently affixed to the vehicle. This label shall conform in content to the label shown in Figure 12 of this standard and shall comply with the requirements of S4.5.1(e)(3)(i) through S4.5.1(e)(3)(iv).
- (i) The heading area shall be yellow with black text.
- (ii) The message area shall be white with black text. The message area shall be no less than 30 cm^2 (4.7 in 2).
- (iii) If the vehicle does not have a back seat, the label shown in Figure 12 may be modified by omitting the statement: "The back seat is the safest place for children."
- (iv) If the vehicle does not have a back seat or the back seat is too small to accommodate a rear-facing child restraint consistent with S4.5.4.1, the label shown in Figure 12 may be modified by omitting the statement: "Never put a rear-facing child seat in the front."

Bentley states that it has corrected the problem that caused these errors so that they will not be repeated in future production. Bentley also states that it believes the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted

Bentley explains that instead of the "advanced air bag" warning labels required pursuant to the paragraphs S4.5.1(b)(3) and S4.5.1(e)(3) of FMVSS No. 208 the affected vehicles were equipped with the "pre-advanced" air bag warning labels conforming to paragraph S4.5.1(b)(1) and S4.5.1(e)(1).

Bentley argues that because the "preadvanced" sun visor labels used on the vehicles carry essentially the equivalent or even more emphatic warnings to