

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Ann Johnson, Aerospace Engineer, FAA, Wichita ACO, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: 316-946-4105; fax: 316-946-4107; e-mail address: ann.johnson@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(h) AMOCs approved for AD 2008-10-02 are approved for this AD.

Material Incorporated by Reference

(i) You must use Cessna Single Engine Service Bulletin, SB08-34-02, Revision 1, dated October 6, 2008; Cessna Caravan Service Bulletin CAB08-4, Revision 1, dated October 6, 2008; Cessna Single Engine Service Bulletin SEB08-5, dated October 13, 2008; and Cessna Multi-engine Service Bulletin MEB08-6, dated October 13, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Cessna Aircraft Company, P.O. Box 7704, Wichita, Kansas 67277; telephone: (800) 423-7762 or (316) 517-6056; Internet: <http://www.cessna.com>.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on December 15, 2008.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-30465 Filed 12-23-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-1120; Directorate Identifier 2008-CE-064-AD; Amendment 39-15767; AD 2008-26-01]

RIN 2120-AA64

Airworthiness Directives; Air Tractor, Inc. Models AT-200, AT-300, AT-400, AT-500, AT-600, and AT-800 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) to supersede AD 2008-11-17, which applies to certain Air Tractor, Inc. Models AT-200, AT-300, AT-400, AT-500, AT-600, and AT-800 series airplanes. AD 2008-11-17 currently requires you to install an overturn skid plate kit or a modification to the overturn skid plate already installed. Since we issued AD 2008-11-17, the manufacturer has notified us that Model AT-401B airplanes also need a modification to the overturn skid plate. Consequently, this AD would retain the actions of AD 2008-11-17 and add the requirement to modify the overturn skid plate installed on Model AT-401B airplanes. We are issuing this AD to prevent the front and rear connections of the overturn skid plate to the airplane from breaking, which could allow foreign debris to enter the cockpit during an airplane overturn. This condition, if not corrected, could lead to pilot injury.

DATES: This AD becomes effective on January 28, 2009.

On January 28, 2009, the Director of the **Federal Register** approved the incorporation by reference of Snow Engineering Co. Service Letter #97, revised September 19, 2008, listed in this AD.

As of July 7, 2008 (73 FR 31351, June 2, 2008), the Director of the **Federal Register** approved the incorporation by reference of Snow Engineering Co. Service Letter #97, revised November 7, 2007, listed in this AD.

ADDRESSES: For service information identified in this AD, contact Air Tractor Inc., P.O. Box 485, Olney, Texas 76374; telephone: (940) 564-5616; fax: (940) 564-5612; e-mail: airmail@airtractor.com; Internet: <http://www.airtractor.com>.

To view the AD docket, go to U.S. Department of Transportation, Docket

Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, or on the Internet at <http://www.regulations.gov>. The docket number is FAA-2008-1120; Directorate Identifier 2008-CE-064-AD.

FOR FURTHER INFORMATION CONTACT:

Andy McAnaul, Aerospace Engineer, ASW-150, FAA San Antonio MIDO-43, 10100 Reunion Pl., Ste. 650, San Antonio, Texas 78216; telephone: (210) 308-3365; fax: (210) 308-3370.

SUPPLEMENTARY INFORMATION:**Discussion**

On October 14, 2008, we issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Air Tractor, Inc. Models AT-200, AT-300, AT-400, AT-500, AT-600, and AT-800 series airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on October 23, 2008 (73 FR 63096). The NPRM proposed to supersede AD 2008-11-17 with a new AD that would retain the actions of AD 2008-11-17 and add the requirement to modify the overturn skid plate installed on Model AT-401B airplanes.

Comments

We provided the public the opportunity to participate in developing this AD. We received no comments on the proposal or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Costs of Compliance

We estimate that this AD affects 1,309 airplanes in the U.S. registry.

In determining the total cost on U.S. operators, we presume all airplanes in the U.S. fleet have an overturn skid plate installed (as required by AD 2002-25-09) and the only cost is to incorporate the modification kit P/N 11411-1-501. We estimate the following costs to do the modification of installing the overturn skid plate modification kit P/N 11411-1-501 to those planes that

currently have the overturn skid plate installed:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
2 work-hours × \$80 per hour = \$160	\$42	\$202	\$264,418

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- 1. Is not a “significant regulatory action” under Executive Order 12866;
- 2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD (and other information as included in the Regulatory Evaluation) and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include “Docket No. FAA–2008–1120; Directorate Identifier 2008–CE–064–AD” in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator,

the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2008–11–17, Amendment 39–15540 (73 FR 31351, June 2, 2008), and adding the following new AD:

2008–26–01 Air Tractor, Inc.: Amendment 39–15767; Docket No. FAA–2008–1120; Directorate Identifier 2008–CE–064–AD.

Effective Date

- (a) This AD becomes effective on January 28, 2009.

Affected ADs

- (b) This AD supersedes AD 2008–11–17, Amendment 39–15540.

Applicability

- (c) This AD applies to the following airplane models and serial numbers that are certificated in any category:

Group 1 models	Serial Nos.
AT–250, AT–300, AT–301, AT–302, AT–400, AT–400A, AT–401, AT–401A, AT–402, AT–402A, and AT–402B.	–0001 through –1196.
AT–501, AT–502, AT–502A, and AT–502B	–0001 through –2620.
AT–602	–0337 through –1153.
AT–802A	–0003 through –0282.
Group 2 models	Serial Nos.
AT–401B	–0952 through –1196.

Unsafe Condition

(d) Since we issued AD 2008–11–17, the manufacturer has notified us that Model AT–401B airplanes also need a modification to the overturn skid plane. Consequently, this AD retains the actions of AD 2008–11–17 and

adds the requirement to modify the overturn skid plate installed on Model AT–401B airplanes. We are issuing this AD to prevent the front and rear connections of the overturn skid plate to the airplane from breaking, which could allow foreign debris to enter the cockpit during an airplane overturn. This

condition, if not corrected, could lead to pilot injury.

Compliance

- (e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
(1) <i>For Group 1 airplanes:</i> If overturn skid plate part number (P/N) 11411–1–500 or an FAA-approved equivalent P/N is already installed then install P/N 11411–1–501 modification kit.	Within the next 180 days after July 7, 2008 (the effective date of AD 2008–11–17).	Follow Snow Engineering Co. Service Letter #97, revised November 7, 2007; or Snow Engineering Co. Service Letter #97, revised September 19, 2008.

Actions	Compliance	Procedures
(2) <i>For Group 1 airplanes:</i> If there is no overturn skid plate installed, then install overturn skid plate kit P/N 11411-1-502 or an FAA-approved equivalent part number.	Within the next 180 days after July 7, 2008 (the effective date of AD 2008-11-17).	Follow Snow Engineering Co. Service Letter #97, revised November 7, 2007; or Snow Engineering Co. Service Letter #97, revised September 19, 2008.
(3) <i>For Group 2 airplanes:</i> Install P/N 11411-1-501 modification kit.	Within the next 180 days after January 28, 2009 (the effective date of this AD).	Follow Snow Engineering Co. Service Letter #97, revised September 19, 2008.

Alternative Methods of Compliance (AMOCs)

(f) The Manager, Fort Worth Airplane Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Andy McAnaul, Aerospace Engineer, ASW-150, FAA San Antonio MIDO-43, 10100 Reunion Pl., Ste. 650, San Antonio, Texas 78216; telephone: (210) 308-3365; fax: (210) 308-3370. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Snow Engineering Co. Service Letter #97, revised November 7, 2007; or Snow Engineering Co. Service Letter #97, revised September 19, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Snow Engineering Co. Service Letter #97, revised September 19, 2008, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On July 7, 2008 (73 FR 31351, June 2, 2008), the Director of the Federal Register approved the incorporation by reference of Snow Engineering Co. Service Letter #97, revised November 7, 2007.

(3) For service information identified in this AD, contact Air Tractor Inc., P.O. Box 485, Olney, Texas 76374; telephone: (940) 564-5616; fax: (940) 564-5612; e-mail: airmail@airtractor.com; Internet: <http://www.airtractor.com>.

(4) You may review copies of the service information incorporated by reference for this AD at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the Central Region, call (816) 329-3768.

(5) You may also review copies of the service information incorporated by reference for this AD at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on December 9, 2008.

John Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-29568 Filed 12-23-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0858; Directorate Identifier 2008-NM-054-AD; Amendment 39-15773; AD 2008-26-07]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-8-11, DC-8-12, DC-8-21, DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, and DC-8-43 Airplanes; Model DC-8-50 Series Airplanes; Model DC-8F-54 and DC-8F-55 Airplanes; Model DC-8-60 Series Airplanes; Model DC-8-60F Series Airplanes; Model DC-8-70 Series Airplanes; and Model DC-8-70F Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all McDonnell Douglas airplanes identified above. This AD requires repetitive inspections of the lower skin and stringers at stations Xw=408 and Xw=-408, and corrective actions if necessary. This AD results from reports of cracks in the skins and stringers at the end fasteners common to the stringer end fittings at stations Xw=408 and Xw=-408 wing splice joints. We are issuing this AD to detect and correct fatigue cracking in the skins and stringers at the end fasteners common to the stringer end fittings at certain station and wing splice joints, which could result in wing structure that might not sustain limit load, and consequent loss of structural integrity of the wing.

DATES: This AD is effective January 28, 2009.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 28, 2009.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service

Management, Dept. C1-L5A (D800-0024); telephone 206-544-9990; fax 206-766-5682; e-mail DDCS@boeing.com; Internet <https://www.myboeingfleet.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dara Albouyeh, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5222; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to all McDonnell Douglas Model DC-8-11, DC-8-12, DC-8-21, DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, and DC-8-43 airplanes; Model DC-8-50 series airplanes; Model DC-8F-54 and DC-8F-55 airplanes; Model DC-8-60 series airplanes; Model DC-8-60F series airplanes; and Model DC-8-70 series airplanes. That NPRM was published in the **Federal Register** on August 12, 2008 (73 FR 46823). That NPRM proposed to require repetitive inspections of the lower skin and stringers at stations Xw=408 and Xw=-408, and corrective actions if necessary.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comment received from the commenters.