

Federal Register published on April 11, 2000 (65 FR 19477–78).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2012-27-01 Rolls-Royce Deutschland Ltd & Co KG (Formerly Rolls-Royce plc, Derby, England): Amendment 39-17313; Docket No. FAA-2012-1350; Directorate Identifier 2012-NE-40-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective January 25, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Rolls-Royce Deutschland Ltd & Co KG (RRD) Tay 620-15 turbofan engines, serial numbers 17085, 17088, 17166, 17072, 17073, 17078, and 17079.

(d) Reason

This AD was prompted by evidence of excessive leading edge erosion of the low-pressure compressor (LPC) fan blades on certain Tay 620-15 engines. We are issuing this AD to prevent failure of the LPC fan blade, which could result in uncontained engine failure and damage to the airplane.

(e) Actions and Compliance

Unless already done, do the following.

(1) Before the next flight after the effective date of the AD, inspect the leading edge of the LPC fan blades and determine if excessive erosion is evident. Guidance on conducting the inspection can be found in RRD Alert Non-Modification Service Bulletin (NMSB) TAY-72-A1777, dated October 26, 2012.

(2) If the measured blade chordal width is outside the requirements, before the next flight, replace the complete set of LPC fan blades with a set of LPC fan blades eligible for installation.

(3) Within 30 days after performing the inspection required by paragraph (e)(1) of this AD, provide, for all repaired blades, the actual chordal width measurement to RRD, Service Engineering.

(f) Paperwork Reduction Act Burden Statement

For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should

be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(h) Related Information

(1) For more information about this AD, contact Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7779; fax: 781-238-7199; email: frederick.zink@faa.gov.

(2) Refer to European Aviation Safety Agency Emergency AD 2012-0234, dated November 6, 2012, and RRD Alert NMSB TAY-72-A1777.

(3) For service information identified in this AD, contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, Dahlewitz, 15827 Blankenfelde-Mahlow, Germany; phone: 49 0 33-7086-1883; fax: 49 0 33-7086-3276. You may view this service information at FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(i) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on December 27, 2012.

Colleen M. D'Alessandro,

Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2013-00128 Filed 1-9-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0901; Directorate Identifier 2012-NE-19-AD; Amendment 39-17314; AD 2012-27-02]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Turbomeca S.A. Arriel 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S, and 1S1 turboshaft engines. This AD requires performing a high gas generator speed (NG) rating vibration check. This AD was prompted by several reports of uncommanded in-flight shutdown on

Arriel 1 engines. We are issuing this AD to prevent an uncommanded in-flight shutdown of the engine, which could result in an emergency landing.

DATES: This AD becomes effective February 14, 2013.

ADDRESSES: The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

FOR FURTHER INFORMATION CONTACT: Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; email: frederick.zink@faa.gov; phone: 781-238-7779; fax: 781-238-7199.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 13, 2012 (77 FR 56585). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Several cases of uncommanded in-flight shut-down (IFSD) have been reported on ARRIEL 1 engines. Results of subsequent investigations showed that some Gas Generator (GG) rear bearing failures have occurred following "Level 3" maintenance actions on the GG rotating assembly. Some of these maintenance actions may have created an unbalanced condition of the GG rotating assembly and, ultimately, failure of the GG rear bearing.

This condition, if not detected and corrected, could lead to an uncommanded engine in-flight shut down and may ultimately lead to an emergency landing.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (77 FR 56585, September 13, 2012).

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed (77 FR 56585, September 13, 2012).

Costs of Compliance

Based on the service information, we estimate that this AD affects about 1,445 engines installed on airplanes of U.S. registry. We also estimate that it will take about 1 hour per product to comply with this AD. The average labor rate is \$85 per hour. Based on these figures, we

estimate the cost of the AD on U.S. operators to be \$122,825.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (phone: (800) 647-5527) is provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2012-27-02 Turbomeca S.A.: Amendment 39-17314; Docket No. FAA-2012-0901; Directorate Identifier 2012-NE-19-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective February 14, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Turbomeca S.A. ARRIEL 1A1, 1A2, 1B, 1C, 1C1, 1C2, 1D, 1D1, 1E2, 1K1, 1S, and 1S1 turboshaft engines.

(d) Reason

This AD was prompted by several reports of uncommanded in-flight shutdown on Arriel 1 engines. We are issuing this AD to prevent an uncommanded in-flight shutdown of the engine, which could result in an emergency landing.

(e) Actions and Compliance

Unless already done, from the effective date of this AD, do the following. After any Level 3 maintenance action on the gas generator (GG) rotating assembly and before returning the engine to service, accomplish a high GG speed (NG) rating vibration check.

(f) Definition

Level 3 maintenance on the GG rotating assembly is when the Module 03 is removed from the helicopter for implementation of deep maintenance operation to be performed in accordance with the applicable maintenance instructions.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(h) Related Information

(1) For more information about this AD, contact Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803;

email: frederick.zink@faa.gov; phone: 781-238-7779; fax: 781-238-7199.

(2) Refer to Mandatory Continuing Airworthiness Information AD 2012-0117, dated July 3, 2012, for related information.

Issued in Burlington, Massachusetts, on December 31, 2012.

Kevin Dickert,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2013-00130 Filed 1-9-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2012-0750; Airspace Docket No. 11-AWP-4]

RIN 2120-AA66

Establishment of VOR Federal Airway V-629; Las Vegas, NV

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes VHF omnidirectional range (VOR) Federal airway V-629, near Las Vegas, NV, to supplement the existing routes structure for aircraft navigating in an area of marginal radar coverage. This action enhances the safety and efficiency of the National Airspace System.

DATES: Effective date 0901 UTC, March 7, 2013. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace Policy and ATC Procedures Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

History

On September 6, 2012, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to establish V-629 near Las Vegas, NV. (77 FR 54859). Interested parties were invited to participate in this rulemaking effort by submitting written comments on this proposal to the FAA. No comments were received.

The Rule

The FAA is amending Title 14, Code of Federal Regulations (14 CFR) part 71

by establishing VOR Federal airway V-629, near Las Vegas, NV, to supplement the existing route structure and provide positive course guidance for aircraft navigating in an area of marginal radar coverage.

VOR Federal airways are published in paragraph 6010(a) of FAA Order 7400.9W signed August 8, 2012 and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airway listed in this document will be published subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes a VOR Federal airway to enhance the safety and efficiency of the National Airspace System in the vicinity of Las Vegas, NV. Except for editorial changes, this rulemaking is the same as published in the NPRM.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, Environmental Impacts: Policies and Procedures, paragraph 311a. This airspace action is not expected to cause any potentially

significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p.389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the FAA Order 7400.9W, Airspace Designations and Reporting Points, signed August 8, 2012, and effective September 15, 2012, is amended as follows:

Paragraph 6010(a)—Domestic VOR Federal Airways.

* * * * *

V-629 [New]

From INT Goffs, CA, 033° and the Boulder City, NV, 182° radials to Boulder City.

Issued in Washington, DC, on December 12, 2012.

Gary A. Norek,

Manager, Airspace Policy and ATC Procedures Group.

[FR Doc. 2013-00289 Filed 1-8-13; 4:15 pm]

BILLING CODE 4910-13-P

FEDERAL TRADE COMMISSION

16 CFR Part 305

RIN 3084-AB15

Energy Labeling Rule

AGENCY: Federal Trade Commission (FTC or Commission).

ACTION: Final rule.

SUMMARY: As part of its ongoing regulatory review of the Appliance Labeling Rule ("Rule"), the Commission amends the Rule by streamlining data reporting requirements for manufacturers, clarifying testing requirements and enforcement provisions, improving online energy label disclosures, and making several minor technical changes and