

ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(l) Related Information

(1) For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6447; fax: 425-917-6590; email: wayne.lockett@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 767-53A0261, dated August 12, 2014.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 9, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-32596 Filed 12-30-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-1480; Directorate Identifier 2014-SW-071-AD; Amendment 39-18352; AD 2015-26-04]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters (Previously Eurocopter France)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding airworthiness directive (AD) 2002-13-11 for Eurocopter France (now Airbus Helicopters) Model EC120B helicopters. AD 2002-13-11 required installing front and side covers on the cabin floor to protect the yaw control at both the pilot and co-pilot stations. Since we issued AD 2002-13-11, we have determined that the required actions should apply only to the cabin's right-hand pilot station. This AD retains the requirements of AD 2002-13-11 but for only the pilot station. These actions are intended to prevent an object from sliding between the canopy and the cabin floor, loss of yaw control, and subsequent loss of helicopter control.

DATES: This AD is effective February 4, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 4, 2016.

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2015-1480 or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the Direction Generale de l'Aviation Civile (DGAC) AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Robert Grant, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email robert.grant@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to remove AD 2002-13-11, Amendment 39-12799 (67 FR 45295, July 9, 2002) and add a new AD. AD 2002-13-11 applied to Airbus Model EC120B helicopters, serial numbers 1001 through 1278, and required installing front and side covers to protect the yaw control at the pilot and co-pilot flight control stations. AD 2002-13-11 was prompted by AD No. 2001-386-007(A), dated September 5, 2001, issued by the DGAC, the airworthiness authority for France, to correct an unsafe condition for the Model EC120B helicopter. The DGAC advises of a yaw-control jamming caused by an object that slid between the canopy and the cabin floor.

After we issued AD 2002-13-11 (67 FR 45295, July 9, 2002), we determined that the front and side protections are required only at the pilot station. The NPRM published in the **Federal Register** on May 14, 2015 (80 FR 27605), and proposed to supersede AD 2002-13-11 to require installing the front and side covers only at the pilot station. It also reflected that Eurocopter France had changed its name to Airbus Helicopters.

Since we issued the NPRM, we discovered it contains a typographical error in the date of the service information. Also, the FAA Southwest Regional Office has relocated and a group email address has been established for requesting an FAA Alternate Method of Compliance for a helicopter of foreign design. We have

corrected the error in the service information date and revised the contact information throughout this Final Rule.

Comments

We gave the public the opportunity to participate in developing this AD, but we received no comments on the NPRM (80 FR 27605, May 14, 2015).

FAA's Determination

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, the DGAC, its technical representative, has notified us of the unsafe condition described in the DGAC AD. We are issuing this AD because we evaluated all information provided by the DGAC and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed, except for the minor editorial changes described previously. These changes are consistent with the intent of the proposals in the NPRM (80 FR 27605, May 14, 2015) and will not increase the economic burden on any operator nor increase the scope of this AD.

Related Service Information Under 14 CFR Part 51

We reviewed Eurocopter Alert Service Bulletin No. 67A005, Revision 0, dated August 1, 2001 (ASB), which specifies installing a front and side protection on the cabin floor to protect the yaw control. The DGAC classified this ASB as mandatory and issued AD No. 2001-386-007(A), dated September 5, 2001, and AD 2001-386-007(A)R1, dated February 6, 2002, to ensure the continued airworthiness of these helicopters in France.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

We estimate that this AD affects 37 helicopters of U.S. Registry and that labor costs average \$85 a work-hour. Required parts cost about \$584 and it takes about 2 work-hours to accomplish the required actions. Based on these figures, we estimate that the total cost of this AD is \$754 per helicopter and \$27,898 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2002-13-11, Amendment 39 12799 (67 FR 45295, July 9, 2002), and adding the following new AD:

2015-26-04 Airbus Helicopters (Previously Eurocopter France): Amendment 39-18352; Docket No. FAA-2015-1480; Directorate Identifier 2014-SW-071-AD.

(a) Applicability

This AD applies to Model EC120B helicopters, serial numbers 1001 through 1278, inclusive, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as an object sliding between the canopy and the cabin floor. This condition could result in loss of yaw control and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 2002-13-11, Amendment 39-12799 (67 FR 45295, July 9, 2002).

(d) Effective Date

This AD becomes effective February 4, 2016.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

Within 90 days, install front and side covers (protections) to protect the yaw control in accordance with the Accomplishment Instructions, paragraph 2.B., of Eurocopter Alert Service Bulletin No. 67A005, Revision 0, dated August 1, 2001, except the correct reference to the Aircraft Maintenance Manual in subparagraph 2.B.2 of the ASB is 20-10-00, 3-8.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

The subject of this AD is addressed in the Direction General De L'Aviation Civile (DGAC) AD No. 67A005, Revision 1, dated February 6, 2002. You may view the DGAC AD on the Internet at <http://>

www.regulations.gov in Docket No. FAA–2015–1480.

(i) Subject

Joint Aircraft Service Component (JASC)
Code: 2500, Cabin Equipment/Furnishings.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Alert Service Bulletin No. 67A005, Revision 0, dated August 1, 2001.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641–0000 or (800) 232–0323; fax (972) 641–3775; or at <http://www.airbushelicopters.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on December 15, 2015.

Lance T. Gant,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2015–32258 Filed 12–30–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 744

Control Policy: End-User and End-Use Base

CFR Correction

In Title 15 of the Code of Federal Regulations, Parts 300 to 799, revised as of January 1, 2015, on page 414, in supplement no. 4 to part 744, remove the entry for “Sergey Grinenko” from “GREECE” and add it in alphabetical order under “GERMANY”.

[FR Doc. 2015–33049 Filed 12–30–15; 8:45 am]

BILLING CODE 1505–01–D

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 774

The Commerce Control List

CFR Correction

In Title 15 of the Code of Federal Regulations, Parts 300 to 799, revised as of January 1, 2015, on page 999, in Supplement 1 to Part 774, in Category 9, Export Control Classification Number (ECCN) 9E003, in the Items section, remove the second introductory text of paragraph f.1.

[FR Doc. 2015–33047 Filed 12–30–15; 8:45 am]

BILLING CODE 1505–01–D

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Part 342

[Docket No. RM15–20–000]

Five-Year Review of the Oil Pipeline Index

AGENCY: Federal Energy Regulatory Commission, DOE.

ACTION: Order establishing index level.

SUMMARY: The Federal Energy Regulatory Commission (Commission) issues this Final Order concluding its five-year review of the index level used to determine annual changes to oil pipeline rate ceilings. The Commission establishes an index level of Producer Price Index for Finished Goods plus 1.23 percent (PPI–FG+1.23) for the five-year period commencing July 1, 2016.

DATES: December 31, 2015.

FOR FURTHER INFORMATION CONTACT:

Andrew Knudsen (Legal Information), Office of the General Counsel, 888 First Street NE., Washington, DC 20426, (202) 502–6527
Monil Patel (Technical Information), Office of Energy Market Regulation, 888 First Street NE., Washington, DC 20426, (202) 502–8296

SUPPLEMENTARY INFORMATION:

Order Establishing Index Level

(Issued December 17, 2015)

1. On June 30, 2015, the Commission issued a Notice of Inquiry initiating its five-year review to establish the oil pipeline index level for the July 1, 2016 to June 30, 2021 time period.¹ The June

¹ *Five-Year Review of the Oil Pipeline Index*, 80 FR 39010 (July 8, 2015), FERC Stats. & Regs. ¶

2015 NOI requested comment regarding (a) a proposed index level between Producer Price Index for Finished Goods (PPI–FG)+2.0 percent and PPI–FG+2.4 percent² and (b) any alternative methodologies for calculating that index level.

2. For the reasons discussed below, the Commission adopts an index level of the PPI–FG+1.23 percent. The departure from the June 2015 NOI results from (a) the use of FERC Form No. 6 page 700 (page 700) data that directly measures changing pipeline costs as opposed to the estimates previously used to calculate the index level³ and (b) updated Form No. 6 filings and other corrections to the data set. The Commission’s indexing calculations and other data analysis are contained in Attachment A to this order. As discussed below, the Commission rejects other changes to the index calculation proposed by commenters.

I. Background

A. Establishment of the Indexing Methodology

3. The Energy Policy Act of 1992 (EPAct 1992) required the Commission to establish a “simplified and generally applicable” ratemaking methodology⁴ that also was consistent with the just and reasonable standard of review of the Interstate Commerce Act (ICA).⁵ To implement EPAct 1992’s mandate, the Commission issued Order No. 561⁶ establishing an indexing methodology that allows oil pipelines to change their rates subject to certain ceiling levels as opposed to making cost-of-service filings.⁷

35,053 (cross-referenced at 151 FERC ¶ 61,278 at P 1 (June 2015 NOI)).

² The June 2015 NOI included a range as opposed to a specific index level because some pipelines had yet to report FERC Form No. 6 (Form No. 6) data for 2014.

³ The index range presented in the June 2015 NOI was calculated based on estimates derived from FERC Form No. 6 accounting data on pages 110–111, 114, and page 600.

⁴ Public Law 102–486, 106 Stat. 3010, 1801(a) (Oct. 24, 1992). EPAct 1992’s mandate to establish a simplified and generally applicable method of regulating oil transportation rates specifically excluded the Trans-Alaska Pipeline System (TAPS), or any pipeline delivering oil, directly or indirectly, into it. *Id.* 1804(2)(B).

⁵ 49 U.S.C. app. 1 (1988).

⁶ *See Revisions to Oil Pipeline Regulations Pursuant to the Energy Policy Act of 1992*, Order No. 561, FERC Stats. & Regs. ¶ 30,985 (1993), *order on reh’g*, Order No. 561–A, FERC Stats. & Regs. ¶ 31,000 (1994), *aff’d*, *Assoc. of Oil Pipelines v. FERC*, 83 F.3d 1424 (D.C. Cir. 1996).

⁷ Pursuant to the Commission’s indexing methodology, oil pipelines change their rate ceiling levels effective every July 1 by “multiplying the previous index year’s ceiling level by the most recent index published by the Commission.” 18 CFR 342.3(d)(1) (2015). Oil pipeline rates may be adjusted to the ceiling levels pursuant to the