

Rules and Regulations

Federal Register

Vol. 84, No. 202

Friday, October 18, 2019

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0500; Product Identifier 2019-NM-078-AD; Amendment 39-19759; AD 2019-20-06]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A310 series airplanes. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 22, 2019.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of November 22, 2019.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAW, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at

<http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0500.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0500; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225.

SUPPLEMENTARY INFORMATION:

Discussion

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0091, dated April 26, 2019 (“EASA AD 2019-0091”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A310 series airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A310 series airplanes. The NPRM published in the **Federal Register** on July 1, 2019 (84 FR 31249). The NPRM was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

The FAA is issuing this AD to address fatigue cracking, damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane. See the MCAI for additional background information.

Comment

The FAA gave the public the opportunity to participate in developing this final rule. The FAA considered the comment received. FedEx had no objection to the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

Airbus has issued Airbus A310 Airworthiness Limitations Section (ALS), Part 2, Damage Tolerant Airworthiness Limitation Items (DT-ALI), Revision 03, dated December 14, 2018 (“Airbus A310 ALS, Part 2, DT-ALI, Revision 03”), as supplemented by Airbus A310 ALS, Part 2, DT-ALI, Variation 3.1, Issue 01, dated December 20, 2018 (“Airbus A310 ALS, Part 2, DT-ALI, Variation 3.1, Issue 01”). Airbus A310 ALS, Part 2, DT-ALI, Revision 03, describes mandatory maintenance tasks that operators must perform at specified intervals. Airbus A310 ALS, Part 2, DT-ALI, Variation 3.1, Issue 01, describes additional mandatory maintenance tasks related to widespread fatigue damage that operators must perform at specified intervals.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 4 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD.

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 workhours per operator, although the FAA recognizes that this number may vary from operator to operator. In the

past, the FAA has estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the FAA estimates the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–20–06 Airbus SAS: Amendment 39–19759; Docket No. FAA–2019–0500; Product Identifier 2019–NM–078–AD.

(a) Effective Date

This AD is effective November 22, 2019.

(b) Affected ADs

This AD affects AD 2017–21–08, Amendment 39–19079 (82 FR 48904, October 23, 2017) ("AD 2017–21–08"); and AD 2018–19–31, Amendment 39–19432 (83 FR 48930, September 28, 2018) ("AD 2018–19–31").

(c) Applicability

This AD applies to Airbus SAS Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address fatigue cracking, damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Airbus A310 Airworthiness Limitations Section (ALS), Part 2, Damage Tolerant Airworthiness Limitation Items (DT–ALI),

Revision 03, dated December 14, 2018 ("Airbus A310 ALS, Part 2, DT–ALI, Revision 03"), as supplemented by Airbus A310 ALS, Part 2, DT–ALI, Variation 3.1, Issue 01, dated December 20, 2018 ("Airbus A310 ALS, Part 2, DT–ALI, Variation 3.1, Issue 01"). The initial compliance time for doing the tasks is at the time specified in Airbus A310 ALS, Part 2, DT–ALI, Revision 03, as supplemented by Airbus A310 ALS, Part 2, DT–ALI, Variation 3.1, Issue 01; or within 90 days after the effective date of this AD; whichever occurs later.

(h) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions and intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j)(1) of this AD.

(i) Terminating Action for AD 2017–21–08 and AD 2018–19–31

Accomplishing the actions required by this AD terminates all requirements of AD 2017–21–08 and AD 2018–19–31.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Union Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can

be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2019-0091, dated April 26, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0500.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3225.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus A310 Airworthiness Limitations Section (ALS), Part 2, Damage Tolerant Airworthiness Limitation Items (DT-ALI), Revision 03, dated December 14, 2018.

(ii) Airbus A310 Airworthiness Limitations Section (ALS), Part 2, Damage Tolerant Airworthiness Limitation Items (DT-ALI), Variation 3.1, Issue 01, dated December 20, 2018.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on October 3, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-22603 Filed 10-17-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE INTERIOR

Bureau of Safety and Environmental Enforcement

30 CFR Part 250

Bureau of Ocean Energy Management

30 CFR Part 585

[201E1700D2 ET1SF0000.EAQ000 EEEE500000]

Department of the Interior Policy Statement on Regulating Workplace Safety and Health Conditions on Renewable Energy Facilities on the Outer Continental Shelf

AGENCY: Bureau of Ocean Energy Management, Interior; Bureau of Safety and Environmental Enforcement, Interior.

ACTION: Notification of policy statement.

SUMMARY: This policy statement clarifies the role of the Department of the Interior (DOI) in regulating workplace safety and health conditions on renewable energy facilities on the Outer Continental Shelf (OCS). This policy does not apply to workplace safety and health requirements for OCS marine hydrokinetic (*i.e.*, wave, tidal, and ocean current) energy projects, for which operational requirements are within the jurisdiction of the Federal Energy Regulatory Commission, or OCS renewable energy facility support vessels, which are under the authority of the United States Coast Guard (USCG).

DATES: This policy statement is effective on October 18, 2019.

FOR FURTHER INFORMATION CONTACT: Cheri Hunter, Bureau of Safety and Environmental Enforcement Renewable Energy Program Coordinator, (703) 787-1681, or by email: cheri.hunter@bsee.gov.

SUPPLEMENTARY INFORMATION:

Authority

The Energy Policy Act of 2005, Public Law 109-58, amended the Outer Continental Shelf Lands Act (OCSLA) to grant the Secretary of the Interior (Secretary) the authority to oversee renewable energy activities on the OCS (43 U.S.C. 1337(p)). Under section 8(p) of OCSLA, the Secretary has the authority to issue leases, rights-of-way (ROW), and rights-of-use and easements (RUE) on the OCS for activities that produce, or that support the production, transportation, or transmission of, energy from sources other than oil and gas, not otherwise authorized by other

laws. Section 8(p) also gives the Secretary the specific authority to issue regulations to implement its provisions.¹

Pursuant to 43 U.S.C. 1337(p)(4)(A), the Secretary has the statutory authority to ensure that activities conducted on renewable energy leases are carried out in a manner that provides for safety. The DOI has exercised this authority by promulgating regulations that govern renewable energy activities, set forth in 30 CFR part 585, including provisions to ensure that renewable energy activities on the OCS and activities involving the alternate use of OCS facilities for energy or marine-related purposes are conducted in a safe and environmentally sound manner, in conformance with the requirements of subsection 8(p) of the OCS Lands Act, other applicable laws and regulations, and the terms of the lease, ROW grant, RUE grant, or Alternate Use RUE grant.² These include requirements for Safety Management Systems and self-inspections, as well as provisions for agency-conducted inspections, incident reporting, investigations, and enforcement. See Memorandum of Understanding between the U.S. Department of the Interior and Federal Energy Regulatory Commission, Apr. 9, 2009.

DOI Regulatory Requirements Regarding Workplace Safety and Health

Under 30 CFR part 585, subpart H, regulated entities³ must implement a Safety Management System (SMS) for activities conducted on OCS renewable energy leases.⁴ An SMS provides a structured approach for the identification of hazards and risks, management of risks through identified methods, implementation of policies and procedures to ensure safety, and periodic assessment of conformance to expectations. An SMS addresses the management of both occupational and process safety risks associated with construction, operation, maintenance, and decommissioning of renewable energy facilities.

In addition to SMS requirements, DOI has promulgated regulations requiring self- and agency-conducted inspections

¹ 43 U.S.C. 1337(p)(8).

² 30 CFR 585.101(c).

³ The requirements are applicable to "You," which is defined to include "an applicant, lessee, the operator, or designated operator, ROW grant holder, RUE grant holder, or Alternate Use RUE grant holder under this part, or the designated agent of any of these, or the possessive of each, depending on the context," as well as "contractors and subcontractors of the entities" listed previously. 30 CFR 585.112.

⁴ 30 CFR 585.810.