

2020, Financial Institution A does not meet the loan-volume test described in § 1003.2(g)(1)(v)(A) if it originated fewer than 25 closed-end mortgage loans during either 2018 or 2019.

2. *Adjustment of exemption threshold for banks, savings associations, and credit unions.* For data collection in 2020, the asset-size exemption threshold is \$47 million. Banks, savings associations, and credit unions with assets at or below \$47 million as of December 31, 2019, are exempt from collecting data for 2020.

3. *Merger or acquisition—coverage of surviving or newly formed institution.* After a merger or acquisition, the surviving or newly formed institution is a financial institution under § 1003.2(g) if it, considering the combined assets, location, and lending activity of the surviving or newly formed institution and the merged or acquired institutions or acquired branches, satisfies the criteria included in § 1003.2(g). For example, A and B merge. The surviving or newly formed institution meets the loan threshold described in § 1003.2(g)(1)(v)(B) if the surviving or newly formed institution, A, and B originated a combined total of at least 500 open-end lines of credit in each of the two preceding calendar years. Likewise, the surviving or newly formed institution meets the asset-size threshold in § 1003.2(g)(1)(i) if its assets and the combined assets of A and B on December 31 of the preceding calendar year exceeded the threshold described in § 1003.2(g)(1)(i). Comment 2(g)–4 discusses a financial institution's responsibilities during the calendar year of a merger.

4. *Merger or acquisition—coverage for calendar year of merger or acquisition.* The scenarios described below illustrate a financial institution's responsibilities for the calendar year of a merger or acquisition. For purposes of these illustrations, a "covered institution" means a financial institution, as defined in § 1003.2(g), that is not exempt from reporting under § 1003.3(a), and "an institution that is not covered" means either an institution that is not a financial institution, as defined in § 1003.2(g), or an institution that is exempt from reporting under § 1003.3(a).

i. Two institutions that are not covered merge. The surviving or newly formed institution meets all of the requirements necessary to be a covered institution. No data collection is required for the calendar year of the merger (even though the merger creates an institution that meets all of the requirements necessary to be a covered institution). When a branch office of an institution that is not covered is acquired by another institution that is not covered, and the acquisition results in a covered institution, no data collection is required for the calendar year of the acquisition.

ii. A covered institution and an institution that is not covered merge. The covered institution is the surviving institution, or a new covered institution is formed. For the calendar year of the merger, data collection is required for covered loans and applications handled in the offices of the merged institution that was previously covered and is optional for covered loans and applications handled in offices of the merged

institution that was previously not covered. When a covered institution acquires a branch office of an institution that is not covered, data collection is optional for covered loans and applications handled by the acquired branch office for the calendar year of the acquisition.

iii. A covered institution and an institution that is not covered merge. The institution that is not covered is the surviving institution, or a new institution that is not covered is formed. For the calendar year of the merger, data collection is required for covered loans and applications handled in offices of the previously covered institution that took place prior to the merger. After the merger date, data collection is optional for covered loans and applications handled in the offices of the institution that was previously covered. When an institution remains not covered after acquiring a branch office of a covered institution, data collection is required for transactions of the acquired branch office that take place prior to the acquisition. Data collection by the acquired branch office is optional for transactions taking place in the remainder of the calendar year after the acquisition.

iv. Two covered institutions merge. The surviving or newly formed institution is a covered institution. Data collection is required for the entire calendar year of the merger. The surviving or newly formed institution files either a consolidated submission or separate submissions for that calendar year. When a covered institution acquires a branch office of a covered institution, data collection is required for the entire calendar year of the merger. Data for the acquired branch office may be submitted by either institution.

5. *Originations.* Whether an institution is a financial institution depends in part on whether the institution originated at least 25 closed-end mortgage loans in each of the two preceding calendar years or at least 500 open-end lines of credit in each of the two preceding calendar years. Comments 4(a)–2 through –4 discuss whether activities with respect to a particular closed-end mortgage loan or open-end line of credit constitute an origination for purposes of § 1003.2(g).

6. *Branches of foreign banks—treated as banks.* A Federal branch or a State-licensed or insured branch of a foreign bank that meets the definition of a "bank" under section 3(a)(1) of the Federal Deposit Insurance Act (12 U.S.C. 1813(a)) is a bank for the purposes of § 1003.2(g).

7. *Branches and offices of foreign banks and other entities—treated as nondepository financial institutions.* A Federal agency, State-licensed agency, State-licensed uninsured branch of a foreign bank, commercial lending company owned or controlled by a foreign bank, or entity operating under section 25 or 25A of the Federal Reserve Act, 12 U.S.C. 601 and 611 (Edge Act and agreement corporations) may not meet the definition of "bank" under the Federal Deposit Insurance Act and may thereby fail to satisfy the definition of a depository financial institution under § 1003.2(g)(1). An entity is nonetheless a financial institution if it meets the definition

of nondepository financial institution under § 1003.2(g)(2).

* * * * *

Dated: December 17, 2019.

Thomas Pahl,

Policy Associate Director, Bureau of Consumer Financial Protection.

[FR Doc. 2019–27522 Filed 12–18–19; 4:15 pm]

BILLING CODE 4810-AM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0704; Product Identifier 2019–NM–132–AD; Amendment 39–19813; AD 2019–24–10]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A350–941 airplanes. This AD was prompted by an investigation that identified the cargo lining gutter assembly would be unable to drain a certain quantity of water in case of leakage or rupture of certain water pipes. This AD requires modification of the cargo lining gutter assemblies, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective January 24, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 24, 2020.

ADDRESSES: For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for

and locating Docket No. FAA–2019–0704.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0704; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3218.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0183, dated July 26, 2019 (“EASA AD 2019–0183”) (also referred to as the

Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A350–941 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A350–941 airplanes. The NPRM published in the **Federal Register** on September 25, 2019 (84 FR 50339). The NPRM was prompted by an investigation that identified the cargo lining gutter assembly would be unable to drain a certain quantity of water in case of leakage or rupture of certain water pipes. The NPRM proposed to require modification of the cargo lining gutter assemblies.

The FAA is issuing this AD to address this condition, which, if not corrected, could lead to fluid contamination of certain electrical equipment and connectors, possibly resulting in the loss of several flight control functions, with consequent reduced control of the airplane. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comments received. The commenter John Motzel and two anonymous

commenters stated support for the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0183 describes procedures for modifying the cargo lining gutter assemblies. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 5 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
17 work-hours × \$85 per hour = \$1,445	\$12,000	\$13,445	\$67,225

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil

aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–24–10 Airbus SAS: Amendment 39–19813; Docket No. FAA–2019–0704; Product Identifier 2019–NM–132–AD.

(a) Effective Date

This AD is effective January 24, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A350–941 airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019–0183, dated July 26, 2019 (“EASA AD 2019–0183”).

(d) Subject

Air Transport Association (ATA) of America Code 92, Electric and electronic common installation.

(e) Reason

This AD was prompted by an investigation that identified the cargo lining gutter assembly would be unable to drain a certain quantity of water in case of leakage or rupture of certain water pipes. The FAA is issuing this AD to address this condition, which, if not corrected, could lead to fluid contamination of certain electrical equipment and connectors, possibly resulting in the loss of several flight control functions, with consequent reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019–0183.

(h) Exception to EASA AD 2019–0183

The “Remarks” section of EASA AD 2019–0183 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019–0183 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3218.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019–0183, dated July 26, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019–0183, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADS@easa.europa.eu; Internet www.easa.europa.eu. You may find this

EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0704.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 27, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–27468 Filed 12–19–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2019–0698; Product Identifier 2019–NM–109–AD; Amendment 39–19814; AD 2019–24–11]

RIN 2120–AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2014–16–26 and AD 2017–19–04, which applied to certain Dassault Aviation Model FALCON 900EX airplanes. Those ADs required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance requirements and/or airworthiness limitations. Since the FAA issued AD 2014–16–26 and AD 2017–19–04, the FAA determined that new or more restrictive airworthiness limitations are necessary. This AD continues to require those maintenance or inspection program revisions, and also requires revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 24, 2020.