

We believe the questions below may help guide commenters in developing their submissions.

1. Is the information provided adequate to understand how to use the tool?
2. Is the format easy to use?
3. Are there other resources that should be included?
4. Will this tool be beneficial to State, local, territorial and tribal drug-impaired driving criminal justice programs?
5. What changes are needed to make the tool more beneficial?

Public Participation:

How do I prepare and submit comments?

Your comments must be written and in English. To ensure that your comments are filed correctly in the docket, please include the docket number of this document in your comments.

Please submit one copy (two copies if submitting by mail or hand delivery) of your comments, including any attachments, to the docket following the instructions given above under **ADDRESSES**. Please note, if you are submitting comments electronically as a PDF (Adobe) file, we ask that the documents submitted be scanned using an Optical Character Recognition (OCR) process, thus allowing the agency to search and copy certain portions of your submissions.

How do I submit confidential business information?

Any submissions containing Confidential Information must be delivered to NHTSA in the following manner:

- Submitted in a sealed envelope marked "confidential treatment requested";
- Accompanied by an index listing the document(s) or information that the submitter would like the Departments to withhold. The index should include information such as numbers used to identify the relevant document(s) or information, document title and description, and relevant page numbers and/or section numbers within a document; and
- Submitted with a statement explaining the submitter's grounds for objecting to disclosure of the information to the public.

NHTSA also requests that submitters of Confidential Information include a non-confidential version (either redacted or summarized) of those confidential submissions in the public docket. In the event that the submitter

cannot provide a non-confidential version of its submission, NHTSA requests that the submitter post a notice in the docket stating that it has provided NHTSA with Confidential Information. Should a submitter fail to docket either a non-confidential version of its submission or to post a notice that Confidential Information has been provided, we will note the receipt of the submission on the docket, with the submitter's organization or name (to the degree permitted by law) and the date of submission.

Will the Agency consider late comments?

NHTSA will consider all comments received before the close of business on the comment closing date indicated above under **DATES**. To the extent possible, the agency will also consider comments received after that date.

How can I read the comments submitted by other people?

You may read the comments received at the address given above under **COMMENTS**. The hours of the docket are indicated above in the same location. You may also see the comments on the internet, identified by the docket number at the heading of this notice, at <https://www.regulations.gov>.

Authority: 23 U.S.C. 403(b).

Issued in Washington, DC.

Nanda Narayanan Srinivasan,
Associate Administrator, Research and Program Development.

[FR Doc. 2020-03917 Filed 2-26-20; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2019-0008; Notice 1]

Daimler Trucks North America, Receipt of Petition for Decision of Inconsequential Noncompliance

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

ACTION: Receipt of petition.

SUMMARY: Daimler Trucks North America (DTNA) has determined that certain model year (MY) 2017-2019 Freightliner Cascadia motor vehicles do not fully comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 108, *Lamps, Reflective Devices, and Associated Equipment*. DTNA filed a noncompliance report dated January 16, 2019. DTNA subsequently petitioned

NHTSA on February 8, 2019, for a decision that the subject noncompliance is inconsequential as it relates to motor vehicle safety. This document announces receipt of DTNA's petition.

DATES: The closing date for comments on the petition is March 30, 2020.

ADDRESSES: Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket number and notice number cited in the title of this notice and may be submitted by any of the following methods:

- **Mail:** Send comments by mail addressed to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver comments by hand to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except for Federal Holidays.

- **Electronically:** Submit comments electronically by logging onto the Federal Docket Management System (FDMS) website at <https://www.regulations.gov>. Follow the online instructions for submitting comments.

- Comments may also be faxed to (202) 493-2251.

Comments must be written in the English language, and be no greater than 15 pages in length, although there is no limit to the length of necessary attachments to the comments. If comments are submitted in hard copy form, please ensure that two copies are provided. If you wish to receive confirmation that comments you have submitted by mail were received, please enclose a stamped, self-addressed postcard with the comments. Note that all comments received will be posted without change to <https://www.regulations.gov>, including any personal information provided.

All comments and supporting materials received before the close of business on the closing date indicated above will be filed in the docket and considered. All comments and supporting materials received after the closing date will also be filed and considered to the fullest extent possible.

When the petition is granted or denied, a notice of the decision will also be published in the **Federal Register** pursuant to the authority indicated at the end of this notice.

All comments, background documentation, and supporting

materials submitted to the docket may be viewed by anyone at the address and times given above. The documents may also be viewed on the internet at <https://www.regulations.gov> by following the online instructions for accessing the dockets. The docket ID number for this petition is shown in the heading of this notice.

DOT's complete Privacy Act Statement is available for review in a **Federal Register** notice published on April 11, 2000, (65 FR 19477–78).

SUPPLEMENTARY INFORMATION:

I. Overview: DTNA has determined that certain MY 2017–2019 Freightliner Cascadia motor vehicles do not fully comply with paragraph S6.2.1 of FMVSS No. 108, *Lamps, Reflective Devices, and Associated Equipment*. (49 CFR 571.108). DTNA filed a noncompliance report dated January 16, 2019, pursuant to 49 CFR part 573, *Defect and Noncompliance Responsibility and Reports*. DTNA subsequently petitioned NHTSA on February 8, 2019, for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential as it relates to motor vehicle safety pursuant to 49 U.S.C. 30118(d) and 30120(h) and 49 CFR part 556, *Exemption for Inconsequential Defect or Noncompliance*.

This notice of receipt of DTNA petition is published under 49 U.S.C. 30118 and 30120, and does not represent any agency decision or other exercises of judgment concerning the merits of the petition.

II. Trucks Involved: Approximately 74,675 MY 2017–2019 Freightliner Cascadia motor vehicles, manufactured between May 3, 2016, and December 17, 2018, are potentially involved.

III. Noncompliance: DTNA stated that the noncompliance is that the subject vehicles are equipped with brake lights that illuminate when the low air warning light illuminates and therefore, does not meet the requirements specified in paragraph S6.2.1 of FMVSS No. 108.

IV. Rule Requirements: Paragraph S6.2.1 of FMVSS No. 108, includes the requirements relevant to this petition. No additional lamp, reflective device, or other motor vehicle equipment is permitted to be installed that impairs the effectiveness of lighting equipment required by FMVSS No. 108.

V. Summary of DTNA's Petition: The following views and arguments presented in this section, V. Summary of DTNA's Petition, are the views and arguments provided by DTNA. They have not been evaluated by the agency

and do not reflect the views of the agency.

DTNA described the subject noncompliance and stated its belief that the noncompliance is inconsequential as it relates to motor vehicle safety.

DTNA submitted the following background information on how their air brake system affects the stop lamps:

DTNA's air brake system is comprised of two brake systems, primary and secondary. The primary system controls the service brakes on the drive axles and the secondary system controls the service brakes on the steer axle, and the higher pressure of these two control the trailer service brakes. These two systems are isolated from each other so that if there is an air loss in one system, the other system will still be functional to control the vehicle service brakes. When either one of the systems drops below 70 psi, the low air warning indicator light on the dash turns ON and the brake lights illuminate. It does not mean that the drive axle parking brakes are starting to apply. The air that holds off the drive axle parking brakes, is the higher of either primary or secondary air. Therefore, if the primary falls below 70 psi, the indicator light and brake lights illuminate, but the parking brakes do not start to drag since the secondary air (presumably unaffected) still remains high and holds off the parking springs. In the same manner, the trailer parking brakes are held off by the higher of either primary or secondary air. Only when both air systems drop below about 70 psi will the trailer parking brakes begin to apply.

DTNA submitted the following views and arguments in support of the petition:

1. The normal operating air pressure of the vehicle is between 110 and 130 PSI. There is a regulator that turns on the air compressor if the air pressure is below 110 PSI and turns off the air compressor when the system pressure is above 130 PSI. If the air pressure begins to drop and reaches approximately 70 PSI the air system pressure is not adequate to maintain optimum operation, a warning signal illuminates on the dash and buzzer activates to alert the driver to this condition. On these vehicles, the brake lights illuminate when the warning signal illuminates on the dash. The events contributing to a low air condition after initial vehicle startup are rare and are not expected in normal operation. If the condition was to occur during operation, the driver would be alerted to the circumstances with audible and visual low air warning and would be expected to apply the service brakes and pull over in a safe manner. Additionally, if the pressure in

both air systems drops below 70 psi, the parking brakes will slowly begin to apply.

2. The Freightliner Cascadia Driver's Manual states "If the low air pressure warning is activated, check the air pressure gauges to determine which system has low air pressure. Although the vehicle's speed can be reduced using the foot brake control pedal, either the front or rear service brakes will not be operating at full capacity, causing a longer stopping distance. Bring the vehicle to a safe stop and have the air system repaired before continuing."

3. Brakes are commonly applied—causing the brake lights to illuminate—when a driver sees a vehicle display warning or senses that the vehicle is experiencing a problem. Reducing vehicle speed in relation to a vehicle operational problem increases safety, providing following drivers the opportunity to increase the following distance. Low air warning would likely cause the vehicle driver to immediately engage the brake system and bring the vehicle to a safe stop. Brake light illumination for a brake system low air event would help provide early warning to following drivers to slow down.

4. DTNA stated, in "Motorcoach Brake Systems and Safety Technologies," Federal Motor Carrier Administration issued guidance, while directed toward Motorcoach drivers, that supports the expectation that a driver, upon receipt of a low-pressure warning, would apply brakes and pull off the roadway. FMCSA stated: "Low Pressure Warning—In most cases, you should notice an air leak or malfunction before getting a low-pressure warning; however, when a low-pressure warning occurs, immediately bring the motorcoach to a safe stop, off of the roadway. Continuing to operate the motorcoach could result in an automatic application of the park brakes, possibly leading to a loss of control or a stop in an unsafe position."

5. DTNA is not aware of any accidents, injuries, owner complaints or field reports related to this condition on the subject vehicles.

6. DTNA also stated that NHTSA has previously granted petitions for decisions of inconsequential noncompliance for lighting requirements where technical noncompliance exists, but does not create a negative impact on safety:

- In Docket No. 66 FR 32871 (June 18, 2001) a Petition for inconsequentiality by GM was granted by NHTSA. In this instance, certain models could have unintended CHMSL illumination briefly if the hazard warning lamp switch is depressed to its limit of travel. NHTSA

stated: “The intended use of a hazard warning lamp and the momentary activation of a CHMSL do not provide a conflicting message. The illumination of the CHMSL is intended to signify that the vehicle’s brakes are being applied and that the vehicle might be decelerating. Hazard warning lamps are intended as a more general message to nearby drivers that extra attention should be given to the vehicle. A brief illumination of the CHMSL while activating the hazard warning lamps would not confuse the intended general message, nor would the brief illumination in the absence of the other brake lamps cause confusion that the brakes were unintentionally applied.”

- In Docket No. 83 FR 7847 (Feb 22, 2018) a Petition for inconsequentiality by GM was granted by NHTSA. In this instance, under certain conditions, the parking lamps on the subject vehicles fail to meet the requirement that parking lamps must be activated when headlamps are activated in a steady burning state. NHTSA stated: “. . . The Agency agrees with GM that in this case, this situation would have a low probability of occurrence and, if it should occur, it would neither be long-lasting nor likely to occur during a period when parking lamps are generally in use. Importantly, when the noncompliance does occur, other lamps remain functional. The combination of all of the factors, specific to this case, abate the risk to safety.”

- In Docket No. 64 FR 62609 (Sept. 02, 1999) a Petition for inconsequentiality by GM was granted by NHTSA. In this instance, a certain model equipped with an electronic turn signal was affected by random inputs that cause the internal timing of the electronic circuit to become unsynchronized causing the left front turn signal lamp to flash at a rapid rate while the left rear turn signal lamp illuminates but does not flash. These conditions can continue after the turn signal lever automatically returns to the off position. NHTSA stated: “We have concluded that the few vehicles affected by this noncompliance, as well as the fact that the turn signals show the driver that they have failed, warrant a finding that this noncompliance is inconsequential with regard to motor vehicle safety.”

7. DTNA believes that a technical non-compliance exists, but does not create a negative impact on safety when the brake lamps illuminate during a brake system low air warning event. The brake light illumination serves to emphasize the message to following drivers that the vehicle is experiencing trouble and they should pay close

attention. The Brake Air warning indicator light, on the driver’s display panel, shows the driver that there is an issue with the air brake system. This would result in the driver bringing the vehicle to a safe stop and having the air system repaired before continuing.

DTNA concluded by expressing the belief that the subject noncompliance is inconsequential as it relates to motor vehicle safety, and that its petition to be exempted from providing notification of the noncompliance, as required by 49 U.S.C. 30118, and a remedy for the noncompliance, as required by 49 U.S.C. 30120, should be granted.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that DTNA no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after DTNA notified them that the subject noncompliance existed.

Authority

49 U.S.C. 30118, 30120; Delegations of authority at 49 CFR 1.95 and 501.8.

Otto G. Matheke III,

Director, Office of Vehicle Safety Compliance.

[FR Doc. 2020-03960 Filed 2-26-20; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF THE TREASURY

Office of the Comptroller of the Currency

Agency Information Collection Activities: Information Collection Renewal; Comment Request; Assessment of Fees

AGENCY: Office of the Comptroller of the Currency (OCC), Treasury.

ACTION: Notice and request for comment.

SUMMARY: The OCC, as part of its continuing effort to reduce paperwork and respondent burden, invites the general public and other Federal agencies to take this opportunity to

comment on a continuing information collection as required by the Paperwork Reduction Act of 1995 (PRA).

In accordance with the requirements of the PRA, the OCC may not conduct or sponsor, and the respondent is not required to respond to, an information collection unless it displays a currently valid Office of Management and Budget (OMB) control number. The OCC is soliciting comment concerning the renewal of its information collection titled, “Assessment of Fees.”

DATES: You should submit written comments by April 27, 2020.

ADDRESSES: Commenters are encouraged to submit comments by email, if possible. You may submit comments by any of the following methods:

- *Email:* prainfo@occ.treas.gov.

- *Mail:* Chief Counsel’s Office,

Attention: Comment Processing, Office of the Comptroller of the Currency, Attention: 1557-0223, 400 7th Street SW, Suite 3E-218, Washington, DC 20219.

- *Hand Delivery/Courier:* 400 7th Street SW, Suite 3E-218, Washington, DC 20219.

- *Fax:* (571) 465-4326.

Instructions: You must include “OCC” as the agency name and “1557-0223” in your comment. In general, the OCC will publish comments on www.reginfo.gov without change, including any business or personal information provided, such as name and address information, email addresses, or phone numbers. Comments received, including attachments and other supporting materials, are part of the public record and subject to public disclosure. Do not include any information in your comment or supporting materials that you consider confidential or inappropriate for public disclosure.

You may review comments and other related materials that pertain to this information collection beginning on the date of publication of the second notice for this collection¹ by any of the following methods:

- *Viewing Comments Electronically:*

Go to www.reginfo.gov. Click on the “Information Collection Review” tab. Underneath the “Currently under Review” section heading, from the drop-down menu select “Department of the Treasury” and then click “Submit.” This information collection can be located by searching by OMB control number “1557-0223” or “Assessment of Fees.” Upon finding the appropriate information collection, click on the

¹ Following the close of this notice’s 60-day comment period, the OCC will publish a second notice with a 30-day comment period.