

(2) Where EASA AD 2019–0073 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where the service information required by EASA AD 2019–0073 specifies returning a part to the manufacturer, this AD does not include that requirement.

(4) This AD does not require the “Remarks” section of EASA AD 2019–0073.

(5) Where paragraph (2) of EASA AD 2019–0073 specifies to replace if there are burn signs or other damage, for this AD, other damage is defined as being consistent with wire overheating (e.g., possible melted or exposed wires).

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2019–0073 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Jacob Fitch, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; phone: (817) 222-4130; email: jacob.fitch@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019–0073, dated March 28, 2019.

(ii) [Reserved]

(3) For EASA AD 2019–0073, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; Internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0671.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 7, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–24153 Filed 11–4–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0659; Project Identifier 2018–SW–112–AD; Amendment 39–21763; AD 2021–21–03]

RIN 2120–AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Leonardo S.p.a. Model A109A, A109A II, A109C, A109E, A109K2, A109S, AW109SP, A119, and AW119 MKII helicopters. This AD was prompted by a report of damage to a rigid connecting link (rod), and loosening of the nut on the upper rod end. This AD requires a visual inspection of the affected rods for damage, cracks, or abnormal play, and corrective actions if necessary, as specified in a European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective December 10, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 10, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3,

50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0659.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0659; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Darren Gassetto, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; phone: (516) 228–7323; email: darren.gassetto@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018–0280, dated December 17, 2018 (EASA AD 2018–0280) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for Leonardo S.p.a. (formerly Finmeccanica S.p.a., AgustaWestland S.p.a., Agusta S.p.a.; and AgustaWestland Philadelphia Corporation, formerly Agusta Aerospace Corporation) Model A109A, A109A II, A109C, A109E, A109K2, A109S, A109LUH, AW109SP, A119, and AW119 MKII helicopters. Model A109LUH helicopters are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those helicopters in the applicability.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR

part 39 by adding an AD that would apply to certain Leonardo S.p.a. Model A109A, A109A II, A109C, A109E, A109K2, A109S, AW109SP, A119, and AW119 MKII helicopters. The NPRM published in the **Federal Register** on August 13, 2021 (86 FR 44657). The NPRM was prompted by a report of damage to a rod, and loosening of the nut on the upper rod end. The NPRM proposed to require a visual inspection of the affected rods for damage, cracks, or abnormal play, and corrective actions if necessary, as specified in an EASA AD.

The FAA is issuing this AD to address damage to the rod, and loosening of the nut on the upper rod end, which could result in failure of the rod, possibly resulting in reduced control of the helicopter. See the MCAI for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA gave the public the opportunity to participate in developing

this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2018–0280 requires a visual inspection of the affected rods for damage, cracks, or evidence of abnormal play, and, depending on findings, any applicable corrective actions (which include replacing damaged or cracked connecting links and actions to address abnormal play).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Interim Action

The FAA considers this AD interim action. The inspection reports that are required by this AD will enable the manufacturer to obtain better insight into the nature, cause, and extent of the cracking, and eventually to develop final action to address the unsafe condition. Once final action has been identified, the FAA might consider further rulemaking.

Costs of Compliance

The FAA estimates that this AD affects 291 helicopters of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS *

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Visual Inspection	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$24,735

* Table does not include estimated costs for reporting.

The FAA estimates that it would take about 1 work-hour per product to comply with the reporting requirement in this AD. The average labor rate is \$85 per hour. Based on these figures, the

FAA estimates the cost of reporting the inspection results on U.S. operators to be \$24,735, or \$85 per product.

The FAA estimates the following costs to do any necessary on-condition

replacements that would be required based on the results of the inspection. The agency has no way of determining the number of aircraft that might need these on-condition replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replacement	3 work-hour × \$85 per hour = \$255	Up to \$2,351	Up to \$2,606.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information

required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to Information Collection Clearance Officer, Federal Aviation Administration, 10101 Hillwood Pkwy., Fort Worth, TX 76177–1524.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–21–03 Leonardo S.p.a.: Amendment 39–21763; Docket No. FAA–2021–0659; Project Identifier 2018–SW–112–AD.

(a) Effective Date

This airworthiness directive (AD) is effective December 10, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Leonardo S.p.a. Model A109A, A109A II, A109C, A109E, A109K2, A109S, AW109SP, A119, and AW119 MKII helicopters, certificated in any category, with an affected part as identified in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2018–0280, dated December 17, 2018 (EASA AD 2018–0280).

(d) Subject

Joint Aircraft Service Component (JASC) Codes: 6700, Rotorcraft Flight Control; 6730, Rotorcraft Servo System.

(e) Unsafe Condition

This AD was prompted by a report of damage to a rigid connecting link (rod), and loosening of the nut on the upper rod end. The FAA is issuing this AD to address damage to the rod, and loosening of the nut on the upper rod end. The unsafe condition, if not addressed, could result in failure of the rod, possibly resulting in reduced control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2018–0280.

(h) Exceptions to EASA AD 2018–0280

- (1) Where EASA AD 2018–0280 requires compliance in terms of flight hours, this AD requires using hours time-in-service.
- (2) Where EASA AD 2018–0280 requires compliance from its effective date, this AD requires using the effective date of this AD.
- (3) Where EASA AD 2018–0280 specifies action if “any discrepancy” is found, for this AD, discrepancies include damage, cracks, and evidence of abnormal play.
- (4) Where the service information specified in EASA AD 2018–0280 specifies to “replace the damaged connecting link”, for this AD, if any damage or cracks are found, remove the rod from service.
- (5) Where the service information specified in EASA AD 2018–0280 specifies to “contact Leonardo Helicopters” if abnormal play is detected, for this AD if any abnormal play is detected, corrective action must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Leonardo S.p.a.’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(6) Where EASA AD 2018–0280 requires reporting inspection results to Leonardo S.p.a. within 14 days after the effective date of EASA AD 2018–0280, this AD requires reporting inspection results at the applicable time in paragraph (h)(6)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 14 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 14 days after the effective date of this AD.

(7) This AD does not require the “Remarks” section of EASA AD 2018–0280.

(i) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Darren Gassetto, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; phone: (516) 228–7323; email: darren.gassetto@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018–0280, dated December 17, 2018.

(ii) [Reserved]

(3) For EASA AD 2018–0280, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; Internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0659.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on September 30, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–24151 Filed 11–4–21; 8:45 am]

BILLING CODE 4910–13–P