

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0137, dated July 12, 2023.

(ii) [Reserved]

(3) For EASA AD 2023–0137, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on February 8, 2024.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024–05192 Filed 3–11–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1810; Project Identifier MCAI–2023–00267–T; Amendment 39–22679; AD 2024–03–09]

RIN 2120–AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD–500–1A11 airplanes. This AD was prompted by a manufacturing issue with an electrical connector that may prevent the connector from self-locking. This AD requires removing the affected connector, installing a new connector, and testing the emergency power supply units (EPSUs), as specified in a Transport Canada AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 16, 2024.

The Director of the Federal Register approved the incorporation by reference

of a certain publication listed in this AD as of April 16, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2023–1810; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email TC.AirworthinessDirectives-Consignesde navigabilite.TC@tc.gc.ca; website tc.canada.ca/en/aviation.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at regulations.gov under Docket No. FAA–2023–1810.

FOR FURTHER INFORMATION CONTACT:

William Reisenauer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Canada Limited Partnership Model BD–500–1A11 airplanes. The NPRM published in the **Federal Register** on August 31, 2023 (88 FR 60160). The NPRM was prompted by AD CF–2023–08, dated February 13, 2023, issued by Transport Canada, which is the aviation authority for Canada (Transport Canada AD CF–2023–08) (also referred to as the MCAI). The MCAI states that a manufacturing molding issue with an electrical connector may prevent the connector from self-locking. The connector may become loose over time, preventing the charging of EPSUs 3 and 4 and lead to the loss of emergency lights, possibly resulting in injury to occupants during an evacuation.

In the NPRM, the FAA proposed to require removing the affected connector, installing a new connector, and testing the EPSUs, as specified in Transport Canada AD CF–2023–08. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA–2023–1810.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from Delta Air Lines (DAL). The following presents the comment received on the NPRM and the FAA’s response.

Request To Specify No U.S.-Registered Airplanes

DAL stated that via the FAA U.S. registry, the four affected airplanes are not U.S.-registered. The FAA assumes Delta would like the AD to specify no U.S.-registered airplanes.

The FAA agrees that the affected airplanes are not registered in the United States. The Costs of Compliance section of the final rule has been changed accordingly.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, and any other changes described previously, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 14 CFR Part 51

Transport Canada AD CF–2023–08 specifies procedures for removing the affected connector, installing a new connector, and testing the EPSUs. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

Currently, there are no affected U.S.-registered airplanes. If an affected airplane is imported and placed on the

U.S. Register in the future, the FAA provides the following cost estimates to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product
3.5 work-hours × \$85 per hour = \$298	\$1,534	\$1,832

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024–03–09 Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.): Amendment 39–22679; Docket No. FAA–2023–1810; Project Identifier MCAI–2023–00267–T.

(a) Effective Date

This airworthiness directive (AD) is effective April 16, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Canada Limited Partnership (Type Certificate previously held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Model BD–500–1A11 airplanes, certificated in any category, as identified in Transport Canada AD CF–2023–08, dated February 13, 2023 (Transport Canada AD CF–2023–08).

(d) Subject

Air Transport Association (ATA) of America Code: 25, Equipment/furnishings.

(e) Unsafe Condition

This AD was prompted by a manufacturing molding issue with an electrical connector that may prevent the connector from self-locking. The FAA is issuing this AD to ensure the connector does not become loose over time and prevent the charging of emergency power supply units (EPSUs) 3 and 4. The unsafe condition, if not addressed, could result in loss of emergency lights, possibly resulting in injury to occupants during an evacuation.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Transport Canada AD CF–2023–08.

(h) Exception to Transport Canada AD CF–2023–08

Where Transport Canada AD CF–2023–08 refers to its effective date, this AD requires using the effective date of this AD.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the airplane to a location where the actions required by this AD can be accomplished, provided no passengers are onboard.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership’s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Additional Information

For more information about this AD, contact William Reisenauer, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email 9-avs-nyaco-cos@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF–2023–08, dated February 13, 2023.

(ii) [Reserved]

(3) For Transport Canada AD CF–2023–08, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email TC.AirworthinessDirectives-Consignesde navigabilite.TC@tc.gc.ca; website tc.canada.ca/en/aviation.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on March 5, 2024.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024–05193 Filed 3–11–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

U.S. Customs and Border Protection

DEPARTMENT OF THE TREASURY

19 CFR Part 12

[CBP Dec. 24–06]

RIN 1515–AE86

Extension of Import Restrictions Imposed on Archaeological and Ecclesiastical Ethnological Material From Honduras

AGENCY: U.S. Customs and Border Protection, Department of Homeland Security; Department of the Treasury.

ACTION: Final rule.

SUMMARY: This document amends the U.S. Customs and Border Protection (CBP) regulations to extend import restrictions on certain archaeological and ecclesiastical ethnological material from Honduras. The Assistant Secretary for Educational and Cultural Affairs, United States Department of State, has made the requisite determinations for extending the import restrictions, which were originally imposed by CBP Decision (CBP Dec.) 04–08 and last extended by CBP Dec. 19–03. The United States and Honduras have also agreed to extend the restrictions for an additional five-year period. Accordingly, these import restrictions will remain in effect for an additional five years, and the CBP regulations are being amended to reflect this further extension through March 12, 2029.

DATES: Effective March 12, 2024.

FOR FURTHER INFORMATION CONTACT: For legal aspects, W. Richmond Beevers, Chief, Cargo Security, Carriers and Restricted Merchandise Branch, Regulations and Rulings, Office of Trade, (202) 325–0084, ot-otrrculturalproperty@cbp.dhs.gov. For operational aspects, Julie L. Stoeber, Chief, 1USG Branch, Trade Policy and Programs, Office of Trade, (202) 945–7064, 1USGBranch@cbp.dhs.gov.

SUPPLEMENTARY INFORMATION:

Background

The Convention on Cultural Property Implementation Act (Pub. L. 97–446, 19 U.S.C. 2601 *et seq.*) (CPIA), which implements the 1970 United Nations Educational, Scientific and Cultural Organization (UNESCO) Convention on the Means of Prohibiting and Preventing the Illicit Import, Export and Transfer of Ownership of Cultural Property (823 U.N.T.S. 231 (1972)) (the Convention), allows for the conclusion of an agreement between the United States and another party to the Convention to impose import restrictions on eligible archaeological and ethnological materials. Under the CPIA and the applicable U.S. Customs and Border Protection (CBP) regulations, found in §§ 12.104 through 12.104i of title 19 of the Code of Federal Regulations (19 CFR 12.104 through 12.104i), the restrictions are effective for no more than five years beginning on the date on which an agreement enters into force with respect to the United States (19 U.S.C. 2602(b)). This period may be extended for additional periods, each extension not to exceed five years, if it is determined that the factors justifying the initial agreement still pertain and no cause for suspension of the agreement exists (19 U.S.C. 2602(e); 19 CFR 12.104g(a)).

On March 12, 2004, the United States entered into a bilateral agreement with the Republic of Honduras (Honduras) to impose import restrictions on certain archaeological material representing the Pre-Columbian cultures of Honduras and ranging in date from approximately 1200 B.C. to 1500 A.D. On March 16, 2004, CBP published a final rule (CBP Dec. 04–08) in the **Federal Register** (69 FR 12267), which amended 19 CFR 12.104g(a) to reflect the imposition of these restrictions, and included a list designating the types of archaeological materials covered by the restrictions.

The import restrictions were subsequently extended three times in accordance with 19 U.S.C. 2602(e) and 19 CFR 12.104g(a), and the designated list was amended once. On March 11, 2009, CBP published a final rule (CBP

Dec. 09–05) in the **Federal Register** (74 FR 10482), which amended § 12.104g(a) to reflect the extension of these import restrictions for an additional five years. On March 12, 2014, CBP published a final rule (CBP Dec. 14–03) in the **Federal Register** (79 FR 13873), which amended § 12.104g(a) to reflect the extension of these import restrictions for an additional five years as well as amending the Designated List to add restrictions on ecclesiastical ethnological material dating to the Colonial period of Honduras, c. A.D. 1502 to 1821.

Subsequently, on March 5, 2019, the United States and Honduras entered into a superseding memorandum of understanding (MOU), that extended the import restrictions for an additional five years. On March 12, 2019, CBP published a final rule (CBP Dec. 19–03) in the **Federal Register** (84 FR 8807), which amended § 12.104g(a) to reflect the extension of these import restrictions for an additional five years. These import restrictions are due to expire on March 12, 2024.

On August 8, 2023, the United States Department of State proposed in the **Federal Register** (88 FR 53576) to extend the MOU. On January 24, 2024, after considering the views and recommendations of the Cultural Property Advisory Committee, the Assistant Secretary for Educational and Cultural Affairs, United States Department of State, made the necessary determinations to extend the import restrictions for an additional five years. Following an exchange of diplomatic notes, the United States Department of State and the Government of the Republic of Honduras have agreed to extend the restrictions for an additional five-year period, through March 12, 2029.

Accordingly, CBP is amending 19 CFR 12.104g(a) to reflect the extension of these import restrictions. The restrictions on the importation of archaeological and ecclesiastical ethnological material from Honduras will continue in effect through March 12, 2029. Importation of such material from Honduras continues to be restricted through that date unless the conditions set forth in 19 U.S.C. 2606 and 19 CFR 12.104c are met.

The Designated List and additional information may also be found at the following website address: <https://eca.state.gov/cultural-heritage-center/cultural-property/current-agreements-and-import-restrictions> by selecting the material for “Honduras.”