

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2024–04–05 Leonardo S.p.a.:** Amendment 39–22684; Docket No. FAA 2023–2231; Project Identifier MCAI–2022–01623–R.

#### (a) Effective Date

This airworthiness directive (AD) is effective April 19, 2024.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Leonardo S.p.a. Model AB412 and AB412 EP helicopters, certificated in any category.

#### (d) Subject

Joint Aircraft Service Component (JASC) Code: 6320, Main Rotor Gearbox.

### (e) Unsafe Condition

This AD was prompted by reports of cracks in the lateral mounts of the main transmission support case. The FAA is issuing this AD to detect and address cracking of the main transmission support case. The unsafe condition, if not addressed, could result in the loss of load carrying capabilities of the main transmission and subsequent loss of control of the helicopter.

### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0258, dated December 20, 2022 (EASA AD 2022–0258).

### (h) Exceptions to EASA AD 2022–0258

(1) Where EASA AD 2022–0258 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where the service information referenced in EASA AD 2022–0258 specifies contacting Product Support Engineering for possible repairs regarding corrosion or pitting in a case bushing that exceeds allowable limits, this AD requires repair done in accordance with a method approved by the Manager, International Validation Branch, FAA; or EASA; or Leonardo S.p.a. Helicopters’ EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Where paragraphs (3) and (4) of EASA AD 2022–0258 require replacing a component, this AD requires removing the component from service.

(4) Where paragraph (5) of EASA AD 2022–0258 requires replacing the main transmission support case, this AD requires removing the main transmission support case assembly from service.

(5) Where paragraph (2) of EASA AD 2022–0258 requires accomplishing a fluorescent penetrant inspection (FPI) of the main transmission support case, this AD requires that FPI be accomplished by a Level II or Level III inspector certified in the FAA-acceptable standards for nondestructive inspection personnel.

**Note 1 to paragraph (h)(5):** Advisory Circular 65–31B contains examples of FAA-acceptable Level II and Level III qualification standards criteria for inspection personnel doing nondestructive test inspections.

(6) This AD does not adopt the “Remarks” section of EASA AD 2022–0258.

### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly

to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

### (j) Related Information

For more information about this AD, contact Sungmo Cho, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (781) 238–7241; email: [sungmo.d.cho@faa.gov](mailto:sungmo.d.cho@faa.gov).

### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022–0258, dated December 20, 2022.

(ii) [Reserved]

(3) For EASA AD 2022–0258, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone +49 221 8999 000; email [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find the EASA material on the EASA website [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222 5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on February 16, 2024.

### Victor Wicklund,

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2024–05478 Filed 3–14–24; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 39

[Docket No. FAA–2023–2148; Project Identifier MCAI–2022–00706–R; Amendment 39–22680; AD 2024–04–01]

RIN 2120–AA64

### Airworthiness Directives; Airbus Helicopters Deutschland GmbH (AHD) Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters. This AD was prompted by the determination that Instrument Flight Rules (IFR) screens obstruct the pilot's view. This AD requires removing certain part-numbered IFR screens, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective April 19, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 19, 2024.

**ADDRESSES:**

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-2148; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

*Material Incorporated by Reference:*

- For EASA material identified in this final rule, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email: [ADS@easa.europa.eu](mailto:ADS@easa.europa.eu); website: [easa.europa.eu](https://easa.europa.eu). You may find the EASA material on the EASA website [ad.easa.europa.eu](https://ad.easa.europa.eu).

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-2148.

*Other Related Service Information:* For Airbus Helicopters service information identified in this final rule, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or website [airbus.com/en/products-services/helicopters/hcare-services/airbusworld](https://airbus.com/en/products-services/helicopters/hcare-services/airbusworld). You may also view this service

information at the FAA contact information under *Material Incorporated by Reference* above.

**FOR FURTHER INFORMATION CONTACT:** Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342-1080; email [william.mccully@faa.gov](mailto:william.mccully@faa.gov).

**SUPPLEMENTARY INFORMATION:****Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0097, dated June 1, 2022 (EASA AD 2022-0097), to correct an unsafe condition on Airbus Helicopters Deutschland GmbH Model EC135 P1, EC135 P2, EC135 P2+, EC135 P3, EC135 T1, EC135 T2, EC135 T2+, EC135 T3, EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, EC635 T3, MBB-BK117 C-2, MBB-BK117 D-2, MBB-BK117 D-3, and MBB-BK117 D-3m helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters. The NPRM published in the **Federal Register** on November 13, 2023 (88 FR 77536). The NPRM was prompted by the determination that IFR screens obstruct the pilot's views. These IFR screens may be used for IFR training. According to Airbus Helicopters, the IFR screens obstruct the pilot's view to the front and to the right. The NPRM proposed to require removing certain part-numbered IFR screens, as specified in EASA AD 2022-0097.

The FAA is issuing this AD to address the obstructed views, which could lead to reduced situational awareness of the pilot and subsequent mid-air collision. See EASA AD 2022-0097 for additional background information.

**Discussion of Final Airworthiness Directive****Comments**

The FAA received no comments on the NPRM or on the determination of the costs.

**Conclusion**

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition

described in its AD. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. This AD is adopted as proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

EASA AD 2022-0097 requires removing certain part-numbered IFR screens and prohibits installing them on any helicopter.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Other Related Service Information**

The FAA also reviewed Airbus Helicopters Alert Service Bulletin (ASB) EC135-25A-033, ASB EC135H-25A-007, ASB MBB-BK117 C-2-25A-022, and ASB MBB-BK117 D-2-25A-023, each Revision 0 and dated May 23, 2022, which specify procedures for removing the lower, pilot door, and upper IFR screens from the helicopter. This service information also specifies that the lower, pilot door, and upper IFR screens must not be installed on a helicopter and the respective maintenance manual task is invalid and must no longer be used.

**Differences Between This AD and the EASA AD**

EASA AD 2022-0097 applies to Model EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, EC635 T3, and MBB-BK117 D-3m helicopters, whereas this AD does not because those model helicopters are not FAA type-certificated and are not included on the U.S. type certificate data sheet except where the U.S. type certificate data sheet explains that the Model EC635T2+ helicopter having serial number 0858 was converted from Model EC635T2+ to Model EC135T2+.

**Costs of Compliance**

The FAA estimates that this AD affects 573 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

Removing the IFR screens takes approximately 0.5 work-hour for an estimated cost of \$43 per helicopter and up to \$24,639 for the U.S. fleet.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

#### 2024-04-01 Airbus Helicopters

**Deutschland GmbH (AHD):** Amendment 39-22680; Docket No. FAA-2023-2148; Project Identifier MCAI-2022-00706-R.

#### (a) Effective Date

This airworthiness directive (AD) is effective April 19, 2024.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Airbus Helicopters Deutschland GmbH (AHD) Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, EC135T3, MBB-BK 117 C-2, MBB-BK 117 D-2, and MBB-BK 117 D-3 helicopters, certificated in any category.

**Note 1 to paragraph (c):** Helicopters with an EC135P3H designation are Model EC135P3 helicopters, helicopters with an EC135T3H designation are Model EC135T3 helicopters, and helicopters with an MBB-BK117 C-2e designation are Model MBB-BK117 C-2 helicopters.

#### (d) Subject

Joint Aircraft Service Component (JASC) Code: 2500, Cabin Equipment/Furnishings.

#### (e) Unsafe Condition

This AD was prompted by the determination that Instrument Flight Rules (IFR) screens obstruct the pilot's views. The FAA is issuing this AD to address the obstructed views caused by the IFR screens. The unsafe condition, if not addressed, could result in reduced situational awareness of the pilot and subsequent mid-air collision.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022-0097, dated June 1, 2022 (EASA AD 2022-0097).

#### (h) Exceptions to EASA AD 2022-0097

(1) Where EASA AD 2022-0097 refers to its effective date, this AD requires using the effective date of this AD.

(2) This AD does not adopt the "Remarks" section of EASA AD 2022-0097.

#### (i) No Reporting Requirement

Although the service information referenced in EASA AD 2022-0097 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD.

Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (k) Related Information

For more information about this AD, contact Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (303) 342-1080; email [william.mccully@faa.gov](mailto:william.mccully@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022-0097, dated June 1, 2022.

(ii) [Reserved]

(3) For EASA AD 2022-0097, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); website [easa.europa.eu](http://easa.europa.eu). You may find the EASA material on the EASA website [ad.easa.europa.eu](http://ad.easa.europa.eu).

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on February 12, 2024.

#### Victor Wicklund,

*Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2024-05475 Filed 3-14-24; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2023-1801; Airspace Docket No. 23-AAL-33]

RIN 2120-AA66

#### Modification of Class E Airspace; Klawock Airport, Klawock, AK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies the Class E airspace extending upward from 700 feet above the surface and removes the