Corrections

Federal Register

Vol. 70, No. 21

Wednesday, February 2, 2005

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2004–CE–01–AD; Amendment 39–13943; AD 2005–01–18]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company Beech 100, 200, and 300 Series Airplanes

Correction

In rule document 05–716 beginning on page 2941 in the issue of Wednesday, January 19, 2005 make the following correction:

§39.13 [Corrected]

On page 2942, in the third column, § 39.13(c), the table should appear as follows:

Model	Serial Nos.	
(1) A100–1 (U–21J)	BB-3 through BB-5	

	Model	Serial Nos.	Model	Serial Nos.
ıle, are	(2) 200 and B200	BB–2 and BB–6 through BB–1462.	(21) B200CT	FG-1 and FG-2. FA-1 through FA-
e n	(3) A200 (C–12A) and A200 (C–12C).	BC-1 through BC-75 and BD-1 through BD-30.	(23) 300	228. FF–1 through FF–19.
	(4) A200C (UC–12B) (5) A200CT (C–12D).	BJ–1 through BJ–66. BP–1, BP–22, and	(24) B300	FL-1 through FL- 103.
	(5) A200C1 (C-12D).	BP-1, BP-22, and BP-24 through BP-51.	(25) B300C (26) B300C	FM–1 through FM–8. FN–1.
ON	(6) A200CT (FWC– 12D).	BP-7 through BP-11.	FR Doc. C5–716 Filed 2–1–05; 8:45 am] BILLING CODE 1505–01–D	
	(7) A200CT (RC– 12D).	GR–1 through GR– 13.		
	(8) A200CT (C-12F)	BP–52 through BP– 63.	DEPARTMENT OF 1	BANSPORTATION
ent	(9) A200CT (RC– 12G).	FC-1 and FC-3.	Federal Aviation Administration	
	(10) A200CT (RC– 12H).	GR–14 through GR– 19.		
	(11) A200CT (RC– 12K).	FE-1 through FE-9.	Notice of Intent To Rule on Application 05–04–C–00–SAT To Impose and Use	
ind	(12) A200CT (RC– 12P).	FE–10 through FE– 24.	the Revenue From a Passenger Facility Charge (PFC) at San Antonio	
	(13) Á200CT (RC– 12K).	FE–25 through FE– 31.	International Airport, San Antonio, TX	
ıg	(14) 200C and B200C	BL-1 through BL-72 and BL-124	Correction	
day,	(15) 200CT and B200CT.	through BL–138. BN–1 through BN–4.	In notice document 05–123 beginning on page 936 in the issue of Wednesday,	
	(16) 200T and B200T (17) B200C (C–12F)	BT–1 through BT–38. BL–73 through BL–	January 5, 2005, mal correction:	ke the following
, §	(, 52000 (0 121)	112 and BL–118 through BL–123.	On page 936, in th under the heading ''	
	(18) B200C (C-12F)	BP–64 through BP– 71.	second line, ''Januar read ''February 4, 20	y 4, 2005'' should
	(19) B200C (UC–12F) (20) B200C (UC–	BU–1 through BU–10. BV–1 through BV–12.	[FR Doc. C5–123 Filed 2–1–05; 8:45 am]	
-5	12M).	-	BILLING CODE 1505-01-D	