

**DATES:** Comments on petitions received must identify the petition docket number involved and must be received on or before October 24, 2006.

**ADDRESSES:** You may submit comments [identified by DOT DMS Docket Number FAA-2006-25049] by any of the following methods:

- *Web site:* <http://dms.dot.gov>.

Follow the instructions for submitting comments on the DOT electronic docket site.

- *Fax:* 1-202-493-2251.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

*Docket:* For access to the docket to read background documents or comments received, go to <http://dms.dot.gov> at any time or to Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

**FOR FURTHER INFORMATION CONTACT:** Tim Adams (202) 267-8033, Sandy Buchanan-Sumter (202) 267-7271, or John Linsenmeyer (202) 267-5174, Office of Rulemaking (ARM-1), Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591. This notice is published pursuant to 14 CFR 11.85 and 11.91.

Issued in Washington, DC, on September 22, 2006.

**Brenda D. Courtney,**

*Acting Director, Office of Rulemaking.*

### Petitions for Exemption

*Docket No.:* FAA-2006-25049.

*Petitioner:* American Airlines, Inc.

*Section of 14 CFR Affected:* 14 CFR 121.619

*Description of Relief Sought:*

To permit American Airlines, Inc. (American), its certificated dispatchers, and its pilots in command to dispatch flights to domestic airports at which for at least 1 hour before and 1 hour after the estimated time of arrival at the destination airport the appropriate weather reports or forecasts, or any combination of them, indicate the ceiling may be reduced from at least 2,000 feet to 1,000 feet above the airport elevation and visibility may be increased from at least 2 miles to 3 miles. If this exemption is granted,

American will maintain at least a Category I approach authorization and the intended destination airport must have at least one operational Category I Instrument Landing System.

[FR Doc. E6-16389 Filed 10-3-06; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Motor Carrier Safety Administration

#### Sunshine Act Meetings; Unified Carrier Registration Plan Board of Directors

**AGENCY:** Federal Motor Carrier Safety Administration, DOT.

**TIME AND DATE:** October 11, 2006, 8:30 a.m. to 5 p.m.

**PLACE:** Holiday Inn Capitol, 550 C Street, SW., Washington, DC 20024.

**STATUS:** Open to the public.

**MATTERS TO BE CONSIDERED:** An overview of the Unified Carrier Registration Plan and Agreement requirements set forth under section 4305 of the Safe, Accountable, Flexible, Efficient Transportation Equity Act: A Legacy for Users, and the administrative functioning of the Board. In addition, the Board will continue its work in developing the Unified Carrier Registration Agreement procedures and toward recommending UCRA fees to the Secretary.

**FOR FURTHER INFORMATION CONTACT:** Ms. Shannon L. Watson, (202) 366-0702, Office of Safety Programs, Federal Motor Carrier Safety Administration, or Mr. Bryan Price, (412) 395-4816, FMCSA Pennsylvania Division Office.

Dated: October 2, 2006.

**John H. Hill,**

*Administrator.*

[FR Doc. 06-8514 Filed 10-2-06; 2:13 pm]

**BILLING CODE 4910-EX-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-2006-25975; Notice 1]

#### American Honda Motor Co., Inc., Receipt of Petition for Decision of Inconsequential Noncompliance

American Honda Motor Co., Inc. (Honda) has determined that the certification labels for certain Pilot trucks that it produced in 2006 do not comply with S5.3 of 49 CFR 571.120, Federal Motor Vehicle Safety Standard (FMVSS) No. 120, "Tire selection and rims for motor vehicles other than

passenger cars." Honda has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Pursuant to 49 U.S.C. 30118(d) and 30120(h), Honda has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of Honda's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

Affected are a total of approximately 23,000 model year 2006 and 2007 Honda Pilot trucks produced between February 17, 2006 and August 10, 2006. S5.3.2 of FMVSS No. 120 requires that the vehicles shall show the size designation appropriate for the tires. The noncompliant vehicles have certification labels stating that the rim size is 6 inches, when in fact the rim size is 16 inches. Honda has corrected the problem that caused these errors so that they will not be repeated in future production.

Honda believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. Honda presents the following basis for its petition:

First, most vehicle owners, dealers, and tire service technicians would refer to the vehicles' existing tires and/or the separate Tire Placard to determine the appropriate size for a replacement tire rather than to the Certification Label. Second, if the vehicle owner, dealer or tire service technician read the incorrect rim size on the Certification Label, it would be obvious that a full size vehicle could not use 6 inch wheels. Third, the tire size is listed correctly on the Certification Label. Fourth, the owner's manual contains the correct rim size information. Fifth, the correct rim size is cast into the wheel itself.

Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited at the beginning of this notice and be submitted by any of the following methods. *Mail:* Docket Management Facility, U.S. Department of Transportation, Nassif Building, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590-0001. *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC. It is requested, but not required, that two copies of the comments be provided. The Docket Section is open on