

accordance with Bombardier Repair Drawing (RD) 8/4-32-059, Issue 4, dated September 14, 2007.

Note 2: Bombardier Repair Drawing 8/4-32-059 refers to Goodrich Service Concession Request SCR 086-07, Revision C, dated September 14, 2007 (specifically item 14), as an additional source of service information for adjusting the retracted length of the rod end, torquing the jam nut, installing a wire lock, and lubricating the piston if necessary, as required by paragraph (g) of this AD.

Detailed Inspection of the Retract Actuator of the MLG

(h) For airplanes on which the retract actuator of the MLG, part number 46550-7 or 46550-9, has accumulated 8,000 or more total landings or has been in-service 4 or more years since new as of the effective date of this AD: Before further flight, do a detailed inspection of affected parts for any signs of corrosion or wear, and applicable related investigative and corrective actions, in accordance with Bombardier Repair Drawing 8/4-32-059, Issue 4, dated September 14, 2007.

Note 3: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

(i) For airplanes other than those identified in paragraph (h) of this AD with a retract actuator of the MLG, part number 46550-7 or 46550-9: Do a detailed inspection of affected parts for any signs of corrosion or wear, and applicable related investigative and corrective actions, in accordance with Bombardier RD 8/4-32-059, Issue 4, dated September 14, 2007; at the later of the times specified in paragraphs (i)(1) and (i)(2) of this AD.

(1) Before the accumulation of 4,000 total landings or 2 years since new, whichever occurs first.

(2) Within 500 flight hours after the effective date of this AD.

Note 4: Bombardier Repair Drawing 8/4-32-059 refers to Goodrich Service Concession Request SCR 086-07, Revision C, dated September 14, 2007, as an additional source of service information for accomplishing the applicable related investigative and corrective actions required by paragraphs (h) and (i) of this AD.

Actions Done in Accordance with Previous Issues of Service Information

(j) Actions done before the effective date of this AD in accordance with Bombardier Repair Drawing 8/4-32-059, Issue 1, dated September 12, 2007; Issue 2, dated September 13, 2007; or Issue 3, dated September 13, 2007; are acceptable for compliance with the corresponding actions specified in paragraphs (g) through (i) of this AD.

Reporting Requirement

(k) Submit a report of any discrepancy found during any inspection required by this AD to the Bombardier Technical Help Desk, at the applicable time specified in paragraph (k)(1) or (k)(2) of this AD; telephone (416) 375-4000; fax (416) 375-4539; e-mail: thd.qseries@aero.bombardier.com. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) If the inspection was done after the effective date of this AD: Submit the report within 7 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 7 days after the effective date of this AD.

Special Flight Permit

(l) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be inspected (if the operator elects to do so), provided that the procedures and limitations in paragraphs (l)(1) and (l)(2) of this AD are adhered to.

(1) *Flight Crew Limitations and Procedures:*

(i) Ferry flight with gear extended and pinned.

(ii) Landing to be conducted at a minimum descent rate.

(iii) Minimize braking on landing.

(iv) Flight to be conducted in accordance with Section 4.8 of the Aircraft Operating Manual (AOM).

(v) Essential crew only on board.

(vi) Flight in known or forecast icing condition is prohibited.

(2) *Maintenance Procedures:*

(i) Do the general visual inspection required by paragraph (g) of this AD.

(ii) Do the general visual inspections of the stabilizer stay and the hinge points of the MLG for general condition and security, in accordance with Bombardier Q400 All Operator Message 236A, dated September 11, 2007.

(iii) If no discrepancy is detected during the inspections required by paragraph (l)(2)(i) and (l)(2)(ii) of this AD, before further flight, insert the ground lock pins and a wire lock of the MLG in place.

(iv) Ensure the ground lock of the nose landing gear is engaged.

Alternative Methods of Compliance (AMOCs)

(m)(1) The Manager, New York ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(n) Canadian airworthiness directive CF-2007-20, dated September 12, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(o) You must use Bombardier Repair Drawing 8/4-32-059, Issue 4, dated September 14, 2007, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-21178 Filed 10-29-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2007-0023; Airspace Docket No. 07-AEA-08]

Establishment of Class E Airspace; Muncy, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule, request for comments.

SUMMARY: This action establishes Class E Airspace at Muncy, PA, to provide adequate airspace for a new Area Navigation (RNAV) Global Positioning System (GPS) Special Instrument Approach Procedure (IAP) that has been developed to serve the Muncy Valley Hospital (7PS5), Muncy, PA.

DATES: Effective 0901 UTC, December 20, 2007. The Director of the **Federal Register** approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments. Comments for inclusion in the Rules Docket must be received on or before November 28, 2007.

ADDRESSES: Send comments on this rule to: Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket No. FAA-2007-0023; Airspace Docket No. 07-AEA-08, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the rule, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room C210, 1701 Columbia Avenue, College Park, Georgia 30337.

FOR FURTHER INFORMATION CONTACT:

Daryl Daniels, Airspace Specialist, System Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5581.

SUPPLEMENTARY INFORMATION:

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or negative comments, and, therefore, issues it as a direct final rule. The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Unless a written adverse or negative comment or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the effective date. If the FAA receives, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify both docket numbers and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action would be needed. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. Those wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2007-0023; Airspace Docket No. 07-AEA-08." The postcard will be date stamped and returned to the commenter.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 amends Class E airspace at Muncy, PA establishing the required controlled airspace to support the new RNAV (GSP) helicopter Point in Space (PinS) approach at Muncy Valley Hospital. A new Copter RNAV (GPS) 240 Point in Space (PinS) Special IAP serving the Muncy valley Hospital has been developed. Controlled airspace extending upward from 700 feet Above Ground Level (AGL) is required to contain the IAP and for Instrument Flight Rule (IFR) operations to the extent practical, therefore, the FAA is amending Title 14, Code of Federal Regulations (14 CFR) part 71 to establish Class E5 Airspace at Muncy, PA. The controlled airspace around Muncy does not adequately encompass the airspace needed for this new approach. This action provides that required controlled airspace. Designations for Class E airspace areas extending upward from 700 feet or more above the surface of the

Earth are published in FAA Order 7400.9R, signed August 15, 2007 effective September 15, 2007, which is incorporated by reference in 14 CFR 71.1. The Class E designations listed in this document will be published subsequently in the Order.

Agency Findings

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart 1, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Muncy Valley Hospital, Muncy, PA.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9R, Airspace Designations and Reporting Points, effective September 15, 2007, is amended as follows:

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.

* * * * *

AEA PA E5 Muncy, PA [New]

Muncy Valley Hospital, PA
Point in Space Coordinates

(Lat. 41°13'05" N., long. 76°45'46" W.)

That airspace within a 6-mile radius of the point in space (lat. 41°13'05" N., long. 76°45'46" W.) serving the Muncy Valley Hospital.

* * * * *

Issued in College Park, Georgia, on October 5, 2007.

Mark D. Ward,

Manager, System Support Group, Eastern Service Center.

[FR Doc. 07–5324 Filed 10–29–07; 8:45 am]

BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2007–29375; Airspace Docket No. 07–AEA–06]

Amendment of Class E Airspace; State College, PA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule, request for comments.

SUMMARY: This action amends Class E Airspace at State College, PA to provide adequate airspace for a new Area Navigation (RNAV) Global Positioning System (GPS) Special Instrument Approach Procedure (IAP) that has been

developed to serve the Centre Community Hospital (PS57), State College, PA.

DATES: Effective 0901 UTC, December 20, 2007. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments. Comments for inclusion in the Rules Docket must be received on or before November 28, 2007.

ADDRESSES: Send comments on this rule to Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey, SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001; Telephone: 1–800–647–5527; Fax: 202–493–2251. You must identify the Docket No. FAA–2007–29375; Airspace Docket No. 07–AEA–06, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the rule, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room C210, 1701 Columbia Avenue, College Park, Georgia 30337.

FOR FURTHER INFORMATION CONTACT: Daryl Daniels, Airspace Specialist, System Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–5581.

SUPPLEMENTARY INFORMATION:**The Direct Final Rule Procedure**

The FAA anticipates that this regulation will not result in adverse or negative comments, and, therefore, issues it as a direct final rule. The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Unless a written adverse or negative comment or a written notice of intent to submit and adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative

comments were received and confirming the effective date. If the FAA receives, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify both docket numbers and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action would be needed. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA–2007–29375; Airspace Docket No. 07–AEA–06." The postcard will be date stamped and returned to the commenter.

The Rule

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 amends Class E airspace at State College, PA establishing the additionally required controlled airspace to support the new RNAV helicopter Point in Space (PinS) approach at Centre Community Hospital. A new Copter RNAV (GPS) 234 Point in Space (PinS) Special IAP serving the Centre Community Hospital has been developed. Controlled airspace extending upward from 700 feet Above Ground Level (AGL) is required to encompass the IAP and for Instrument Flight Rule (IFR) operations, therefore,