

comment on the proposed requirements of that NPRM.

DATES: We must receive comments on this proposed AD by December 20, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2797; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: We proposed to amend 14 CFR part 39 with a notice of proposed rulemaking (NPRM) for an AD for certain Airbus Model A330 airplanes and A340-200 and -300 series airplanes. The NPRM was published in the **Federal Register** on September 28, 2007 (72 FR 55108). The NPRM proposed to require the inspection of the fuselage to identify possible permanent skin repairs and permanent longitudinal lap joint repairs and to apply the associated corrective actions. The NPRM action invites comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD.

Actions Since NPRM was Issued

Since we issued the NPRM, the DOT's Docket Management System (DMS) was replaced by the Federal Docket Management System (FDMS). FDMS is a government-wide, electronic docket management system, which contains the public dockets and is the method used for submitting comments on the overall regulatory, economic, environmental, and energy aspects of proposed rulemaking actions. However, due to the service disruption caused by the transition from DOT's DMS to the FDMS, the docket material was not posted on the FDMS until November 1, 2007. Therefore, we have determined that the public was not provided adequate opportunity to submit comments on the NPRM. As a result, we have decided to reopen the comment period for 30 days to receive additional comments.

No part of the regulatory information has been changed; therefore, the NPRM is not republished in the **Federal Register**.

Comments Due Date

We must receive comments on this AD action by December 20, 2007.

Issued in Renton, Washington, on November 8, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-22632 Filed 11-19-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-29337; Directorate Identifier 2007-NM-150-AD]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Model Avro 146-RJ Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: This document announces a reopening of the comment period for the above-referenced NPRM. The NPRM proposed the adoption of a new airworthiness directive for all BAE Systems (Operations) Limited Model BAe 146 and Model Avro 146-RJ airplanes. That NPRM invites comments

concerning the proposed requirements for repetitive detailed visual inspections for corrosion, pitted fasteners, or pillowing of the APU heat shield and surrounding skin and, if applicable, removal of the heat shield and repair. This reopening of the comment period is necessary to provide additional opportunity for public comment on the proposed requirements of that NPRM.

DATES: We must receive comments on this proposed AD by December 20, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: We proposed to amend 14 CFR part 39 with a notice of proposed rulemaking (NPRM) for an AD for all BAE Systems (Operations) Limited Model BAe 146 and Model Avro 146-RJ airplanes. The NPRM was published in the **Federal Register** on September 28, 2007 (72 FR 55122). The NPRM proposed to require

repetitive detailed visual inspections for corrosion, pitted fasteners, or pillowing of the APU heat shield and surrounding skin and, if applicable, removal of the heat shield and repair. The NPRM action invites comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD.

Actions Since NPRM Was Issued

Since we issued the NPRM, the DOT's Docket Management System (DMS) was replaced by the Federal Docket Management System (FDMS). FDMS is a government-wide, electronic docket management system, which contains the public dockets and is the method used for submitting comments on the overall regulatory, economic, environmental, and energy aspects of proposed rulemaking actions. However, due to the service disruption caused by the transition from DOT's DMS to the FDMS, the docket material was not posted on the FDMS until November 1, 2007. Therefore, we have determined that the public was not provided adequate opportunity to submit comments on the NPRM. As a result, we have decided to reopen the comment period for 30 days to receive additional comments.

No part of the regulatory information has been changed; therefore, the NPRM is not republished in the **Federal Register**.

Comments Due Date

We must receive comments on this AD action by December 20, 2007.

Issued in Renton, Washington, on November 8, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-22631 Filed 11-19-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-29331; Directorate Identifier 2007-NM-136-AD]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB-Fairchild SF340A (SAAB/SF340A) and SAAB 340B Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: This document announces a reopening of the comment period for the above-referenced NPRM. The NPRM proposed the adoption of a new airworthiness directive for certain Saab Model SAAB-Fairchild SF340A (SAAB/SF340A) and SAAB 340B airplanes. That NPRM invited comments concerning the proposed requirements for doing repetitive ultrasonic inspections to detect cracking in the axle adaptor, replacing the axle adaptor if necessary, and ultimately doing the terminating action of inspecting and modifying the main landing gear shock strut and axle adaptors. This reopening of the comment period is necessary to provide additional opportunity for public comment on the proposed requirements of that NPRM.

DATES: We must receive comments on this proposed AD by December 20, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Mike Borfitz, Aerospace Engineer,

International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2677; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: We proposed to amend 14 CFR part 39 with a notice of proposed rulemaking (NPRM) for an AD for certain Saab Model SAAB-Fairchild SF340A (SAAB/SF340A) and SAAB 340B airplanes. The NPRM was published in the **Federal Register** on September 28, 2007 (72 FR 55116). The NPRM proposed to require doing repetitive ultrasonic inspections to detect cracking in the axle adaptor, replacing the axle adaptor if necessary, and ultimately doing the terminating action of inspecting and modifying the main landing gear shock strut and axle adaptors. The NPRM action invites comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD.

Actions Since NPRM Was Issued

Since we issued the NPRM, the DOT's Docket Management System (DMS) was replaced by the Federal Docket Management System (FDMS). FDMS is a government-wide, electronic docket management system, which contains the public dockets and is the method used for submitting comments on the overall regulatory, economic, environmental, and energy aspects of proposed rulemaking actions. However, due to the service disruption caused by the transition from DOT's DMS to the FDMS, the docket material was not posted on the FDMS until November 1, 2007. Therefore, we have determined that the public was not provided adequate opportunity to submit comments on the NPRM. As a result, we have decided to reopen the comment period for 30 days to receive additional comments.

No part of the regulatory information has been changed; therefore, the NPRM is not republished in the **Federal Register**.

Comments Due Date

We must receive comments on this AD action by December 20, 2007.

Issued in Renton, Washington, on November 8, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-22630 Filed 11-19-07; 8:45 am]

BILLING CODE 4910-13-P