

---

# Corrections

Federal Register

Vol. 72, No. 231

Monday, December 3, 2007

---

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

---

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-0109; Directorate Identifier 2007-NM-235-AD]

RIN 2120-AA64

#### Airworthiness Directives; Lockheed Model 382, 382B, 382E, 382F, and 382G Series Airplanes

##### *Correction*

In proposed rule document 07-5595 beginning on page 64005 in the issue of

Wednesday, November 14, 2007, make the following corrections:

1. On page 64006, in the second column, under the "Development of the SSIP" heading, in the eighth line, "easement" should read "reassessment".

2. On page 64007, in the Estimated Costs table, in the third column, in the second entry, "80" should read "\$80".

#### **§ 39.13 [Corrected]**

3. On page 64008, in the first column, in § 39.13(g), in the second line, "incorpote" should read "incorporate".

[FR Doc. C7-5595 Filed 11-30-07; 8:45 am]

BILLING CODE 1505-01-D