

subsequent analysis showing that the shelf modification has not sufficiently addressed failure of an ADIRU. We are issuing this AD to prevent failure of an ADIRU during flight, which could result in loss of one source of critical attitude and airspeed data and reduce the ability of the flightcrew to control the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2003–26–03

Modification

(f) For Model A319, A320, and A321 series airplanes, equipped with any Litton ADIRU installed in accordance with Airbus Modification 24852, 25108, 25336, 26002, or 28218: Within 2 years after January 27, 2004 (the effective date of AD 2003–26–03), do the modifications specified in paragraphs (f)(1), (f)(2), and (f)(3) of this AD, as applicable, in accordance with paragraphs A. through D. of the Accomplishment Instructions of Airbus Service Bulletin A320–25–1248, dated February 16, 2001; or Airbus Service Bulletin A320–25–1248, Revision 01, dated April 16, 2003; as applicable.

(1) For all airplanes: Modify the shelf (floor panel) above ADIRU 3 by installing shims between the shelf and the webs of the shelf support structure.

(2) For airplanes with Airbus Modification 25900P3941 or Airbus Service Bulletin A320–25–1200 accomplished as of January 27, 2004: Modify the polycarbonate guard (umbrella) protecting the ADIRUs by installing shims between the guard and the shelf support structure.

(3) For airplanes with Airbus Modification 23027P2852 or Airbus Service Bulletin A320–52–1038 accomplished as of January 27, 2004: Modify the ladder located in the avionics compartment by machining the slot at the foot of the ladder to increase the depth by 0.236 inch.

New Requirements of This AD

Modification for Certain Airplanes

(g) For all airplanes equipped with any ADIRU installed in accordance with Airbus Modification 31070, 31742, or 35517, except airplanes on which Airbus Modification 30650 or 30872 has been accomplished in production: Within 46 months after the effective date of this AD, modify the ADIRU shelf supports by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Airbus Service Bulletin A320–25–1248, Revision 01, dated April 16, 2003.

Replacement of ADIRUs

(h) For all airplanes except those on which Airbus Modification 35517 has been incorporated in production: Within 46 months after the effective date of this AD, replace all three ADIRUs with improved ADIRUs having P/N 465020–0303–0316 in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–34–1350, dated March 20, 2006.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(j) European Aviation Safety Agency airworthiness directive 2007–0217, dated August 9, 2007, also addresses the subject of this AD.

Issued in Renton, Washington, on January 14, 2008.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. E8–1135 Filed 1–23–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Part 284

[Docket No. RM08–2–000]

Transparency Provision Under Section 23 of the Natural Gas Act

January 10, 2008.

AGENCY: Federal Energy Regulatory Commission, DOE.

ACTION: Notice of Technical Conference.

SUMMARY: The Federal Energy Regulatory Commission is holding a technical conference to address implementation issues associated with the Commission's posting proposal, such as obtaining and posting actual and scheduled flow information and obtaining and posting flow information from storage facilities, as set for in the Notice of Proposed Rulemaking issued December 21, 2007, in Commission Docket No. RM08–2–000.

DATES: The conference is to be held on February 28, 2008.

FOR FURTHER INFORMATION CONTACT: Saida E. Shaalan, Energy Information Analyst, Federal Energy Regulatory Commission, 888 First Street, NE., Washington, DC 20426, 202–502–8278, saida.shaalan@ferc.gov.

SUPPLEMENTARY INFORMATION:

Notice of Technical Conference

The staff of the Federal Energy Regulatory Commission (Commission) will hold a technical conference in the above-referenced proceeding on February 28, 2008, at the Federal Energy Regulatory Commission, 888 First Street, NE., Washington, DC 20426 in the Commission Meeting Room (2–C) from 9:30 a.m. until 3 p.m. (EST). The staff is holding this conference to address implementation issues associated with the posting proposal, such as obtaining and posting actual and scheduled flow information and obtaining and posting information from storage facilities. This is as set forth in the Notice of Proposed Rulemaking (NOPR), *Pipeline Posting Requirements under Section 23 of the Natural Gas Act*, 73 FR 1116 (January 7, 2008), FERC Stat. & Regs. ¶ 32,626 (2007).

People interested in speaking at the conference may send brief descriptions of the issues they would like to address to Saida Shaalan at Saida.Shaalan@FERC.gov.

This conference will not be Web-cast or transcribed. All interested persons are invited, and there is *no* registration fee to attend. Comments should be filed in Docket RM08–2–000, in accordance with the dates set in the rulemaking docket.

Commission conferences are accessible under section 508 of the Rehabilitation Act of 1973. For accessibility accommodations please send an e-mail to accessibility@ferc.gov or call toll free 1–866–208–3372 (voice) or 202–208–1659 (TTY), or send a FAX to 202–208–2106 with the required accommodations.

Questions about the conference should be directed to Saida Shaalan by e-mail at Saida.Shaalan@FERC.gov or by phone at 202–502–8278.

Kimberly D. Bose,

Secretary.

[FR Doc. E8–1152 Filed 1–23–08; 8:45 am]

BILLING CODE 6717–01–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG–107592–00; REG–105964–98]

RIN 1545–BA11; RIN 1545–AW30

Consolidated Returns; Intercompany Obligations; Hearing

AGENCY: Internal Revenue Service (IRS), Treasury.