**Note:** Approved lives in the table are in flight cycles

(2) Record the mandatory maximum approved life in the applicable lifing documentation. It is mandatory to use the values given in the two tables in step (e)(1) of this AD.

# Alternative Methods of Compliance (AMOCs)

(f) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

#### **Related Information**

(g) Refer to EASA Emergency Airworthiness Directive 2007–0152–E, dated June 1, 2007, for related information.

(h) Contact Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: *jason.yang@faa.gov*; telephone (781) 238–7747; fax (781) 238–7199, for more information about this AD.

Issued in Burlington, Massachusetts, on March 19, 2008.

#### Ann C. Mollica,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. E8–6866 Filed 4–2–08; 8:45 am] BILLING CODE 4910-13–P

### DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

## 14 CFR Part 71

[Docket FAA No. FAA–2008–0180; Airspace Docket No. 08–AAL–6]

## Proposed Revocation of Area Navigation Jet Routes J–888R and J–996R; Alaska

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM); correction.

**SUMMARY:** This action corrects a notice of proposed rulemaking (NPRM) published in the **Federal Register** March 12, 2008 (73 FR 13159), Airspace Docket No. 08–AAL–6, FAA Docket No. FAA– 2008–0111. In that rule, the FAA docket number is incorrect. The correct FAA docket number should state FAA–2008– 0180, instead of FAA–2008–0111. In addition, a typographical error to one Jet Route was made in the title. The title of the NPRM should reference Jet Route J– 888R, instead of J–889R. This action corrects those errors.

DATES: *Effective Date:* 0901 UTC, April 3, 2008.

**FOR FURTHER INFORMATION CONTACT:** Ken McElroy, Airspace and Rules Group, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–8783.

## SUPPLEMENTARY INFORMATION:

#### History

On March 12, 2008, an NPRM was published in the **Federal Register** for Airspace Docket No. 08–AAL–6, FAA Docket No. FAA–2008–0111 (73 FR 13159), revoking Area Navigation Jet Routes J–889R and J–996R in Alaska. Subsequent to publication, it was found that the FAA docket number was incorrect; the correct number is FAA– 2008–0180. In addition, the reference to one Area Navigation Jet Route was incorrectly stated in the title of the NPRM. The correct Jet Route should have stated J–888R, instead of J–889R. This action corrects those errors.

## **Correction to Final Rule**

Accordingly, pursuant to the authority delegated to me, the FAA docket number and the title of the NPRM as published in the **Federal Register** on March 12, 2008 (73 FR 13159), Airspace Docket No. 08–AAL–6, FAA Docket No. FAA–2008–0111, and incorporated by reference in 14 CFR 71.1, is corrected as follows:

### §71.1 [Amended]

On page 13159, correct the FAA docket number and the title to read as follows:

Docket No. FAA-2008-0180

Proposed Revocation of Area Navigation Jet Routes J–888R and J–996R; Alaska

Issued in Washington, DC, on March 27, 2008.

### Stephen L. Rohring,

Acting Manager, Airspace and Rules Group. [FR Doc. E8–6935 Filed 4–2–08; 8:45 am] BILLING CODE 4910–13–P

## DEPARTMENT OF HOMELAND SECURITY

# **Coast Guard**

# 33 CFR Part 165

[Docket No. USCG-2008-0162]

RIN 1625-AA00

# Safety Zone; Red Bull Air Race; San Diego Bay, San Diego, CA

**AGENCY:** Coast Guard, DHS. **ACTION:** Notice of proposed rulemaking.

**SUMMARY:** The Coast Guard proposes establishing a temporary safety zone on

the navigable waters of San Diego Bay, CA in support of the Red Bull Air Race. The safety zone would be necessary to provide for the safety of the crew, spectators, participants in the event, participating vessels and other vessels and users of the waterway. Persons and vessels would be prohibited from entering into, transiting through, or anchoring within this safety zone unless authorized by the Captain of the Port or his designated representative.

**DATES:** Comments and related material must reach the Coast Guard on or before April 11, 2008.

**ADDRESSES:** You may submit comments identified by Coast Guard docket number USCG–2008–0162 to the Docket Management Facility at the U.S. Department of Transportation. To avoid duplication, please use only one of the following methods:

(1) Online: http:// www.regulations.gov.

(2) *Mail:* Docket Management Facility (M–30), U.S. Department of Transportation, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590– 0001.

(3) *Hand delivery:* Room W12–140 on the Ground Floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202–366–9329.

(4) Fax: 202-493-2251.

FOR FURTHER INFORMATION CONTACT: If you have questions on this proposed rule, call Petty Officer Adam Proctor, Waterways Management Division, U.S. Coast Guard Sector San Diego, CA, at telephone (619) 278–7277. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202–366–9826. SUPPLEMENTARY INFORMATION:

# Public Participation and Request for Comments

We encourage you to participate in this rulemaking by submitting comments and related materials. All comments received will be posted, without change, to *http:// www.regulations.gov* and will include any personal information you have provided. We have an agreement with the Department of Transportation (DOT) to use the Docket Management Facility. Please see DOT's "Privacy Act" paragraph below.

#### **Submitting Comments**

If you submit a comment, please include the docket number for this