

**Replacement of Groups 2, 3, and 4 EECs**

(h) Replace the following groups of EECs with a serviceable EEC, or any EEC that does not violate the EEC installation procedure as provided by paragraphs (k), (l), and (m) of this AD, as follows:

(1) Group 2 EECs, before reaching 4,000 CIS since new, but not later than 2 years after the effective date of this AD.

(2) Group 3 EECs, before reaching 14,000 CIS since new, but not later than 6 years after the effective date of this AD.

**Definition of Serviceable EECs**

(i) A serviceable EEC is an EEC that does not violate the EEC installation procedure as provided by paragraphs (k), (l), and (m) of this AD, or is marked as Group 4 per P&W ASB No. PW4ENG 73-214, Revision 2, dated May 23, 2008, or has been repaired per P&W Service Bulletin (SB) No. PW4ENG 73-216, dated April 8, 2008. Once an EEC has been repaired, it is viewed as a Group 4 EEC.

(j) Information on obtaining a serviceable EEC can be found in P&W SB No. PW4ENG 73-216, dated April 8, 2008.

**EEC Installation Prohibition**

(k) Do not install any Group 1 EEC after 1 year from the effective date of this AD or any Group 1 EEC that has reached 2,000 CIS since new.

(l) Do not install any Group 2 EEC after 2 years from the effective date of this AD or any Group 2 EEC that has reached 4,000 CIS since new.

(m) Do not install any Group 3 EEC after 6 years from the effective date of this AD or any Group 3 EEC that has reached 14,000 CIS since new.

**Alternative Methods of Compliance**

(n) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

**Related Information**

(o) Contact V. Rose Len, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: [rose.len@faa.gov](mailto:rose.len@faa.gov); telephone (781) 238-7772; fax (781) 238-7199, for more information about this AD.

Issued in Burlington, Massachusetts, on August 8, 2008.

**Peter A. White,**

*Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. E8-18811 Filed 8-13-08; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF THE TREASURY****Internal Revenue Service****26 CFR Part 1**

[REG-103146-08]

RIN 1545-BH69

**Information Reporting Requirements Under Internal Revenue Code Section 6039; Correction**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Correction to notice of proposed rulemaking.

**SUMMARY:** This document contains corrections to a notice of proposed rulemaking (REG-103146-08) that was published in the *Federal Register* on Thursday, July 17, 2008 (73 FR 40999) relating to the return and information statement requirements under section 6039 of the Internal Revenue Code. These regulations reflect changes to section 6039 made by section 403 of the Tax Relief and Health Care Act of 2006. These proposed regulations affect corporations that issue statutory stock options and provide guidance to assist corporations in complying with the return and information statement requirements under section 6039.

**FOR FURTHER INFORMATION CONTACT:** Thomas Scholz, (202) 622-6030 (not a toll-free number).

**SUPPLEMENTARY INFORMATION:****Background**

The correction notice that is the subject of this document is under section 6039 of the Internal Revenue Code.

**Need for Correction**

As published, the notice of proposed rulemaking (REG-103146-08) contains errors that may prove to be misleading and are in need of clarification.

**Correction of Publication**

Accordingly, the publication of the notice of proposed rulemaking (REG-103146-08), which was the subject of FR Doc. E8-16177, is corrected as follows:

**§ 1.6039-1 [Corrected]**

1. On page 41002, column 2, § 1.6039-1(a)(1), line 5 of the column, the language “a return with respect each transfer made” is corrected to read “a return with respect to each transfer made”.

2. On page 41002, column 2, § 1.6039-1(b)(1), line 12, the language “calendar year, file a return with

respect” is corrected to read “calendar year, file a return with respect to”.

3. On page 41002, column 2, § 1.6039-1(b)(1)(iv), the language “The fair market value of the stock on the date the option was granted;” is corrected to read “The fair market value of a share of stock on the date the option was granted;”.

4. On page 41002, column 3, § 1.6039-1(b)(1)(vii), the language “The fair market value of the stock on the date the option was exercised by the transferor;” is corrected to read “The fair market value of a share of stock on the date the option was exercised by the transferor;”.

**§ 1.6039-2 [Corrected]**

5. On page 41003, column 1, § 1.6039-2(b), line 4, the language “section 6039(a)(2). (1) Every corporation” is corrected to read “section 6039(b). (1) Every corporation”.

**LaNita Van Dyke,**

*Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).*

[FR Doc. E8-18784 Filed 8-13-08; 8:45 am]

**BILLING CODE 4830-01-P**

**ENVIRONMENTAL PROTECTION AGENCY****40 CFR Part 63**

[EPA-R09-OAR-2008-0555; FRL-8701-6]

**Delegation of National Emission Standards for Hazardous Air Pollutants for Source Categories; State of Arizona, Arizona Department of Environmental Quality, Pima County Department of Environmental Quality**

**AGENCY:** Environmental Protection Agency (EPA).

**ACTION:** Proposed rule.

**SUMMARY:** Pursuant to section 112(l) of the 1990 Clean Air Act, EPA granted delegation of specific national emission standards for hazardous air pollutants (NESHAP) to the Arizona Department of Environmental Quality on June 4, 2008, and to the Pima County Department of Environmental Quality on June 16, 2008. EPA is proposing to revise the Code of Federal Regulations to reflect the current delegation status of NESHAP in Arizona.

**DATES:** Any comments on this proposal must arrive by September 15, 2008.

**ADDRESSES:** Submit comments, identified by docket number EPA-R09-OAR-2008-0555, by one of the following methods: