

and corrective actions before further flight. Repeat the applicable inspection thereafter at the applicable interval specified in Paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2439, Revision 2, dated July 17, 2008.

(1) Where Boeing Alert Service Bulletin 747-53A2439, Revision 2, dated July 17, 2008, specifies a compliance time relative to the date of issuance of that service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 747-53A2439, Revision 2, dated July 17, 2008, specifies contacting Boeing for repair data: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (o) of this AD.

Optional New Modification for Areas 1, 2, 3, and 4

(m) For areas 1, 2, 3, and 4 as defined in Boeing Alert Service Bulletin 747-53A2439, Revision 2, dated July 17, 2008: Doing the modification and post-modification actions specified in Boeing Alert Service Bulletin 747-53A2696, dated October 16, 2008, terminates the repetitive inspection requirements of paragraphs (g) and (h) of this AD. Doing the modification and post-modification actions specified in Boeing Alert Service Bulletin 747-53A2696, dated October 16, 2008, terminates the repetitive inspection requirements of paragraph (l) of this AD, except at the upper deck floor beam at body station (BS) 460 and 480 and the upper deck floor beams aft of BS 520.

No Reporting Requirement

(n) Although Boeing Alert Service Bulletin 747-53A2439, Revision 1, dated March 10, 2005; and Boeing Alert Service Bulletin 747-53A2439, Revision 2, dated July 17, 2008; specify to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(o)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) AMOCs approved previously in accordance with AD 2006-08-02, are approved as AMOCs for the corresponding provisions of this AD.

(4) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on August 3, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-19262 Filed 8-11-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2009-0513; Airspace Docket No. 09-ASW-13]

Proposed Amendment of Class E Airspace; Midlothian-Waxahachie, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Midlothian-Waxahachie, TX. Additional controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Mid-Way Regional Airport, Midlothian-Waxahachie, TX. This action would also reflect the name change to Mid-Way Regional Airport and update the geographic coordinates. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) operations for SIAPs at Mid-Way Regional Airport.

DATES: 0901 UTC. Comments must be received on or before September 28, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2009-0513/Airspace Docket No. 09-ASW-13, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9

a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd, Fort Worth, TX 76137; telephone: (817) 321-7716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2009-0513/Airspace Docket No. 09-ASW-13." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration (FAA), Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), part 71 by adding additional Class E airspace extending upward from 700 feet above the surface for SIAPs operations at Mid-Way Regional Airport, Midlothian-Waxahachie, TX. This action would also reflect the name change of the airport from Midlothian-Waxahachie Municipal Airport to Mid-Way Regional Airport and update the geographic coordinates. Controlled airspace is needed for the safety and management of IFR operations at the airport.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9S, dated October 3, 2008, and effective October 31, 2008, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would add additional controlled airspace at Mid-Way Regional Airport, Midlothian-Waxahachie, TX.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9S, Airspace Designations and Reporting Points, dated October 3, 2008, and effective October 31, 2008, is amended as follows:

Paragraph 6005 Class E Airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ASW TX E5 Midlothian-Waxahachie, TX [Amended]

Mid-Way Regional Airport, TX
(Lat. 32°27'22" N., long. 96°54'46" W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of Mid-Way Regional Airport and within 1.8 miles each side of the 184° bearing from the airport extending from the 6.5-mile radius to 9.8 miles south of the airport.

* * * * *

Issued in Fort Worth, TX, on July 30, 2009.

Anthony D. Roetzel,

Manager, Operations Support Group, ATO
Central Service Center.

[FR Doc. E9–19251 Filed 8–11–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2009–0318; Airspace
Docket No. 09–AAL–8]

Proposed Revision of Class E Airspace; Noorvik, AK

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish Class E airspace at the Robert

(Bob) Curtis Memorial Airport at Noorvik, AK. Two Standard Instrument Approach Procedures (SIAPs) are being developed for the Robert (Bob) Curtis Memorial Airport at Noorvik, AK. Additionally, one textual Obstacle Departure Procedure (ODP) is being developed. Adoption of this proposal would result in establishing Class E airspace upward from 700 feet (ft.) above the surface at the Robert (Bob) Curtis Memorial Airport at Noorvik, AK. **DATES:** Comments must be received on or before September 28, 2009.

ADDRESSES: Send comments on the proposal to the Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001. You must identify the docket number FAA–2009–0318/Airspace Docket No. 09–AAL–8, at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800–647–5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Manager, Safety, Alaska Flight Service Operations, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513–7587.

FOR FURTHER INFORMATION CONTACT: Gary Rolf, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513–7587; telephone number (907) 271–5898; fax: (907) 271–2850; email: gary.ctr.rolf@faa.gov. Internet address: http://www.faa.gov/about/office_org/headquarters_offices/ato/service_units/systemops/fs/alaskan/rulemaking/.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related