

**Unsafe Condition**

(e) This AD results from a report of fatigue cracking of the wing upper and lower rainbow fittings during durability testing and on in-service airplanes. Analysis of in-service cracking has shown that these rainbow fittings are susceptible to multiple site fatigue damage. The Federal Aviation Administration is issuing this AD to detect and correct such fatigue cracks, which could grow large and lead to the failure of the fitting and a catastrophic failure of the center wing.

**Compliance**

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Initial Inspections**

(g) At the later of the times specified in paragraphs (g)(1) and (g)(2) of this AD: Do eddy current inspections to detect cracking of the center wing upper and lower rainbow fittings on the left and right side of the airplane. Do the actions in accordance with the Accomplishment Instructions of Lockheed Service Bulletin 382-57-82, Revision 3, including Appendixes A and B, dated April 25, 2008. Any cracks found during the inspections required by paragraph (g) of this AD must be repaired before further flight in accordance with the actions required by paragraph (l) of this AD.

(1) Before the accumulation of 15,000 total flight hours on the rainbow fitting.

(2) Within 365 days or 600 flight hours on the rainbow fitting after the effective date of this AD, whichever occurs first.

**Repetitive Inspection Schedule**

(h) Repeat the inspection required by paragraph (g) of this AD at intervals not to exceed 3,600 flight hours on the center wing, until the rainbow fitting has accumulated 30,000 total flight hours. Any cracks found during the inspections required by paragraph (h) of this AD must be repaired before further flight in accordance with the actions required by paragraph (l) of this AD.

**Rainbow Fitting Replacements**

(i) Before the accumulation of 30,000 flight hours on the rainbow fitting or within 600 flight hours after the effective date of this AD, whichever occurs later: Replace the rainbow fitting, do all related investigative actions, and do all applicable corrective actions, in accordance with paragraph 2.C. of the Accomplishment Instructions of Lockheed Service Bulletin 382-57-82, Revision 3, including Appendix C, dated April 25, 2008. Replace the rainbow fitting thereafter at intervals not to exceed 30,000 flight hours.

**Post-Replacement Repetitive Inspections**

(j) For upper and lower rainbow fittings replaced in accordance with paragraph (i) or (k) of this AD: Do the eddy current inspections specified in paragraph (g) of this AD within 15,000 flight hours after doing the replacement and repeat the eddy current inspections specified in paragraph (h) of this AD thereafter at intervals not to exceed 3,600 flight hours until the rainbow fittings are

replaced in accordance with paragraph (i) or (k) of this AD.

**Repair of Damaged Rainbow Fittings and Associated Areas**

(k) If, during any inspection required by paragraph (g) or (h) of this AD, any crack is detected, before further flight, replace the rainbow fitting, do all related investigative actions and do all applicable corrective actions, in accordance with Paragraph 2.C. of the Accomplishment Instructions of Lockheed Service Bulletin 382-57-82, Revision 3, including Appendix C, dated April 25, 2008, except as provided by paragraph (l) of this AD.

**Exceptions to Service Bulletin**

(l) Where Lockheed Service Bulletin 382-57-82, Revision 3, including Appendixes A, B, and C, dated April 25, 2008, specifies to contact the manufacturer for disposition of certain repair conditions, and where the service bulletin does not specify corrective actions if certain conditions are found, this AD requires repairing those conditions using a method approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. For a repair method to be approved by the Manager, Atlanta ACO, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

**Alternative Methods of Compliance (AMOCs)**

(m)(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Carl Gray, Aerospace Engineer, Airframe Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, Georgia 30337; telephone (404) 474-5554; fax (404) 474-5606.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Issued in Renton, Washington, on March 17, 2010.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2010-6307 Filed 3-22-10; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2010-0052; Airspace Docket No. 10-ASO-13]

**Amendment of Class E Airspace; Clemson, SC and Establishment of Class E Airspace; Pickens, SC**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend Class E airspace at Clemson, SC, to correct the airspace description and establish Class E airspace at Pickens, SC, to achieve an additional 1000' of airspace to support a new LPV Approach (Localizer Performance with Vertical Guidance) that has been developed for Pickens County Airport. This action enhances the safety and airspace management of Clemson-Oconee County Airport, SC and Pickens County Airport, Pickens, SC.

**DATES:** Comments must be received on or before May 7, 2010.

**ADDRESSES:** Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2010-0052; Airspace Docket No. 10-ASO-13, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** Melinda Giddens, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5610.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-

2010-0052; Airspace Docket No. 10-ASO-13) and be submitted in triplicate to the Docket Management System (*see ADDRESSES* section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Comments wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2010-0052; Airspace Docket No. 10-ASO-13." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at [http://www.faa.gov/airports/airtraffic/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (*see the ADDRESSES* section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, room 210, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

#### The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class E airspace at Clemson, SC, to remove Pickens County Airport from the airspace description and establish Class E airspace at Pickens, SC, to support a

new LPV Approach developed for Pickens County Airport.

Class E airspace designations extending upward from 700 feet or more above the surface of the Earth are published in Paragraph 6005 of FAA Order 7400.9T, signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR 71.1. The Class E designation listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in subtitle vii, part, a, subpart i, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority as it amends Class E airspace at Clemson, SC, and establishes Class E airspace at Pickens, SC.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

#### The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D, AND CLASS E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

#### § 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9T, Airspace Designations and Reporting Points, signed August 27, 2009, effective September 15, 2009, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

#### ASO SC E5 Clemson, SC [AMENDED]

Clemson-Oconee County Airport, SC  
(Lat. 34°40'19" N., long. 82°53'12" W.)

That airspace extending upward from 700 feet above the surface within a 7-mile radius of Clemson-Oconee County Airport.

\* \* \* \* \*

#### ASO SC E5 Pickens, SC [NEW]

Pickens County Airport, SC  
(Lat. 34°48'36" N., long. 82°42'10" W.)

That airspace extending upward from 700 feet above the surface within a 6.5-mile radius of the Pickens County Airport and within 3.6 miles each side of the 044° bearing from the airport, extending from the 6.5-mile radius to 11-miles northeast of the airport.

Issued in College Park, Georgia on March 15, 2010.

**Michael Vermuth,**

*Acting Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.*

[FR Doc. 2010-6281 Filed 3-22-10; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2010-0054; Airspace Docket No. 10-ASO-11]

#### Establishment of Class D Airspace, Modification of Class E Airspace; Columbus, GA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM); withdrawal.

**SUMMARY:** This action withdraws the Notice of Proposed Rulemaking (NPRM)