

requirements of Annex I, paragraph 3(a) of 72 COLREGS, and Annex I, Section 84.05(a) of the Inland Rules Act.

This notice is issued under authority of 33 U.S.C. 1605(c), and 33 CFR 81.18.

Dated: June 22, 2010.

By Direction of the Commander, Eighth Coast Guard District.

J.W. Johnson,

Commander, U.S. Coast Guard, Chief, Inspections & Investigations Branch.

[FR Doc. 2010-16958 Filed 7-12-10; 8:45 am]

BILLING CODE 9110-04-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

[Docket No. USCG-2010-0551]

Certificate of Alternative Compliance for the Offshore Supply Vessel CALLAIS SEARCHER

AGENCY: Coast Guard, DHS.

ACTION: Notice.

SUMMARY: The Coast Guard announces that a Certificate of Alternative Compliance was issued for the offshore supply vessel CALLAIS SEARCHER as required by 33 U.S.C. 1605(c) and 33 CFR 81.18.

DATES: The Certificate of Alternate Compliance was issued on June 8, 2010.

ADDRESSES: The docket for this notice is available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. You may also find this docket on the Internet by going to <http://www.regulations.gov>, inserting USCG-2010-0551 in the "Keyword" box, pressing Enter, and then clicking "Search."

FOR FURTHER INFORMATION CONTACT: If you have questions on this notice, call LTJG Christine Dimitroff, District Eight, Prevention Branch, U.S. Coast Guard, telephone 504-671-2167. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION:

Background and Purpose

A Certificate of Alternative Compliance, as allowed for under Title 33, Code of Federal Regulation, Parts 81 and 89, has been issued for the offshore supply vessel CALLAIS SEARCHER, O.N. 1226876. The horizontal distance

between the forward and aft masthead lights may be 20'-8⁵/₈". Placing the aft masthead light at the horizontal distance from the forward masthead light as required by Annex I, paragraph 3(a) of the 72 COLREGS, and Annex I, Section 84.05(a) of the Inland Rules Act, would result in an aft masthead light location directly over the cargo deck where it would interfere with loading and unloading operations. The offset from centerline of the RAM/NUC lights may be 3'. Offsetting the RAM/NUC lights 2 meters from the centerline as required by Annex I paragraph 3(c) of the 72 COLREGS and Annex I, Section 84.05(c) of the Inland rules Act would place them in an exposed position beyond the width of the aft end of the pilothouse.

A Certificate of Alternative Compliance, as allowed for under Title 33, Code of Federal Regulation, Parts 81 and 89, has been issued for the offshore supply vessel CALLAIS SEARCHER, O.N. 1226876. The Certificate of Alternative Compliance allows for the horizontal separation of the forward and aft masthead lights to deviate from the requirements of Annex I, paragraph 3(a) of 72 COLREGS, and Annex I, Section 84.05(a) of the Inland Rules Act as well as the offset of the RAM/NUC lights to deviate from the requirements of Annex I, paragraph 3(c) of 72 COLREGS and Annex I, Section 84.05(c) of the Inland Rules Act.

This notice is issued under authority of 33 U.S.C. 1605(c), and 33 CFR 81.18.

Dated: June 22, 2010.

J.W. Johnson

Commander, U.S. Coast Guard, Chief, Inspections & Investigations Branch, By Direction of the Commander, Eighth Coast Guard District.

[FR Doc. 2010-16957 Filed 7-12-10; 8:45 am]

BILLING CODE 9110-04-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

[Docket No. USCG-2010-0554]

Certificate of Alternative Compliance for the Offshore Supply Vessel MARIE ELISE

AGENCY: Coast Guard, DHS.

ACTION: Notice.

SUMMARY: The Coast Guard announces that a Certificate of Alternative Compliance was issued for the offshore supply vessel MARIE ELISE as required by 33 U.S.C. 1605(c) and 33 CFR 81.18.

DATES: The Certificate of Alternate Compliance was issued on June 8, 2010.

ADDRESSES: The docket for this notice is available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. You may also find this docket on the Internet by going to <http://www.regulations.gov>, inserting USCG-2010-0554 in the "Keyword" box, and then clicking "Search."

FOR FURTHER INFORMATION CONTACT: If you have questions on this notice, call LTJG Christine Dimitroff, District Eight, Prevention Branch, U.S. Coast Guard, telephone 504-671-2176. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION:

Background and Purpose

A Certificate of Alternative Compliance, as allowed for under Title 33, Code of Federal Regulation, Parts 81 and 89, has been issued for the offshore supply vessel MARIE ELISE, O.N. 1223872. Full compliance with 72 COLREGS and the Inland Rules Act would hinder the vessel's ability to conduct loading and unloading operations, and would hinder the vessel's ability to maneuver within close proximity to offshore platforms. Placing the aft masthead light at the horizontal distance from the forward masthead light as required by Annex I, paragraph 3(a) of the 72 COLREGS, and Annex I, Section 84.05(a) of the Inland Rules Act, would result in an aft masthead light location directly over the aft cargo deck where it would interfere with loading and unloading operations and would make the most highly susceptible to damage during such operations. The horizontal distance between the forward and aft masthead lights may be 19'11³/₈", placing the aft masthead light over the pilot house.

In addition, due to the design of the vessel it would be difficult and impractical to build a supporting structure that would put the side lights within 10% inboard from the greatest breadth of the vessel, as required by Annex I, paragraph 3(b) of the 72 COLREGS and Annex I, Section 84.05(b), of the Inland Rules Act. Compliance with the rule would cause the side lights to be in a location which will be highly susceptible to damage from offshore platforms. Locating the side lights 7'¹/₄" inboard from the greatest breadth of the vessel on the pilot house will provide a sheltered