

to the International Branch, send it to *Attn:* Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be e-mailed to: *9-ANM-116-AMOC-REQUESTS@faa.gov*.

Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### Related Information

(1) Refer to MCAI EASA Airworthiness Directive 2009-0058, dated March 13, 2009; and Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008; for related information.

#### Material Incorporated by Reference

(m) You must use Airbus Mandatory Service Bulletin A310-53-2074, Revision 04, dated October 24, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail *account.airworth-eas@airbus.com*; Internet *http://www.airbus.com*.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: *http://www.archives.gov/federal\_register/code\_of\_federal\_regulations/ibr\_locations.html*.

Issued in Renton, Washington, on April 22, 2011.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2011-10688 Filed 5-10-11; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG-2011-0330]

#### Drawbridge Operation Regulations; Hackensack River, Jersey City, NJ

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of temporary deviation from regulations.

**SUMMARY:** The Commander, First Coast Guard District, has issued a temporary deviation from the regulation governing the operation of the Lower Hack Bridge across the Hackensack River, mile 3.4, at Jersey City, New Jersey. The deviation is necessary to repair structural steel members on the lift span. This deviation allows the bridge to remain in the closed position to facilitate the above repairs.

**DATES:** This deviation is effective from 10 p.m. on May 26, 2011 through 5 a.m. on May 27, 2011.

**ADDRESSES:** Documents mentioned in this preamble as being available in the docket are part of docket USCG-2011-0330 and are available online at *http://www.regulations.gov*, inserting USCG-2011-0330 in the "Keyword" and then clicking "Search." They are also available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**FOR FURTHER INFORMATION CONTACT:** If you have questions on this rule, call or e-mail Mr. Joe Arca, Project Officer, First Coast Guard District, *joe.m.arca@uscg.mil*, telephone (212) 668-7165. If you have questions on viewing the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

**SUPPLEMENTARY INFORMATION:** The Lower Hack Bridge, across the Hackensack River at mile 3.4, has a vertical clearance in the closed position of 40 feet at mean high water and 45 feet at mean low water. The existing drawbridge operation regulations are listed at 33 CFR 117.723(b).

The waterway accommodates both commercial and recreational vessels of various sizes. Recreational navigation passes under the bridge without requiring any drawbridge openings.

The owner of the bridge, New Jersey Transit, requested a temporary deviation

to facilitate necessary structural steel repairs at the bridge.

Under this temporary deviation the Lower Hack Bridge, across the Hackensack River at mile 3.4, may remain in the closed position from 10 p.m. on May 26, 2011 through 5 a.m. on May 27, 2011. Vessels that can pass under the bridge without a bridge opening may do so at all times.

In accordance with 33 CFR 117.35(e), the bridge must return to its regular operating schedule immediately at the end of the designated time period. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: May 2, 2011.

**Gary Kassof,**

*Bridge Program Manager, First Coast Guard District.*

[FR Doc. 2011-11545 Filed 5-10-11; 8:45 am]

**BILLING CODE 9110-04-P**

## DEPARTMENT OF HOMELAND SECURITY

### Coast Guard

#### 33 CFR Part 117

[Docket No. USCG-2011-0291]

#### Drawbridge Operation Regulation; Atlantic Intracoastal Waterway, Albemarle and Chesapeake Canal, Chesapeake, VA

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of temporary deviation from regulations.

**SUMMARY:** The Commander, Fifth Coast Guard District, has issued a temporary deviation from the regulations governing the operation of the SR170 Centerville Turnpike Bridge across the Atlantic Intracoastal Waterway, Albemarle and Chesapeake Canal, mile 15.2, at Chesapeake, VA. The deviation is necessary to facilitate urgent mechanical structural repairs to the swing span. Under this deviation, the drawbridge will be allowed to operate on a limited schedule for the extent of the effective period, specifically affecting four specific dates during the effective time-period: May 14, 2011; May 15, 2011; June 4, 2011; and June 5, 2011.

**DATES:** This deviation is effective from 8 a.m. on May 14, 2011 to 8 p.m. on June 5, 2011.

**ADDRESSES:** Documents mentioned in this preamble as being available in the docket USCG-2011-0291 and are available online by going to *http://www.regulations.gov*, inserting USCG-2011-0291 in the "Keyword" box, and