7, Antenna (GPS Antenna), Colson Board Room.

Plenary Session—See Agenda Below

Friday, June 17, 2011

- Chairman's Introductory Remarks.
- Approval of Summary of the Eighty-Fourth and Eighty-Fifth Meetings held February 11, 2011 and May 26, 2011, RTCA Paper No. 082–11/ SC159–991 and RTCA Paper No. 099–11/SC159–995, respectively.
- Review Working Group (WG) Progress and Identify Issues for Resolution.
 - GPS/3rd Civil Frequency (WG-1).
 - GPS/WAAS (WG–2).
 - GPS/GLONASS (WG–2A).
 - GPS/Inertial (WG–2C).
 - GPS/Precision Landing Guidance (WG-4).
 - GPS/Airport Surface Surveillance (WG–5).
 - GPS/Interference (WG–6).
- GPS/Antennas (WG–7).
- Review of EUROCAE Activities.
 ADS-B GAP Analysis Ad Hoc—
- Report.
- Assignment/Review of Future Work.Other Business.
- Date and Place of Next Meeting.
- Adjourn.

Attendance is open to the interested public but limited to space availability. With the approval of the chairman, members of the public may present oral statements at the meeting. Persons wishing to present statements or obtain information should contact the person listed in the FOR FURTHER INFORMATION CONTACT section. Members of the public may present a written statement to the committee at any time.

Issued in Washington, DC, on May 26, 2011.

Robert L. Bostiga,

RTCA Advisory Committee. [FR Doc. 2011–13945 Filed 6–6–11; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Pipeline and Hazardous Materials Safety Administration

[Docket No. PHMSA-2011-0122, Notice No. 11-4]

Safety Advisory; Unauthorized Marking of Compressed Gas Cylinders

AGENCY: Pipeline and Hazardous Materials Safety Administration (PHMSA), DOT.

ACTION: Safety Advisory Notice.

SUMMARY: This notice advises the public that PHMSA has recently confirmed an undetermined number of certain

(aluminum) cylinders were improperly marked and represented as DOT specification 3AL cylinders. The cylinders were neither marked nor certified by an authorized independent inspection agency (IIA) with its official mark and date, in accordance with the applicable regulatory requirements. Therefore, the cylinders are unauthorized for hazardous materials service. Prior to filling these cylinders, a person must verify that the IIA's official mark is stamped between the month and year manufactured. The evidence suggests that if the cylinder is marked with a period (.) rather than the official IIA mark, the cylinder did not undergo the complete series of safety tests and inspections required by the Hazardous Materials Regulations (HMR) and may not possess the structural integrity to safely contain its contents under pressure during normal transportation and use. Extensive property damage, serious personal injury, or death could result from a rupture of the cylinder. Individuals who identify a cylinder marked with only a period (.) between the month and year are advised to remove these cylinders from service and contact PHMSA directly at the below address for further instructions.

FOR FURTHER INFORMATION CONTACT: Ms. Yuying Chen, U.S. Agent for Shanghai Qingpu Fire Fighting Equipment Company, Ltd., 1005 Mirror Street, Pittsburgh, PA 15217, Telephone (412) 235–7880, *E-mail: yvonnechan2001@yahoo.com.*

SUPPLEMENTARY INFORMATION: An undetermined number of the cylinders (typically used for home kegerators). were manufactured between 2009 through 2011 and improperly marked with the manufacturer's symbol "M0306." The cylinders have been stamped with a period (.) between the month and year of manufacture, *i.e.*, "8.10." PHMSA issued the manufacturing symbol "M0306" to Shanghai Qingpu Fire Fighting Equipment Company, Ltd. (Qingpu), located in Shanghai, China. Arrowhead Industrial Services, Inc. (Arrowhead), as Qingpu's authorized independent inspection agency, would have marked the cylinders that passed inspection with its official mark (the letter "A" inside of an arrowhead) between the month and year of manufacture.

Prior to filling these cylinders, a person must verify that Arrowhead's official mark is stamped between the month and year manufactured. Arrowhead does not use a period (.) between the month and year of manufacturing as part of its official mark.

If the cylinder is identified as marked with a period (.) between the month and year, in lieu of the authorized Arrowhead mark, the person in possession of the cylinder is advised to remove that cylinder from service and contact Qingpu's U.S. Agent at the address in this notice.

Issued in Washington, DC, on June 1, 2011. Magdy El-Sibaie,

Associate Administrator for Hazardous Materials Safety.

[FR Doc. 2011–13952 Filed 6–6–11; 8:45 am] BILLING CODE 4910–60–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

Agency Information Collection Activity; Proposed Collection

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice and request for comments.

SUMMARY: The Department of the Treasury, as part of its continuing effort to reduce paperwork and respondent burden, invites the general public and other Federal agencies to take this opportunity to comment on proposed and/or continuing information collections, as required by the Paperwork Reduction Act of 1995, Public Law 104–13 (44 U.S.C. 3506(c)(2)(A)).

DATES: Written comments should be received on or before August 8, 2011 to be assured of consideration.

ADDRESSES: Direct all written comments to Yvette Lawrence, Internal Revenue Service, Room 6129, 1111 Constitution Avenue, NW., Washington, DC 20224. FOR FURTHER INFORMATION CONTACT: Requests for additional information or copies of the regulation should be directed to R. Joseph Durbala, at (202) 622–3634, or at Internal Revenue Service, Room 6129, 1111 Constitution Avenue, NW., Washington, DC 20224, or through the Internet, at *RJoseph.Durbala@irs.gov.*

SUPPLEMENTARY INFORMATION: *Title:* General Revision of Regulations Relating to Withholding of Tax on Certain U.S. Source Income Paid to Foreign Persons and Related Collection, Refunds and Credits; Revision of Information Reporting and Backup Withholding Regulations; and Removal of Regulations Under part 35a and of Certain Regulations Under Income Tax Treaties.