

(1) If a P/N TDF11755 elevator pushrod assembly is installed, or if the part number cannot be determined: Before further flight, replace the affected elevator pushrod assembly with a P/N R20990 elevator pushrod assembly, in accordance with the

Accomplishment Instructions of Saab Service Bulletin 340–27–100, dated February 1, 2011.
 (2) If a P/N 12003–33 or P/N R20990 elevator pushrod assembly is installed: Do a detailed inspection for individual play between the rod end and the pushrod at the locking device and degradation of the

elevator pushrod assembly (including rod end threads not visible through the inspection hole in the pushrod, and the nut and locking device not properly locked with the lock wire), in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–27–100, dated February 1, 2011.

TABLE 1—COMPLIANCE TIMES

Total flight hours accumulated as of the effective date of this AD	Compliance time
For airplanes with 30,000 total flight hours or more	Within 6 months after the effective date of this AD.
For airplanes with 28,000 total flight hours or more, but less than 30,000 total flight hours.	Before the accumulation of 30,000 total flight hours or within 6 months after the effective date of this AD, whichever occurs later.
For airplanes with less than 28,000 total flight hours	Before the accumulation of 30,000 total flight hours.

(h) Corrective Action

If, during the inspection of the elevator pushrod assembly required by paragraph (g)(2) of this AD, individual play between the rod end and the pushrod at the locking device, or degradation of the elevator pushrod assembly (including rod end threads not visible through the inspection hole in the pushrod, and the nut and locking device not properly locked with the lock wire) is found: Before further flight, replace the affected elevator pushrod assembly with a new elevator pushrod assembly, P/N R20990, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–27–100, dated February 1, 2011.

(i) Parts Installation

As of the effective date of this AD, no person may install an elevator pushrod assembly with P/N TDF11755, on any airplane.

(j) Reporting Requirement

Submit a report of the findings (both positive and negative) of the inspection and replacement required by paragraphs (g) and (h) of this AD to Saab AB, Support and Services, SE–581 88 Linköping, Sweden; fax +46 13 18 48 74; email saab340.techsupport@saabgroup.com; at the applicable time specified in paragraph (j)(1) or (j)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind

Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1112; fax (425) 227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(l) Related Information

Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2011–0078, dated May 5, 2011; and Saab Service Bulletin 340–27–100, dated February 1, 2011; for related information.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise.

(i) Saab Service Bulletin 340–27–100, dated February 1, 2011.

(3) For service information identified in this AD, contact Saab AB, Saab Aerosystems, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 15, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–15426 Filed 6–27–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2011–1142; Airspace Docket No. 11–AGL–22]

Amendment of Class D Airspace; Pontiac, MI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule, technical amendment.

SUMMARY: This action amends Class D airspace within the Pontiac, MI, area by changing the name of the airport from

Oakland-Pontiac Airport to Oakland County International Airport and updating the geographic coordinates. This action does not change the boundaries or operating requirements of the airspace.

DATES: *Effective date:* July 30, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone 817-321-7716.

SUPPLEMENTARY INFORMATION:

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by changing the airport formerly known as Oakland-Pontiac Airport to Oakland County International Airport and adjusting the geographic coordinates within Class D airspace to coincide with the FAA's aeronautical database. This is an administrative change and does not affect the boundaries, altitudes, or operating requirements of the airspace, therefore, notice and public procedures under 5 U.S.C. 553(b) are unnecessary.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that

section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends controlled airspace at Oakland County International Airport, Pontiac, MI.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

- 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E. O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

- 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9V, Airspace Designations and Reporting Points, dated August 9, 2011, and effective September 15, 2011, is amended as follows:

Paragraph 5000 Class D airspace.

* * * * *

AGL MI D Pontiac, MI [Amended]

Oakland County International Airport, MI (Lat. 42°39'56" N., long. 83°25'14" W.)

That airspace extending upward from the surface to and including 3,500 feet MSL within a 4.2-mile radius of Oakland County International Airport. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

Issued in Fort Worth, Texas, on June 13, 2012.

David P. Medina,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2012-15706 Filed 6-27-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2012-0196; Airspace Docket No. 12-AWP-2]

Amendment of Class E Airspace; Fairfield, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E airspace at Travis Air Force Base (AFB), Fairfield, CA. The projected decommissioning of the Travis VHF Omni-Directional Radio Range (VOR) has made this action necessary for the safety and management of Instrument Flight Rules (IFR) operations at the airport.

DATES: Effective date, 0901 UTC, September 20, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:

History

On April 18, 2012, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to amend controlled airspace at Fairfield, CA (77 FR 23171). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. Two comments were received in favor of the airspace amendment. Except for a minor editorial change, this rule is the same as published in the NPRM.

Class E airspace designations are published in paragraph 6004, of FAA Order 7400.9V dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in that Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by amending Class E airspace designated as an extension to Class D surface area at Travis AFB, Fairfield, CA. Airspace reconfiguration is necessary due to the