

Proposed Rules

Federal Register

Vol. 77, No. 183

Thursday, September 20, 2012

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Animal and Plant Health Inspection Service

9 CFR Part 107

[Docket No. APHIS-2011-0048]

RIN 0579-AD66

Viruses, Serums, Toxins, and Analogous Products; Exemptions From Preparation Pursuant to an Unsuspended and Unrevoked License

AGENCY: Animal and Plant Health Inspection Service, USDA.

ACTION: Proposed rule; reopening of comment period.

SUMMARY: We are reopening the comment period for our proposed rule that clarified our interpretation of the veterinary practitioner exemption provided by the Virus-Serum-Toxin Act. This action will allow interested persons additional time to prepare and submit comments.

DATES: We will consider all comments that we receive on or before November 16, 2012.

ADDRESSES: You may submit comments by either of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov/#!documentDetail;D=APHIS-2011-0048-0001>.

- *Postal Mail/Commercial Delivery:* Send your comment to Docket No. APHIS-2011-0048, Regulatory Analysis and Development, PPD, APHIS, Station 3A-03.8, 4700 River Road Unit 118, Riverdale, MD 20737-1238.

Supporting documents and any comments we receive on this docket may be viewed at <http://www.regulations.gov/#!docketDetail;D=APHIS-2011-0048> or in our reading room, which is located in room 1141 of the USDA South Building, 14th Street and Independence Avenue SW., Washington, DC. Normal reading room hours are 8 a.m. to 4:30 p.m., Monday through Friday, except holidays. To be sure someone is there to

help you, please call (202) 799-7039 before coming.

FOR FURTHER INFORMATION CONTACT: Dr. Donna Malloy, Operational Support Section, Center for Veterinary Biologics, Policy, Evaluation, and Licensing, VS, APHIS, 4700 River Road Unit 148, Riverdale, MD 20737-1231; phone (301) 851-3426, fax (301) 734-4314.

SUPPLEMENTARY INFORMATION: The Virus-Serum-Toxin Act, as amended (21 U.S.C. 151-159) includes an exemption that allows veterinary biologics to be prepared by a veterinary practitioner solely for administration to animals in the course of a State-licensed professional practice of veterinary medicine under a veterinarian-client-patient relationship. On July 18, 2012, we published in the **Federal Register** (77 FR 42195-42197, Docket No. APHIS-2011-0048) a proposal that clarified our interpretation of this exemption.

Comments on the proposed rule were required to be received on or before September 17, 2012. We are reopening the comment period on Docket No. APHIS-2011-0048 for an additional 60 days. This action will allow interested persons additional time to prepare and submit comments. We will also consider all comments received between September 18, 2012, (the day after the close of the original comment period) and the date of this notice.

Authority: 21 U.S.C. 151-159; 7 CFR 2.22, 2.80, and 371.4.

Done in Washington, DC, this 14th day of September 2012.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 2012-23202 Filed 9-19-12; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0986; Directorate Identifier 2012-NM-077-AD]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft Industries, Ltd.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft Industries, Ltd.) Model Gulfstream G150 airplanes. This proposed AD was prompted by a review that determined that the runway slope and anti-ice corrections to V₁ and take-off distances in the Gulfstream G150 Airplane Flight Manual (AFM) were presented in a non-conservative manner. This proposed AD would require revising the performance section of the AFM to include procedures to advise the flightcrew of certain runway slope and anti-ice corrections and take-off distance values. We are proposing this AD to prevent the use of published non-conservative data, which could result in the inability to meet the required take-off performance, with consequent hazard to safe operation during performance-limited take-off operations.

DATES: We must receive comments on this proposed AD by November 5, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D-25, Savannah, GA 31402-2206; telephone 800-810-4853; fax 912-965-3520; email pubs@gulfstream.com; Internet http://www.gulfstream.com/product_support/technical_pubs/pubs/index.htm. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Groves, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1503; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0986; Directorate Identifier 2012-NM-077-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Civil Aviation Authority of Israel (CAAI), which is the aviation authority for Israel, has issued Israeli

Airworthiness Directive 01-12-02-02, dated March 2, 2012 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

This [Israeli] AD mandates revised limitations in the G150 AFM, pertaining to the Performance Section. Each operator must incorporate Temporary Rev.3 to the G150 AFM.

The unsafe condition is the use of published non-conservative data, which could result in the inability to meet the required take-off performance, with consequent hazard to safe operation during performance-limited take-off operations. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Gulfstream has issued Gulfstream G150 Temporary Revision 3, dated December 14, 2011, to Section V, Performance, of the Gulfstream G150 AFM. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 56 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$4,760, or \$85 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft

Industries, Ltd.): Docket No. FAA–2012–0986; Directorate Identifier 2012–NM–077–AD.

(a) Comments Due Date

We must receive comments by November 5, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Gulfstream Aerospace LP (Type Certificate previously held by Israel Aircraft Industries, Ltd.) Model Gulfstream G150 airplanes; certificated in any category; all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 01, Operations information.

(e) Reason

This AD was prompted by a review that determined that the runway slope and anti-ice corrections to V_1 and take-off distances in the G150 Airplane Flight Manual (AFM) were presented in a non-conservative manner. We are issuing this AD to prevent the use of published non-conservative data, which could result in the inability to meet the required take-off performance, with consequent hazard to safe operation during performance-limited take-off operations.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) AFM Revision

Within 60 days after the effective date of this AD, revise Section V, Performance, of the Gulfstream G150 AFM to include the information in Gulfstream G150 Temporary Revision 3, dated December 14, 2011. This TR introduces corrections for runway slope. Operate the airplane according to the procedures in the TR.

Note 1 to paragraph (g) of this AD: This may be done by inserting copies of Gulfstream G150 TR Revision 3, dated December 14, 2011, in the AFM. When this TR has been included in general revisions of the AFM, the general revisions may be inserted in the AFM, provided the relevant information in the general revision is identical to that in Gulfstream G150 TR Revision 3, dated December 14, 2011, and the TR may be removed.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Groves, Aerospace Engineer,

International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1503; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Special Flight Permits

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

(j) Related Information

(1) Refer to MCAI Israeli Airworthiness Directive 01–12–02–02, dated March 2, 2012; and Gulfstream G150 TR Revision 3, dated December 14, 2011, to Section V, Performance of the Gulfstream G150 AFM; for related information.

(2) For service information identified in this AD, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D–25, Savannah, GA 31402–2206; telephone 800–810–4853; fax 912–965–3520; email pubs@gulfstream.com; Internet http://www.gulfstream.com/product_support/technical_pubs/pubs/index.htm. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on September 7, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–23149 Filed 9–19–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2012–0987; Directorate Identifier 2012–NM–130–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737–300, 737–400, 737–500, and 757–200 series airplanes. This proposed AD was prompted by a report of damage caused by electrical arcing to the wires that connect seat electronics boxes (SEBs). This proposed AD would require installing a new relay and doing certain wiring changes of the entertainment control switch if necessary. We are proposing this AD to prevent power from being supplied to passenger seats when the entertainment control switch is in the OFF position, which could cause an electrical shock hazard resulting in serious or fatal injury to maintenance personnel.

DATES: We must receive comments on this proposed AD by November 5, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.