

(k) New Requirement: Corrective Action

If, during any inspection required by paragraph (i) or (j) of this AD, any crack is detected: Before further flight, repair the crack in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, or EASA (or its delegated agent).

(l) New Requirement: Reporting Requirement

Submit a one-time report of the findings (both positive and negative) of the inspections required by paragraphs (i) and (j) of this AD to Airbus, Sebastien Faure, SEES1, SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 31 68; fax +33 5 61 93 36 14; email sebastien.s.faure@airbus.com, at the applicable time specified in paragraph (l)(1) or (l)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(m) New Requirement: Terminating Action

Accomplishment of the one-time eddy current inspection or a liquid penetrant inspection required by paragraph (j) of this AD, including doing all applicable repairs, constitutes terminating action for the inspections required by paragraph (i) of this AD.

(n) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD. AMOCs approved previously in accordance with AD 2010-06-05, Amendment 39-16229 (75 FR 11435, March 11, 2010), are approved as AMOCs for the corresponding provisions of this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they

are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(o) Related Information

Refer to MCAI EASA Airworthiness Directive 2011-0163, dated August 30, 2011, and the service information specified in paragraphs (o)(1) through (o)(6) of this AD, for related information.

(1) Airbus All Operator Telex A300-53A0391, dated August 9, 2011.

(2) Airbus All Operator Telex A300-57A6111, dated August 9, 2011.

(3) Airbus Mandatory Service Bulletin A300-57A6108, including Appendices 01 and 02, dated September 12, 2008.

(4) Airbus Mandatory Service Bulletin A300-53A0387, including Appendices 01 and 02, dated September 12, 2008.

(5) Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002.

(6) Airbus Service Bulletin A300-57-6052, Revision 03, dated May 27, 2002, including Airbus Drawings 15R53810394, Issue A, dated December 21, 1998, and 21R57110247, Issue A, dated June 20, 1997.

(p) Material Incorporated by Reference

(1) The Director of the **Federal Register** approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on January 30, 2013.

(i) Airbus All Operator Telex A300-53A0391, dated August 9, 2011. (The issue date and document number of this document are specified on only the first page of the document.)

(ii) Airbus All Operator Telex A300-57A6111, dated August 9, 2011. (The issue date and document number of this document are specified on only the first page of the document.)

(4) The following service information was approved for IBR on April 15, 2010 (75 FR 11435, March 11, 2010).

(i) Airbus Mandatory Service Bulletin A300-57A6108, including Appendices 01 and 02, dated September 12, 2008.

(ii) Airbus Mandatory Service Bulletin A300-53A0387, including Appendices 01 and 02, dated September 12, 2008.

(iii) Airbus Service Bulletin A300-53-0268, Revision 06, dated January 7, 2002. (Pages 1-6, 9, 10, and 25-27 of this document are identified as Revision 06, dated January 7, 2002. Pages 7, 8, 11-24, and 28-84 of this AD document are identified as Revision 05, dated June 9, 2000).

(iv) Airbus Service Bulletin A300-57-6052, Revision 03, dated May 27, 2002, which includes Airbus Drawing 15R53810394, Issue A, dated December 21, 1998 and Airbus Drawing 21R57110247, Issue A, dated June 20, 1997. Airbus Drawing 21R57110247, Issue A, dated June 20, 1997 has effective pages 1 and 2, dated May 28, 1997 and pages 3 and 4, dated June 20, 1997.

(5) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(6) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on December 4, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-29992 Filed 12-21-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2012-0660; Airspace Docket No. 12-ANM-20]

Establishment of Class E Airspace; Walsenburg, CO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace at Spanish Peaks Airfield, Walsenburg, CO, to accommodate aircraft using new Area Navigation (RNAV) Global Positioning System (GPS) standard instrument approach

procedures at the airport. This improves the safety and management of Instrument Flight Rules (IFR) operations at the airport. Also, the geographic coordinates of the airport are updated at the request of National Aeronautical Navigation Services.

DATES: Effective date, 0901 UTC, March 7, 2013. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA, 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:

History

On September 11, 2012, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to establish controlled airspace at Spanish Peaks Airfield, Walsenburg, CO (77 FR 55776). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005, of FAA Order 7400.9W dated August 8, 2012, and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in that Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by establishing Class E airspace extending upward from 700 and 1,200 feet above the surface, at Spanish Peaks Airfield, Walsenburg, CO, to accommodate IFR aircraft executing new RNAV (GPS) standard instrument approach procedures at the airport. Also, the geographic coordinates of the airport are updated to coincide with the FAA's aeronautical database. This action is necessary for the safety and management of IFR operations.

The FAA has determined this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3)

does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106 discusses the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Spanish Peaks Airfield, Walsenburg, CO.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures," paragraph 311a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E. O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9W, Airspace Designations and Reporting Points, dated August 8, 2012, and

effective September 15, 2012 is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ANM CO E5 Walsenburg, CO [New]

Walsenburg, Spanish Peaks Airfield, CO (Lat. 37°41'47" N., long. 104°47'05" W.)

That airspace extending upward from 700 feet above the surface within a 9.7-mile radius of the Spanish Peaks Airfield; that airspace extending upward from 1,200 feet above the surface within an area bounded by lat. 37°58'00" N., long. 105°00'00" W.; to lat. 37°52'00" N., long. 104°13'00" W.; to lat. 37°17'00" N., long. 104°10'00" W.; to lat. 37°22'00" N., long. 105°22'00" W., thence to the point of beginning.

Issued in Seattle, Washington, on November 8, 2012.

John Warner,

Manager, Operations Support Group, Western Service Center.

[FR Doc. 2012-30792 Filed 12-21-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2012-1150; Airspace Docket No. 12-ANE-16]

RIN 2120-AA66

Amendment of Time of Designation for Restricted Area R-6501B; Underhill, VT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the time of designation for restricted area R-6501B, Underhill, VT by adding a requirement for issuance of a Notice to Airmen (NOTAM) 24 hours in advance of any activation of the restricted area. This action does not affect the boundaries, altitudes or activities conducted within the area.

DATES: Effective date 0901 UTC, January 10, 2013.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace Policy and ATC Procedures Group, AJV-11, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

The current time of designation of restricted area R-6501B reads