

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2013-17-06 Fokker Services B.V.:

Amendment 39-17570. Docket No. FAA-2012-0270; Directorate Identifier 2011-NM-113-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 18, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Fokker Services B.V. Model F.27 Mark 050 airplanes, and Model F.28 Mark 0070 and 0100 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electric power.

(e) Reason

This AD was prompted by reports of loose nuts on contactors in the electrical power center (EPC), and in some cases, burned contactors. We are issuing this AD to detect and correct loose nuts, which could result in arcing and potentially an onboard fire, possibly resulting in damage to the airplane and injury to occupants or maintenance personnel.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 24 months after the effective date of this AD, do the actions specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD.

(1) Do a torque check of the nuts and circuit breakers, contactors, and terminal blocks of the EPC and battery relay panel, as applicable; and do all applicable adjustments of the torque values; in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF50-24-032, dated February 10, 2011 (for Model F.27 Mark 050 airplanes); or the Accomplishment Instructions of Fokker Service Bulletin SBF100-24-043, Revision 1, dated December 15, 2011 (for Model F.28 Mark 0070 and 0100 airplanes). Do all applicable adjustments before further flight.

(2) Do a general visual inspection of the contacts and nuts on circuit breakers, contactors, and terminal blocks of the EPC and battery relay panel to determine if either the lock washer, flat washer and nut, or locking nut and flat washer are installed; and do all applicable installations; in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF50-24-032,

dated February 10, 2011 (for Model F.27 Mark 050 airplanes); or the Accomplishment Instructions of Fokker Service Bulletin SBF100-24-043, Revision 1, dated December 15, 2011 (for Model F.28 Mark 0070 and 0100 airplanes). Do all applicable installations before further flight.

(3) Before further flight, after accomplishing any check required by paragraph (g)(1) of this AD or any inspection required by paragraph (g)(2) of this AD: Apply torque inspection lacquer, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF50-24-032, dated February 10, 2011 (for Model F.27 Mark 050 airplanes); or the Accomplishment Instructions of Fokker Service Bulletin SBF100-24-043, Revision 1, dated December 15, 2011 (for Model F.28 Mark 0070 and 0100 airplanes).

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directive 2012-0050, dated March 27, 2012, for related information, which can be found in the AD docket on the Internet at <http://www.regulations.gov>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Fokker Service Bulletin SBF50-24-032, dated February 10, 2011.

(ii) Fokker Service Bulletin SBF100-24-043, Revision 1, dated December 15, 2011.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; telephone +31 (0)252-627-350; fax +31 (0)252-627-211; email technicalservices.fokkerservices@stork.com; Internet <http://www.myfokkerfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 16, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-21672 Filed 9-12-13; 8:45 am]

BILLING CODE 4910-13-P

PENSION BENEFIT GUARANTY CORPORATION**29 CFR Parts 4022 and 4044****Allocation of Assets in Single-Employer Plans; Benefits Payable in Terminated Single-Employer Plans; Interest Assumptions for Valuing and Paying Benefits**

AGENCY: Pension Benefit Guaranty Corporation.

ACTION: Final rule.

SUMMARY: This final rule amends the Pension Benefit Guaranty Corporation's regulations on Benefits Payable in Terminated Single-Employer Plans and Allocation of Assets in Single-Employer Plans to prescribe interest assumptions under the benefit payments regulation for valuation dates in October 2013 and interest assumptions under the asset allocation regulation for valuation dates in the fourth quarter of 2013. The interest assumptions are used for valuing and paying benefits under terminating single-employer plans covered by the pension insurance system administered by PBGC.

DATES: Effective October 1, 2013.

FOR FURTHER INFORMATION CONTACT: Catherine B. Klion (*Klion.Catherine@PBGC.gov*), Assistant General Counsel for Regulatory Affairs, Pension Benefit Guaranty Corporation, 1200 K Street

NW., Washington, DC 20005, 202-326-4024. (TTY/TDD users may call the Federal relay service toll free at 1-800-877-8339 and ask to be connected to 202-326-4024.)

SUPPLEMENTARY INFORMATION: PBGC's regulations on Allocation of Assets in Single-Employer Plans (29 CFR Part 4044) and Benefits Payable in Terminated Single-Employer Plans (29 CFR Part 4022) prescribe actuarial assumptions—including interest assumptions—for valuing and paying plan benefits under terminating single-employer plans covered by title IV of the Employee Retirement Income Security Act of 1974. The interest assumptions in the regulations are also published on PBGC's Web site (<http://www.pbgc.gov>).

The interest assumptions in Appendix B to Part 4044 are used to value benefits for allocation purposes under ERISA section 4044. PBGC uses the interest assumptions in Appendix B to Part 4022 to determine whether a benefit is payable as a lump sum and to determine the amount to pay. Appendix C to Part 4022 contains interest assumptions for private-sector pension practitioners to refer to if they wish to use lump-sum interest rates determined using PBGC's historical methodology. Currently, the rates in Appendices B and C of the benefit payment regulation are the same.

The interest assumptions are intended to reflect current conditions in the financial and annuity markets. Assumptions under the asset allocation regulation are updated quarterly; assumptions under the benefit payments regulation are updated monthly. This final rule updates the benefit payments

interest assumptions for October 2013 and updates the asset allocation interest assumptions for the fourth quarter (October through December) of 2013.

The fourth quarter 2013 interest assumptions under the allocation regulation will be 3.00 percent for the first 20 years following the valuation date and 3.31 percent thereafter. In comparison with the interest assumptions in effect for the third quarter of 2013, these interest assumptions represent no change in the select period (the period during which the select rate (the initial rate) applies), an increase of 0.40 percent in the select rate, and a decrease of 0.12 percent in the ultimate rate (the final rate).

The October 2013 interest assumptions under the benefit payments regulation will be 1.75 percent for the period during which a benefit is in pay status and 4.00 percent during any years preceding the benefit's placement in pay status. In comparison with the interest assumptions in effect for September 2013, these interest assumptions represent an increase of 0.25 percent in the immediate annuity rate and are otherwise unchanged.

PBGC has determined that notice and public comment on this amendment are impracticable and contrary to the public interest. This finding is based on the need to determine and issue new interest assumptions promptly so that the assumptions can reflect current market conditions as accurately as possible.

Because of the need to provide immediate guidance for the valuation and payment of benefits under plans with valuation dates during October

2013, PBGC finds that good cause exists for making the assumptions set forth in this amendment effective less than 30 days after publication.

PBGC has determined that this action is not a "significant regulatory action" under the criteria set forth in Executive Order 12866.

Because no general notice of proposed rulemaking is required for this amendment, the Regulatory Flexibility Act of 1980 does not apply. See 5 U.S.C. 601(2).

List of Subjects

29 CFR Part 4022

Employee benefit plans, Pension insurance, Pensions, Reporting and recordkeeping requirements.

29 CFR Part 4044

Employee benefit plans, Pension insurance, Pensions.

In consideration of the foregoing, 29 CFR parts 4022 and 4044 are amended as follows:

PART 4022—BENEFITS PAYABLE IN TERMINATED SINGLE-EMPLOYER PLANS

- 1. The authority citation for part 4022 continues to read as follows:

Authority: 29 U.S.C. 1302, 1322, 1322b, 1341(c)(3)(D), and 1344.

- 2. In appendix B to part 4022, Rate Set 240, as set forth below, is added to the table.

Appendix B to Part 4022—Lump Sum Interest Rates For PBGC Payments

* * * * *

Rate set	For plans with a valuation date		Immediate annuity rate (percent)	Deferred annuities (percent)				
	On or after	Before		i_1	i_2	i_3	n_1	n_2
*	*	*	*	*	*	*	*	*
240	10-1-13	11-1-13	1.75	4.00	4.00	4.00	7	8

- 3. In appendix C to part 4022, Rate Set 240, as set forth below, is added to the table.

Appendix C to Part 4022—Lump Sum Interest Rates For Private-Sector Payments

* * * * *

Rate set	For plans with a valuation date		Immediate annuity rate (percent)	Deferred annuities (percent)				
	On or after	Before		i_1	i_2	i_3	n_1	n_2
*	*	*	*	*	*	*	*	*
240	10-1-13	11-1-13	1.75	4.00	4.00	4.00	7	8

PART 4044—ALLOCATION OF ASSETS IN SINGLE-EMPLOYER PLANS

■ 4. The authority citation for part 4044 continues to read as follows:

Authority: 29 U.S.C. 1301(a), 1302(b)(3), 1341, 1344, 1362.

■ 5. In appendix B to part 4044, a new entry for October–December 2013, as set forth below, is added to the table.

Appendix B to Part 4044—Interest Rates Used to Value Benefits

* * * * *

For valuation dates occurring in the month—	The values of i_t are:					
	i_t	for $t =$	i_t	for $t =$	i_t	for $t =$
October–December 2013	0.0300	1–20	0.0331	>20	N/A	N/A

Issued in Washington, DC, on this 9th day of September 2013.

Judith Starr,

General Counsel, Pension Benefit Guaranty Corporation.

[FR Doc. 2013–22355 Filed 9–12–13; 8:45 am]

BILLING CODE 7709–02–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG–2013–0243]

RIN 1625–AA09

Drawbridge Operation Regulation; Lafourche Bayou, Larose, LA

AGENCY: Coast Guard, DHS.

ACTION: Final rule.

SUMMARY: The Coast Guard is modifying its drawbridge operation regulations by replacing the reference to the SR 310 (Larose Pontoon) Bridge with the LA 657 (Larose) Vertical Lift Bridge. The SR 310 bridge has been taken out of service and has been replaced by the LA 657 bridge. This substitution will also permit the LA 657 bridge to operate under the same schedule as the five other bridges in this area, as opposed to its current open-on-demand schedule.

DATES: This rule is effective October 15, 2013.

ADDRESSES: Documents mentioned in this preamble are part of docket [USCG–2013–0243]. To view documents mentioned in this preamble as being available in the docket, go to <http://www.regulations.gov>, type the docket number in the “SEARCH” box and click “SEARCH.” Click on Open Docket Folder on the line associated with this rulemaking. You may also visit the Docket Management Facility in Room W12–140 on the ground floor of the Department of Transportation West Building, 1200 New Jersey Avenue SE.,

Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email Kay Wade, Bridge Branch Office, Coast Guard; telephone 504–671–2128, email Kay.B.Wade@uscg.mil. If you have questions on viewing the docket, call Barbara Hairston, Program Manager, Docket Operations, telephone 202–366–9826.

SUPPLEMENTARY INFORMATION:

Table of Acronyms

CFR Code of Federal Regulations
 DHS Department of Homeland Security
 FR Federal Register
 NPRM Notice of Proposed Rulemaking
 § Section Symbol
 U.S.C. United States Code

A. Regulatory History and Information

The Coast Guard is issuing this final rule without prior notice and opportunity to comment pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b)). This provision authorizes an agency to issue a rule without prior notice and opportunity to comment when the agency for good cause finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under 5 U.S.C. 553(b), the Coast Guard finds that good cause exists for not publishing a notice of proposed rulemaking (NPRM) with respect to this rule. Providing an opportunity for comment regarding this rule is unnecessary because this rule does not impose any new operational restrictions on the waterway. It merely changes the bridge to which these restrictions apply. Providing an opportunity for comment regarding this rule is impracticable because the SR 310 bridge no longer exists and traffic from this bridge has been diverted to the new LA 657 bridge.

The SR 310 (Larose Pontoon) Bridge was removed from the waterway in April 2013 and replaced by the new LA 657 (Larose) Vertical Lift Bridge, which

is located approximately one-half mile away from the old bridge. The old SR 310 bridge was one in a series of six bridges that feed the local school system, and operated in accordance with the requirements of 33 CFR 117.465(a). The operating requirements for the old SR 310 bridge are specifically located at 33 CFR 117.465(a)(6).

The new LA 657 bridge is located less than one-half mile from the old SR 310 bridge, and essentially replaces the SR 310 bridge in this series. However, the new LA 657 bridge currently operates under the default operating requirements of 33 CFR 117.5, which require that the bridge open on signal. This default operating requirement conflicts with the operating requirements of the other five bridges in this area. Therefore, this rule will essentially replace the SR 310 bridge with the LA 657 bridge at 33 CFR 117.465(a)(6), thus allowing the new bridge to operate under the same requirements as the old bridge, and under the same requirements as the other five bridges in this area.

B. Basis and Purpose

The purpose of this rule is to modify paragraph (a)(6) of 33 CFR 117.465. This paragraph currently refers to the SR 310 (Larose Pontoon) Bridge across Lafourche Bayou at mile 39.1. This bridge has been replaced by the newly constructed LA 657 (Larose) Vertical Lift Bridge across Lafourche Bayou at mile 38.7.

The LA 657 Bridge is the first bridge south of the Gulf Intracoastal Waterway intersection. This bridge is located just south of a flood control structure that has a horizontal clearance of 56 feet and a depth over the sill of 10 feet. Navigation at the site of the bridge consists primarily of tugs with tows, fish, shrimp, crew, and pleasure boats. There is considerable commerce on the bayou in seafood products, sugar, petroleum products, cement, lumber and piles, clays and drilling mud, liquid sulfur, sand and gravel, oil well pipe,