

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that a regulatory distinction is required, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2013-11-05, Amendment 39-17465 (78 FR 33204, June 4, 2013), and adding the following new AD:

2014-12-01 Bell Helicopter Textron, Inc. (Bell): Amendment 39-17862; Docket No. FAA-2013-0697; Directorate Identifier 2013-SW-009-AD.

(a) Applicability

This AD applies to Bell Model 214B helicopters, serial number (S/N) 28001 through 28070, Model 214B-1 helicopters, S/N 28001 through 28070, and Model 214ST helicopters, S/N 28101 through 28200, with a tail rotor hanger bearing (bearing), part number (P/N) 214-040-606-005 or 214-040-606-101 installed, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as a bearing with incorrect seal material, which could fail under extreme temperature or environmental conditions, resulting in loss of tail rotor control and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 2013-11-05, Amendment 39-17465 (78 FR 33204, June 4, 2013).

(d) Effective Date

This AD becomes effective July 14, 2014.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

- (1) Within 10 hours time in service (TIS):
 - (i) Inspect each bearing to determine whether the seal material is correct, as described in the Accomplishment Instructions, Part 1—Inspection, paragraphs 1.a. through 2. and Figure 1 of Bell Alert Service Bulletin (ASB) No. 214-13-74, Revision A, dated March 25, 2013, for Model 214B and 214B-1 helicopters and ASB No. 214ST-13-90, Revision A, dated March 25, 2013, for Model 214ST helicopters.
 - (ii) For each bearing with black seal material, before further flight and thereafter at intervals not to exceed 10 hours TIS, inspect the bearing for leakage, slung grease, or damage. If there is any leakage, slung grease, or damage, before further flight, replace the bearing with an airworthy bearing with red/orange to brown color seal material.
 - (2) Within 500 hours TIS or 6 months, whichever occurs earlier, replace any bearing with black seal material with an airworthy bearing with red/orange to brown color seal material.
 - (3) Do not install bearing P/N 214-040-606-005 or 214-040-606-101 with black seal material on any helicopter.

(g) Special flight permits

Special flight permits are prohibited.

(h) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Rotorcraft Certification Office, FAA, may approve AMOCs for this AD. Send your proposal to: Joon Kim, Aviation Safety Engineer, Rotorcraft Certification Office, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5762; email 7-AVS-ASW-170@faa.gov.
- (2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 6500: Tail Rotor Drive Bearing.

(j) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (3) The following service information was approved for IBR on June 19, 2013 (78 FR 33204, June 4, 2013).
 - (i) Bell Alert Service Bulletin No. 214-13-74, Revision A, dated March 25, 2013.

(ii) Bell Alert Service Bulletin No. 214ST-13-90, Revision A, dated March 25, 2013.

(4) For Bell service information identified in this AD, contact Bell Helicopter Textron, Inc., P.O. Box 482, Fort Worth, Texas 76101; telephone (817) 280-3391; fax (817) 280-6466; or at <http://www.bellcustomer.com/files/>.

(5) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(6) You may also view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on May 30, 2014.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2014-13260 Filed 6-6-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2013-0914; Airspace Docket No. 13-AGL-29]

Establishment of Class E Airspace; Mineral Point, WI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace at Mineral Point, WI. A Class E surface area is necessary to accommodate increased business aviation and flight instruction activity at Iowa County Airport. The FAA is taking this action to enhance the safety and management of Instrument Flight Rule (IFR) operations for SIAPs at the airport. Geographic coordinates of the existing Class E airspace are also updated.

DATES: *Effective date:* 0901 UTC, July 24, 2014. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone 817-321-7716.

SUPPLEMENTARY INFORMATION:**History**

On March 3, 2014, the FAA published in the **Federal Register** a notice of proposed rulemaking (NPRM) to establish Class E airspace for the Mineral Point, WI, area, creating additional controlled airspace at Iowa County Airport (79 FR 11732) Docket No. FAA–2013–0914. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received. Class E airspace designations are published in paragraph 6002 and 6005, respectively, of FAA Order 7400.9X dated August 7, 2013, and effective September 15, 2013, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) Part 71 by establishing Class E airspace designated as a surface area within a 4.1-mile radius of Iowa County Airport, Mineral Point, WI. Increases in business aviation, air cargo, and flight instruction operations under instrument meteorological conditions have made this addition of controlled airspace necessary for the safety and management of IFR operations at the airport. Geographic coordinates of the airport in Class E airspace extending upward from 700 feet above the surface are also adjusted to coincide with the FAA's aeronautical database.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority of the FAA Administrator. Subtitle VII,

Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace at Iowa County Airport, Mineral Point, WI.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures," paragraph 311a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9X, Airspace Designations and Reporting Points, dated August 7, 2013, and effective September 15, 2013, is amended as follows:

Paragraph 6002 Class E Airspace Designated as Surface Areas.

* * * * *

AGL WI E2 Mineral Point, WI [New]

Mineral Point, Iowa County Airport, WI (Lat. 42°53'13" N., long. 90°14'12" W.)

Within a 4.1-mile radius of Iowa County Airport. This Class E airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will

thereafter be continuously published in the Airport/Facility Directory.

Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface.

* * * * *

AGL WI E5 Mineral Point, WI [Amended]

Mineral Point, Iowa County Airport, WI (Lat. 42°53'13" N., long. 90°14'12" W.)

Mineral Point NDB

(Lat. 42°53'17" N., long. 90°13'35" W.)

That airspace extending upward from 700 feet above the surface within a 7.2-mile radius of Iowa County Airport, and within 2.6 miles each side of the 029° bearing from the Mineral Point NDB extending from the 7.2-mile radius to 7.4 miles northeast of the airport.

Issued in Fort Worth, Texas, on May 20, 2014.

Kent M. Wheeler,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2014–13277 Filed 6–6–14; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2014–0178; Airspace Docket No. 13–ASW–23]

Establishment of Class E Airspace; Conway, AR

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace at Conway, AR. Controlled airspace is necessary to accommodate new Area Navigation (RNAV) Standard Instrument Approach Procedures at Cantrell Field. The FAA is taking this action to enhance the safety and management of Instrument Flight Rule (IFR) operations at the airport.

DATES: *Effective date:* 0901 UTC, July 24, 2014. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Raul Garza, Jr., Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone 817–321–7654.

SUPPLEMENTARY INFORMATION: