

Bombardier, Inc.: Docket No. FAA–2015–0822; Directorate Identifier 2014–NM–210–AD.

(a) Comments Due Date

We must receive comments by May 28, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the airplanes, certificated in any category, identified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD.

(1) Bombardier, Inc. Model CL–600–2C10 (Regional Jet Series 700, 701, & 702) airplanes, serial numbers 10002 through 10336 inclusive.

(2) Bombardier, Inc. Model CL–600–2D15 (Regional Jet Series 705), and Model CL–600–2D24 (Regional Jet Series 900) airplanes, serial numbers 15001 through 15297 inclusive.

(3) Bombardier, Inc. Model CL–600–2E25 (Regional Jet Series 1000) airplanes, serial numbers 19001 through 19038 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by results of a design review indicating that the burst pressure of the flexible hose, used to vent oxygen from the high-pressure relief valve of the oxygen cylinder overboard, was lower than the opening pressure of the high-pressure relief valve, which could cause the flexible hose to burst before it can vent the excess oxygen overboard. We are issuing this AD to prevent the accumulation of oxygen in an enclosed space, which could result in an uncontrolled oxygen-fed fire if an ignition source is nearby.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Before the accumulation of 5,800 total flight hours, or within 44 months after the effective date of this AD, whichever occurs first, replace all oxygen hose assemblies having part number (P/N) S6946–01 with new, improved assemblies having P/N BA670–44025–001, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 670BA–35–013, Revision A, dated September 23, 2013, including Appendix A, dated May 21, 2013. For airplanes on which Supplemental Type Certificate ST01648NY ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01648NY.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01648NY.pdf)) is installed, only PART B of the Accomplishment Instructions of Bombardier Service Bulletin 670BA–35–013, Revision A, dated September 23, 2013, is required.

(h) Credit for Previous Actions

This paragraph provides credit for the replacement specified in paragraph (g) of this

AD, if that action was performed before the effective date of this AD using Bombardier Service Bulletin 670BA–35–013, dated May 21, 2013, which is not incorporated by reference in this AD.

(i) Parts Installation Prohibition

As of the effective date of this AD, no person may install an oxygen hose assembly, P/N S6946–01, on any airplane.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2014–37, dated October 17, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–0822.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crij@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on March 27, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–08329 Filed 4–10–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 93

[Docket No. FAA–2014–1073; Notice No. 14–11B]

RIN 2120–AJ89

Slot Management and Transparency for LaGuardia Airport, John F. Kennedy International Airport, and Newark Liberty International Airport; Notice of Availability of Responses to Clarifying Questions; Request for Extension of Comment Period

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking; clarification.

SUMMARY: This action announces the placement in the docket of a response to requests for clarification of the notice of proposed rulemaking (NPRM) published on January 8, 2015. In the NPRM, the U.S. Department of Transportation (DOT) and the FAA proposed to replace the Orders limiting scheduled operations at John F. Kennedy International Airport (JFK) and Newark Liberty International Airport (EWR), and limiting scheduled and unscheduled operations at LaGuardia Airport (LGA). The Orders are scheduled to expire when the rulemaking is final and in effect, but not later than October 29, 2016. The proposed rule is intended to provide a longer-term and comprehensive approach to slot management at JFK, EWR, and LGA.

By letters posted to the public docket, Airlines for America and Sabre Corporation submitted questions regarding various provisions in the NPRM they believe need further clarification before meaningful comments can be submitted to the docket. The DOT and the FAA have reviewed these requests and a coordinated response has been placed in the docket. That document also responds to Airlines for America's renewed request for an extension of the comment period and request for a public meeting.

DATES: Send comments on or before May 8, 2015.

ADDRESSES: You may send comments identified by docket number FAA–2014–1073 using any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the online instructions for sending your comments electronically.

- *Mail:* Send comments to Docket Operations, M–30; U.S. Department of

Transportation (DOT), 1200 New Jersey Avenue SE., Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* Fax comments to Docket Operations at 202-493-2251.

Privacy: In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to www.regulations.gov, as described in the system of records notice (DOT/ALL-14 FDMS), which can be reviewed at www.dot.gov/privacy.

Docket: Background documents or comments received may be read at <http://www.regulations.gov> at any time. Follow the online instructions for accessing the docket or Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: For technical questions concerning this action, contact Molly Smith, Office of Aviation Policy and Plans, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone (202) 267-3274; email molly.w.smith@faa.gov; Susan Pfingstler, System Operations Services, Air Traffic Organization, Federal Aviation Administration, 600 Independence Avenue SW., Washington, DC 20591; telephone (202) 267-6462; email susan.pfingstler@faa.gov; or Peter Irvine, U.S. Department of Transportation, Office of Aviation Analysis, 1200 New Jersey Avenue SE., Washington, DC 20590; telephone (202) 366-3156; email peter.irvine@dot.gov.

For legal questions concerning this action, contact Bonnie Dragotto, Office of the Chief Counsel, Regulations Division, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone (202) 267-3808; email bonnie.dragotto@faa.gov; or Cindy Baraban, U.S. Department of Transportation, Office of the General Counsel, 1200 New Jersey Avenue SE., Washington, DC 20590; telephone (202) 366-9159; email cindy.baraban@dot.gov.

SUPPLEMENTARY INFORMATION:

Additional Information

Comments Invited

The FAA invites interested persons to participate in this rulemaking by submitting written comments, data, or views. The agency also invites comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

The FAA will file in the docket all comments it receives, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the DOT and the FAA will consider all comments received on or before the closing date for comments. We will also consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The agency may change this proposal in light of the comments it receives.

Proprietary or Confidential Business Information: Do not file proprietary or confidential business information in the docket. Such information must be sent or delivered directly to the person identified in the **FOR FURTHER INFORMATION CONTACT** section of this document, and marked as proprietary or confidential. If submitting information on a disk or CD ROM, mark the outside of the disk or CD ROM, and identify electronically within the disk or CD ROM the specific information that is proprietary or confidential.

Under 14 CFR 11.35(b), if the FAA is aware of proprietary information filed with a comment, the agency does not place it in the docket. It is held in a separate file to which the public does not have access, and the FAA places a note in the docket that it has received it. If the FAA receives a request to examine or copy this information, it treats it as any other request under the Freedom of Information Act (5 U.S.C. 552). The FAA processes such a request under the DOT procedures found in 49 CFR part 7.

Availability of Rulemaking Documents

An electronic copy of rulemaking documents may be obtained from the Internet by—

1. Searching the Federal eRulemaking Portal (<http://www.regulations.gov>);
2. Visiting the FAA's Regulations and Policies Web page at http://www.faa.gov/regulations_policies or
3. Accessing the Government Printing Office's Web page at <http://www.gpo.gov/fdsys/>.

Copies may also be obtained by sending a request to the Federal Aviation Administration, Office of Rulemaking, ARM-1, 800 Independence Avenue SW., Washington, DC 20591, or by calling (202) 267-9677. Commenters must identify the docket or notice number of this rulemaking.

All documents the FAA considered in developing this proposed rule, including economic analyses and technical reports, may be accessed from the Internet through the Federal eRulemaking Portal referenced in item (1) above.

Issued under authority provided by 49 U.S.C. 106(f) in Washington, DC, on April 6, 2015.

Brandon Belford,

Deputy Assistant Secretary for Aviation and International Affairs.

Richard M. Swayze,

Assistant Administrator for Policy, International Affairs, and Environment.

[FR Doc. 2015-08168 Filed 4-10-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No.: FAA-2015-0783; Notice No. 15-02]

RIN 2120-AA65

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to remove certain redundant or underutilized ground-based non-directional beacon and very high frequency, omnidirectional radio range Standard Instrument Approach Procedures based on the criteria established by the FAA's Policy for Discontinuance of Certain Instrument Approach Procedures.

DATES: Send comments on or before May 28, 2015.