

(a) Effective Date

This AD is effective November 23, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model DHC-8-301, -311, and -315 airplanes, certificated in any category, serial numbers 100 through 672 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by reports indicating that the forward right-hand type I emergency exit door could not be opened during maintenance. An investigation determined that the exit door handle was jammed due to corroded center and lower shaft ball bearings. We are issuing this AD to address corrosion of the emergency exit door ball bearings, which could result in the inability to open the emergency exit door during an emergency evacuation and consequently impede airplane egress.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of Maintenance or Inspection Program

Within 60 days after November 23, 2018 (the effective date of this AD): Revise the maintenance or inspection program, as applicable, to incorporate de Havilland Inc. Dash 8 Series 300 Maintenance Task Card Task Number 5220/12 ("Servicing of Forward RH Emergency Exit Mechanisms"), dated March 15, 2017; and Temporary Revision 52-042, dated April 10, 2018, to the DHC-8-300 Aircraft Maintenance Manual (AMM). The initial compliance time for doing the task is at the time specified in de Havilland Inc. Dash 8 Series 300 Maintenance Task Card Task Number 5220/12 ("Servicing of Forward RH Emergency Exit Mechanisms"), dated March 15, 2017, or within 60 days after November 23, 2018, whichever occurs later.

(h) Inspection and Replacement

Within 5,000 flight hours or 36 months, whichever occurs first, after November 23, 2018 (the effective date of this AD): Do a detailed inspection of all ball bearings of the forward right-hand type I emergency exit for corrosion, seal damage, and loss of lubricant; replace bearings as applicable; and apply corrosion inhibiting compound (CIC); in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-52-65, dated July 26, 2017. Do all applicable replacements before further flight.

(i) No Alternative Actions or Intervals

After the maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions and intervals are approved as an alternative method of compliance (AMOC) in accordance with the

procedures specified in paragraph (j)(1) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2017-30, dated August 30, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0586.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Admin Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on November 23, 2018 (83 FR 52754, October 18, 2018).

(i) Bombardier Service Bulletin 8-52-65, dated July 26, 2017.

(ii) de Havilland Inc. Dash 8 Series 300 Maintenance Task Card Task Number 5220/12 ("Servicing of Forward RH Emergency Exit Mechanisms"), dated March 15, 2017.

(iii) Temporary Revision (TR) 52-042, dated April 10, 2018, to the DHC-8-300 Aircraft Maintenance Manual (AMM).

(4) For service information identified in this AD, contact Bombardier, Inc. Q-Series

Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; internet <http://www.bombardier.com>.

(5) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 8, 2018.

Chris Spangenberg,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-25002 Filed 11-16-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 117**

[Docket No. USCG-2018-0980]

Drawbridge Operation Regulation; Sacramento River, Rio Vista, CA

AGENCY: Coast Guard, DHS.

ACTION: Notice of deviation from drawbridge regulation.

SUMMARY: The Coast Guard has issued a temporary deviation from the operating schedule that governs the Rio Vista Drawbridge across Sacramento River, mile 12.8 at Rio Vista, CA. The deviation is necessary to allow the bridge owner to conduct preventative maintenance on the bridge. This deviation allows the bridge to operate at various specified times during the deviation period.

DATES: This deviation is effective without actual notice from November 19, 2018 to 11:50 p.m. on February 15, 2019. For the purposes of enforcement, actual notice will be used from November 15, 2018 through November 19, 2018.

ADDRESSES: The docket for this deviation, USCG-2018-0980, is available at <http://www.regulations.gov>. Type the docket number in the "SEARCH" box and click "SEARCH." Click on Open Docket Folder on the line associated with this deviation.

FOR FURTHER INFORMATION CONTACT: If you have questions on this temporary

deviation, call or email Carl T. Hausner, Chief, Bridge Section, Eleventh Coast Guard District; telephone 510-437-3516, email Carl.T.Hausner@uscg.mil.

SUPPLEMENTARY INFORMATION: The California Department of Transportation has requested a temporary change to the operation of the Rio Vista Drawbridge, mile 12.8, over the Sacramento River, at Rio Vista, CA. The drawbridge navigation span provides a vertical clearance of 18 feet above Mean High Water in the closed-to-navigation position. In accordance with 33 CFR 117.5, the draw opens on signal. Navigation on the waterway is commercial and recreational.

From November 15, 2018 to February 15, 2019, the draw shall open for recreational vessels in accordance with the following schedule: Monday through Friday, 7 a.m. to 3:30 p.m., the draw need not open for the passage of recreational vessels except between 11 a.m. and noon when the draw shall open on signal when notice is given to the bridge tender. The draw shall open on signal, Monday through Friday, 3:30 p.m. to 7 a.m. the following morning, if at least a 4-hour notification is given to the bridge tender. The draw shall open on signal from 7 a.m. on Saturday through 11:59 p.m. on Sunday when notice is given to the bridge tender.

From November 15, 2018 to February 15, 2019, the draw shall open for commercial vessels in accordance with the following schedule: The draw shall open on signal from midnight on Monday through 7 a.m. on Saturday if at least a 4-hour notification is given to the bridge tender. The draw shall open on signal from 7 a.m. on Saturday through 11:59 p.m. on Sunday when notice is given to the bridge tender.

The temporary schedule change will allow the bridge owner to conduct needed maintenance and painting on the lift span portion of the bridge. This temporary deviation has been coordinated with the waterway users. No objections to the proposed temporary deviation were raised.

Vessels able to pass through the bridge in the closed position may do so at anytime. The bridge will be able to open for emergencies in accordance with 33 CFR 117.31(b). There is no immediate alternate route for vessels to pass. The Coast Guard will also inform the users of the waterway through our Local and Broadcast Notices to Mariners of the change in operating schedule for the bridge so vessel operators can arrange their transits to minimize any impact caused by the temporary deviation.

In accordance with 33 CFR 117.35(e), the drawbridge must return to its regular

operating schedule immediately at the end of the effective period of this temporary deviation. This deviation from the operating regulations is authorized under 33 CFR 117.35.

Dated: November 6, 2018.

Carl T. Hausner,

District Bridge Chief, Eleventh Coast Guard District.

[FR Doc. 2018-25153 Filed 11-16-18; 8:45 am]

BILLING CODE 9110-04-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket Number USCG-2018-0371]

RIN 1625-AA00

Safety Zone; Penn's Landing Fireworks, Delaware River, Philadelphia PA

AGENCY: Coast Guard, DHS.

ACTION: Final rule.

SUMMARY: The Coast Guard is amending the existing recurring fireworks safety zone on the Delaware River Adjacent to Penn's Landing in Philadelphia, Pennsylvania. This amendment allows the Coast Guard to enforce the safety zone at this location throughout the entire year. The Coast Guard will notify the public of upcoming enforcement of the zone through publication of a Notice of Enforcement in the **Federal Register** and Broadcast Notice to Mariners. This change will expedite public notification of events at the location and ensure the protection of the maritime public and event participants from the hazards associated with fireworks displays in the Delaware River adjacent to Penn's Landing.

DATES: This rule is effective December 19, 2018.

ADDRESSES: To view documents mentioned in this preamble as being available in the docket, go to <https://www.regulations.gov>, type USCG-2018-0371 in the "SEARCH" box and click "SEARCH." Click on Open Docket Folder on the line associated with this rule.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email Petty Officer Edmund Ofalt, U.S. Coast Guard, Sector Delaware Bay, Waterways Management Division; telephone 215-271-4814, email Edmund.J.Ofalt@uscg.mil.

SUPPLEMENTARY INFORMATION:

I. Table of Abbreviations

CFR Code of Federal Regulations
DHS Department of Homeland Security
FR Federal Register
NPRM Notice of proposed rulemaking
§ Section
U.S.C. United States Code

II. Background Information and Regulatory History

The Coast Guard routinely receives requests for fireworks displays in the Delaware River Adjacent to Penn's Landing in Philadelphia, Pennsylvania. As a result, the Coast Guard previously issued a rule creating a recurring safety zone location for this location, listed as entry (a)16 in the table to 33 CFR 165.506. That regulation lists possible days of anticipated enforcement as July 2nd, 3rd, 4th, or 5th; Columbus Day; December 31st, and January 1st. In recent years, however, the number of firework events at this location have significantly increased. To date in the year 2018 there have been 13 requests for fireworks events at this location—many more than the anticipated number of approximately 3 events covered by the current regulation. The additional requests fall outside the enforcement dates listed in the CFR. As a result, the Coast Guard had to issue numerous temporary safety zones to cover the additional events that fall outside of the coverage of the current regulation. In accordance with good cause exceptions found in 5 U.S.C. 553, the rules creating these temporary safety zones are generally not preceded by notice of proposed rulemaking due to the short lead-time often provided to the Coast Guard.

In response, on September 21, 2018, the Coast Guard published a notice of proposed rulemaking (NPRM) titled "Safety Zone; Penn's Landing Fireworks, Delaware River, Philadelphia PA" (83 FR 47852). There we stated why we issued the NPRM, and invited comments on our proposed regulatory action. During the comment period that ended October 22, 2018, we received one comment.

III. Legal Authority and Need for Rule

The Coast Guard is issuing this rule under authority in 33 U.S.C. 1231. The Captain of the Port Delaware Bay (COTP) has determined that potential hazards associated with the fireworks to be used in this type of display will be a safety concern for anyone within a 500 yard radius of the fireworks barge. The purpose of this rule is to ensure safety of vessels and the navigable waters in the safety zone before, during and after the scheduled event.