

fit as specified in A330–53–3215, R3, as applicable; and A330–53–3215, R3; specifies to contact Airbus for repair instructions, and specifies that action as “RC,” before further flight, repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Accomplishment of corrective actions, as required by paragraph (h)(1) of this AD, does not constitute terminating action for the repetitive inspections required by the introductory text of paragraph (h) of this AD.

(4) Accomplishment of a repair on an airplane, as required by paragraph (h)(2) of this AD, does not constitute terminating action for the repetitive inspections required by the introductory text of paragraph (h) of this AD for that airplane, unless the method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA DOA indicates otherwise.

**(i) No Reporting Requirement**

Although A330–53–3215, R3, specifies to submit certain information to the manufacturer, and specifies that action as RC, this AD does not include that requirement.

**(j) Credit for Previous Actions**

This paragraph provides credit for the inspections required by the introductory text of paragraph (h) of this AD and the related investigative and corrective actions required by paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD, using Airbus Service Bulletin A330–53–3215, dated June 21, 2013; or Revision 01, dated April 17, 2014; or Revision 02, dated November 23, 2016.

**(k) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: Except as specified by paragraphs (h)(1), (h)(2), and

(i) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(l) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0146, dated July 12, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0800.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330–53–3215, Revision 03, dated January 22, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

**John P. Piccola,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–26474 Filed 12–7–18; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

[Docket No. FAA–2018–0685; Airspace Docket No. 18–AGL–19]

RIN 2120–AA66

**Amendment of Class D Airspace; Detroit, MI**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class D airspace at Coleman A. Young Municipal Airport (formerly Detroit City Airport), Detroit, MI, by changing the airspace designation to Detroit, MI, thereby removing the old airport name. The name and geographic coordinates of this airport are also updated to coincide with the FAA’s aeronautical database. This action is necessary to keep information current for the safety and management of aircraft within the national airspace system.

**DATES:** Effective 0901 UTC, February 28, 2019. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202) 741–6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5711.

**SUPPLEMENTARY INFORMATION:**

### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class D airspace at Coleman A. Young Memorial Airport, Detroit, MI.

### History

The FAA published a notice of proposed rulemaking in the **Federal Register** (83 FR 47580; September 20, 2018) for Docket No. FAA-2018-0685 to amend Class D airspace at Coleman A. Young Memorial Airport, Detroit, MI. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Subsequent to publication, the FAA discovered that the longitudinal geographic coordinate for the airport was published incorrectly. That error is corrected in this final rule.

Class D airspace designations are published in paragraph 5000 of FAA Order 7400.11C, dated August 13, 2018, and effective September 15, 2018, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designations listed in this document will be published subsequently in the Order.

### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018. FAA Order 7400.11C is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11C lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

### The Rule

This amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 modifies the Class D airspace by updating for the location in the header of the airspace legal description to Detroit, MI (previously Detroit City Airport, MI), at Coleman A. Young

Municipal Airport (formerly Detroit City Airport), Detroit, MI, to comply with FAA Order 7400.2L, Procedures for Handling Airspace Matters. The name and geographic coordinates of the airport are also updated to coincide with the FAA's aeronautical database.

The longitudinal geographic coordinate for the airport is corrected to "83°00'37" W" Except for this change, this rule is the same as published in the NPRM.

### Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

### Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

### § 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018, is amended as follows:

*Paragraph 5000 Class D Airspace.*

\* \* \* \* \*

### AGL MI D Detroit, MI [Amended]

Coleman A. Young Municipal Airport, MI (Lat. 42°24'34" N, long. 83°00'37" W)

That airspace extending upward from the surface to and including 3,100 feet MSL within a 4.1-mile radius of the Coleman A. Young Municipal Airport.

Issued in Fort Worth, Texas, on November 26, 2018.

**Walter Tweedy,**

*Acting Manager, Operations Support Group, ATO Central Service Center.*

[FR Doc. 2018-26503 Filed 12-7-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 71

[Docket No. FAA-2018-0698; Airspace Docket No. 18-AGL-20]

RIN 2120-AA66

### Amendment of Class D Airspace; Pontiac, MI

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action modifies Class D airspace at Oakland County International Airport, Pontiac, MI, due to the decommissioning of the Pontiac VHF omnidirectional range (VOR) navigation aid, which provided navigation information for the instrument procedures at this airport, as part of the VOR Minimum Operational Network (MON) Program. This action also replaces the outdated term Airport/Facility Directory with Chart Supplement. Airspace redesign is necessary for the safety and management of instrument flight rules (IFR) operations at this airport.

**DATES:** Effective 0901 UTC, February 28, 2019. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order