

requirements subject to the Paperwork Reduction Act.

List of Subjects in 5 CFR Part 532

Administrative practice and procedure, Freedom of information, Government employees, Reporting and recordkeeping requirements, Wages.

Office of Personnel Management.

Alexys Stanley,
Regulatory Affairs.

Accordingly, OPM is proposing to amend 5 CFR part 532 as follows:

PART 532—PREVAILING RATE SYSTEMS

■ 1. The authority citation for part 532 continues to read as follows:

Authority: 5 U.S.C. 5343, 5346; § 532.707 also issued under 5 U.S.C. 552.

■ 2. In Appendix D to subpart B amend the table by revising the wage area listing for the State of North Carolina to read as follows:

Appendix D to Subpart B of Part 532—Nonappropriated Fund Wage and Survey Areas

DEFINITIONS OF WAGE AREAS AND WAGE AREA SURVEY AREAS

*	*	*	*	*
NORTH CAROLINA				
Craven				
<i>Survey Area</i>				
North Carolina:				
Craven				
<hr/>				
<i>Area of Application. Survey area plus:</i>				
North Carolina:				
Carteret				
Dare				
Cumberland				
<i>Survey Area</i>				
North Carolina:				
Cumberland				
<i>Area of Application. Survey area plus:</i>				
North Carolina:				
Durham				
Forsyth				
Rowan				
Onslow				
<i>Survey area</i>				
North Carolina:				
Onslow				
<i>Area of Application. Survey area plus:</i>				
North Carolina:				
New Hanover				
Wayne				
<i>Survey area</i>				
North Carolina:				
Wayne				
<i>Area of Application. Survey area plus:</i>				
North Carolina:				
Halifax				
Pitt				
*	*	*	*	*

[FR Doc. 2019-28007 Filed 12-30-19; 8:45 am]

BILLING CODE 6325-39-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0991; Product Identifier 2019-NM-179-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2016-16-09 and AD 2019-03-20, which apply to Dassault Aviation Model FALCON 7X airplanes. Those ADs require revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. Since the FAA issued AD 2019-03-20, the FAA has determined that new or more restrictive airworthiness limitations are necessary. This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by February 14, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0991.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0991; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0991; Product Identifier 2019-NM-179-AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact the agency receives about this NPRM.

Discussion

The FAA issued AD 2019–03–20, Amendment 39–19572 (84 FR 6059, February 26, 2019) (“AD 2019–03–20”), which applied to certain Dassault Aviation Model FALCON 7X airplanes. AD 2019–03–20 requires revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. The FAA issued AD 2019–03–20 to address reduced structural integrity and reduced control of airplanes due to the failure of system components.

AD 2019–03–20 specifies that accomplishing the revision required by paragraph (g) of that AD terminates all requirements of AD 2016–16–09, Amendment 39–18607 (81 FR 52752, August 10, 2016). AD 2019–03–20 also specifies that accomplishing the revisions required by paragraph (g) of that AD terminates the requirements of paragraph (q) of AD 2014–16–23, Amendment 39–17947 (79 FR 52545, September 4, 2014); that provision is part of this proposed AD.

Actions Since AD 2019–03–20 Was Issued

Since the FAA issued AD 2019–03–20, the FAA has determined that new or more restrictive airworthiness limitations are necessary.

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0257, dated October 17, 2019 (“EASA AD 2019–0257”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Dassault Aviation Model FALCON 7X airplanes. EASA AD 2019–0257 supersedes EASA AD 2018–0277, dated December 17, 2018, which in turn superseded EASA AD 2018–0101, dated May 3, 2018 (FAA AD 2019–03–20 corresponds to EASA AD 2018–0101).

Airplanes with an original airworthiness certificate or original export certificate of airworthiness issued after June 1, 2019, must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this proposed AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is proposing this AD to address reduced structural integrity and reduced control of

airplanes due to the failure of system components. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0257 describes new or more restrictive maintenance airworthiness limitations for airplane structures and systems.

This AD would also require Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X Maintenance Manual (MM), which the Director of the Federal Register approved for incorporation by reference as of April 2, 2019 (84 FR 6059, February 26, 2019).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the FAA evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Proposed AD Requirements

This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, which are specified in EASA AD 2019–0257, described previously, as incorporated by reference. Any differences with EASA AD 2019–0257 are identified as exceptions in the regulatory text of this proposed AD.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (*e.g.*, inspections) and Critical Design Configuration Control Limitations (CDCCLs). Compliance with these actions and CDCCLs is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request

approval for an alternative method of compliance according to paragraph (m)(1) of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2019–0257 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2019–0257 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD.

Service information specified in EASA AD 2019–0257 that is required for compliance with EASA AD 2019–0257 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0992 after the FAA final rule is published.

Airworthiness Limitation ADs Using the New Process

The FAA’s new process, which uses MCAI ADs as the primary source of information for compliance with corresponding FAA ADs, has been limited to certain MCAI ADs (primarily those with service bulletins as the primary source of information for accomplishing the actions required by the FAA AD). However, the FAA is now expanding the process to include MCAI ADs that specify the incorporation of airworthiness limitation documents.

Although the format of the airworthiness limitation ADs using the new process is different than the FAA’s existing format for airworthiness limitation ADs, the FAA requirements are the same: Operators must revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in the new airworthiness limitation document.

The previous format of the airworthiness limitation ADs included a paragraph that specified that no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in the AMOCs paragraph under “Other FAA Provisions.” This new format includes a “New Provisions for Alternative Actions, Intervals, and CDCCLs” paragraph that does not specifically refer to AMOCs, but operators may still request an AMOC to use an alternative action, interval, or CDCCL.

Costs of Compliance

The FAA estimates that this proposed AD affects 67 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

The FAA estimates the total cost per operator for the retained actions from AD 2019–03–20 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. In the past, the agency has estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. The FAA estimates the total cost per operator for the new proposed actions to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2016–16–09, Amendment 39–18607 (81 FR 52752, August 10, 2016), and AD 2019–03–20, Amendment 39–19572 (84 FR 6059, February 26, 2019), and adding the following new AD:

Dassault Aviation: Docket No. FAA–2019–0991; Product Identifier 2019–NM–179–AD.

(a) Comments Due Date

The FAA must receive comments by February 14, 2020.

(b) Affected ADs

(1) This AD replaces AD 2016–16–09, Amendment 39–18607 (81 FR 52752, August 10, 2016) and AD 2019–03–20, Amendment 39–19572 (84 FR 6059, February 26, 2019) (“AD 2019–03–20”).

(2) This AD affects AD 2014–16–23, Amendment 39–17947 (79 FR 52545, September 4, 2014) (“AD 2014–16–23”).

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before June 1, 2019.

Note 1 to paragraph (c): Model FALCON 7X airplanes with modifications M1000 and M1254 incorporated are commonly referred to as “Model FALCON 8X” airplanes as a marketing designation.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity and reduced control of airplanes due to the failure of system components.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Maintenance or Inspection Program Revision, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2019–03–20, with no changes. Within 90 days after April 2, 2019 (the effective date of AD 2019–03–20), revise the existing maintenance or inspection program, as applicable, by incorporating the information specified in Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X Maintenance Manual (MM). The initial compliance times for the tasks specified in Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X MM are at the applicable compliance times specified in Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X MM, or within 90 days after April 2, 2019, whichever occurs later. Accomplishing the maintenance or inspection program revision required by paragraph (i) of this AD terminates the requirements of this paragraph.

(h) Retained No Alternative Actions, Intervals, or Critical Design Configuration Control Limitations (CDCCLs), With a New Exception

This paragraph restates the requirements of paragraph (i) of AD 2019–03–20, with a new exception. Except as required by paragraph (i) of this AD, after the maintenance or inspection program, as applicable, has been revised as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (m)(1) of this AD.

(i) New Maintenance or Inspection Program Revision

Except as specified in paragraph (j) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019–0257, dated October 17, 2019 (“EASA AD 2019–0257”). Accomplishing the maintenance or inspection program revision required by this paragraph terminates the requirements of paragraph (g) of this AD.

(j) Exceptions to EASA AD 2019–0257

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2019–0257 do not apply to this AD.

(2) Where paragraph (3) of EASA AD 2019–0257 specifies a compliance time of “Within 12 months” after its effective date to “revise the approved AMP [Aircraft Maintenance Program],” this AD requires “revising the existing maintenance or inspection program, as applicable” to incorporate the “limitations, tasks and associated thresholds and intervals” specified in paragraph (3) of EASA AD 2019–0257 within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2019–0257 is at the applicable “associated thresholds” specified in paragraph (3) of EASA AD 2019–0257, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2019–0257 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2019–0257 does not apply to this AD.

(k) New Provisions for Alternative Actions, Intervals, and CDCCLs

After the maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (*e.g.*, inspections), intervals, and CDCCLs are allowed except as specified in the provisions of the “Ref. Publications” section of EASA AD 2019–0257.

(l) Terminating Action for Certain Requirements in AD 2014–16–23

Accomplishing the actions required by paragraph (i) of this AD terminates the requirements of paragraph (q) of AD 2014–16–23.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (n)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA AD 2019–0257 that contains RC procedures and tests: Except as required by paragraph (m)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(n) Related Information

(1) For information about EASA AD 2019–0257, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0992.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226.

Issued in Des Moines, Washington, on December 12, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–27886 Filed 12–30–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–0404; Product Identifier 2015–SW–066–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters (Previously Eurocopter France)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2008–24–04 for Eurocopter France (now Airbus Helicopters) Model AS355E, AS355F, AS355F1, AS355F2, and AS355N helicopters. AD 2008–24–04 requires repetitively inspecting the lubricating pump and checking the magnetic chip detector plug (chip detector) and the main gearbox (MGB) oil-sight glass. Since the FAA issued AD 2008–24–04, Airbus Helicopters has developed an alteration of the MGB oil flow distribution that corrects the unsafe condition. This proposed AD would retain the requirements of AD 2008–24–04 and would allow the option of altering the MGB oil flow distribution as a terminating action for the inspections. The actions of this proposed AD are intended to address an unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by March 2, 2020.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <https://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202–493–2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590–0001.

- *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.