

the quarterly Call Report for the quarter ending March 31, 2023 and ending with the quarterly Call Report for the quarter ending December 31, 2025.

#### § 702.703 CECL transition provisions.

(a) *Eligibility*—The NCUA shall use the transition provisions of this subpart in determining a credit union's net worth category under this part, as applicable, if:

(1) The credit union has not adopted CECL before December 15, 2022; and

(2) The credit union records a reduction in retained earnings due to the adoption of CECL.

(b) *Determination of CECL transition amount.* (1) For purposes of calculating the first three quarters of the transition period, as described in paragraph (c)(1) of this section, the CECL transitional amount is equal to the difference between the credit union's retained earnings on December 15, 2022, and the credit union's retained earnings on January 1, 2023.

(2) For purposes of calculating the fourth through twelfth quarters of the transition period, as described in paragraphs (c)(2) and (3) of this section, the CECL transitional amount is equal to the difference between the credit union's retained earnings on December 31, 2023, and the credit union's retained earnings on December 30, 2024.

(c) *Calculation of CECL transition provision.* In determining the net worth category of a credit union as provided in paragraph (a) of this section, the NCUA shall:

(1) Increase retained earnings and total assets as reported on the Call Report for purposes of the net worth ratio by 100 percent of its CECL transitional amount during the first three quarters of the transition period (first three reporting quarters of 2023);

(2) Increase retained earnings and total assets as reported on the Call Report for purposes of the net worth ratio by sixty-seven percent of its CECL transitional amount during the second four quarters of the transition period (fourth reporting quarter of 2023 and first three reporting quarters of 2024); and

(3) Increase retained earnings and total assets as reported on the Call Report for purposes of the net worth ratio by thirty-three percent of its CECL transitional amount during the final four quarters of the transition period (fourth reporting quarter of 2024 and first three reporting quarters of 2025).

[FR Doc. 2020-16987 Filed 8-18-20; 8:45 am]

BILLING CODE P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-0778; Product Identifier 2020-NM-097-AD]

RIN 2120-AA64

#### Airworthiness Directives; Dassault Aviation Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede Airworthiness Directive (AD) 2019-23-05, which applies to all Dassault Aviation Model MYSTERE-FALCON 900 airplanes. AD 2019-23-05 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. Since the FAA issued AD 2019-23-05, the agency has determined that new or more restrictive airworthiness limitations are necessary. This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by October 5, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material that will be incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet:

[www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. For Dassault service information identified in this proposed AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; phone: 201-440-6700; internet: <http://www.dassaultfalcon.com>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0778.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0778; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3226; email: [tom.rodriguez@faa.gov](mailto:tom.rodriguez@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2020-0778; Product Identifier 2020-NM-097-AD" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments that are received, without change, to <https://www.regulations.gov>, including any personal information you provide.

The FAA will also post a report summarizing each substantive verbal contact the FAA receives about this NPRM.

### Confidential Business Information

Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to the person identified in the **FOR FURTHER INFORMATION CONTACT** section. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

### Discussion

The FAA issued AD 2019–23–05, Amendment 39–19799 (84 FR 67169, December 9, 2019) ("AD 2019–23–05"), for all Dassault Aviation Model MYSTERE–FALCON 900 airplanes. AD 2019–23–05 requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2019–23–05 to address reduced structural integrity of the airplane. AD 2019–23–05 specifies that accomplishing paragraph (g) or (i) of that AD terminates the requirements of paragraph (g)(1) of AD 2010–26–05, Amendment 39–16544 (75 FR 79952, December 21, 2010), for Dassault Aviation Model MYSTERE–FALCON 900 airplanes.

### Actions Since AD 2019–23–05 Was Issued

Since the FAA issued AD 2019–23–05, the FAA has determined that new or more restrictive airworthiness limitations are necessary.

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2020–0115, dated May 20, 2020 ("EASA AD 2020–0115") (also referred to as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct

an unsafe condition for all Dassault Aviation Model MYSTERE–FALCON 900 airplanes.

This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is proposing this AD to address reduced structural integrity of the airplane. See the MCAI for additional background information.

### Related IBR Material Under 1 CFR Part 51

EASA AD 2020–0115, dated May 20, 2020, describes new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This proposed AD would also require Chapter 5–40, Airworthiness Limitations, Revision 24, dated September 2018, of the Dassault Aviation Falcon 900 Maintenance Manual, which the Director of the Federal Register approved for incorporation by reference as of January 13, 2020 (84 FR 67169, December 9, 2019).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because the FAA has evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

### Proposed AD Requirements

This proposed AD would retain the requirements of AD 2019–23–05. This proposed AD would also require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, which are specified in EASA AD 2020–0115 described previously, as incorporated by reference. Any differences with EASA AD 2020–0115 are identified as exceptions in the regulatory text of this AD.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance

with these actions [and CDCCLs] is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (m)(1) of this proposed AD.

### Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020–0115 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2020–0115 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD.

Service information specified in EASA AD 2020–0115 that is required for compliance with EASA AD 2020–0115 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0778 after the FAA final rule is published.

### Airworthiness Limitation ADs Using the New Process

The FAA's process of incorporating by reference MCAI ADs as the primary source of information for compliance with corresponding FAA ADs has been limited to certain MCAI ADs (primarily those with service bulletins as the primary source of information for accomplishing the actions required by the FAA AD). However, the FAA is now expanding the process to include MCAI ADs that require a change to airworthiness limitation documents,

such as airworthiness limitation sections.

For these ADs that incorporate by reference an MCAI AD that changes airworthiness limitations, the FAA requirements are unchanged. Operators must revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in the new airworthiness limitation document. The airworthiness limitations must be followed according to 14 CFR 91.403(c) and 91.409(e).

### Costs of Compliance

The FAA estimates that this proposed AD affects 105 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

The FAA estimates the total cost per operator for the retained actions from AD 2019–23–05 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. In the past, the agency has estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new proposed actions to be \$7,650 (90 work-hours × \$85 per work-hour).

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
  - a. Removing Airworthiness Directive (AD) 2019–23–05, Amendment 39–19799 (84 FR 67169, December 9, 2019), and
  - b. Adding the following new AD:

**Dassault Aviation:** Docket No. FAA–2020–0778; Product Identifier 2020–NM–097–AD.

#### (a) Comments Due Date

The FAA must receive comments by October 5, 2020.

#### (b) Affected ADs

- (1) This AD replaces AD 2019–23–05, Amendment 39–19799 (84 FR 67169, December 9, 2019) ("AD 2019–23–05").
- (2) This AD affects AD 2010–26–05, Amendment 39–16544 (75 FR 79952, December 21, 2010) ("AD 2010–26–05").

#### (c) Applicability

This AD applies to all Dassault Aviation Model MYSTERE–FALCON 900 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

#### (e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Revision of Existing Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2019–23–05, with no changes. Within 90 days after January 13, 2020 (the effective date of AD 2019–23–05), revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 5–40, Airworthiness Limitations, Revision 24, dated September 2018, of the Dassault Aviation Falcon 900 Maintenance Manual. The initial compliance times for doing the tasks are at the times specified in Chapter 5–40, Airworthiness Limitations, Revision 24, dated September 2018, of the Dassault Aviation Falcon 900 Maintenance Manual, or within 90 days after January 13, 2020, whichever occurs later. The term "LDG" in the "First Inspection" column of any table in the service information specified in this paragraph means total airplane landings. The term "FH" in the "First Inspection" column of any table in the service information specified in this paragraph means total flight hours. The term "FC" in the "First Inspection" column of any table in the service information specified in this paragraph means total flight cycles. The term "M" in the "First Inspection" column of any table in the service information specified in this paragraph means months since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness. Accomplishing the maintenance or inspection program revision required by paragraph (i) of this AD terminates the requirements of this paragraph.

#### (h) Retained Restrictions on Alternative Actions or Intervals, With a New Exception

This paragraph restates the requirements of paragraph (h) of AD 2019–23–05, with a new exception. Except as required by paragraph (i) of this AD, after the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an AMOC in accordance with the procedures specified in paragraph (m)(1) of this AD.

#### (i) New Maintenance or Inspection Program Revision

Except as specified in paragraph (j) of this AD: Comply with all required actions and

compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2020-0115, dated May 20, 2020 (“EASA AD 2020-0115”). Accomplishing the maintenance or inspection program revision required by this paragraph terminates the requirements of paragraph (g) of this AD.

#### (j) Exceptions to EASA AD 2020-0115

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2020-0115 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2020-0115 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, to incorporate the “limitations, tasks and associated thresholds and intervals” specified in paragraph (3) of EASA AD 2020-0115 within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2020-0115 is at the applicable “associated thresholds” specified in paragraph (3) of EASA AD 2020-0115, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraphs (4) and (5) of EASA AD 2020-0115 do not apply to this AD.

(5) The “Remarks” section of EASA AD 2020-0115 does not apply to this AD.

#### (k) New Provisions for Alternative Actions or Intervals

After the maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections) or intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2020-0115.

#### (l) Terminating Actions for Certain Requirements in AD 2010-26-05

Accomplishing the actions required by paragraph (g) or (i) of this AD terminates the requirements of paragraph (g)(1) of AD 2010-26-05, for Dassault Aviation Model MYSTERE-FALCON 900 airplanes.

#### (m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (n)(4) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2019-23-05 are approved as AMOCs for the corresponding provisions of EASA AD 2020-0115 that are required by paragraph (i) of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (n) Related Information

(1) For information about EASA AD 2020-0115, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet: [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(2) For Dassault service information identified in this proposed AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; phone: 201-440-6700; internet: <http://www.dassaultfalcon.com>.

(3) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0778.

(4) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3226; email: [tom.rodriguez@faa.gov](mailto:tom.rodriguez@faa.gov).

Issued on August 13, 2020.

#### Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-18026 Filed 8-18-20; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF VETERANS AFFAIRS

### 38 CFR Part 9

#### RIN 2900-AQ53

### Servicemembers’ Group Life Insurance Traumatic Injury Protection Program Amendments

**AGENCY:** Department of Veterans Affairs.  
**ACTION:** Proposed rule.

**SUMMARY:** The Department of Veterans Affairs (VA) proposes to amend its regulations that govern the Servicemembers’ Group Life Insurance

(SGLI) Traumatic Injury Protection (TSGLI) program, to clarify the eligibility criteria, add definitions, and explain the application and appeals processes, including the submission of supporting evidence and the interaction between the administrative appeals process and a Federal lawsuit on a claim. VA proposes to recodify the definitions in the current regulation that are pertinent to the schedule of losses, revise existing definitions, and add new definitions. VA would add a new regulation to codify the text at the beginning of the schedule of losses, recodify that schedule, and amend the criteria for certain losses in the schedule. This rulemaking also responds to a petition for rulemaking.

**DATES:** Comments must be received on or before October 19, 2020.

**ADDRESSES:** Written comments may be submitted through <http://www.Regulations.gov>; by mail or hand-delivery to: Director, Office of Regulation Policy and Management (OOREG), Department of Veterans Affairs, 810 Vermont Ave. NW, Room 1064, Washington, DC 20420; or by fax to (202) 273-9026. (This is not a toll-free telephone number.) Comments should indicate that they are submitted in response to “RIN 2900-AQ53 Servicemembers’ Group Life Insurance Traumatic Injury Protection Program Amendments.” Copies of comments received will be available for public inspection in the Office of Regulation Policy and Management, Room 1064, between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday (except holidays). Please call (202) 461-4902 for an appointment. (This is not a toll-free telephone number.) In addition, during the comment period, comments may be viewed online through the Federal Docket Management System (FDMS) at <http://www.Regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** Paul Weaver, Department of Veterans Affairs Insurance Center (310/290B), 5000 Wissahickon Avenue, Philadelphia, PA 19144, (215) 842-2000, ext. 4263. (This is not a toll-free number.)

**SUPPLEMENTARY INFORMATION:** TSGLI provides up to \$100,000 of traumatic injury coverage to all servicemembers enrolled in SGLI. TSGLI provides a financial benefit to seriously injured SGLI insureds to assist them with expenses incurred during long periods of recovery and rehabilitation. Since the program began issuing benefits on December 22, 2005, through June 30, 2019, over \$1 billion has been paid to almost 18,500 injured servicemembers. TSGLI is modeled after commercial Accidental Death and Dismemberment