1609. The tests must be conducted with an undeformed floor, at the most-critical yaw cases for injury, and with all lateral structural supports (*e.g.*, armrests or walls) installed.

Note: Airbus must demonstrate that the installation of seats via plinths or pallets meet all applicable requirements. Compliance with the guidance contained in policy memorandum PS—ANM—100—2000—00123, "Guidance for Demonstrating Compliance with Seat Dynamic Testing for Plinths and Pallets," dated February 2, 2000, is acceptable to the FAA.

8. İnflatable Airbag Restraint Systems Special Conditions:

If inflatable airbag-restraint systems are also installed, the airbag systems must meet the requirements in the airbag (inflatable restraint) special conditions applicable to the Airbus Model A321 series airplanes.

Issued in Des Moines, Washington, on January 11, 2021.

#### Suzanne Masterson,

Manager, Transport Airplane Strategic Policy Section, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2021-05307 Filed 3-12-21; 8:45 am]

BILLING CODE 4910-13-P

## **DEPARTMENT OF TRANSPORTATION**

# **Federal Aviation Administration**

## 14 CFR Part 25

[Docket No. FAA-2020-1206; Special Conditions No. 25-781-SC]

Special Conditions: Rockwell Collins, Bombardier Model BD-100-1A10 Airplane; Electronic-System Security Protection From Unauthorized External Access

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final special conditions; request

for comments.

**SUMMARY:** These special conditions are issued for the Bombardier Model BD-100-1A10 airplane. This airplane, as modified by Rockwell Collins, will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. This design feature is the installation of a system that allows connection to airplane electronic systems and networks, and access from aircraft external to the previously isolated internal airplane electronic assets. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this

design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

**DATES:** This action is effective on Rockwell Collins on March 15, 2021. Send comments on or before April 29, 2021.

**ADDRESSES:** Send comments identified by Docket No. FAA–2020–1206 using any of the following methods:

- Federal eRegulations Portal: Go to http://www.regulations.gov/ and follow the online instructions for sending your comments electronically.
- Mail: Send comments to Docket Operations, M–30, U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.
- Hand Delivery or Courier: Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* Fax comments to Docket Operations at 202–493–2251.

Privacy: Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received without change, to <a href="http://www.regulations.gov/">http://www.regulations.gov/</a>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposal.

Confidential Business Information: Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this Notice contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this Notice, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and the indicated comments will not be placed in the public docket of this Notice. Send submissions containing CBI to the person indicated in the Contact section below. Comments the FAA receives,

which are not specifically designated as CBI, will be placed in the public docket for this rulemaking.

Docket: Background documents or comments received may be read at http://www.regulations.gov/ at any time. Follow the online instructions for accessing the docket or go to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

## FOR FURTHER INFORMATION CONTACT:

Varun Khanna, Aircraft Information Systems Section, AIR–622, Technical Innovation Policy Branch, Policy and Innovation Division, Aircraft Certification Service, Federal Aviation Administration, 2200 South 216th Street, Des Moines, Washington 98198; telephone and fax 206–231–3159; email varun.khanna@faa.gov.

**SUPPLEMENTARY INFORMATION:** The substance of these special conditions has been published in the **Federal Register** for public comment in several prior instances with no substantive comments received. Therefore, the FAA finds, pursuant to 14 CFR 11.38(b), that new comments are unlikely, and notice and comment prior to this publication are unnecessary.

# **Comments Invited**

The FAA invites interested people to take part in this rulemaking by sending written comments, data, or views. The most helpful comments reference a specific portion of the special conditions, explain the reason for any recommended change, and include supporting data.

The FAA will consider all comments received by the closing date for comments. The FAA may change these special conditions based on the

comments received.

# Background

On May 3, 2019, Rockwell Collins applied for a supplemental type certificate for installation of the Rockwell Collins Pro Line Fusion System in the Bombardier Model BD–100–1A10 airplane, requiring security protection from unauthorized external access. The Bombardier Model BD–100–1A10 airplane is a twin-engine, transport-category airplane with a passenger capacity of 19 and a maximum takeoff weight of 40,600 pounds.

# **Type Certification Basis**

Under the provisions of title 14, Code of Federal Regulations (14 CFR) 21.101, Rockwell Collins must show that the Bombardier Model BD–100–1A10

airplane, as changed, continues to meet the applicable provisions of the regulations listed in Type Certificate No. T00005NY, or the applicable regulations in effect on the date of application for the change, except for earlier amendments as agreed upon by the FAA.

If the Administrator finds that the applicable airworthiness regulations (e.g., 14 CFR part 25) do not contain adequate or appropriate safety standards for the Bombardier Model BD–100–1A10 airplane because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

Special conditions are initially applicable to the model for which they are issued. Should the applicant apply for a supplemental type certificate to modify any other model included on the same type certificate to incorporate the same novel or unusual design feature, these special conditions would also apply to the other model under § 21.101.

In addition to the applicable airworthiness regulations and special conditions, the Bombardier Model BD—100—1A10 airplane must comply with the fuel-vent and exhaust-emission requirements of 14 CFR part 34, and the noise-certification requirements of 14 CFR part 36.

The FAA issues special conditions, as defined in 14 CFR 11.19, in accordance with § 11.38, and they become part of the type certification basis under § 21.101.

# **Novel or Unusual Design Features**

The Bombardier Model BD–100–1A10 airplane, as modified by Rockwell Collins, will incorporate the following novel or unusual design feature:

Installation of the Rockwell Collins Pro Line Fusion System, which allows connection to airplane electronic systems and networks, and access from aircraft external sources (e.g., operator networks, wireless devices, internet connectivity, service provider satellite communications, electronic flight bags, etc.) to the previously isolated airplane electronic assets.

## Discussion

The Bombardier Model BD–100–1A10 airplane architecture and network configuration is novel or unusual for commercial transport airplanes because it may allow increased connectivity to and access from external network sources and airline operations and maintenance networks to the airplane control domain and airline information services domain. The airplane control domain and airline information-services domain perform functions required for

the safe operation and maintenance of the airplane. Previously, these domains had very limited connectivity with external network sources. This data network and design integration creates a potential for unauthorized persons to access the aircraft-control domain and airline information-services domain, and presents security vulnerabilities related to the introduction of computer viruses and worms, user errors, and intentional sabotage of airplane electronic assets (networks, systems, and databases) critical to the safety and maintenance of the airplane.

The existing FAA regulations did not anticipate these networked airplane system architectures. Furthermore, these regulations and the current guidance material do not address potential security vulnerabilities, which could be exploited by unauthorized access to airplane networks, data buses, and servers. Therefore, these special conditions ensure that the security (i.e., confidentiality, integrity, and availability) of airplane systems is not compromised by unauthorized wired or wireless electronic connections. This includes ensuring that the security of the airplane's systems is not compromised during maintenance of the airplane's electronic systems. These special conditions also require the applicant to provide appropriate instructions to the operator to maintain all electronic-system safeguards that have been implemented as part of the original network design so that this feature does not allow or reintroduce security threats.

These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

# **Applicability**

As discussed above, these special conditions are applicable to the Bombardier Model BD–100–1A10 airplane. Should Rockwell Collins apply at a later date for a supplemental type certificate to modify any other model included on Type Certificate No. T00005NY to incorporate the same novel or unusual design feature, these special conditions would apply to that model as well.

# Conclusion

This action affects only a certain novel or unusual design feature on one model of airplane, as modified by Rockwell Collins. It is not a rule of general applicability and affects only the applicant.

## List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

## **Authority Citation**

The authority citation for these special conditions is as follows:

**Authority:** 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, 44704.

## The Special Conditions

- Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Bombardier Model BD-100-1A10 airplanes, as modified by Rockwell Collins, for airplane electronic-system security protection from unauthorized external access.
- 1. The applicant must ensure airplane electronic-system security protection from access by unauthorized sources external to the airplane, including those possibly caused by maintenance activity.
- 2. The applicant must ensure that electronic-system security threats are identified and assessed, and that effective electronic-system security-protection strategies are implemented to protect the airplane from all adverse impacts on safety, functionality, and continued airworthiness.
- 3. The applicant must establish appropriate procedures to allow the operator to ensure that continued airworthiness of the airplane is maintained, including all post-type-certification modifications that may have an impact on the approved electronic-system security safeguards.

Issued in Des Moines, Washington, on February 9, 2021.

## Suzanne Masterson,

Manager, Transport Airplane Strategic Policy Section, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2021–05294 Filed 3–12–21; 8:45 am]

BILLING CODE 4910-13-P

## **DEPARTMENT OF TRANSPORTATION**

## **Federal Aviation Administration**

## 14 CFR Part 39

[Docket No. FAA-2020-0916; Product Identifier 2015-SW-055-AD; Amendment 39-21449; AD 2021-05-06]

# RIN 2120-AA64

# Airworthiness Directives; Airbus Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.