

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2021–15–52 Various Restricted Category Helicopters:** Amendment 39–21664; Docket No. FAA–2021–0605; Project Identifier AD–2021–00805–R.

#### (a) Effective Date

This airworthiness directive (AD) is effective without actual notice on August 13, 2021. Emergency AD 2021–15–52, issued on July 8, 2021, which contained the requirements of this amendment, was effective with actual notice.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to various restricted category helicopters originally manufactured by Bell Textron Inc. (Bell), certificated in any category, with an outboard main rotor hub strap pin (pin) part number 204–012–104–005 with a serial number prefix “FNFS” installed. These helicopters include but are not limited to:

- (1) Rotorcraft Development Corporation Model HH–1K helicopters;
- (2) Robinson Air Crane Inc.; Rotorcraft Development Corporation; and Tamarack Helicopters, Inc., Model TH–1F helicopters;
- (3) Bell; Overseas Aircraft Support, Inc. (type certificate previously held by JTBAM, Inc.); and Rotorcraft Development Corporation Model TH–1L helicopters;
- (4) Richards Heavylift Helo, Inc., Model UH–1A helicopters;
- (5) International Helicopters, Inc.; Overseas Aircraft Support, Inc.; Red Tail Flying Services, LLC; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation International, Inc.; and WSH, LLC (type certificate previously held by San Joaquin Helicopters), Model UH–1B helicopters;

**Note 1 to paragraph (c)(5):** Helicopters with an SW204 or SW204HP designation are Southwest Florida Aviation International, Inc., Model UH–1B helicopters.

- (6) Bell; Overseas Aircraft Support, Inc.; Rotorcraft Development Corporation; Smith Helicopters; and West Coast Fabrications Model UH–1E helicopters;
- (7) AST, Inc.; California Department of Forestry; Robinson Air Crane, Inc.; Rotorcraft Development Corporation; and Tamarack Helicopters, Inc., Model UH–1F helicopters;
- (8) Arrow Falcon Exporters Inc.; Global Helicopter Technology, Inc.; Hagglund Helicopters, LLC; JJASPP Engineering Services, LLC; Northwest Rotorcraft, LLC; Overseas Aircraft Support, Inc.; Richards Heavylift Helo, Inc.; Rotorcraft Development Corporation; Southwest Florida Aviation

International, Inc.; and Tamarack Helicopters, Inc., Model UH–1H helicopters;

**Note 2 to paragraph (c)(8):** Helicopters with an SW205 designation are Southwest Florida Aviation International, Inc. Model UH–1H helicopters.

(9) Bell; Overseas Aircraft Support, Inc.; and Rotorcraft Development Corporation Model UH–1L helicopters; and

(10) Robinson Air Crane, Inc.; and Rotorcraft Development Corporation Model UH–1P helicopters.

#### (d) Subject

Joint Aircraft System Component (JASC) Code: 6200, Main Rotor System.

#### (e) Unsafe Condition

This AD was prompted by a fatal accident in which a pin sheared off during flight, which resulted in the main rotor blade and the main rotor head detaching from the helicopter. The FAA is issuing this AD to address this unsafe condition and prevent loss of control of the helicopter.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

(1) Before further flight, remove from service any pin that is identified in the introductory text of paragraph (c) of this AD.

(2) As of the effective date of this AD, do not install any pin that is identified in the introductory text of paragraph (c) of this AD on any helicopter.

#### (h) Special Flight Permits

Special flight permits are prohibited.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, DSCO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the DSCO Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-ASW-190-COS@faa.gov](mailto:9-ASW-190-COS@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Related Information

(1) For more information about this AD, contact David Wilson, Aerospace Engineer, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5786; email [david.wilson@faa.gov](mailto:david.wilson@faa.gov).

(2) The subject of this AD is addressed in Transport Canada Emergency AD CF–2021–23, dated July 5, 2021 and FAA Emergency AD 2021–15–51, dated July 6, 2021. You may view those ADs at <https://www.regulations.gov> in Docket No. FAA–2021–0605.

Issued on July 21, 2021.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021–16222 Filed 7–27–21; 11:15 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2020–0544; Airspace Docket No. 19–AAL–93]

RIN 2120–AA66

#### Removal of Air Traffic Service (ATS) Route V–482; Alaska

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action revokes one Alaskan VHF Omnidirectional Range (VOR) Federal airway V–482 in the state of Alaska. The removal is required due to tree encroachment on the Johnstone Point VOR/Distance Measuring Equipment (DME) that renders the airway unusable.

**DATES:** Effective date 0901 UTC, October 7, 2021. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**FOR FURTHER INFORMATION CONTACT:** Christopher McMullin, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

**SUPPLEMENTARY INFORMATION:**

### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it supports modifying, removing, and establishing the air traffic service route structure in Alaska to maintain the efficient flow of air traffic.

### History

The FAA published a notice of proposed rulemaking for Docket No. FAA-2020-0544 in the **Federal Register** (85 FR 37033; June 19, 2020), removing VOR Federal airway V-482 in the state of Alaska. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. No comments were received.

Alaskan VOR Federal airways are published in paragraph 6010(b) of FAA Order 7400.11E dated July 21, 2020, and effective September 15, 2020, which is incorporated by reference in 14 CFR 71.1. The Alaskan VOR Federal airway listed in this document will be subsequently removed from this Order.

### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020, and effective September 15, 2020. FAA Order 7400.11E is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11E lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

### The Rule

This action amends 14 CFR part 71 by removing Alaskan VOR Federal airway V-482.

**V-482:** V-482 currently extends between Johnstone Point, AK to Gulkana, AK. This action removes the entire route.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

### Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Environmental Review

The FAA has determined that this action of revoking VOR Federal airway V-482 in Alaska qualifies for categorical exclusion under the National Environmental Policy Act (42 U.S.C. 4321 *et seq.*) and its implementing regulations at 40 CFR part 1500, and in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5a, with categorically excludes from further environmental impact review rulemaking actions that designate or modify classes of airspace areas, airways, routes, and reporting points (see 14 CFR part 71, Designation of Class A, B, C, D, and E Airspace Areas; Air Traffic Service Routes; and Reporting Points). As such, this action is not expected to cause any potentially significant environmental impacts. In accordance with FAA Order 1050.1F, paragraph 5-2 regarding Extraordinary Circumstances, the FAA has reviewed this action for factors and circumstances in which a normally categorically excluded action may have a significant environmental impact requiring further analysis. The FAA has determined that no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### The Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

#### § 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020, and effective September 15, 2020, is amended as follows:

*Paragraph 6010(b) Alaskan VOR Federal Airways.*

\* \* \* \* \*

#### V-482 [Remove]

\* \* \* \* \*

Issued in Washington, DC, on July 22, 2021.

**George Gonzalez,**

*Acting Manager, Rules and Regulations Group.*

[FR Doc. 2021-16024 Filed 7-28-21; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2020-0567; Airspace Docket No. 20-AAL-15]

RIN 2120-AA66

### Amendment to Federal Airways Amber 15 (A-15), V-444, J-502, J-511, and Extension of Canadian Area Navigation Routes Q-902 and Q-811; Alaska

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This action corrects a final rule published by the FAA in the **Federal Register** on July 15, 2021. This action amends Federal airways, A-15, V-444, J-502, and J-511 in Alaska. It also establishes an extension of two Canadian Area Navigation Q routes, Q-811, and Q-902. The modifications are necessary due to the decommissioning of the Burwash Non-Directional Beacon (NDB) in Yukon Territory, Canada, which provides navigation guidance for portions of the affected routes. The Burwash NDB was decommissioned effective March 26, 2020 due to ongoing maintenance problems and logistic issues.